

2. எண்ணிக்கை - 14
4. தி. நாள் - மார்ச்சி 1991
அ. சிவசுப்பிரமணியம் by

P. 001.

1337
18-5 1893

சுவாமி

1331

Buildings and Roads.
Civil Works.

Proceedings of the Board of Revenue (Separate Revenue), dated 17th April
1893. Mis. No. 1403.

I have the honour to request that the Board will be good enough to obtain the sanction of Government to the Public Works Workshops providing two new turn-tables in the Custom house in lieu of the present ones, which have become unfit for use from corrosion and are irreparable.

3. I enclose a report received from the Superintendent, Public Works Workshops, regarding the condition of the present turn-tables and the estimated cost of replacing them by smaller ones which would answer as well.

Copy of communication from L. L. WICKHAM, Esq., General Superintendent, Public Works
Workshops, to the Consulting Architect to Government, dated 18th February 1893.
No. 15 C.A.

2. The deterioration of the old ones is, I think, due to improper drainage and want of painting and the iron work has been allowed to rust right through. It is questionable whether it is worthwhile to put down such large ones again as the trucks that enter the Custom house have, I suppose, to be able to be turned on the table on the pier which are $10\frac{1}{2}$ feet diameter against 15 feet diameter in the Custom house.

$10\frac{1}{2}$ feet	...	...	...	...	...	...	...	...	...	Rs.
15 "	...	...	...	...	...	...	...	...	...	1,350
										3,000
								Difference		<u>1,650</u>

18TH MAY 1893, No. 1337 W., PUBLIC WORKS.

Resolution—dated 17th April 1893, Mis. No. 1403.

The Board recommends, for the sanction of Government and for execution in the Public Works Department, the Collector's proposal to replace the two old truck turn-
tables in the Custom house, which are considered to be irreparable, by two smaller
ones of 10½ feet diameter, which, according to the report of the Superintendent of the
Public Works Workshops, will cost Rs. 1,350 each.

(True Copies and Extract.)

(Signed) EDMUND MILLETT,
Assistant Secretary.

No. 161, Revenue.

Transferred to the Public Works Department for the issue of the necessary
orders.

OOTACAMUND,
9th May 1893.

(Signed) R. H. CAMPBELL,
Acting Under Secretary.

ORDER—dated 18th May 1893, No. 1337 W., Public Works.

The estimate of Rs. 2,700 for supplying two new turn-tables to the Sea Customs
house is sanctioned as a charge against "Civil Buildings, Original Works." The
work will be carried out by the General Superintendent, Public Works Workshops,
and the charge debited to the Consulting Architect's division.

2. An allotment of Rs. 2,700 is made to that division from the Provincial
reserve.
3. This sanction has been registered as Provincial No. 24 W. of 1893-94.

(True Extract.)

Major, R.E.,
Under Secy. to Govt., P.W.D.

To the Consulting Architect.
" Superintending Engineer, V Circle.
" Examiner, Public Works Accounts.
" Revenue Department.

Exd. A. D. Xavier.
Spare Copies

1337
2

BUILDINGS AND ROADS.
CIVIL WORKS.

Gobt. of {1893} Madras.

PUBLIC WORKS.

Dated May, 18th.

Recd.

Encl.

G.O., 18th May 1893, No. 1337 W.

MAY.

Turn-tables to the Sea Customs
House

Estimate of Rs. 2,700 for supplying two new — sanctioned, the work being carried out by the General Superintendent, Public Works Workshops, and the charge debited to the Consulting Architect's division.

Office of the Consulting Architect
to the Government of Madras

No. Chepauk 1893

Copy of communication from L. L. Wickham Esq. General Superintendent P. W. Workshops to the Consulting Architect to Government No. $\frac{15}{C.A}$ dated 18th February 1893

With reference to your letter No. 2002 dated the 30th September 1892 I have the honor to state that the Turntables in the Custom House have been inspected and found to be irreparable. An estimate amounting to Rs. 6,000 for providing 2 new Turntables is herewith sent. The proposed new Turntables are similar in size to the old ones.

The deterioration of the old ones is I think, due to improper drainage and want of painting and the ironwork has been allowed to rust right through. It is questionable whether it is worthwhile to put down such large ones again as the Trucks that enter the Custom House have I suppose to be able to be turned on the Table on the pier which

are $10\frac{1}{2}$ feet diameter, against 15 feet diameter in the Custom House.

3. The difference in the cost is

$10\frac{1}{2}$ feet - - - 1350

15 feet - - - 3000

Difference 1650

(SD) Henry Irvine
Consulting Architect to Govt

(True Copy)

Sea Custom House } (SD) W Austin
Madras 11th April 1893 } Collector of Sea Customs

(True Copy)

Board of Revenue }
Separate Revenue }
17th April 1893 }

Commissioner
Assistant Secretary

W.A.

8.1
No 1605/93



Read the following
No. 1403, 1405, 1407

Proceedings of the Board of Revenue

(Separate Revenue).

Dated 17th April 1893.

No. 1403 Meis.

Read the following letter from
W. P. Austin Esq. Collector of Sea Customs,
Madras to the Secretary to the Commissioner
of Salt, Akhri and Separate Revenue
Madras, dated 11th April 1893 No. 600 G.

I have the honor to request that
the Board will be good enough to obtain
the sanction of Government to the Public
Works Workshops providing 2 new turn-
tables in the Custom House in lieu of the
present ones, which have become unfit
for use from corrosion and are irreparable.

2. I regret that no papers can be
traced to show when the present tables
were laid down and from what source
their cost was met, but I presume that
they must have been provided for in
the general estimate in connection

with

1337
4

ar with the construction of the pier. The
dis cost of shifting the position of one of
3. them in 1881 appeared however to have
been borne by Government, the work
having been classified as civil buildings-
original works. Vide Board's Proceedings
No. 2127 dated 22nd September 1881

3. I enclose a report received from
the Superintendent, Public Works
Workshops regarding the ^{condition} position of the
present turntables and the estimated cost
of replacing them by smaller ones
which would answer as well.

Resolution dated 17th April 1882 No. 1403

The Board recommends for the sanction
of Government, and for execution in the
Public Works Department the Collector's proposal
to replace the two old truck turn tables in the
Custom House which are considered
to be irreparable by two smaller ones of
10½ feet diameter which according to the report
of the Superintendent of the Public Works
Workshops will cost Rs. 1350 each.

(True Copy and Extract)

Kamasa Muthu

Assistant Secretary

To
The Secretary to Government, Revenue Dept.
Collector of Beaulieu and Newstead
New

fm

1337

2. New Turn Tables
6th Seafront
House Meadow

14605

Govt. of Madras.
PUBLIC WORKS.

Dated

Read

Encl.

G.O. 18 May 1883 No. 1337W

Memorandum to the
Sea Customs House

=

Estimate of Rs 2700
for supplying two new
sanctuaries, the
work being carried
out by the Govt. Engineer
P.W.D. & the charges
debited to the Coring
Architect Dr.

85/6

2.10.1914 1915