

- (1) பக்கங்களின் எண்ணிக்கை 16
- (2) புதுக்கித் திருப்பிய நாள் ஜனவரி 1991
- (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 10/3

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

11.10.91 வந்த துறை

அரசாணை எண்.	2240	அச்சகம்
மு. கோப்புத் தாள் எண்.		பலவகை
நாள் :	31.8.1993.	198

சுருக்கொப்பம்

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

READ—the following paper:—

From A. A. G. MALET, Esq., Executive Engineer, Kistna Western division, to the Superintending Engineer, II Circle, dated 24th July 1893, No. 219 S.

In G.O., No. 785 W., dated 22nd March 1893, it is stated "... and there would be a free passage by day as well as by night through his (the cashier's) room by the doors C and D ..."

2. This evidently contemplates having doors C and D of the cashier's room open all night for the beat of the Police guard. It is therefore to be presumed that there is no intention to close these two doors, C and D, at night.

3. As clerks and others must enter by one or the other of these two doors during the day, it is evident that one door at least must be kept open during the day, but it is possible that on account of strong winds, &c., one or other of the two doors may be closed during the day.

4. The estimate provides for iron grated doors with strong batten shutters for the doors C and D.

5. This seems to me to be a most unnecessary expense, and for the reasons given above it would suffice to provide glazed doors which would keep out wind but let in light if closed during the day time.

	RS.
The cost at the workshops of two iron grated doors with strong batten shutters is	223
The cost at the workshops of two glazed doors	111
Difference	112

and the cost of carrying the former would of course be greater than that of carrying the latter to site of work.

6. In Chief Engineer, Public Works Department's memo. No. 4236 C., dated 23rd September 1892, the ventilators in rear wall of passage and treasury are ordered to be built up. This order should, for exactly the same reasons, be extended to the ventilator in rear wall of head accountant's room.

7. The ventilator in the rear wall of the head accountant's room could be built in as it comes opposite to the centre of the record room, but it would give neither light nor ventilation.

No. 1107 K.S.

Forwarded to the Chief Engineer, Public Works Department, for disposal.

2. It seems to me that it is quite unnecessary to provide iron grated doors at C and D and that an ordinary batten door at each place would answer requirements. I think glazed doors need not be provided.

3. I think the other alterations suggested by the Executive Engineer should be carried out.

29th July 1893.

(Signed) J. W. MARTIN,
Superintending Engineer, II Circle.

31st August 1893, No. 2240 W., Public Works.

ORDER—dated 31st August 1893, No. 2240 W., Public Works.

As the doors C and D are to be left open at night, there is no necessity for their being of the description provided in the estimate, viz., iron grated with strong batten shutters. They should be constructed venetianed and panelled in keeping with the other outer doors of the building.

2. The ventilator in the head accountant's room should remain as designed.

3. The necessary corrections should be made in the type design circulated with G.O., No. 3043 W., dated 11th November 1891.

(True Extract.)

Major, R.E.,
Under Secy. to Govt., P.W.D.

To Superintending Engineers.
„ the Consulting Architect.
„ the Revenue Department.

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of {1893} Madras.
PUBLIC WORKS.

Dated August, 31st.

Recd.

Encl.

G.O., 31st Aug. 1893, No. 2240 W.

AUGUST.

Type design of Taluk Offices

Certain corrections in the — circulated
with G.O., No. 3023 W., dated 11th
November 1891, ordered.

From A. A. G. & Malet Esquiro, Engineer,
Western Division to
the Superintending Engineer, W. A.
dated 24th July 1893 No. 219 S.

In G.O. No. 785 W. A., 22nd March
1893, it is stated: " * * and there
" would be a free passage by day
" as well as by night through his
" (the Cashier's) room by the doors C
" and D * * * "

2. This evidently contemplates
having doors C and D of the Cashier's
room open all night for the use
of the Police guard. It is therefore
to be presumed that there is no
intention to close these 2 doors C
and D at night.

3. As clerks and others must enter
by one or the other of these 2 doors
during the day it is evident that
one door at least must be kept
open during the day but it is
possible that on account of strong
winds &c one or other of the 2 doors
may be closed during the day.

4. The Estimate provides for iron
grated doors with strong hatter
shutters.

shutters for the doors C & D.

5. This seems to me to be a most unnecessary expense, and for the reasons given above, it would suffice to provide glazed doors which would keep out wind, but let in light if closed during the daytime.

The cost at the Workshops
of 2 iron grated doors with
strong hatched shutters is—

R's

223

do - do of 2 glazed doors. 111

Difference 112

and the cost of carrying the former would of course be greater than that of carrying the latter to site of work.

6. In Chief Engineer, P. W. D. S. Memo No. 4236 C of 23-9-92 the ventilators in rear wall of passage & Treasury are ordered to be built up. This order should, for exactly the same reasons, be extended to the ventilator in rear wall of Head Accountants Room.

7. The ventilator in the rear wall of the Head Accountants Room could be built in as it comes opposite to the Centre of the Records Room, but it would give neither light nor

nor ventilation.

No 11076
29-7-93

21/4

Forwarded to the
Chief Engineer, P. W. Department
for disposal.

2. It seems to me that ^{it} is quite unnecessary to provide iron grated doors at C & D. and that an ordinary hatched door at each place would answer requirements. I think glazed doors need not be provided.

3. I think the other alterations suggested by the Executive Engineer should be carried out.

L. W. Martin

Superintending Engineer

X. H. C. 11 C. 11

29-7-93

22 1495 W 8 3. 6. 87
2023 W 8 11. 11. 94
1533 W 8 12. 8. 92
4226 E 8 20. 9. 92
750-0 8 22. 0. 90

From
The Sup. Engr. in
20 Circle

To The Chief Engineer
Public Works Dept.
Madras

Order 31-7-93
Dated 29-7-93

No 1107 Ks

First class Drawing Office
Type plans for - forwards
Copy of Krishna W. S. S. S.
Office letter suggesting certain
alterations in the - for
disposal.

OK 196
20/9

N^o 2240 W of 31st August 1893.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

2200
Read the following


From the Supt. Engr., II Circle, No. 1107 K. S.
dated 29th July 1893

30

As the doors C and D
are to be left open at night
there is no necessity for their
being of the description provided
in the estimate viz: Iron grated,
with strong batten shutters. They
should be constructed venetian
and panelled in keeping with
the other outer doors of the
building.

2. The ventilator in the Head
Accountant's room should remain
as designed.

3. The necessary corrections
should be made in the type
design circulated with G.O. No. 3023
W dated 11th November 1891.



tg. Engineers
Comm. Architect
Revenue Dept.
10-200-22-5-93.

28/8/93
11/11/93

OK 196
20/9

Read the following:— ^{22/10}

From the Suptg. Engineer's File N° 1107 H. d. 29. vii. 93.

FOR ORDERS.

As the doors C and D are to be left open at night, there is no necessity for their being of the description provided in the estimate, viz, iron grated, with strong latten shutters.

It is suggested that they be constructed veneered and panelled, in keeping with the other outer doors of the building.

The ventilator in the Head Accountants room should remain as designed.

J. H.
B.

Yes.
No.

all
9.8.93

11/12/8

22/196
22/10/8

which was with small
in chard

H. 924
 Type Designs
 of Salubrious

2240

025196
 H. 11/8

2240
 8
 Current W. 6651

note

2240/7

The suggestions of the E. E. regarding
 sing deviation to the Cuckins were
 doors appear to be reasonable but
 it is submitted for orders that
 variations & panel doors ~~may~~
 appear to be the best arrange-
 ment, as it will then be in
 keeping with the other outer
 doors of the Telling Office.

Glazed shutters will do very
 well to shut out the wind &
 still admit light but the S.E.'s
 suggestion to provide bottom
 shutters may not appear
 suitable, as it will preclude
 light in case of wind.

Regarding the ~~vent~~ ven-
 tilator referred to it was
 intentionally omitted when
 the correction memo (W. 4236
 of 23rd Sept 1892) was submitted
 for approval.

Though there will be no light
 nor ventilation, as stated by
 the E. E., still it is submitted
 that a free current of fresh
 air will be admitted through
 this ventilation if built to the
 second room which will generally
 be closed.

For order: 4/11/3

CW 6657

Govt. of India
PUBLIC WORKS.

Date

By

Line

6031 Aug 1887, No. 2240N

Type designs of taluk
offices

=

Certain corrections
in the — circulation
with G.O. No. 3023 W of
11.11.91, ordered.

W
K

3 C. 214
2/9