(1) பக்கங்களின் எண்ணிக்கை 20
(2) புதுக்கித் திருப்பிய நாள் 1/93
(3) ஆதாரங் குறிப்பவர் சுருக்கொப்பம்

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

துறை

அரசாணை எண்.
மு. கோப்புத் தாள் எண். 2481

அச்சகம்
பலவகை

நாள் : 27-9-1893 ~~199~~

10

மடிக்கவோ கண்டபடி கையாளவோ கூடாது.

27th September 1893, No. 2481 W., Public Works.

2481/1

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

Read—again the following paper:—

G.O., dated 12th August 1893, No. 2076 W., Public Works.

Read—the following papers:—

From Major A. W. SMART, R.E., Superintending Engineer, IV Circle, to the Chief Engineer, Public Works Department, dated Coimbatore, 15th June 1893, No. 239 E.W.

The Executive Engineer, Salem division, brings to notice that, with the sanction of Government conveyed in G.O., No. 380 M., dated 12th August 1885, the European burial-ground at Salem was closed from 1st December 1885 and another one on the Omalúr road was provided for at the cost of the municipality; and it was decided in G.O., No. 458 M., Local and Municipal, dated 5th May 1888, that the cemetery is the property of Government; but this item was through oversight omitted to be included in the list of churches and cemeteries, printed with G.O., Nos. 2746 W. and 572 W. of 17th October 1891 and 20th February 1892, respectively, which are to be maintained and repaired by the Public Works Department.

2. I have the honour to request you will be good enough to cause the cemetery to be included in the list to enable the Executive Engineer to execute the needful repairs.

No. 423 D.

Referred to the Ecclesiastical Department for remarks.

(Signed) J. HANNAN,
Ag. Joint Secy. to Govt., P.W.D.

19th June 1893.

No. 1129, Ecclesiastical.

Referred to the Venerable the Archdeacon for favour of remarks.

(Signed) J. F. PRICE,
Chief Secretary.

Ootacamund,
28th June 1893.

G.O., dated 28th July 1893, No. 63, Ecclesiastical.

Read—endorsement of the Public Works Department, dated 19th July 1893, No. 423 D., on letter from the Superintending Engineer, IV Circle, dated 13th June 1893, No. 239.

Read—the following letter from the Venerable the Archdeacon of Madras, dated 22nd July 1893, No. 1556 :—

I have the honour to acknowledge the receipt of your endorsement, dated 28th June 1893, No. 1129, on Public Works Current No. 5433—Ecclesiastical Current No. 145.

2. The Superintending Engineer, IV Circle, is mistaken in supposing that the cemetery on the Omalúr road, Salem, was through oversight omitted to be included in the list of cemeteries which are to be maintained and repaired by the Public Works Department. It was intentionally omitted.

3. I have the honour to point out that, if this cemetery be included in the list of those cemeteries which are to be repaired by the Public Works Department, the clearly defined line which is followed in that list will be broken.

4. The list of churches and cemeteries to be repaired by the Public Works Department, as approved in G.O., dated 17th October 1891, No. 2746 W., Public Works, includes only (1) military churches, (2) military cemeteries, (3) those churches and cemeteries which are in Madras, Bangalore and on the Nilgiris and which have been placed under the Public Works Department by various Government Orders.

5. If any churches or cemeteries which are not military and neither in the Presidency town or Bangalore or in the Nilgiri division be placed under the Public Works Department, there will, I think, be in the future, as there was in the past, some confusion. I respectfully suggest therefore that the new cemetery at Salem should not be placed under the Public Works Department.

Order—dated 28th July 1893, No. 63, Ecclesiastical.

The Venerable the Archdeacon's letter read above will be communicated to the Public Works Department.

(True Extract.)

(Signed) J. F. PRICE,
Chief Secretary.

Order—dated 12th August 1893, No. 2076 W., Public Works.

Communicated to the Superintending Engineer, IV Circle, with reference to his letter No. 239 E.W., dated 13th June 1893.

2. In the circumstances stated the new cemetery at Salem will not be brought on the Public Works list.

(True Extract.)

(Signed) J. HANNAN,
Ag. Joint Secy. to Govt., P.W.D.,
General, Buildings and Roads Branch.

2481/2

Read—also the following paper :—

From G. E. MANSON, Esq., Executive Engineer, Salem Division, to the Superintending Engineer, IV Circle, dated 6th September 1893, No. 380 S.E.

[*Reference.*—Your No. 280 S.L., dated 31st August 1893, regarding the new cemetery at Salem.]

The new cemetery at Salem has been repaired and the work paid for, as the work was urgently needed. It was carried out at the request of the lay trustees, as the repairs by this department appeared to be required, as already reported, under *G.O., No. 458 M., dated 5th May* 1888, which declares that Government is responsible for its maintenance.

2. I request that you will give a circle register number to the estimate as the work is already done in order to obviate objections to the expenditure incurred by the Examiner, Public Works Accounts.

3. If this work should not have been executed by this department, I request that you will inform me who is responsible for the repair of this cemetery to enable me to take steps for the adjustment of the expenditure incurred.

No. 349 E.W.

Copy forwarded to the Chief Engineer, Public Works Department, for favour of instructions with reference to G.O., No. 2076 W., dated 12th August 1893.

2. In the circumstances explained by the Executive Engineer, it is presumed that the cost of maintaining the cemetery should be met from the Public Works grant although it is not brought on the Public Works list, and until orders of Government are issued that such charges should be borne by any other department.

(Signed) A. W. SMART, Lt.-Col., R.E.,
Suptg. Engineer, IV Circle.

10th September 1893.

Order—dated 27th September 1893, No. 2481 W., Public Works.

The cost of repairs to Government churches and cemeteries not on the Public Works list should be met from the allotment made in the Ecclesiastical budget under "Petty construction and repairs."

2. The expenditure incurred by the Public Works Department on the cemetery at Salem should be transferred to the Civil Department.

(True Extract.)

Major, R.E.,
Under Secy. to Govt., P.W.D.

To the Superintending Engineer, IV Circle.
,, other Superintending Engineers.
,, the Consulting Architect to Government.
,, the Examiner, Public Works Accounts.
,, the Ecclesiastical Department.

Exd. C. A. Munisawmy.
Spare Copies

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of {1893} Madras.
PUBLIC WORKS.

Dated September, 27th.

Recd. Encl.

G.O., 27th Sept. 1893, No. 2481 W.

SEPTEMBER.

Government Churches and Cemeteries

Orders regarding incidence of the cost of repairing — not on the Public Works list.

Supdg: Engr: Office 4th C
No. 239/E.W. Coimbatore 13th June 1893,

2481/3

From

Major A. W. Smart, R.E.
Superintending Engineer
4th Circle,

To

The Chief Engineer
P. W. Department

Sir,

The Executive Engineer Salem Division brings to notice that with the sanction of Government conveyed in G. O. No. 380 M dated 12th August 1885, the European Burial ground at Salem was closed from December 1885, and another one on the Omalur road was provided for at the cost of the Municipality, and it was decided in G. O. No. 458 M. Local and Municipal dated 5th May 1888 that the Cemetery is the propert property of Government, but this item was through oversight omitted to be included in the list of Churches and Cemeteries printed with G.O. No 2746 W and 572 W of 27th October 1891 and 20th February 1892 respectively which are to be maintained and repaired by the D.P.W.

2 I have the honor to request you will be good enough to cause the Cemetery to be included in the list to enable the Executive Engineer to execute the needful repairs.

I have the honor to be
Sir,
Your most Obedt. Servt.

Major R.E.
Superintending Engineer 4th C

E/1

P. W. CURRENT No. 5433

From

6956/93

The Supg. Engineer,

Fourth circle.

19 JUN 93

Eccl. G.O. 428 d 15-6-92 [illegible]
" 19 d 15-3-92
" 1 d 4-1-92
" 39 d 8-6-92
" 99 d 21-12-91 [illegible]
" 110 d 16-12-91 [illegible]
" 94 d 3-12-91 [illegible]
" 188 d 6-11-91 [illegible]
Lim. 45 [illegible] 5-5-93 [illegible]
Fncl. 380 d 12-9-93 [illegible]

Dated 13th June/93.

Recd: 14. 6. 93

No: 239
E.W.

New Cemetery at Salem.

Requesting that the — be included in the list of Churches and Cemeteries to be maintained and repaired by this department.

No. 2746 W d 17.10.91
" 572 W d 20.2.92

No. 423 D dy 19th June/93

Referred to the Ecclesiastical Dept. for remarks

J. Hamm[illegible]

Ag. Joint Secty to Govt
P.W.D.

No 1129

Referred to the Venerable the Archdeacon for favour of remarks.

Chief Secretary

P.D. 23/6
Ootacamund 28.VI.93

To The Venerable the Archdeacon

[G. / 68]

Ecclesiastical Department

2418
3

CHIEF SECRETARIAT, MADRAS.

G.O. dated 28 July 1893 No. 63, Eccl.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following papers— 48

Endorsement of the Public Works Departmen
dated 19th July 1893 No. 423 D. on letter from the
Superintending Engineer, 4th Circle, dated 13th June 1893
No. 239.

Letter from the Venerable the Archdeacon
of Madras, dated 22nd July 1893 No. 1556.

I have the honor to acknow
the receipt of your endorsement dated 28th Ju
1893 No. 1129 on P. W. Current No. 5433 Eccl.
current No. 145.

2 The Superintending Engineer, 4th circle
is mistaken in supposing that the
cemetery on the Omalur Road, Salem, wa
through oversight omitted to be included in the list
of cemeteries which are to be maintained
and repaired by the D. P. W. It was
intentionally omitted.

3. I have the honor to point ou
that if this cemetery be included in the
list

list of those cemeteries which are to be repaired by the Public Works Department, the clearly defined line which is followed in that list will be broken.

4. The list of churches and cemeteries to be repaired by the Public Works Department as approved in G.O. of 17th October 1891 No. 2746 W. Public Works includes only (1) Military churches (2) Military cemeteries (3) those churches and cemeteries which are in Madras, Bangalore and on the Nilgiris; and which have been placed under the Public Works Department by various Government orders.

5. If any churches or cemeteries which are not Military; and neither in the Presidency Town, or Bangalore, or in the Nilgiri Division, be placed under the Public Works Department there will I think be in the future, as there was in the past, some confusion. I respectfully suggest therefore that the new cemetery at Salem should not be placed under the Public Works Department.

Order 28th July 1893 No. [illegible]

The

The Venerable the Archdeacon's letter read above, will be communicated to the Public Works Department.

248/6

(True Extract) S.P.

Under Secy P.W.D.,
for Chief Secy.

To
The Public Works Dept.
with c. No. 145

No. 380 P.E.

Executive Engineer's office,
Salem Division,
6th September 1893.

From,

G. E. Manson, Esq., 2481
Executive Engineer,
Salem Division,

To,

The Superintending Engineer,
Fourth Circle,
Coimbatore.

Ref: Your No. 280 S.L., dated 31st August 1893, regarding the new Cemetery at Salem.

Sir,

The new Cemetery at Salem has been repaired, and the work paid for, as the work was urgently needed. It was carried out at the request of the Lay Trustees as the repairs by this Department appeared to be required; as already reported; under G.O. No. 458M, dated 5th May 1888 which declares that Government is responsible for its maintenance.

N.T. Concerned to P.W. Dept.

2. I request that you will give a Circle Register No. to the estimate as the work is already done, in order to obviate objections to the expenditure incurred, by the Examina P.W. Accounts.

3. If this work should not have been executed by this Department I request that you will inform me who is responsible for the repair of this Cemetery, to enable me to take steps for the adjustment of the expenditure incurred.

I have &c.,
(Sd) G. E. Manson,
Executive Engineer

No. 349/S.W. d/10-9-93.

Copy forwarded to the Chief Engineer, P.W.D. for favor of instructions with reference to G.O. No. 2076 W, dated 12th August 1893.

2. In the circumstances explained by the Executive Engineer, it is presumed that the cost of maintaining the Cemetery should be met from the Public Works grant although it is not brought on the P.W. List and until orders of Government are issued that such charges should be borne by any other department.

Lt. Col. R.E.,
Supg. Engineer, 4 Circle.

[G/15] P. W. CURRENT No. 6796

Govt. of { 18 } Madras.

No. 2746 W of 17. 10. 91
" 572 W of 20. 2. 92
" 423 I of 19. 6. 93

6 Pink

No. 2076 W a/ 12. August 1893.

To

The Public Works Depts

Communicated to the Supdg. Engr. IV Circle with reference to his letter No. 239 BW of 13th June 1893.

2. In the circumstances stated the new cemetery at Salem will not be brought on the P.W. List.

JH
8/8

Recd. 4. 8. 93

OOB
7. 8. 93

Proceedings, dated 28 July 1893
No. 63.

Subject.

Communicating to the P.W. Depts letter from the Venerable the archdeacon stating why the Bomalur road cemetery should not be placed on the list of cemeteries to be repaired by P.W. Depts

DESPATCHED
14 AUG. 93

Tho. Desp.

D 14/8

S. E. IV Circle

I. C. 15/VIII

202
29/8

I 22/8

28/81
9

P. W. CURRENT No. 7854

From

The Supg. Engineer
IV Circle.

Dated 10th }
Despd 12th } September 1893
Recd 14th }

No. 349
S.W.

New Cemetery at Salem.

Requesting instructions regarding the expenditure already incurred in repairing the —

No 2746 W d/ 17.10.91
" 572 W d/ 20.2.92
" 423 D d/ 19.6.93
" 2076 W d/ 12.8.93

Recd
Cur 52433
" 6796
G.O. 2076 W / 12.8.93
Cur 7854
} Print

~~Ans~~
A

Civil works
No 2481 W. d/27 Sept 93

The cost of repairs to Govt. churches and cemeteries not on the P.W. list, should be met from the allotment made in the Ecclesiastical Budget under "Petty Construction and Repairs"

2. The expenditure incurred by the P.W. Dept. on the Cemetery at Salem should be transferred to the Civil Dept.

18.9.93

25/9/93

18.9

DESPATCHED
4 OCT 93

The S.E. IV Circle
other S.Es
C.A. to Govt.
Secr P.W. Accts.
Ecclesiastical Dept

4293 Cur
1.9.7

12/7/7

248/10

C No. 7854

Govt. of 1893 Madras.
PUBLIC WORKS.

G.O. 27th Sept 1893, No. 2481W.

Government
Churches and
Cemeteries

Orders regarding
incidence of the
cost of repairing —
not on the P.W.
List.

22/14

J.C. 28.14

Jd/28/9