

4

- (1) பக்கத்தின் எண்ணிக்கை 8
- (2) புதுக்கித் திருப்பிய நாள் 17.2.92
- (3) ஆதாரக் குறிப்பவர் சுருக்கப்படும் 2

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

P.W. துறை

அரசாணை எண்.	3290	அச்சகம்
மு. கோப்புத் தாள் எண்.	P.W.D	பலவகை
நாள் :	18 12 1893	199

மடிக்கவோ கண்டபடி கையாள்வோ கூடாது.

[Handwritten signature]

ஆவண. கா. 1-18,006-6-9-90.

18TH DECEMBER 1893, No. 3290 W., PUBLIC WORKS.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

General.
Account.

READ—the following paper :—

From the Director-General of Stores, India Office, to the Secretary to the Government of Madras, Public Works Department, dated Whitehall, S.W., 24th November 1893, No. S. 11031.

With reference to your letter of 8th September 1893, No. 2319 W., I regret to learn that the leather hose was not found satisfactory, and I think that there can be no doubt that this kind of hose is unsuited to your climate, as a sample of the supply which was retained in this country is still in good condition.

2. With regard to the statement by the Consulting Architect in the enclosure to your letter that in parts of the hose the leather appeared new and good and in other parts old and deteriorated, I have to observe that this is due to the fact that it is usual when leather hose is found on inspection to contain one or two defective strips to allow the contractor to put in fresh strips.

3. The fresh supply of hose has been ordered of canvas lined with rubber and I hope it will be found satisfactory.

ORDER—dated 18th December 1893, No. 3290 W., Public Works.

Communicated to the officers concerned with reference to G.O., No. 2318 W., dated 8th September 1893.

(True Extract.)

Major, R.E.,
Under Secy. to Govt., P.W.D.

To the Consulting Architect.
„ Superintending Engineer, V Circle.

Exd. C. A. Munisawmy.
Spare Copies

GENERAL
ACCOUNT.

Gobt. of {1893} Madras.
PUBLIC WORKS.

Dated December, 18th.

Recd.

Encl.

G.O., 18th Dec. 1893, No. 3290 W.

DECEMBER.

Hose

Letter from the Director-General of Stores regarding the unsatisfactory results obtained from the leather — originally supplied with the steam fire-engine for use at Chépák, Madras, and stating that a fresh supply has been ordered of canvas inlined with rubber, communicated to officers concerned.

DUPLICATE

22/3290

24th November 1893.

With reference to your letter of 3th September 1893, No. 2819 W, I regret to learn that the leather hose was not found satisfactory, and I think that there can be no doubt that this kind of hose is unsuited to your climate, as a sample of the supply which was retained in this country is still in good condition.

With regard to the statement by the Consulting Architect in the enclosure to your letter that in parts of the hose the leather appeared new and good and in other parts old and deteriorated, I have to observe that this is due to the fact that it is usual when leather hose is found on inspection to contain one or two defective strips to allow the Contractor to cut in fresh strips.

The fresh supply of hose has been ordered of canvas inlined with rubber and I hope it will be found satisfactory.

I have the honour to be, Sir,

Your obedient Servant,

J. PARKER

Director General of Stores.

The Secretary to Government,
Public Works Department,
Madras.

It is requested that in any further communication on this subject the under-mentioned letter and number may be quoted, and the reply addressed to

The Director General of Stores,

India Office,

Whitehall,

London, S.W.

S. 11031.

India Office,

Whitehall, S.W.

3
3290

24th November 1893.

Sir,

With reference to your letter of 8th September 1893, No. 2319 W, I regret to learn that the leather hose was not found satisfactory, and I think that there can be no doubt that this kind of hose is unsuited to your climate, as a sample of the supply which was retained in this country is still in good condition.

With regard to the statement by the Consulting Architect in the Enclosure to your letter that in parts of the hose the leather appeared new and good and in other parts old and deteriorated, I have to observe that this is due to the fact that it is usual when leather hose is found on inspection to contain one or two defective strips to allow the Contractor to put in fresh strips.

The fresh supply of hose has been ordered of canvas lined with rubber and I hope it will be found satisfactory.

I have the honour to be, Sir,

Your obedient Servant,

J. Parker

Director General of Stores.

The Secretary to Government,
Public Works Department,
Madras.

St. H *gent*
4th
N^o 3290. W. d/18th Dec-1893

Communicated to
the officers concerned
with reference to
L.O. 23854 of 8 Sept.
1893.

S *ovls*
14.11.93

CA ✓
S. E. D. Litch

LS *8/1/94*

DESPATCHED
6 JAN 94

4
3290

Case 10631

Govt. of Madras

PUBLIC WORKS.

20/12

18 Dec 3 3290W

J.C. 18/12
Hose

Letter from the
Director General
of Stores regarding
the unsatisfactory
results obtained
from the leathers
originally supplied
with the steam fire
engine for use at
Chepark, Madras,
and stating that
a fresh supply has
been ordered of
caneas joined into
rubber canvas
to officers concerned.

20/12

20/12