

(1) பத்தங்களின் எண்ணிக்கை

(2) புதுக்கித் திருப்பிய நாள்

(3) ஆதாரம் குறிப்பவர் சுருக்கொப்பம்

10

10/92

10

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

மேலாட்சிப் பணித் துறை

அரசாணை எண்.	846. W	அச்சகம்
மு. கோப்புத் தாள் எண்.		பலவகை
நாள் :	28-3-1893-	199

25

மடிக்கவோ சுண்டபடி கையாளவோ கூடாது.

2647

846
2

Dr

No orders are
now required as regards
the objection, which
has been removed.

For orders, the
Concurrence may be
expressed in the
Superior's opinion
that the explanation
as to the irregular
outlay is unsatisfactory.

The work was
begun in anticipation
of action because
one room was said
to be in a dangerous
state.

Ces

18/11/13

The explanation is
unsatisfactory - so
also is the fact that
more than a year
has elapsed since

5113
This explanation
was asked for

ours

2-5-93

He

So for J. W. J. 93

No 6414

From

84/2

The Executive Engineer

Chingleput Division

To,

The Sub Engineer

Chingleput.

Dated 29th March 1890

Recd. 29th March 1890

Improving & repairing the lower floor of the
Deputy Superintendents Quarters Chingleput.

It has the honor to request that the above work
may be put in hand at once according to estimate
of estimate herewith sent. There is one room which
is dangerous and it should be made safe with
an iron rail at once as provided in the estimate.
Meanwhile it should not be occupied.

(Signed) C. H. B. Bullon
Executive Engineer

(Signed) J. F. Wilson

Exec. Engineer Chingleput Dist.

J. H. Wilson

Superintendent Engineer
Chingleput

29th March 1890.

Mr 617

P.W.D.
Chungking Division Office
20 February 1893.

From

J. J. Wilson Esquire
Executive Engineer

846/37

Chungking Division

To


The Superintending Engineer
V. Caile.

Sir,

In reply to yours No. 273 en of 5 April 1893.
I have the honor to forward herewith a copy of
the Executive Engineer's order to commence the work
which was apparently given in anticipation
of sanction to the estimate owing to one of the
rooms being considered to be in a dangerous condition.

I have &c

(Signed) J. J. Wilson
Executive Engineer


Superintending Engineer
V. Caile

100 March 1893.

SUPERINTENDING ENGINEER'S OFFICE,

V CIRCLE, MADRAS,

Chopdk. 1st March 1893.

No. 784

From

J. Hannan Esq

SUPERINTENDING ENGINEER,

V CIRCLE,

To

The

Chief Engineer
P.W.D.

846
X

SIR,

With reference to orders passed in G.O. 587 of 20 February 1892 against item 6 of the Provincial Statement of objectionable items for the period ending 30 November 1891, I have the honor to enclose copy of letter No. 6414 of 29 March 1890 from the Executive Engineer Chingleput Division showing the circumstances under which outlay was incurred on the work "Im proving and repairing the lower floor of Dy Superin tendent's Quarters at Chingleput" before the estimate for it was sanctioned.

The explanation is unsatisfactory.

I leave the honor to be

set.

Your most obedient servant

J. Hannan
Superintending Engineer
V Circle

Enclosures 2

Copy of letters

P. W. CURRENT No. 2054

From

THE SUPERINTENDING ENGINEER,

V CIRCLE,

To

THE

Chief Engineer

P. W. Department.

Dated

Recd.

March

1893.

18.3.93

21372 W 20-5-91 ✓

2149 W 11-8-91 ✓

3239 W 3-12-91 ✓

567 W 20-2-92 ✓

ENCLOSURES 2

1418 W 6-5-92 ✓

1079 C 8-3-93 ✓

No. 78 W.

Improving and repairing
the lower floor of Deputy
Supt's Quarters at
the Reformatory
School.

Forwarding Copies of
correspondence showing
the circumstances under
which outlay was incurred
in the absence of sanction



No. 1099 C d/8 March/93
To C

For favour of
report whether the
objection to the item
has been removed.

[Signature]
G. S. 193

W. S.
6.2.93

No. 887 - C d/17.3.93

To W.

The objection has been removed.

[Signature]

G.

[Signature]
D. 17/3
(encr)

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following

From the Suptg Engineer V Circle (H.E. No. 78 W d/1 March/93)
From the Examiner P.W. Accounts (H.E. No. 887 C d/17 March/93)

The explanation sub-
mitted is unsatisfactory, and
so also is the fact that more
than a year has elapsed since
it was called for.

[Signature]
W. S.

[Signature]
21/3/93

[Signature]
The Suptg. Engineer V Circle.

[Signature]

Wm

Wm
1893

No 846 Wd/28 March/93

5/11

22/3 R24/3

2 5/4