

- (1) பக்கங்களின் எண்ணிக்கை 8
 (2) புதுக்கித் திருப்பிய நாள் 2/92
 (3) ஆதாரக் குறிப்பவர் சுருக்கொப்பம்


தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

P.W.O. துறை

அரசாணை எண்.	அச்சகம்
மு. கோப்புத் தாள் எண். 782	பலவகை
நாள் : 20.3.1994	199

மடிக்கவோ தண்டபடி கையாளவோ கூடாது.



ஆவண. கா. 1-18,006-6-9-90.

No. 1074 m2,

OFFICE OF THE SUPERINTENDING ENGINEER.

6th CIRCLE.

Trichinopoly.

10th March 1894

5-10/-

FROM

Lt. Col. A. W. Smart R.E.
THE SUPERINTENDING ENGINEER.

6th CIRCLE.

TO

THE CHIEF ENGINEER.

P. W. Department
Madras

SIR,

ENCLOSURES

In the Madara district, which is the second largest in the Presidency, there are only two D. P. W. Inspection bungalows, it is therefore considered that one at Vera-pandy would be a great convenience to all district officers.

2. Mr. Hughes, my predecessor, admitting the necessity for the building, ordered the preparation of an estimate for the same; I have now the honor to request, with reference to G. O. No. 2806 W of the 7th October 1892, that approval of Government be obtained to the proposal for constructing the building which is likely to cost about Rs. 1300. On receipt

$$\frac{782}{2}$$
$$\frac{482}{2}$$

P. W. D. CURRENT No. 1950

P. W. D. 6th CIRCLE

FROM

THE SUPERINTENDING ENGINEER

6th CIRCLE

TO

THE CHIEF ENGINEER

PWD

No. 1074 md

Dated 10th March 1894
Received 12th

Enclosures.

Inspection Bangalore at
Veerapondy:—

Requesting to obtain
the approval of Govt to the
proposal for constructing
the — at a cost of about
Rs 1300 —

No. 2806 w of 7-10-72

C. No. 1950

W.

982
3

For orders
I think that
his sanction request
might be given

DUB
17.3.94

Very desirable, but
I am afraid funds
cannot be provided at
present for anything
so absolutely indispensable
works —

D. M.

No. 782 W. dy. 20th March 1894. PUBLIC WORKS DEPARTMENT.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following

Letter from the S.E. Circle (H.E. No. 1074 M. D. 10.3.94)

W
✓
15 Mar

The provision of
an inspection lun-
galow at Veerapandi
in the Madurai
District is sanctioned,
but the execution of
the work must be
deferred till funds
become available



S.E. Circle
Ex P. W. A.

pub
13th Apr

S
147

PA

H/6

DPW Inspection
by the
Madera district

No. 782 W. dy 20 March 19

PC
28/3

INDEXED
29/