

No. 27

Superintending Engineer's Office,

3RD CIRCLE,

Bellary 1895.

FROM

C. H. J. Norton Esquire
SUPERINTENDING ENGINEER,

3RD CIRCLE,

To

THE

Chief Engineer,

W. D.
Madras.

Sir,

Enclosures

With reference to para 2 of
Order 812 W. dated 2nd April 1895, I
have the honour to state that an
Estimate was received from the Executive
Engineer, Karnool Division in August 1894,
and accompanied by a Side Plan, which
was not received till October of the
same year. When it was received,
it was found that the Executive Engineer
had neglected to mark on the Plan
the position of the Rest House. The Side
Plan had, therefore, to be returned to him
for this purpose. It was received back
in February 1895, and on the 13th of that
month, the Estimates were sent to you.
2. There was not only delay in the Executive
Engineer's Office on the matter, but in
Civil

Circle Office also, as it took ^{nearly} 4 months to
return the Side Plan to the Executive
Engineer for having the position
of the Rest House marked on it.

As I was not here at the time, I am
unable to discover why it took so long
to return the Side Plan to the Executive
Engineer; the delay was in the Drawing
Branch, and the Head Draftsman at
the time is now dead.

3. The Rest House at Shokapally was
begun, but ^{has been} stopped till the land
is put in the possession of the Executive
Engineer. It has addressed to
Collector.

I have the honourable
Sir
Your most obedient servant

Ellis
Superintending Engineer
III Circle
6/5
There was not any delay in the Executive
Engineer's Office on the matter, but in
the

From

The Superintending Engineer,
IIIrd Circle,
Bellary.

no 3239 W 9/14. 12. 95
" 1212 C 8 22. 3. 95
" 812 W 9 2-4-95

To

The *Chief Engineer*
P. W. Dept
Madras

Dated

Received

7th May 189*5*

Enclosures.

No.

264

Subject.

N^o 1135 W. dated 13 May 95

Recorded.

Recorded

S. 15

Maskapur Rest House

*Explaining the cause of
delay in the submission
of the estimate for—*

of 70

12/3/5

INDEXED

22/12/95