

From

THE SUPERINTENDING ENGINEER,
V CIRCLE,

To

THE *Chief Engineer*
P. W. Department

Recd: 12-11-95

En: 1

Dated

9 } *November 1895*

Recd.

Recd En: 2610
6450
8835

No 2934 W of 16 Nov 1895

ENCLOSURES. /

B
Encl - 1

The execution of
the work by the P.W.
dept is sanctioned.

No. 413 W.

Reporting that the Sir-
Temple
-valler ~~Land~~ authorities
are prepared to pay the sum
of Rs 309 towards Establish-
-ment & tools & paint.

S 1411

Copy of
1711

DESPATCHED
18 NOV. 95

P. W. Circle
P. W. Circle
with 5 Encls
Encl
Encl

INDEXED

22/11

No. 308.W.

SUPERINTENDING ENGINEER'S OFFICE,

V CIRCLE, MADRAS,

Camp behind the temple
Chennai 21st August 1895.
Recd 22/8/95.

From

Lieut. Col. C. C. Rawdon R. E.
SUPERINTENDING ENGINEER,

V CIRCLE,

To

THE Chief Engineer P. W. Department.

SIR,

Enclosures

With reference to your reminder No. 1858C dated 16th Instant, calling attention to your Memo No. 1858C dated 20th May 1895, regarding the Estimate for rebuilding the slipped portion of the steps of the temple tank at Timmaller in the Chindpet District. I have the honour to inform you that the Collector has not yet replied to the question as to whether the temple authorities are prepared to pay the charges on account of "Establishment" and "Tools and Plant" also, and that a reminder was sent to him on the 9th Instant.

I have the honour to be, Sir,

your most Obedt. Servant

Ch. C. Rawdon

21/8/95

Lt. Colonel R. E.
Supg. Engineer V Circle

250-6-2-94.

Ch. C. Rawdon
19.8.95

From

Col. C. C. Rawson R.E.
THE SUPERINTENDING ENGINEER,

V CIRCLE,

To

THE *Chief Engineer*
P. W. D.

Dated

21st Aug
22nd

1895-

Recd.

ENCLOSURES.

No 1858C/20-5-95

No. 308.W.

Temple Tank at
Trivellur. Chingaput
Dy. —

Informing that the Col.
has not yet replied
whether the temple
authorities are pre-
pared to pay the
charges on account
of establishment
and Talab + Plau

P. W. D. No. 640

Recd 23-8-95

*Await receipt of
final reply.*

*Cross
24/8/95*

o.L.S. 324

No. 413W.

SUPERINTENDING ENGINEER'S OFFICE,

V CIRCLE, MADRAS,

Chepāk, 9th November 1895.

From

Lieut. Colonel C. C. Rawson R. E.

SUPERINTENDING ENGINEER,

V CIRCLE,

To

THE Chief Engineer P. W. Department

SIR,

With reference to your Memorandum No. 1858 C of 20th May 1895, I have the honour to report that the Tiruvallur Temple Authorities are prepared to pay the sum of Rs. 309 towards Establishment and Tools and Plant and that it will be recovered in January 1896 from the Merah due to the temple, vide Copy of letter of 24th October 1895 No. 3696 from the Collector of Chingleput enclosed for information.

2. The surface soil at the South west corner of the Tiruvallur Temple tank is white clay mixed with sand to a depth of 4 feet and the sub soil is black clay to a further depth of 4 feet.

I have the honour to be

Sir

your most obedt. Servt.

C. C. Rawson

9.11.95

Lt Colonel R. E.

Supg Engineer V Circle

Ref on No. 3696 of 1895

Communicated to the Supg. Engineer V Circle with reference to his letter No. 170^m of 28th May 1895. He is requested to take early steps for the repairs of Sri Veeraraghavaswami temple tank and the cost thereof will be paid in January 1896 from the Merah due to the said temple.

Signed - not legible
for as. Collector

24th October
1895

(True Copy)

C. C. Rawson

9.11.95

Lt Colonel R. E.

Supg Engineer V Circle

9th Nov. 1895

P.W. Sec 1
8835/95

7.11.95

Enclosures. /

Ref: on N^o 27^{collr.} of 1895 d/18th October 1895

From the Deputy Collector, Tiruvallur,
To the Collector of Chingleput District

Sir,

In reply to your letter N^o 1153 d/19th August last, I have the honour to state that the Dharmakartas of Sri Veerabhadraswami Temple pleads inability to pay at once the amount of Rs 309 towards establishment, tools and plant &c. He requests that the sum may be deducted from the Inrah payable to the temple for the current fasli and which will become due in January 1896. I am instructing the Tahsildar to note the request and withhold the ^{sum} ~~same~~.

2. In the meanwhile, I beg you to be good enough to request the Engr: Engineer to put the work of repairing the steps in hand at once. The water in the tank is low and this is the best time for carrying out the repairs. As it is, I am told that the steps have slipped even beyond what they were when the estimate was framed. If further time is lost, not only will the cost of repairs become heavy but the danger to the adjacent houses will become imminent.

3. I request very early orders.

I have &c

Signed. Sengaravelu Pillai

Dy. Collector

(True Copy)

N^o 1858C - d/20-5-95

1. Reminder issued 11-8-95
T. K.
BGM

22/5

DM
W

N^o 1858C. dated 20 May 1895 P.W.D.

Memo:

With reference to the estimate of Rs 1260 for rebuilding the slipped portion of steps of the temple tank at Tiruvallur in the Chingleput Dist. submitted by the Suptg. Engineer, V Circle, with his letter No 166 W dated 8 May 1895, the undersigned has the honor to enquire whether the temple authorities are prepared to deposit also Rs 309 being the amount of charges on account of "Establishment" and "Tools and Plant" vide Clause 11, para 82, Chapter IX, vol. I of the P.W. Code. If not, the Collector's opinion should be obtained whether these charges should be waived.

It is observed that the nature of the soil is not noted on the plan. Information concerning this is required. WMS D.W.

Cn

S. 175

a bed of concrete 9 inches in depth with a concrete toe at foot of slope 2'0" x 1'6".

Permission has been made for constructing & running ring road, including boring of water for a lump sum of Rs 200.

The rates are fair, except for removing & repacking gran: the steps which cannot be checked.

The plan & estimate have not been countersigned by the Collector of the Dist. nor any of the temple authorities.

The amount of the estimate viz Rs 1260 is in stated, has been placed to the credit of the P.W.D. in the Casing Treas: sum at Tiruvallur by the temple authorities.

W.V.G.S.

Public Works Department.

Current No. 3610
 Letter No. 166W
 Dated 8th May 1895
 From the Supt. Engineer & Circle.

NOTE BY TECHNICAL SECTION.

Name of work. Rebuilding the slipped
 portion of steps of the temple tank
 at Tiruvallur in the Chingleput
 Dist.

Amount of estimate Rs 1260

The plan & estimate under
 review amounting to Rs 1260
 for rebuilding the steps of the
 temple tank at Tiruvallur
 in the Chingleput District
 have been framed at the re-
 quest of the Collector who
 considers the work to be one
 of public utility and the
 S.E. & Circle submit them
 for the sanction of Govt. under
 para 79, Chap IX, Vol I, of
 the Code.

The estimate provides for
 rebuilding the steps which
 have slipped in 2 places
 for lengths of 120 & 102 feet
 as shown on plan, with the
 existing granite stones, on a

P. W. CURRENT No. 3610

From

THE SUPERINTENDING ENGINEER,

V CIRCLE,

To

THE Chief Engineer
 P. W. Department.

Encls 5 (1 plan)
 Recd: 10.5.95

Dated 8th } May 1895
 Recd. }

ENCLOSURES. 5

No. 166W.

Temple tank at Tiruvallur
 - Chingleput Division -

Requesting that sanction
 may be accorded to the
 work of rebuilding the
 slipped portion of steps
 of the - as per enclosed
 plan & Estimate being
 submitted by this Dept.

OK 82

120/10

1

No. 166 W

SUPERINTENDING ENGINEER'S OFFICE,

V CIRCLE, MADRAS,

Chepak, 8th May 1895.

From Lieut. Col. C. C. Rawdon R.E.

SUPERINTENDING ENGINEER, V CIRCLE,

To

THE Chief Engineer
P. W. Department

SIR,

Enclosures. 5

1 Plan
1 Report
1 Detailed Estimate
1 Abstract Estimate
1 Specification

5

Under para 79 Chapter IX Vol. I
of the Code, I have the honour to request
that sanction may be accorded to the work
"rebuilding the slipped portions of steps
of the temple tank at Tiruvallur," (Chingle-
pud Division as per enclosed plan and
estimate being undertaken by this Depart-
ment

2. The Estimate has been prepared on the
requisition of the Collector Chinglepud District
who considers the work to be one of public
utility in which opinion I concur.

No. 166 W

SUPERINTENDING ENGINEER'S OFFICE,

V CIRCLE, MADRAS,

Chepāk, 8th May 1895.

From Lieut. Col. C. C. Rawson R.E.

SUPERINTENDING ENGINEER, V CIRCLE,

To

THE Chief Engineer
P. W. Department

SIR,

Enclosures. 5

1 Plan
1 Report
1 Detailed Estimate
1 Abstract Estimate
1 Specification

5

Under para 79 Chapter IX Vol. I
of the Code, I have the honour to request
that sanction may be accorded to the work
"rebuilding the slipped portions of steps
of the temple tank at Tiruvallur," Chingle
-put Division as per enclosed plan and
estimate being undertaken by this Depart.
-ment

2. The Estimate has been prepared on the
requisition of the Collector Chingleput District
who considers the work to be one of public
utility; in which opinion I concur.

3. The amount of the Estimate, Rs 1260,
has been paid by the temple authorities
into the taluk treasury at Trivallore to
the credit of the P. W. Department.

I have the honour to be

Sir

Your most obedt. Servt.

C. S. I. S. M.

7/5/95

Lt Colonel R. E.

Supg. Engineer & Circle

From

THE SUPERINTENDING ENGINEER,

V CIRCLE,

To

THE *Chief Engineer*
P. W. Department -

Encls 5 (1 plan)
Recd: 10.5.58

Dated

8th

Recd.

May

1896.

ENCLOSURES. 5

No. 166 W.

Temple South at. Terminal.
for Singlefoot Division

Requesting that sanction
may be accorded to the
work of rebuilding the
slipped portion of steps
of the - as per enclosed
plan & Estimate being
under taken by this Dept.

12/1/58
12/1/58

7