

Govt. of 1893 Madras.
REVENUE.

To

The Public Works Department.

Dated

Recd.

Encl.

Mis. G.O., 28th July, 1893, No. 897

SUBJECT.

Approving the construction of
a new Customs House at
Kaglapattanam, Tinnevely
District.

Deco. 4. 3. 95

Lo 544 W d/ 8 March 1895

B

Communicated to
the Supt. Engr. & Civil
for preparation of the
necessary plans and
estimates.

cross
6/95

Lb

DESPATCHED

To Supt. Engr. & Civil
The Supt. Engr. & Civil

at Kayalpatnam and to issue instructions in
the Public Works Department for the preparation
of the necessary plans and Estimate for the work.
The allotment of Rs 250 for the repairs of the
building is surrendered.

Resolution:— Submitted to Government for
favourable Consideration and Orders.

In the Condition that the present
building is reported to be in, any Annual Expenditure
on its repair will be a waste of money.

Order thereon, dated 28th February 1895 No 897/Dis.

The construction of a new Customs
House at Kayalpatnam is approved.

Orders will issue in the
Public Works Department for the preparation of
the necessary plans and estimates.

(Incl. Extract.)

W. L. S.
Secretary to Government.

The Board of Revenue (Separate Revenue)
Public Works Department.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following Proceedings of

the Board of Revenue (Separate Revenue), dated
9th February 1895, N^o 650 etts, on the following letter
from the Acting Collector of Tinnevely, dated
7th February 1895, Ref on Per N^o 180 of 1894:-
general

In the
Current year's Budget sanctioned in Board's
Proceedings N^o 306, dated 8th August 1894
(Separate Revenue) for repairs to Customs Works
under Civil Buildings in charge of Civil Officer
a provision of Rs 250 is made for the repairs of the
Sea Customs House at Kanjapattanam. It is now
reported that the building is in a very bad state
and requires reconstruction. The walls are built
of Coral stones in clay and plastered over with
mortar. The floor is on the ground level and the
building is surrounded on all sides by drifted
sand to the height of 2 feet above the floor. The
roofing has already begun to sink and is supported
by Palmyrah posts. The Executive Engineer, who
was consulted, is of opinion that the building
should be pulled down and reconstructed.
I have therefore the honor to request that the
Board will be pleased to move Government to
sanction the construction of a new Customs House.