

Public Works (1896) Department.

G.O., No. 196/W

DATED 3 July 1896

[Despatch Abstract.]

Superintendent. The entertainment for
Rs 12 per mensem for the Komati-
gutta Weir in the Kistna Eastern Division
sanctioned.

BACK PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

PUBLIC WORKS DEPARTMENT.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following

For the Suptg. Engineer II Circle, No 223 K 5 d 28 April 1896.
 " the Chief Engineer for Irrigation, No 4113 May 1896.
 " Engineer P.W. Accounts, No 1592 K 46 June 1896.

The entertainment of
 a Superintendent on Rs 12 per
 mensem for the Komatigunta
 Weir in the Kistna Eastern
 Division, is sanctioned.

2. This sanction has been
 registered as Provincial, No 10
 of 1896-97 and classified as
 Establishment Permanent.

In the S.E. II Circle
 Super. P.W. Accounts

NOTES

Reference to P. W. D. Code

Chapter I, Part II

1. All proposals for changes in the scales of permanent establishments must be accompanied by a statement in Part I of this form when the changes relate to the engineer or upper subordinate establishments and in other cases by a statement in Part II of this form.

2. The column headed "present scale" should invariably show the existing sanctioned scale, not the strength of the establishment as it actually stands at the time, and should be verified by the Examiner before the statements are forwarded to the sanctioning authority.

P. W. D. Form No. 113

MADRAS PRESIDENCY

Part II

Tabular statement to accompany proposals for changes in establishments

Letter from the Officer in Charge
Pondicherry dated 20th to the Ins. Engineer
Madras Eastern No. 2, 12.4.96 No. 41 E.

The Head works at Konaipet
which pass down is a weir for over
200,000 acres; they are not being
regulated by a watchman, to whom
orders are given by Generals Subordinate
of different District Divisions and
who from his position in day
is not expected to use much
discretionary powers in regulating
the water. The orders given to him,
by Generals of the District Divisions
During the last year, when Bundam
broke and water was flowing
over the sides of the weir as to
cause enormous damage to the
weir, the watchman was simply
sitting quiet instead of arranging
to cut a breach some yards
higher up the Head works.
So as to save the masonry
works at K.S. he did not even
report of the danger to the Head
works at K.S. it was of his superior.
He could not be held responsible
for this because as at

