

8260
Public Works (1896) Department.

G.O., No. 2685 W

DATED 21st September 1896

22/9

[Despatch Abstract.]

Wire fence. Endrin the Rev. Sept transferring Board's
Pros: recommending that order be issued for putting
up a plain - round the Compound of the Saluk Cutchery
at Tiruppathur, Salem Dist. so as to enclose the other
public buildings as well, Comd^r to S.E. IV Circle
for submission of an estimate for a wire fence.

20/11

22/9
[INDEXED] 21/9

Endorsement in the Revenue Department transferring Board's Proceedings recommending that orders be issued for putting up a plain — round the compound of the taluk cutcherry at Tirupattūr, Salem district, so as to enclose the other public buildings as well, communicated to Superintending Engineer, IV Circle, for submission of an estimate for a —.

GOVERNMENT OF MADRAS.
PUBLIC WORKS DEPARTMENT.

General.
Account.

Read—the following paper :—

Proceedings of the Board of Revenue (Land Revenue), Mis. No. 3860, dated 21st August 1896.

Read—the following letter from C. H. MOUNSEY, Esq., Acting Collector and District Magistrate of Salem, to the Secretary to the Commissioners of Land Revenue, dated 17th July 1896, No. 3885 :—

In the revised estimate sanctioned in G.O., No. 1299 W., dated 22nd April 1896, for the construction of a taluk cutcherry at Tiruppattūr, provision is made for a barbed wire fence round the taluk cutcherry with a gate. In the same block of land there are also other public buildings, such as the Head Assistant Collector's office, the District Munsif's court, the Municipal hospital, the Police station, the buildings recently made over to the Forest Department, &c., as shown in the enclosed map. These have no compound wall. The Head Assistant Collector proposed last year that a compound wall might be built, and on personal inspection of the locality I was convinced of the necessity for it. The Executive Engineer, to whom a reference was made on the subject, stated that a compound wall was likely to cost more than Rs. 500 and that he could not prepare plan and estimate for it without the sanction of Government. A masonry wall with brick in clay is estimated to cost Rs. 4,863, while a mud wall can be constructed for about Rs. 1,089. The cost of a wire fence, excluding the portion appertaining to the taluk cutcherry, amounts to Rs. 1,582-8-0 at 6 annas a foot.

In my opinion the mud wall is the best—it costs less and is less costly to repair. I request that the Public Works Department may be instructed to take steps for putting up a wall or fence as the Board thinks fit. The amount debitable to the several departments in case of a masonry wall, mud wall or wire fence, respectively, is shown roughly in the enclosed three statements, and it can then be ascertained if they will pay.

Resolution—Mis. No. 3860, dated 21st August 1896.

Submitted for the orders of Government, with reference to G.O., No. 1299 W., dated 22nd April 1896, communicated with G.O., No. 1914, Revenue, dated 18th May 1896.

2. The Board is unable to support the Collector's recommendation to substitute a mud wall for the plain wire fence already sanctioned by Government for the taluk cutcherry at Tiruppattūr. A mud wall is usually unsightly and will require constant repairs. The Board accordingly recommends that orders may be issued in the Public Works Department for putting up a plain wire fence round the whole compound, so as to enclose the taluk cutcherry as well as the other public buildings.

No. 2685 W., 21st SEPTEMBER 1896.

3. The attention of the Collector will be drawn to paragraph 4 of G.O., No. 1299 W., dated 22nd April 1896, communicated with Board's Proceedings, No. 2439, dated 29th May 1896, from which he will observe that the revised estimate for the taluk cutcherry at Tiruppattūr provides for a plain wire fence in accordance with G.O., No. 1762 W., dated 13th July 1894, communicated with Board's Proceedings, No. 328, dated 3rd August 1894, and not for a barbed wire fence as stated in the letter read above.

(True Copy and Extract.)

(Signed) R. C. C. CARR,
Acting Secretary.

Mis. No. 3603, Revenue.

Transferred to the Public Works Department for the issue of the necessary orders.

OOTACAMUND,
9th September 1896.

(Signed) LIONEL DAVIDSON,
Ag. Under Secy. to Government.

ORDER—No. 2685 W., dated 21st September 1896.

Communicated to the Superintending Engineer, IV Circle, who will submit an estimate for a wire fence in accordance with the Revenue Board's suggestion.

(True Extract.)

Under Secretary to Government.

To the Superintending Engineer, IV Circle, with four enclosures,
" Revenue Department.

Exd. T. K. Narayana Aiyangar.

Public Works (1896) Department.

CURRENT No. 8260

A
Order No 2685 W, dated 21st

September 1896.

Communicated to
the Super Eng. IV Circle,
who will submit an
estimate for a wire
fence in accordance
with the Rev. Board's
suggestion.

From

The Revenue Dept.

No. 3603 Mis

Dated 9.9.96

Received 14.9.96

Enclosures 6 (11111)

Spare copies .

SUBJECT.

Taluk Cutcherry at Tirupattūr

Requesting that orders may

be issued for putting up a

plain wire fence round

the compound of the —

1. Reminder issued 26-1-97
2. do. 10-4-97
3. do. 9-8-97

cy
S. S. IV Circle
with 4 enclosures
Rev. Secy.

FURTHER PAPERS.

Revenue (1896) Department.

CURRENT No. 6190

From

The Board of Revenue,
Land Revenue.

Order.

Endorsement No. 3603 Mis.

No. 3860 Mis.

Transferred to the Public Works
Department for the issue of the neces-
sary orders.

Dated 21st August 1896.

Received 26th " "

Registered 28th " "

Enclosures 5.

Spare copies

SUBJECT.

Submitting letter from the Collr. of Salem and recommending that orders may be issued in the P.W.D. for putting up a plain wire fence round the compound of the Taluk Cutcherry at Tirupathur so as to enclose the other public buildings as well.

Ootacamund,

9th September 1896.

Recd 10-9-96.

Recd 4.30 P.M.

To the P.W.D.

929

8346

16/9 R 21/9

pin

BACK PAPERS.

G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.

(2,000-27-11-85.)



Proceedings of the Board of Revenue

(Land Revenue),

Dated 21 August 1896,

No. 3860 Miscellaneous.

READ Letter from the Collector of Salem, dated 17 July 96
No. 3885 to the Secretary to the Commissioners
of Land Revenue, Board of Revenue, Madras.

Resolution dated 21 Aug. 1896, No. 3860

Submitted for the orders of Govern-
ment with reference to Government Order No. 1299
dated 22nd April 1896. Communicated with
Government Order, No. 1914 Rev. dated 18th May 96.

2. The Board is unable to support the Collector's
recommendation to substitute a mud wall for
the plain wire fence already sanctioned

by

by Government for the Taluk Cutcherry at
Tirupattur. A mud wall is usually unsightly
and will require constant repairs. The Board
accordingly recommends that orders may be
issued in the P. W. Department for putting
up a plain wire ^{fence} round the whole Compound.
so as to enclose the Taluk Cutcherry as well
as the other public buildings.

3. The attention of the Collector will be drawn
to para 4 of Government Order No. 1299 dated
22nd April 1896, Communicated with Board's
Proceedings No. 2439 dated 29th May 1896 from
which he will observe that the revised estimate
for the Taluk Cutcherry at Tirupattur
provides for a plain wire fence in accordance
with G. O. 1762 W Communicated with B.P. 328
13.7.94 3.8.94
and not for a barbed wire fence as stated in
the letter read above.

True Extract

The Secretary to Govt.
Rev. Dept.
with letter of 4 Encls. in origl. H. H.
The Collector of Salem.

Recd
Ag Secretary

17th July 1896

No. 3885

28-7-96

From C. H. Munnay
G. STOKES, Esq.,


Ag Collector & Dist. Magte. of Salem.

To

The Secretary to the Commissioner of
Land Revenue Madras.

SIR,

In the revised estimate sanctioned
in G. O. No 1299 W dated 22nd April 1896
for the construction of at Taluk Cutcherry
at Tirupattur, provision is made
for a ^{plain?} barbed wire fence round the
Taluk Cutcherry with a gate. In
the same block of land there are
also other public buildings such
as the Head Assistant Collector's office,
the District Munsiff's court, the
Municipal Hospital, the Police Station,
the buildings recently made over
to the Forest Department, etc, as
shown



Shown in the enclosed map. These
have no compound wall. The Head
Assistant Collector proposed last year
that a compound wall might be
built, and on personal inspection
of the locality I was convinced
of the necessity for it. The Executive
Engineer to whom a reference
was made on the subject, stated
that a compound wall was likely
to cost more than Rs 500 and that
he could not prepare plan and
estimate for it without the
Sanction of Government. A
masonry wall with brick in
clay is estimated to cost Rs 4863
while a mud wall can be con-
structed for about Rs 1089. The cost
of a wire fence excluding the
portion appertaining to the Taduk
Cutcherry amounts to Rs 1582-8-4 at
6 annas a foot —

In my opinion the mud wall is
the best, it costs less and is less
costly to repair — I request that the
D. P. W may be instructed to take
steps for putting up a wall or fence
as the Board thinks fit. The
amount debitable to the several
Departments in case of a masonry
wall, mud wall or wire fence —
respectively is shown roughly in
the enclosed three statements and
it can then be ascertained if they
will pay.

I have the honor to be
Sir
Your most obedient servant

M. Wood
27.7
for Acting Collector

Copy
sent

W. J.
27.7

229/7

DEPARTMENT.
BOARD'S GEN. R.G. 4151 OF 1896
LAND REVENUE.

By
THE COLLECTOR AND

DISTRICT MAGISTRATE,



To The Secretary to the
Commissioners of
Land Revenue
Madras

Dated 17 July 1896.

No. 3885

ENCLOSURE. *one file*

SUBJECT.

Submitting proposals
for the construction of
a compound wall for
the block of land
containing public
buildings at Tiruppathur

*9/22
8/26/96*