

Public Works (1897) Department.

G.O., No. 5387

DATED 10 June 1897

[Despatch Abstract.]

Funds: Sanctioning ~~the~~ Certain
transfers of — under "43. minor works
and navigation" for works in the
North Arcot and Salem Divisions.

90
/ 11

22
10/6/97

Sanctioning certain transfers of — under “43. Minor Works and Navigation” for works in the North Arcot and Salem divisions.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Irrigation.
Account.

READ—the following paper:—

From J. HANNAN, Esq., Superintending Engineer, IV Circle, to the Chief Engineer for Irrigation, dated 27th May 1897, No. 92/I.

I have the honour to forward herewith an application for funds required for expenditure on Minor works, Revenue Department, during 1897-98, and to request you will be good enough to have the amounts placed at the disposal of officers concerned as early as possible.

ENCLOSURE.

STATEMENT showing incomplete works of 1896-97 and the demand on the "Reserve" of 1897-98 IV Circle.

Item number.	Name of work.	Amount of estimate.	Number and date of sanction.	Expenditure up to end of March 1897.	Balance of estimate.	Amount applied for.
WORKS OF REVENUE DEPARTMENT.						
Original Works.						
North Arcot Division.						
1	Constructing an earthenware pipe sluice to Pilleri ..	180	Register No. 225 of 1895-96.	27	153	153
2	Constructing a byewash to Pilleri tank ..	46	Register No. 254 of 1895-96.	44	2	2
3	Cutting a supply channel from Pinnapadi tank to Pilleri tank.	900	Register No. 256 of 1895-96.	..	900	900
4	Constructing a kondam across the river at the heads of the channel supplying Vellam tank.	810	Register No. 224 of 1895-96.	1	809	809
	Total, Original works ..	..		..	..	1,864
Repairs.						
5	Repairing the escape in Kallanaramiah cheruvu ..	540	Register No. 254 of 1893-94.	404	136	136
6	Odanagaram tank.—Repairing the bund and constructing high and low level sluices and a calingulah to ..	1,370	Register No. 147 of 1895-96.	1,171	199	199
7	Raising and strengthening the bund of Pilleri tank ..	500	Register No. 253 of 1895-96.	325	175	175
	Total, Repairs ..	..		..	..	510
Salem Division.						
8	Repairs to Thenur anicut ..	3,430	Register No. 12 of 1896-97.	758	2,672	2,672
9	Clearing silt to supply channel to Belur Chinna anicut.	840	Register No. 36 of 1895-96.	672	168	168
	Total, Repairs ..	..		..	..	2,840
	Grand Total ..	..		..	..	5,214

ORDER—No. 538 I., dated 10th June 1897.

The following transfers of funds are sanctioned:—

		Irrigation.		43. Minor Works and Navigation.		Minor Works, Revenue Department.	
Reserve—	From	Rs.	To	Rs.	To	Rs.	To
Original works	...	5,214	North Arcot division—	Original works	...	1,864	...
Establishment	...	1,199	Repairs	...	510	...	...
Tools and plant	...	78	Salem division—	Repairs	...	2,840	...
				Establishment	...	5,214	...
				Tools and plant	...	1,199	...
						78	...
				Total	...	6,491	Total

(True Extract.)

Under Secretary to Government,
Irrigation Branch.

To the Chief Engineer for Irrigation.
Superintending Engineer, IV Circle.
Examiner, Public Works Accounts.

Erd. W. D'Moss.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Under date the

Read the following

From the Supy. Engineer, IV Circle (H. E. No 92 I dated 27 May 1897).
No: 538-2960-6-97

4P

The following transfers
of funds are sanctioned:-

Irrigation.
43. Minor Works & Navigation.
Minor Works Revenue Depart.

From	To
Reserve -	
Original works. 5214'	
Establishment. 1199'	
Tools & plant. 78'	
Total 6491'	

From	To
	North Arcot division - R
	Original works. 1864'
	Repairs. 510'
	2374'
	Salem division -
	Repairs. 2840'
	5214'
	Establishment 1199'
	Tools & plant. 78'
	Total Rs 6491'

24/9/97

Sharp

The Chief Engineer for Irrigation
" Supy. Engineer IV Circle
" Examiner of P.W. Accts

Issue

W.H.
3-6-97

10.31/5/97

12.6/97

Public Works (1897) Department.

CURRENT No. ~~13-17~~
5577

Order

From The Sup. Engineer
to the Circle.

No. 92

Dated 27th May 1897

Received 24-5-97 9-6-97

Enclosures (1) One

Spare copies ✓

SUBJECT.

Funds required for expenditure on Minor works, Rev: Dept., during 1897-98.


Forwards an application for ———

829

100
29/5/97

13/5/97

1472255
1370



Statement showing incomplete works of 1896-97 and the demand on the "Reserve" of 1897-98 III Circle.

Item No.	Name of Work.	Amount of Estimate	Number & date of Sanction	Expenditure up to end of March 1897	Balance of Estimate	Amount applied for	Remarks.
<u>Works of Revenue Department</u>							
<u>Original Works.</u>							
<u>North Arcot Division.</u>							
1.	Constructing an earthenware pipe sluice to Pillari	180	Reg No 255 of 1895-96	27	153	153	
2.	Do a byewash to Pillari tank	46	Do. 254 of 1895-96	44	2	2	
3.	cutting a supply channel from Pinnapadi tank to Pillari tank	900	Do No 256 of 1895-96	"	900	900	
4.	Constructing a Kondam across the river at the head of the Channel Supplying Villam Tank	810	Do No 224 of 1895-96	1	809	809	
				Total original works		1864	
5.	Repairing the escape in Kallanaramiah Cheruvu	540	Do. 254 of 1893-94	404	136	136	
6.	Oldanagaram tank Repair the bund & empty high & low level sluices and a Calinguloh to	1370	Do No 147 of 1895-96	1171	199	199	
7.	Raising & strengthening the bund of Pillari tank	500	Do No 253 of 1895-96	325	175	175	
			Total Repairs			510	
8.	Repairs to Kener Anicut.	3,430	Reg No 12 of 1896-97	758	2,672	2,672	
9.	Clearing silt to supply channel to Belur Chinnai Anicut	840	Do. 36 of 1895-96	672	168	168	
			Total Repairs			2,840	
			Grand Total			5,214	

W m m m

27th May 1897
 Subg Engineer III Circle

Suby Engineers' Office
Freetown, Sierra Leone
27th May 1897.

28
No. 92
From,

J. Hannan, Esq.
Suby Engineers.
4th Circle.

To.
The Chief Engineer
For Investigation
Madras.

Sir,
I have the honour to forward herewith,
an application for funds required for expenditure on minor works, Revenue Department - during 1897-98, and to request you will be good enough to have the ^{amount} placed at the disposal of officers concerned as early as possible.

I have the honour to be
Sir

Your most Obedient Servant

W. Hannan

Suby Engineers 4th Circle.

28