Public Works (1896) Department.

G.O., No. 487

Dated 10-6-96

[Despatch Abstract.]

Funds: Certain transfer of — under Minor Works, Revenue Deptt., to North Arcot and Salem Dts., sanctioned.

BACK PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

IRRIGATION.
ACCOUNT.

Govt. of {1896} Madras.

PUBLIC WORKS.

Dated June, 10th.

Read. *Encl.*

G.O. No. 487 I., 10th June 1896.

JUNE.

Funds

Certain transfers of — under Minor works, Revenue Department, to North Arcot and Salem divisions, sanctioned.

No. 487 I., 10TH JUNE 1896.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Irrigation.
Account.

READ—the following paper :—

From J. C. LARMINIE, Esq., M.I.C.E., Superintending Engineer, IV Circle, to the Chief Engineer for Irrigation, dated Ootacamund, 22nd May 1896, No. 90 I.

I have the honour to forward, herewith, an application for funds required for expenditure on Minor works, Revenue Department, during 1896–97 and to request you will be good enough to have the amounts placed at the disposal of officers concerned as early as possible.

ENCLOSURE.

STATEMENT showing incomplete works of 1895–96 and the demands on the "Reserve" of 1896–97, IV Circle.

Item number.	Name of work.	Amount of estimate.	Number and date of sanction.	Expenditure up to end of March 1896.	Balance of estimate.	Amount applied for.
	WORKS OF REVENUE DEPARTMENT.	RS.		RS.	RS.	RS.
	Original Works.					
	North Arcot Division.					
1	Constructing a low level sluice to Kommavu Kattanayani cheruvu.	450	Register No. 212 of 1891–92.	324	*125	125
2	Lowering the crest of weirs of Velur Hissa tank in Walajah taluk.	55	Register No. 243 of 1895–96.	40	15	15
3	Constructing a Kondam across the Madugu of Alamelumangapuram.	300	Register No. 153 of 1895–96	..	300	300
4	Excavating a new supply channel to Otteri tank from the Kattuvarampolliem main channel.	110	Register No. 165 of 1895–96.	..	110	110
5	Constructing a head sluice at the head of the proposed channel to Otteri tank of Kathivarampolliem.	170	Register No. 166 of 1895–96.	..	170	170
6	Constructing a byewash to Pilleri tank	46	Register No. 254 of 1895–96.	..	46	31
7	,, an earthenware pipe sluice to Pilleri tank.	180	Register No. 255 of 1895–96.	..	180	120
8	,, a supply channel from Sinnapadi tank to Pilleri tank.	900	Register No. 256 of 1895–96.	..	900	600
	Salem Division.					
9	Improvements to Ganajur tank	350	Register No. 32 of 1895–96.	200	150	150
10	Reconstructing Belur chinna anicut	3,950	Register No. 35 of 1895–96.	3,868	82	80
11	Constructing a dam across the Kallathu Kombai channel and improvements to anicut.	420	Register No. 37 of 1895–96.	320	100	100
	Total, Original Works ..	..		..	..	1,801

* No work was done on this estimate in 1895–96 owing to water in tank.

No. 487 I., 10TH JUNE 1896.

Statement showing incomplete works of 1895–96 and the demands on the "Reserve," &c.—*cont.*

Item number.	Name of work.	Amount of estimate.	Number and date of sanction.	Expenditure up to end of March 1896.	Balance of estimate.	Amount applied for.
	WORKS OF REVENUE DEPARTMENT—*cont.*					
	Repairs.	Rs.		Rs.	Rs.	Rs.
	North Arcot Division.					
12	Repairing the band and constructing high and low level sluice and a calingulah to Odanagaram tank.	1,370	Register No. 147 of 1895–96.	..	1,370	1,370
13	Repairing the existing dam or Kondam across the Nandimangalam river.	440	Register No. 116 of 1893–94.	264	176	176
14	,, the escape in Kalyanaramiah cheruvu ..	540	Register No. 254 of 1893–94.	404	*136	136
15	,, dam across Pakamkasam in Gudiyáttam taluk.	270	Register No. 152 of 1895–96.	..	270	270
16	,, and strengthening the band of Pilleri tank.	500	Register No. 253 of 1895–96.	..	500	333
	Salem Division.					
17	Repairs to Ganajur tank	400	Register No. 32 of 1895–96.	209	191	190
18	,, to Anchetti anicut	600	Register No. 33 of 1895–96.	1	599	310
19	Repairing supply channel to Belur chinna anicut..	840	Register No. 36 of 1895–96.	650	190	200
	Total, Repairs ..	..		..	..	2,985

*No work was done on this estimate in 1895–96 owing to water in tank.

ORDER—No. 487 I., dated 10th June 1896.

The following transfers of funds are sanctioned :—

Irrigation.

43. Minor Works and Navigation.

Minor Works, Revenue Department.

From			Rs.	To			Rs.	Rs.
Reserve—				North Arcot Division—				
Original works	...	...	4,786	Original works	...	...	1,471	
Establishment	...	...	1,101	Repairs	...	...	2,285	
Tools and plant	...	...	71					
							3,756	
				Establishment	...	...	864	
				Tools and plant	...	...	56	
				Salem Division—				4,676
				Original works	...	...	330	
				Repairs	...	...	700	
							1,030	
				Establishment	...	...	237	
				Tools and plant	...	...	15	
								1,282
Total	...		5,958	Total	...			5,958

(True Extract.)

Under Secy. to Govt., P.W.D.,
Irrigation Branch.

To the Chief Engineer for Irrigation.
,, Superintending Engineer, IV Circle.
,, Examiner, Public Works Accounts.

Exd. T. K. Narayana Aiyangar.
Spare Copies

A/
Ltr No. 4870, dy 10-June 1896.

PUBLIC WORKS DEPARTMENT,
IRRIGATION BRANCH.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the 30

READ the following

From Supdg Engr. IV Circle, No. 90 I dy 22.5-96

The following transfers of funds are sanctioned :-

Irrigation

43. Minor works Navigation

Minor Works, Rev Dept

From		To	
Reserve -	Rs	North Arcot Dr	Rs
Original Works.	4786	Original Works.	1471
Establishment.	1107	Repairs . .	2285
Tools & Plant.	71		3756
Total	5958	Establishment	864
		Tools & Plant .	56
			4676
		Salem Dr	
		Original Works .	330
		Repairs . .	700
			1030
		Establishment	237
		Tools & Plant .	15
			1282
		Total	5958

DESPATCHED
24 JUN 96

To
The Chief Engr for I
Supdg Engr IV
Exr Exr.

Recd 1/6/96

F. 1. Form No 1–1,000 –27-11-96.

IV Circle

Statement showing incomplete works of 1895-96 and the demands on the "Reserve" of 1896-97

Item No.	Name of work.	Amount of Estimate	Number & date of sanction	Expenditure up to end of March 1896.	Balance of Estimate	Amount applied for.	Remarks.
	Works of Revenue Department.						
	Original works.						
	North Arcot Division						
1	Constructing a low level sluice to Kommavu Kattanayana Cheruvu	450	Rep. No 212 of 1891-92	324	125	125	No work was done on this estimate in 1895-96 owing to water in
10	Reconstructing Vellur Chinna Anicut	3,950	" 38/95-96	3868	82	80	
11	Constructing a dam across the Kallathu Kombai Channel & improvements to Anicut	420	" 37/95-96	320	100	100	330
	Total Original Works.					1,801	
	Repairs						
	North Arcot Division						
12	Repairing the bund and constructing high and low level sluice & a Calingulah to Olanagaram Tank	1,370	Rep. No 147 of 1895-96.	"	1,370	1,370	
13	Repairing the existing dam or Kondam across the Nandivanganam River	440	" 116/93-94	264	176	176	

P. I. Form No 1—1,000 -27-11-96.

	the proposed channel to Otteri Tank of Kathi-varampollicut	170	— " 166/95-96	"	170	170	
6	Constructing a byewash to Otteri Tank	46	— " 254/95-96	"	46	31	
7	Constructing an Earthenware pipe sluice to Otteri Tank	180	— " 255/95-96	"	180	120	
8	Constructing a supply channel from Sinnapadi tank to Otteri Tank	900	— " 256/95-96	"	900	600	Vide 1471
	Salem Division						
9	Improvements to Ganajur Tank	350	— " 32/95-96	200	150	150	
10	Reconstructing ~~Dam~~ Chinna Anicut	3950	— " 35/95-96	3868	82	80	
11	Constructing a dam across the Kallathu Kombai channel & improvements to anicut	420	— " 37/95-96	320	100	100	330
	Total Original Works.					1,801	
	Repairs						
	North Arcot Division						
12	Repairing the bund and constructing high and low level sluice & a Calingulah to Odanagaram Tank	1,370	Page No 147 of 1895-96	"	1,370	1,370	
13	Repairing the existing dam or Kondam across the Nandimangalam Rivers	440	— " 116/93-94	264	176	176	

14	Repairing the escape in Kalyanaramiah channel	540	Rep. No. 254/93-94	404	136	136		No work was done on this Estimate in 1895-96 owing to water in Tank.
15	Repairing dam across Pakamkasam in Gudiyattam Taluq	270	" 152/95-96	"	270	270		
16	Repairing and strengthening the bund of Pillari Tank	500	" 253/95-96	"	500	333		
								Total 2285
	Salem Division							
17	Repairs to Ganajur Tank	400	" 32/95-96	209	191	190		
18	Repairs to Anchetti Anicut	600	" 33/95-96	1	599	310		
19	Repairing supply channel to Belur Chinna Anicut	840	" 36/95-96	650	190	200		700
	Total Repairs					2985		

Supg. Engineer, 4 Circle

CHIEF ENGINEER
FOR IRRIGATION.
27 MAY 96
No. 9-IC

Dec. 1
5257/96

No. 90
D

Supg. Engineer's office, 4th Circle,
Camp Botacaumund 22nd May 1896.

From,

J. C. Larminie, Esq, M. Inst. C.E.
Supg. Engineer, 4th Circle,

To,

The Chief Engineer
for Irrigation.

10

Sir,

I have the honor to forward, herewith,
an application for funds required for
expenditure on Minor works, Revenue Depart-
-ment, during 1896-97 and to request you
will be good enough to have the amounts
placed at the disposal of officers concerned
as early as possible.

Enclosure
1 statement.

I have the honor to be,
Sir,
Your most obedt. servant,

J. C. Larminie
Supg. Engineer, 4th Circle.
22/5

CHIEF ENGINEER
FOR IRRIGATION
21 MAY 96
Recd

6217

From

The Supg. Engineer
1st Circle

Encl 1

Answd 5.6.96

Dated 22nd
Desp - 25th May 1896

No 90
D

Encls: 1.

Funds required for expenditure on Minor Works, Revr Deptt during 1896-97.

Forwards an application for —— & requests to have the amounts placed at the disposal of the Offrs concerned.