Public Works (1896) Department.

G.O., No. 5949

Dated 17/7/96

[Despatch Abstract.]

Minor Irrigation Works

Pros Revenue Dept sanctioning estimates for Estami — requiring repairs in the North Arcot Dt for 1896-97 ; Recorded

[F.W. 25.
2,000—23-10-96.]

BACK PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

(True Extract)

Lionel Davidson
for Ag. Secretary to Govt.

To the Board of Revenue, with 16 Encls.

" P. W. Deptt. (I), with copy of statement.

h/c.

Form No. I – Minor Irrigation

Application for allotment.

Extract

Number	Name of Taluk	Name of village	Name of source	Area of irrigation: Total irrigable Ayakut	Area of irrigation: Present area cultivation average cultivation during last five years	Area of irrigation: Proposed area	Revenue: Assessment on the total irrigable Ayakut	Revenue: Average of past 5 years including water-rate and mamool quitrent: Normal revenue on the present area of irrigation	Revenue: Average of past 5 years including water-rate and mamool quitrent: Actual collection on the present area of irrigation	Revenue: Effected revenue	Date of occurrence of breach or damage	Amount expended on repairs during the previous five years	Sanctioned grant for 1895-96	Grant required for 1896-97	Nature of repairs.	Remarks fully explaining the necessity for the allotment.
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17
				acres	Acres	Acres	Rs	Rs	Rs	Rs		Rs	Rs	Rs		
								Vellore Taluk.								
2	Vellore Taluk	Valluvanam	Panam Tope Kasam	145	145	23	1264	1264	1264	145	..	..	..	1670	Earthwork .... 795-14-1 Rough Stone dams. 45-1-11 Revetment work 829-0-0	Banks around the kasam have fallen down into the Kasam and thereby the latter is much silted up and cannot be repaired by Kudimaramat. The estimate requires the Sanction of Govt under para 3 of G.O. 399 I dt 2nd May 1893. It is herewith submitted with the Special report of the Dn. I Sub-overseer.
								Arcot Taluk								
7	Arcot Taluk	Essayanur	Kasam Channel	101	101	..	1016	1016	1016	..	..	..	..	960	Earthwork ..... 810-0-0 Aqueduct -- 150-0-0	The channel has been out of repair for the last 20 years. It is very narrow and the banks thereof very high. It is now proposed to widen and deepen it so that water may flow freely. It is reported that the work cannot be done by kudimaramat. This is not of the nature of silt clearance and the work however requires the Sanction of Government under Rule 3 of the Rules published in G.O. No. 399 I dated 2nd May 1893. Provision is also made for the Construction of an aqueduct across Natteri Channel which is necessary in order to take the water of the Channel across Natteri Channel.
								Gudiyattam Taluk								
12	Gudiyattam Taluk	Reddionumgopalapan	Kasam Channel	57	56	..	404	404	404	..	..	..	..	150	Earthwork ... 127-9-7 Calingula repair - 22-6-5	The Channel is very shallow and water does not flow freely. It is to be deepened and widened. The soil is very hard and as such the work is not of the nature of silt clearance. The ryots are not able to deepen the Kasam by Kudimaramat. It is to be done at Government Cost. The estimate is enclosed as it requires Government Sanction.

(True Extract Copy)
(Signed) P. Rajaratna Mudali

(Signed) J. B. Burn
for Collector

(True Copy)

for Ag. secretary to Government.

BACK PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

Revenue Department.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

-----:-----

Read the following Proceedings of the Board of Revenue, Revenue Settlement &c., No. 2444 dated 18" May 1896 on the following:---

(1) Letter from the Collector of North Arcot, dated 13" March 1896, Dis. No. 592 Eng. of 1896, and Endorsement thereon of the Chief Engineer for Irrigation, dated 22" April 1896 No. 172 M.

(2) Board's reference thereon to the Chief Engineer for Irrigation, dated the 29" April.

(3) Letter from the Chief Engineer for Irrigation, dated 8" May 1896, No. 208 M.

Resolution:---

⊠ ⊠ ⊠

3. The estimates for items 2, 7 & 12 in the Vellore, Arcot and Gudiyattam taluks, respectively relating to repairs of spring heads or spring channels, will be submitted for the sanction of Government under rule 3 of the rules approved in G. O. 399 I, dated 22" May 1893.

⊠ ⊠ ⊠ ⊠

ORDER thereon, Mis. No. 2171 d/ 4" June 1896.

S a n c t i o n e d .

(True Extract)

for Ag. Secretary to Govt.

To the Board of Revenue, with 16 Encls.

" P. W. Deptt. (I), with copy of statement.

F 21 2,000—18-2-96.

Govt. of {1896} Madras.

REVENUE.

To

The Public Works Dept

Dated
Recd. } Encl.

Mis. / R. G.O., 4th June 1896, No. 2171.

SUBJECT.

Sanctioning the estimates for certain Minor Irrigation Works requiring repairs in the North Arcot District for 1896 - 97.

P. W. CURRENT No. 5550

Encl 1.

Received June 12. 96
Regd: 18. 6. 96.

Rc. 5941 dated 17 July 1896
Records

To the Chief Engr & Ex Engr
Exr of P.W. accts.

Recd 20/6/96

DESPATCHED
18 JUL. 96