

DATED
DESPATCHED
RECEIVED

No. 774

ENCLOSURES. -

SUBJECT.

Viswanathapuram Project -
States that nothing is known
about the — and requests to be
furnished with some particulars

DESPATCHED
18 FEB 95
INDEXED

Rev. Secy
Rev. Asst. Secy

G.O., No. 666W

DATED 22/2/96

[Despatch Abstract.]

Christ Church, Cuddapah.
Does not direct that the onlay
incurred on repairs to — be
transferred to the Civil Dept. for
adjustment.

BACK PAPERS.

FURTHER PAPERS.

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of {1896} Madras.
PUBLIC WORKS.

Dated February, 22nd.

Recd.

Encl.

G.O. No. 666 W., 22nd Feb. 1896.

FEBRUARY.

Christ Church, Cuddapah

Orders directing that the outlay incurred on repairs to — be transferred to the Civil Department for adjustment.

GOVERNMENT OF MADRAS.
PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

Read—the following paper:—

From the Executive Engineer, Cuddapah Division, to the Superintending Engineer, III Circle, dated 6th February 1896, No. C/475 M.

I have the honour to bring to your notice that the roof of Christ Church, Cuddapah, was badly damaged last June, a portion of the tiles at one corner of the building being blown away. The result was that the furniture and fittings of the church were being spoilt. At the request of the Collector I framed an estimate amounting to Rs. 360 for repairing the roof and asked him to obtain the necessary sanction for this amount as soon as possible. This was sent me with his No. 539 Eng., dated 21st August 1895 (copy herewith), and as the repairs were urgent I put the work in hand at once.

I now request you will obtain the sanction of Government to the carrying out of the work as required by Code, Volume II, Chapter III, paragraph 115.
2. The cost of repairs, together with percentage charges on account of establishment and tools and plant, are being debited to the Civil Department.

Enclosures.

Telegram from the Venerable Archdeacon, Madras, to the Lay Trustee, Cuddapah. Repairs to church sanctioned. Letter follows.

Ref. No. 539 Eng.

Copy communicated to the Executive Engineer, Cuddapah, with reference to his letters Nos. 632 and 981, dated 17th June 1895 and 9th August 1895, respectively, for information and necessary action.

(Signed) RAMACHANDRA ROW,
for Acting Collector.

21st August 1895.

No. 3470.

Copy submitted to the Chief Engineer, Public Works Department, for favour of obtaining the necessary sanction of Government.

(Signed) W. B. DEWINTON,
Superintending Engineer, III Circle.

12th February 1896.

GOVERNMENT OF MADRAS.
PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

Read—the following paper:—

From the Executive Engineer, Cuddapah Division, to the Superintending Engineer, III Circle, dated 6th February 1896, No. C/475 M.

I have the honour to bring to your notice that the roof of Christ Church, Cuddapah, was badly damaged last June, a portion of the tiles at one corner of the building being blown away. The result was that the furniture and fittings of the church were being spoilt. At the request of the Collector I framed an estimate amounting to Rs. 360 for repairing the roof and asked him to obtain the necessary sanction for this amount as soon as possible. This was sent me with his No. 539 Eng., dated 21st August 1895 (copy herewith), and as the repairs were urgent I put the work in hand at once.

I now request you will obtain the sanction of Government to the carrying out of the work as required by Code, Volume II, Chapter III, paragraph 115.

2. The cost of repairs, together with percentage charges on account of establishment and tools and plant, are being debited to the Civil Department.

Enclosures.

Telegram from the Venerable Archdeacon, Madras, to the Lay Trustee, Cuddapah. Repairs to church sanctioned. Letter follows.

Ref. No. 539 Eng.

Copy communicated to the Executive Engineer, Cuddapah, with reference to his letters Nos. 632 and 981, dated 17th June 1895 and 9th August 1895, respectively, for information and necessary action.

(Signed) RAMACHANDRA ROW,
for Acting Collector.

21st August 1895.

No. 3470.

Copy submitted to the Chief Engineer, Public Works Department, for favour of obtaining the necessary sanction of Government.

(Signed) W. B. DEWINTON,
Superintending Engineer, III Circle.

12th February 1896.

ORDER—No. 666 W., dated 22nd February 1896.

As Christ Church at Cuddapah does not appear in the list of churches in charge of the Public Works Department, the repairs in question should not have been put in hand without the prior sanction of Government. The outlay incurred will be transferred to the Civil Department for adjustment.

2. No charge need be made on account of establishment and tools and plant, the work being a provincial one.

(True Extract.)

Under Secy. to Govt., P.W.D.

To the Superintending Engineer, III Circle.
 „ Examiner, Public Works Accounts.
 „ Ecclesiastical Department.

Exd. T. K. Narayana Aiyangar.
 Spare Copies

No 666 W of 22 Feby 1896

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following

From the Super Eng: III Circle (H.E. No. 3470 dated 12 Feby. 1896)

As Christ Church at Cuddapah does not appear in the list of churches in charge of the Public Works Department the repairs in question should not have been put in hand without the prior sanction of Government. The outlay incurred will be transferred to the Civil Department for adjustment.

2. No charge need be made on account of Establishment and Tools and Plant, the work being a Provincial one.

DESPATCHED

3-MAR-96

*S. E. III Circle
 Exd. P. W. A.
 Eccles. dep.*

21/4/96

18/2/86

Copy of letter from the
Executive Engineer, Cuddapah Divn
to the Superintending Engineer, 3rd
Circle dated 6th February 1896 No 9/52

Repairs to Christ Church
Cuddapah

I have the honor to bring to your
notice that the roof of Christ Church
Cuddapah was badly damaged last
June a portion of the tiles at one
corner of the building being blown
away. The result was that the fur-
-niture and fittings of the Church
were being spoilt. At the request
of the Collector I framed an estimate
amounting to Rs 360/- for repairing
the roof and asked him to obtain
the necessary sanction for this
amount as soon as possible. This
was sent me with his No 539 Eng, dated
21 August 1895 (Copy herewith) and as
the repairs were urgent I put the work
in hand at once.

I now request you will obtain the
Sanction of Government to the carry
ing out of the work as required by
Code Vol. II Chapter III para 115.

CHIEF SECRETARY
10 FEB. 1896
GOVERNMENT OF MADRAS

Chief Secy
for Govt of Madras

2. The cost of repairs together with percentages charges on account of Establishment and Tools and Plant are being debited to the Civil Department.

No. 3470 Eng
12-2-96

Copy submitted to the Chief Engineer P.W.D for favour of obtaining the necessary sanction of Government.

L. B. Chitambar

Superintending Engineer
3rd Circle

Telegram

Madras
Nungambakum

From

The Venerable Archdeacon

Madras

To

The Lay Trustee

Buddapah.

Repairs to Church sanctioned. Letter follows.

Reference No. 539 of 21-8-95
Engg

Copy communicated to the Executive Engineer Buddapah with reference to his letters No. 632 & 981 of 17-6-95 & 9-8-95 respectively for information and necessary action.

Signed Ramachandra Row.
For Acting Collector

(True copy)

L. B. Chitambar

Superintg Engineer
3rd Circle

Pls. 1

14568/96

Encls 1

Dec: 13. 2. 96

From
H. D. DeWinton Esq
Superintending Engineer
3rd Circle Bellary

To
The Chief Engineer
D. H. Deptt
Madras

No 2746 W. 17-10-91 ✓
" 3346 W. 11-12-91 ✓
" 572 W. 20-2-92 ✓
" 2481 W. 27-9-93 ✓

Dated 12-2-96
Encs 1 No 3470

Christ Church Budday
Requesting to obtain the
Sanction of Government
to the carrying out of
the work of