

Public Works (1897) Department.

G.O., No. 3250 W

DATED 22 November 1897

[Despatch Abstract.]

Lighthouse at Nepapalam, Estimate of Rs. 450 for repairs to the — Approved and returned with the S.E. Clerk for sanction and early execution and a sum of Rs. 450 appropriated for the work from the Reserve under Excluded Local Port Funds. //

P. W. DEPARTMENT.

Papers to be read in proceedings:—

189 , No.

189 , No. *

Current No. 9042

189

189

ORDER.

The estimate of Rs 450 for repairs to the Lighthouse at Negapatam is approved and returned to the Supty. Engineer, V Circle for sanction and early execution. A sum of Rs 450 is appropriated for the work from the reserve with the Govt. under Excluded Local Port Funds.

2. The specification for paint should be obtained from the Consulting Architect

16.11.57

Note

As this is a repair work, provision of an allotment is necessary in the interest of the building.

W.H. 1898

attd. 13/11/97 u

20

The S.R. V circle with
3 inches.

.. Ryan P.W. Accts.

.. Marine Dept^h

23/1/97

His Excellency

FOR ORDERS.

An estimate of Rs 450 for
repairs to the lighthouse
at Negapatam is dealt
with in the accompany-
ing technical note and
submitted for sanction.

C.H.M.S.

13/11/94

H. B. S. 16-11-94

Public Works Department.

Current No. 9042

Letter No. 1832/325 G

Dated 6th September 1897

From the Presidency Port Officer.

NOTE BY TECHNICAL SECTION.

(C)
Name of work Repairs to the Light House
at Negapatam.
Amount of Estimate Rs 450.

The estimate provides for removing the existing paint on the outside of the column and to repaint the interior & exterior of the column with 2 coats of Silicate white paint, as the old paint which is reported to have been laid on 2 years back by the local Port Officer has become dark in places, also for a cut down bearings with angle iron studs to the iron Ties from which signal flags are hoisted, as the swinging of these Ties has damaged the brick cornice. Putting on paint to plastering the walls with cement is also provided for. A lump sum of Rs 140 has been provided for scaffolding.

The rates are fair.

The estimate has been considered by the Presidency Port Officer & is in order.

Accepted
12/11/97

15.9.97

Thro' the Secretary to Govt P. W. Department

Marine (1897) Department.

CURRENT No.

P. W. Current No. 9042

From

The Presidency Port Officer,
Madras

Order

No. $\frac{1832}{325}$ 4

Dated 6th September 1897

Received

Registered

Enclosures 3.

Spare copies

SUBJECT.

Forwards for sanction and
allotment of funds an estimate
amounting to Rs. 50/- for
repairs to the Lighthouse
at Negapatam -

1

No. 1832
325 4

From

To

MARINE DEPARTMENT,

Chepak.

SIR,

I have the honor to be,
 Sir,
 your obedt. servant,
 A. A. Theet
 Commander, R. I. M.
 Oray Port-officer

your 5-97

13

Draft order
ending the estimate
to \$4.75 each, for
penetration & execution
what about
funds?

44

13/8/57

Ex. 1221 W 8 11.5.97
Lighthouse at
Hypobetau - Report
of inspection of the
- counts to the
Marine Dept.

The above Ex. is given
to B for Administration
Report.

Ex. 1221 W 8 11.5.97
Lighthouse at
Hypobetau - Report
of inspection of the
- counts to the
Marine Dept.

The above Ex. is given
to B for Administration
Report.