1-4-20. B. II

Public Works (1897) Department.

G.O., No. ~~2597~~ 858

DATED 20 September 1897

2/7/97

[Despatch Abstract.]

Excess Expenditure. Authorizing the Examiner of P.W. Accounts to admit the — of Rs. 50 incurred on ~~[illegible]~~ certain works in the Kistna Eastern Dn.

90/4

Rec'd 21/2/97

Rec'd 20/2/98

[P.W. 26/ 1,500—30-11-96.]

Indexed.

BACK PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

IRRIGATION.
ACCOUNT.

Government {1897} of Madras.

PUBLIC WORKS.

Recd. } 1897. *Enclosures*
Regd. } *Spare copies*

G.O., No. 858 I., 20th September 1897.

SEPTEMBER.

Excess Expenditure

Authorizing the Examiner of Public Works Accounts to admit the — of Rs. 50 incurred on certain works in the Kistna Eastern division.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Irrigation.
Account.

READ—the following paper :—

No. 172 I.

Note by the Chief Engineer for Irrigation.

The following extract from a list showing excesses incurred over estimates for certain works requiring sanction, forwarded by the Superintending Engineer, II Circle, with his endorsement, No. 1461 K.E., dated 20th August 1897, is submitted to Government :—

Item No.	Name of work.	Amount of estimate.	Expenditure.	Excess.	Explanation of excess.
		Rs.	Rs.	Rs.	
1	Constructing head sluice to Kistnapuram branch of Medur channel, Masulipatam canal.	350	369	19	The excess is due to water having had to be carted from a distance of over one mile and to cost of excavating a pit 13 feet deep at work site to obtain water which, however, was not met with at that depth.
2	Constructing sluice No. 3 to Rallacodu of Kykalur channel.	222	253	31	The excess is due to dressed face stone work not provided for in the estimate and to workshop charges being greater than the provision made in the estimate for shutters.

For the reasons explained, the excesses may be passed.

(Signed) W. HUGHES,
Chief Engineer for Irrigation.

3rd September 1897.

ORDER—No. 858 I., dated 20th September 1897.

The Examiner of Public Works Accounts is authorized to admit the excess expenditure incurred on the works referred to above, the total excess, viz., Rs. 50, being met from the balance of the provision made for item 710 of the statement printed in Proceedings of Madras Government, No. 857 I., dated 11th October 1893.

2. This sanction is registered as No. 81 I. of 1897-98.

(True Extract.)

Under Secretary to Government,
Irrigation Branch.

To the Chief Engineer for Irrigation.
,, Examiner, Public Works Accounts.
,, Superintending Engineer, II Circle.

Exd. T. K. Narayana Aiyangar.

His Excellency the Governor

PUBLIC WORKS DEPARTMENT,
IRRIGATION BRANCH.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the

READ the following

Excess Expenditure over Estimates of certain works in the Kistna Eastern Div.

Irrig

14-9-97

W.H.

I

Pub. W. No. 172-I. dy. 3-9-97

Note by the Chief Engr. for Irrig.

The following extract from a list showing excesses incurred over estimate for certain works requiring sanction, forwarded by the Supg. Engineer, Second Circle with his endorsement No. 1461-K.E. dated 20 August 1897 is submitted to Government:-

Item No.	Name of work.	Amount of Estimate	Expenditure	Excess	Explanation of excess.
		Rs	Rs	Rs	
1	Constructing Head-Sluice to Kistnapuram branch of Medur Channel, Masulipatam Canal.	350.	369	19.	The excess is due to water having had to be carted from a distance of over one mile and to cost of excavating a pit 13 ft. deep at workaite to obtain water which however was not met with at that depth.
2.	Constructing Sluice No. 3 to Rallacodu of Ky-Kalur Channel.	222.	253	31	The excess is due to dressed face stone work not provided for in the estimate and to Workshop charges being greater than the provision made in the estimate for shutters.

For the reasons explained, the excesses may be passed.

No. 858 I & 209-97

Order thereon.

The Examiner of Public Works Accounts is authorized to admit the excess expenditure incurred on the works referred to above, the total excess, viz. Rs. 50- being met from the balance of the provision made for item 710 of the statement printed in P.M.G. No. 857-I dated 11 October 1893.

2. This sanction is registered as No. 81 I of 1897-98.

A.H. 11.9.97

Recd 14/9/97

Flagged H

[signature] 31/8/97.

W.H. 3-9-97

I

To The Chief Engr. for Irrigation
" Examiner P.W. Acct.
" Supg. Engineer, Second Circle

[signature] 27/8/97

E. I. Form No. 1—1,000—2-2-97.

Public Works (1897) Department.

CURRENT No. 9296

Order

From The Chief Engr for Irrn

No. 172 I

Dated 3-9-97

Received 18-9-97

Enclosures 1

Spare copies

SUBJECT.

Excess over estimates of certain works in the Kistna Eastern Division submitted for sanction-

[signature]

BACK PAPERS.

No.	Date.

FURTHER PAPERS.

No.	Date.

Public Works (1897) Department.

8589

CURRENT No. 282 KS

From

Major W. L. C. Baddeley RE
Supg Engr II Civil

Order

No. 1461 KE

Dated 20 August 1897
Received 23 — do —
Registered
Enclosures
Spare copies

SUBJECT.

Excesses over Estimates in K.E.D. Forwards Emerg's explanation for certain —.

Dup disposal pappl.
F.E.I.

27/8/97

23/8/97

24/8/97

24.8.97

BACK PAPERS.

No.	Date.
I 7 KS	dy 14-1-97
R 381-I.	dy 8-7-97
R 891 W.	dy 4-11-93

FURTHER PAPERS.

No.	Date.

List of works noticed by the Chief Engineer for Irrigation in his memo No. II/7 K.S. dy 14.1.97.

Item no	Name of work	Amount of Estimate	Expenditure	Excess	Explanation of excess.
1	Constructing halting shed at Nidumdelock	390	760	370	1. The excess was already explained in this Office No 3719 dy 16.2.97 and it was also sanctioned in Gt. no 579 I dy 25.6.97
2	-do. Hd. Sluice to Kistnapuram branch of Medur Chl. Masulipatam Canal	350	369	19	2. The excess is due to water having had to be carted from a distance of over one mile and to cost of excavating a pit 13 ft deep at work site to obtain water which however was not met with at that depth.
3	Providing banks to Gudinada Chl.	1380	1507	127	3. The excess was explained in this Office no 10 dy 8.4.97 and it was sanctioned in Gt. no 579 I dy 25-6-97.
4	Constg: sluice No 3 to Ralla Codu of Kykalur Channel	222	253	31	4. The excess is due to dressed face stone work not provided for in the Estimate and to workshop charges being greater than the provision made in the Estimate for shutters.

Sanctioned

/50/ J. S. Wilson.
Exe Engr: K. E. Dn.

No. 1461 KE
20.8.97 Forwarded to the Chief Engineer for Irrigation with reference to

to his No. II/7 K.S. dy 14.1.97, for favour of Sanction of Government being obtained to the excesses over Estimates.

CHIEF ENGINEER
FOR IRRIGATION.
23 AUG. 1897
No. 282 KS.

2. The excesses may be met from the balance of the provision of item no 710 of the Statement printed with G.O. no 857 I dy 11-10-93.

Wm. Mis
Exe Engineer
for Supg Engr II Circle.
19.8.97

Le 8
19/97

Rec'd 1
9296/97