

14 12 23 II ✓

# Public Works (1898) Department.

G.O., No.

1676 W

DATED

5 July 98

[Despatch Abstract.]

*Intt. Remarks*  
Tower of the Connemara Library. Intaing, with  
reference to explanation from Lofol Boddy Rk.  
that his share of the blame for the failure of the  
— is considerably less than that of the officer who  
saw & passed the original design of the building —

| OTHER PAPERS. |     |             |       |      |     |             |       |
|---------------|-----|-------------|-------|------|-----|-------------|-------|
| G.O.          | No. | Department. | Date. | G.O. | No. | Department. | Date. |
|               |     |             |       |      |     |             |       |

Read letter from L<sup>d</sup> C. B. Oddy R.E. to you T.C. of  
13 June 1898.

No. 16764 of 7th July 98.

Lt. Colonel Boday  
 submits with his letter  
 read above the explanation  
 called for in para 3 of G.O.  
 3527 W of 16 December 1897.  
 His connection with the  
 design of the Commemorative  
 Library Tower dates from  
 the period of the revised  
 estimate when the Tower  
 was already more than half  
 built. He states that it  
 never occurred to him to  
 test its reliability at this  
 stage, especially as no  
 design was transmitted  
 with the revised estimate.  
 His Excellency the Governor  
 in Council observes that  
 if Lieut. Colonel Boday  
 had fulfilled his duty  
 thoroughly he would have  
 called for this design  
 and scrutinised it properly  
 but there is no doubt that  
 his

seen by GW

Handwritten signature: *Handwritten signature*

The Safety Eng<sup>r</sup> or Cowls

Connemara Free  
Library: — Explaining  
his share of responsibility  
for the failure of  
the tower of the —

Agree with Mr. De Winter's estimate of the degree

at Col. Brady's Home.

Andy's Home. 1A 8A-4H 22.6.91

22/6/92

Aug 23 1866  
A. E. 18.6.90 R23

558.21

FURTHER PAPERS.

No. 1914 TC.

Suz

heretofore Engineering Office

Kodak

17 Lewis

From

kanal. Df. 13' June 1890.  
Df. 15

Lpoo

Sub. C. V. Boddy &c.

perin Auding Esquire,

A handwritten signature in dark ink, appearing to be "L. J." or similar, located at the bottom right of the page.

W Leitch

✓h

Chief Engineer.

Sir

Awd.

With

5327 With reference to para 3 of G.O.  
I am called id 16 December 1897, in which  
in the respon on to explain my share  
the tower of 'ibility for the failure of  
I have the docter Connemara Free Library  
- yet after this to state that the sub.  
before me, in building was first brought  
Chief Engineer my capacity of Deputy  
the Consulting, when, in December 1898,  
submitted for Architect to Government  
statement for sanction Comparative  
for the Commemorative to £ 550 2/-  
- too. Tech

FURTHER PAPERS.

h. 915 TC

Learn

Impressari's office, Messrs  
Kodak & Co. 13 June 1890  
J/15.

Lt Col. A. T. Boddy R.E.  
 Superintendent Engineer  
 17 Circular



The Chief Engineer  
F. W. D.

Sir,

Enc. 1

I have the honor to return  
herewith the papers received with  
your Memorandum No. 1452 C dated  
9<sup>th</sup> March 1878.

I have the honor to be  
Sir,  
Yours most obedt. Servant.

J. V. Hodges Lt. Col. R.E.  
Engineer, 11 Cir.