

Public Works (1898) Department.

G.O., No. 265 9

DATED 28th March 1898

28.3.98

[Despatch Abstract.]

Expenditure: Authorizing the Engineer to admit
the ₹ — incurred on the work "throwing ring bund
round the breach in Vasista left bank below
1 1/2 miles, "Edavari Central D."

80/W Rb
25.3.98
Indexed. 98/3

BACK PAPERS.

Public Works (1898) Department.

CURRENT No. 2738

Order

No. 1079

Dated 24-3-98

Received }
Registered } 24-3-58

Registered

Enclosures /

Spare copies

SUBJECT.

Excess of Rs 596 incurred on
the work. "Throwing ring
bund round the breach in
Basista left bank below
12½ miles Godavari Central
Ln — Note recommending
for sanction the —

FURTHER PAPERS.

His Excellency the Governor.

PUBLIC WORKS DEPARTMENT,
IRRIGATION BRANCH.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the

READ the following

Excess of Rs 59 incurred on the work in
throwing roughened round the breach
on Varsha left bank below 12 1/2 miles
God Centrat In Recommending that the
may be passed

From the Executive Engineer in charge Dist Circle. (H.E. No. 2221-GD dated 12-3-88)
No. 107. I
Noted by the Chief Engineer for Irrigation

x wide letter flagged R

The Executive Engineer, in charge,
First Circle, applies for sanction to the
excess of Rs. 596. incurred on the work,
"Throwing ring bund round the breach
in Vasista left bank below $12\frac{1}{2}$ miles,
Godavari Central division.

2. The excess may be passed. The work
had to be carried out emergently and
proper levels and survey were not
taken, which resulted in the provision
for earthwork in the sanctioned esti-
-mate having been found insuffi-
-cient.

Issue

26.3-95 JAH

2

1005
m/3/25

22/3
98

Not

P-265 J 25.3.98

Order Theorem

The Examiner of Public Works
Account

Account is authorized to admit
the expenditure incurred on the work
referred to.

2. This sanction is registered
as N.P. 193.1 of 1897-98.

A.H.
23.3.98

AL

MT

27/3/95

22/3
98.

7.2.9
24.3.98.

Ans

To The Chief Engineer for Irrigation.
Supp. Engineer, Dist. Circle.
Examiner, P.W. Accounts.

He 100

U.S. Form No. 1-500-1-11-97

24/3/98

H.E. 22/3

Public Works (1898) Department.

CURRENT No. 47 G.D.

From W. De Morgan Esquire
Executive Engineer in charge Circle

Order

No. 2221 G.D.

Dated 12th March 1898

Received 19 — do —

Registered

Enclosures nil

Spare copies

SUBJECT.

Excess expenditure of Rs 596
incurred on the work "Shoring ring
bund round the breach in Varsit left
bank below 12 1/2 miles" - Submitting
explanation for the — and requesting
to obtain the sanction of Government
to the same.

F. E. J.

100
19/3/98

19/3
98

19-3-98

2. The Executive Engineer Godawan Central Division explains that the above excess was due to the insufficient provision

Made in the original estimate for the earth
work both in respect of quantity and rate,
✓ that the work was an emergent one and
proper levels and survey had not been
taken at the time the estimate was prepared.


I have the honor to be

Sir,

Your most obedient servant

W. Morgan

Executive Engineer
Mek. T. Cule



15/3

15/3