8/90 RH

5103/90/RH

5092/90/RH

14/11/93 RH

24/2/97/RH S-6

901/RH 97

8/90/RH

Public Works (1898) Department.

G.O., No. 5689

DATED 22nd July 98

[Despatch Abstract.]

Baggavala Spring Channel : Fwd: Rev.

Dept Sanctioning an Estimate of Rs 623 for repairs to ——— in the Kurnool Dt, to be executed by the Rev. Dept, Communicated to the Chief Engineer for Irrigation.

[P. W. 26. 1,000—2-3-98]

Indexed.

BACK PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

Public Works (1897) Irrigation Department.

CURRENT No. 5548

N- 568 Irr 22 July 98

~~No. 8524 of 21 '98~~ **From**

The Revenue Dept.

Order

Communicated to the Chief Engr for Irrigation.

No. 2645 Irrs.

Dated 22nd June '98.

Received } 4.7.98

Registered }

Enclosures

Spare copies

To the Chief Engr for I. R. S. 9 Irr 23/7/98

lcb 14/7/98

SUBJECT.

Sanctioning an estimate of Rs. 623 for the repair of the Buggumala spring channel, Kurnool Dr.

M 11-7-98

G.O.	No.

BACK PAPERS.

No.	Date.

FURTHER PAP

No.	Da

21 5,000—1-5-97.

REVENUE DEPARTMENT

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read Proceedings of the Board of Revenue, Revenue Settlement &c. dated 3rd June 1898, No.3444 Mis.

-:-

ORDER thereon No.2645 Mis. dated 22nd June 1898.

The estimate of Rs.623 for repairs to the Bugganala spring channel is, in the circumstances reported, sanctioned.

(True extract)

A. Russell

For Secretary to Government.

To the Board of Revenue, Revenue Sett &c. with 2 encls.

Copy to the Public Works Dept. (I)

Rw
29.6.98

F.
21 5,000—1-5-97.

Govt. of {189 } Madras.

REVENUE.

To

Dated

Recd. } Encl.

Mis.
R. G.O., 189 , No.

SUBJECT.

(Sett. 12—2,000—26-5-98.)

REVENUE BOARD OFFICE. MADRAS.

Proceedings of the Board of Revenue

(Revenue Settlement, Land Records and Agriculture),

Dated 3rd June 189 8

No. 3444 Misc

READ 1. Rudravaram Buggan... 68-4-0
2. Gummadapuram Pulla... 72-0-0
3. Rajapuram Pitchi... 108-4-0
4. Damagatla Voora... 871-4-0

the following letter from Mahammed Raza Khan Esq, acting Collector of Kurnool, R. Per. No: 46/81 dated 14th May 1898:-

I have the honour to submit herewith an application for an allotment of Rs 871 for the repairs of the marginally noted minor Irrigation works and to request that the same may be sanctioned for execution by the Revenue Department out of the District allotment of Rs 10,000

2. Work No: 1, Provision has been made for the removal of silt

silt. An extract from the divisional officer's report is herewith submitted. As recommended by him the cost of this item of estimate may be recovered proportionately from the ryots owning wet lands under Bugga after the repairs are completely carried out.

3. Estimates from all the works are submitted herewith

Read also endorsement thereon from the Chief Engineer for Irrigation, Tank Restorations Scheme, No: 1171 T. dated 25th May 1898;

"Forwarded. Item 1 is a spring channel. The estimate is approved on the understanding that the cost of removing silt, which under G.O. 399 dt 2.5.93 is a work that should be done by the interested ryots, will be recovered from them and credited to the estimate, as stated by the Collector. 2- The other items are approved."

Resolution.

The estimates amounting to Rs 248 for items 2 to 4 in the Collector's list are sanctioned.

2. The estimate of Rs 623 for improvements to the Bugga-nala spring channel of Kudaa-varam will be submitted for the sanction of Government with reference to the rules printed in Government Order 399 dated 2nd May 1893. The cost of clearing silt, for which provision is made in the estimate, will be recovered from the interested ryots under section 6 of Act 1 of 1858.

(True copy and Extract.)

Sd/ R. V. Srinivasiar

Secretary.

To the Collector of Kurnool,
with 3 estimates and the
connected reports
the Secretary to Government,
Revenue Department, with one
estimate & 2 reports
Chief Engineer for Irrigation
Tank Restorations Scheme.

(True Copy)

Govindharaman

Sr Secretary.

Encd/97

Application for Revar

No.	Name of Taluk	Name of village	Name of Source	area of Irrigation: Total irrigable ayakat	Present area cultivation during last five years.	Estimated area after repairs	assessment on total irrigable ayakat	Normal area as per present area of wet patch actual collection	average past five years water-rate pattirate	
3	Nandi Kotkur	Rajapuram hamlet of Sannur No. 49	Pichili vanikunta	12.21	12.21	53.88	14-11-11	72-9-11	72-9-11	
					Dry assessment		9-9--			
					water rate		49--			
4	b	Damaputta	Soora cheruvu	40.46	40.46	50.76	141-8-	323	141-8-	
							Dry assessment	19-11-4		
							W.R	162-1--		
								323-7-4		

Kurnool, 14-5-98

...or allotment for Minor Irrigation 1898-99.

...ee of years water can	Revenue expected after repairs	Date of occurrence of breach or damage	Amount expended on repairs during the previous five years	Sanctioned grant for 1898-99	Grant required for 1898-99	Items of estimate (R.P. dated 13-2-94, No:82	Remarks (1) By whom the works were inspected (2) By whom estimates were checked. (3) Whether the estimates provide for complete repairs. (4) Explanation of the necessity for the allotment when the proposed expenditure exceeds the average annual Revenue. (5) Whether the Surplus escapes have been duly examined as per R. Pdated 15.2.94 No:85 (6) Name of minor basin & page of descriptive memoir
10	11	12	13	14	15	16	
Rs	Rs		Rs	Rs	Rs		
58-0-7	570	...	...	..	623	Earth work cutting sides & clearing silt 62-0-0 Stone revetment 536-0-0 Contingencies 25-0-0 623-0-0	(1) Minor Irrigation overseer on 25-1-98 (2) Tahsildar (3) Yes (4) Considering the importance of the work and the revenue expected to be realised, the little excess may be passed. (5) no escapes (6) no information available.
33-0-9	58-0				68	Earth work 43-0-0 Coping planting etc 19-0-0 Plug 5-0-0 Contingencies 1-0-0 68-0-0	(1) Minor Irrigation overseer on 21-1-98 (2) Tahsildar (3) Yes (4) The repairs noted herein are unavoidably necessary and the little increase is therefore recommended to be passed. (5) Yes (6) no information available.

Application

No	Name of taluk	Name of village	Name of source	Area of Irrigation: Total irrigable ayakat	Registered cultivation during last five years, Extent area after repairs	Assessment on the total irrigable ayakat.	Nominal assessment on present area of irrigation
1	2	3	4	5	6	7	8	9
				acres	acres	acres	Rs	Rs
1	Nandikotkur	Rudravaram	Bugganalu					
			Originally registered	216.89				
			Ret ayakat at present	97.13	82.2	99.0	341-13-0	146-6-5
						Dry assessment		25-10-2
						Total		328-0-0
								550-0-7
2	do	Gummadapuram	Pulkamaraju kunta					
			Registered ayakat including tank bed and tank bund shown by metalled rules ayakat in the Settlement Register	38.30				
			Irrigable area at present	10.60	6.53	15.79	36.8-0	5-5-5
						Dry assessment	1-11-4	1-11-4
						W.R	15-3-0	26-0-0

Statement for Minor Irrigation 1898-99.

Revenue expected after repairs	Date of commencement of work or delivery.	Amount expended on repairs during the previous 5 years	Sanctioned / part	Grant required for 1899	Items of Estimate		Remarks
238	3-9-97	-	-	72	Earth work	32	(1) Minor Irrigation overseer on 10-1-99
					stone work	32	(2) Tahsildar
					Masonry backing	6	(3) Yes
					Contingencies	3	(4) Nil
						72	(5) Yes Tungabhadra river
							(6) basin page 34 of the descriptive memoir
358	-	-	-	108	Stone and Chunam work	84	(1) Minor Irrigation overseer on 11-1-98
					wooden Shutters for 2 Sluices	12	(2) Tahsildar
					Earth work	7	(3) yes
					Contingencies	5	(4) Nil
						108	(5) yes.
							(6) Tungabhadra River basin vide page 5 of the descriptive memoir Minor basin No- 29.

(Sd) G. Krishnaswami Naidu
for Rq Collector.

(True Copy)

G. Krishnaswami
Secretary