

P. W.
Marine (1898) Department.

G.O., No. 832 J

DATED 27th October '98

[Despatch Abstract.]

Pilapontthamkulam Tank

The execution by the Sec. Dept. of
certain repairs to _____ in the tank, is
sanctioned.

2d 28/10

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

July 18/10/98

BACK PAPERS.

No.	Date.
2186	29.8.98

FURTHER PAPERS.

No.	Date.

No. 807.T.N.

OFFICE OF THE SUPERINTENDING ENGINEER,

6TH CIRCLE,

Trichinopoly, 15th October 1898. 9/16


From

Robert O. D. Waddy R.E.
Superintending Engineer,
6th Circle.

To

The Chief Engineer,

for Irrigation



/ ENCLOSURES.

x
Repairing the
erosions in the
Dilapourthau -
Lulau - Pichuath
22.

I have the honor to inform you that the execution of the Tank Restoration Scheme work, situated in Timmavelli Taluk and noted in the margin, was entrusted in October 1897 to the Revenue Department, as the work was in an out of way place and there was no subordinate there to carry it out. I forward a copy of the Executive Engineer's letter No. 3641 of 3rd October 1898 on the subject, and, under the circumstances, I request that sanction of Government may be obtained to the procedure adopted, if such sanction is requisite, under paragraph 80, Chapter III, Volume I, P.W.D. Code.

2. It is reported that the work was completed & completion statement sent in.