

Public Works (1898) Department.

G.O., No. 1195 *25*

DATED 12 *Mar* 1898.

[Despatch Abstract.]

Automatic Gates: Letter to the Director General
of Stores India Office, stating that the 6 demands
in indent No 22 were received in 18 cases per
S.S. 'Robertson' and that on the cases being opened
^{Certain} the following breakage were discovered.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

1195 W

PUBLIC WORKS DEPARTMENT.

The Director-General of Stores

India Office .

London

12th May 1898.

I am directed to state that the

6 automatic gauges asked for in in-

dent No. 22 forwarded ~~in~~^{with} my letter

No. 561W dated 26th February 1897

were received in 18 cases per S.S

"Robertson" on the 25th February 1898

and that on the cases being opened

the following breakages were dis-

covered. They are believed to be

due to insecure packing:-

1. Case marked A No. 275-Pendulum bracket broken.
2. -do- B No. 282-One leg of stand broken.
3. -do- C No. 283, -do- .
4. -do- D No. 278-Frame badly broken.
5. -do- D No. 284-One leg of stand broken.

6.

Public Works (1898) Department.

CURRENT No. 3752

6. Case marked E No. 279-Pendulum bracket broken.
7. -do- F No. 280- -do-
8. -do- F No. 286-One leg of stand broken.

I have &c,

Order

From

The Supply Engineer
3rd Field

No. 2852

Dated $\frac{26}{28}$ April 1898.

Received 29.4.98

Enclosures

Spare copies

SUBJECT.

Reporting that 6 Antennae
-his gauges were landed
for "S. S. Robertson" with
certain breakages.

o. L. S. 82 29/5

BACK PAPERS.

FURTHER PAPERS.

No.	Date.
560-61W	26-2-97

No.	Date.

Copy of a letter from H. A. Moss Esquire
General Superintendent, Public Works, St.
dated 16 April 1898, to the Superintending
Engineer 5 Circle.

With reference to G. O. No. 560. U
dated 26th February 1897, I have the honour
to report that 6 Automatic Guages in
18 Cases were landed per "S. S. Robertson"
dated 25th February 1898 and on opening
the cases for the examination of the con-
-tents, the following breakages have come
to light, they are believed to be due to in-
-adequate packing.

- 1, Case marked A No. 275. Pendulum bra-
-cket broken.
- 2, D^o B No. 282 One leg of stand
broken.
- 3, D^o C No. 283 D^o
- 4, D^o D No. 278 Frame ^{body} broken.
- 5, D^o D No. 284 One leg of stand
broken.
- 6, D^o E No. 279. Pendulum bra-
-cket broken
- 7, D^o F No. 280 D^o
- 8, D^o F No. 286 One leg of stand
broken.

(Signed) H. Moss.
General Superintendent. P. W. Stone
Dated 18 April 1898.

No.

No 285

560-61

To the Chief Engineer P. W. D. for
 information, with reference to G. O. No. 56
 dated 26th February 1897.

C. L. A. M.
26/4/96 Colonel
 Superintendent