

Public Works (1899) Department.

G.O., No. 1998 W

DATED 28th July 1899.

[Despatch Abstract.]

Foreshore on the South-Western side of the
Custom House at Goodaipoor

Contd of the S.E. IV circle
Comtg: ~~report~~ the report that the
which had silted up after the last monsoon
has again commenced to be washed
away, recorded with reference to para 5
of G.O. No: 1732 W 27th July 1898.

RK

MRC

CURRENT No. 5564

From The Suptg. Engineer,
4th Circle.

Recorded with
reference to para 5 of
Gov. No. 1732 W dated
7th July 1898.

No. $\frac{364}{100}$

Dated 5th July 1899.

Received 10-7-99

Registered

Enclosures

Spare copies.

SUBJECT.

Foreshore at the Sea Customs
at Coondapoor.

To
The Supt. Ingr. & Circle
Submitting West Coast Div. Office
letter in continuation of this office
12/68 d/23rd Mar/99 for order
regarding the —

02528/215/7

sent again 18/7/98

BACK PAPERS.

No.	Date.
1732W	7-7-99
1932C	6-4-99
5145C	19-11-98
1733W	2-7-98
87W	2-2-98
3412W	30-11-96

FURTHER PAPERS.

No.	Date.
-----	-------

No. 628D
Enq 9/99

South Canara, Collector's Office
Mangalore, 15th June 1899.

From

A. F. Pinhey Esq. 278
Ag Collector of South Canara
The Executive Engineer
West Coast Dist.
Calicut

Sir,

I have the honour to inform
you for such action as you may think
fit to take, that the sea Customs Super-
intendent, Coondapoor, reports that
the foreshore on the South-western
side of the Custom-House which had
silted up after the last monsoon
has again commenced to be washed
away.

I have etc.
(Signed) D. Ananthaya
Ag Collector.

No. 366SE
28.6.99

Copy forwarded to the Suptg
Engineer TC Nile with request that
orders may be passed on this office
nos 158SE + 168SE dated 16th and 25th
March respectively

(Signed) C. J. Nasser
Exec Engr.

No. 364 d/6-7-99

Copy submitted to the Chief Engineer
P.D. in continuation of this office no. 168
of 23.3.99.
Andruud
Suptg Engr TC Nile

x 1932C
6-4-99.

27.7.99