

G.O., No.

G.O., No. 365-J

DATED *18 April* 1899.

Contribution to work

Contribution Work
The Executive of the G. S. D. of W.
of repairing the Pathways Park, at Brambleton,
Richmond, Va. San Antonio

3029

The Supp Inquest
to Circle

Order

Order No. 365 27 1848

No. 628 T.C.

The expenditure by the P.W.D of the work referred to is sanctioned, the contribution being limited to the amount already realised.

Dated 7 April 1899.

Received } 8 - do -
Registered } 11 - 4 - 29

Enclosures —

Spare copies

SUBJECT.

Repairing the Puttu-
-yri tank at Perambur-
-lore — Requesting
sanction of Govt for
the execution of the work
off — as Contributions
attach.

To
The Chief Eng for 9 ✓
Supp Eng 11 ✓
25 PW2 ✓
1000 8

102
874/29

191

of

2

BACK PAPERS.

No.	Date.
-----	-------

FURTHER PAPERS.

No.	
-----	--

From John Lyles Esquire, Executive Engineer, Trichinopoly Division, to the Superintending Engineer, W. Circle, No 21 P.E. dated 5 April 1899: -

I have the honor to report that an estimate amounting to Rs 70 for repairing the Puthurri Tank at Perambalur was sanctioned in Register No. 118 of 97-98. This estimate provides for removing the prickly pear on the bund estimated to cost Rs 22 which should be done by the ryots under Kudi-maramath. As the ryots under the Tank failed to do the same, the work was carried out by this department & the cost thereof - viz. Rs 22 was recovered from the ryots concerned through the Revenue Department and credited to the work.

*
Excluding the
preliminary charge
for establishment
& Tools and Blank.

2. As the Examiner has reported this in the Q. J. Statement and remarked therein that sanction of Government should be obtained for undertaking it as contribution work though it was not sanctioned as such I request that you will be good enough to obtain the necessary

sanction and communicate the same
to the Examiner.

No. 628 T.C. of 7 April 1899
8/7.

Copy submitted to the Chief
Engineer for Irrigation with a request
that, under para 79, Chapter 1X, Volume
I of P.W. D. Code, sanction of Government
may be obtained to the execution of
the work by this Department.

2. The estimate for the work was
sanctioned by the Executive Engineer
in December/97 and registered in this
office in January 1898.

3. It will be seen that the cost of
removing prickly pear, namely Rs 22 has
only been recovered without the usual
percentage for Establishment and Tools
and plant Charge and it is requested
that this procedure may be sanctioned
as a special case.

4. The work has already been completed
and completion report sent in.

P.V. No. 1114 of 11 Feb. 1898.

Engg. Engineer, Or Circle