

ORDINARY, MS.

Public DEPARTMENT.

G.O., DATED *7-11-92*
 No. *768*

When given for copying.

[Despatch Abstract.]

Com to the Supd.
 Archaeological Survey
 and P.H. dept com ltrg
 for the Supd. Insp. & Co.
 regarding the Hoysaleswara
 temple Nelayarpet
 taluk—

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following

Letter from the Executive Engineer
Trichinopoly Division No. 397 Sd. of
10th October 1892.

With reference to the memo
against serial number 30 in the list
of ancient monuments selected for
conservation, received with your
No. 934 Sd. of 16th September 1891,
I have the honor to inform you
that the front Gopura of Brimades-
varaswami temple at Bangaitondai,
Sholapuram, Udayarpalayam Taluk,
is reported by the North Sub-
Divisional Officer to be in such a
dilapidated condition that it is not
possible to preserve it at any
reasonable cost.

2. During the past few years
some vegetation was removed
in the compound of the temple and

this year too it is said that some money would be spent for the purpose by the temple authorities, but nothing can be done for the removal of vegetation from the front of the temple which is inaccessible owing to its dangerous condition.

3. The temple is full of engravings of an ancient type and the Sub Divisional Officer reports that it was once proposed by the temple authorities to blow up the structure by means of gunpowder as access to it is considered very dangerous.

Endorsement by the Superintending Engineer VI Circle No. 1071 S.C. of 13th October 1892.

Copy submitted to the Chief Engineer D. & W. for orders of Government.

2. In the column of remarks against Item 30 in the revised list, which accompanied G.O. No. 2437 W of 10th September 1891, it is stated that

"the front of the temple is in a dangerous state, and needs immediate repair" but from the foregoing report it will be seen that no repair can be attempted to the temple owing to its very dangerous state.

Order thereon No. 2979 W of 27th October 1892

Communicated to the Public Department with reference to G.O. of 24th July 1891, No. 621 Public.

/ J. M. A. /

M. A. A.

Under Secretary to Govt
P. W. D.

Encl. 2. C. & G.

To
The Public Department.

Public (1892) Sept-
Public Works Department.

24/7/91 No 621 Pule-S.
H.M.
Order 57th November/92
N^o 768.

No. 2979 W.
Dated 27th October 1892
Despatched 28th
Received 29th } 29/10/92
Repd. 31st }
Enc: "

bound: to the Supt.
Arch: Survey.

J.D.B.
2/41

SUBJECT.

Sopenam in today's paper
Jaluf: Letter from the
Superintending Engineer
to Civil regarding the
dangerous condition of a
Cabin — Comd to the
Public Dept.

Supt. Arch. Survey dated 29/11/92
Copied 10/11

WITH ORDER

C-4/11
27/11

BACK PAPER, No.

OF 13

FURTHER PAPER, No.

OF 13

READ AGAIN ORDER OF GOVERNMENT, DATED
18, No. , MISCELLANEOUS.

ENCLOSURES.

CURRENT No.

STATEMENT WITH DITTO.

ORDER OF GOVERNMENT.

LETTER OF GOVERNMENT.

STATEMENT WITH DITTO

PAPERS NOT FILED UP, BEING MEANT FOR DESPATCH
IN ORIGINAL (not paged).

N.B.—

- A = Copy in full.
- B = Not to be copied.
- P = Copy abstract only.
- Q = Copy heading only.