

P.W.
~~Marine~~ (1899) Department.

G.O., No.

9430
~~Marine~~

DATED

1st Nov 1899.

[Despatch Abstract.]

Pallikottal channel, Tinnevely taluk.

*the execution, by the P.W.D., of the work
of repairing the ——— sanctioned*

Fallikottai Channel
— Requesting con-
-tion of Govt. to the
execution by this de-
partment of the work
of emergency repairs &-

To
The Chief Eng^r for Immigration
Suff Eng^r, W. Irish
Suff. P.W.D.

1012
1410727

BACK PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.
------	-----	-------------	-------	------	-----	-------------	-------

BACK PAPERS.

FURTHER PAPERS.

No.	Date.
4577 11-7-77	

No.	Date.

No.

820 T.N.

OFFICE OF THE SUPERINTENDING ENGINEER,

6TH CIRCLE,

Trichinopoly, 9 October 1899.

From

Lt. Col. G. V. Boddy R.E.


Superintending Engineer,

6th Circle.

To

The Chief Engineer,

for Irrigation.



SIR,

ENCLOSURES.

Under paragraph 79, Chapter IX Volume I of the Public Works Department Code, I have the honour to request that sanction of Government may be obtained to the execution, by this Department, of the contribution work noted below.

2. An Estimate of Rs. 490 for emergent repairs required to the Pallikottai channel in Tinnevely Taluk, Tinnevely Division, has been prepared. The channel supplies both the Government and Uthumalai Zemindari lands, 998 acres of Government and 488 of Zemindari. A sum of Rs. 161 should therefore be borne by the zemindari being his proportionate share of contribution towards the

the estimated cost of repairs but the work has not been included in the contribution statement forwarded with your No:

VI/45 T.W., dated 11th September 1897. *File X*

3. The Collector has however been addressed to recover the above sum and that officer in returning the estimate countersigned, states that the Deputy Collector, Thernaderi, has been requested to collect the contributions from the Uthumalai Zemindari and report the result soon.

4. The estimate provides chiefly for strengthening the weak portions of the channel bank, clearing silt in the bed of channel at the crossing of inlets, or Odais, and for closing a breach in the left flood bank near the wing of the anicut. The work being urgent has been ordered by the Executive Engineer to be put in hand at once.

5. Under the circumstances, orders are requested to complete the work from Government funds, the contributions being

being credited to the work after it is recovered.

I have the honour to be,

Sir

your most obedient servant.

V. No. 1111 Lt. Col. R.L.

Supg. Engineer, 6th Circle

2/10/97

FROM THE

being entitled to the name of the
company.

of the name of the

is called
the name of the

the name of the

17

T