M.R.O. 14—13,000—27-6-24

# MADRAS RECORD OFFICE.

## Government of Madras.

Revenue **DEPARTMENT.**

G.O. No. 25-95- Press Mis.

614-615

Dated 26-9- 1866..

***Not to be folded or roughly handled***

Misc 1/1929

M.R.O. 14—13,000—27-9-24

# MADRAS RECORD OFFICE.

## Government of Madras.

Revenue **DEPARTMENT.**

G.O. No. 25-95 — Press Mis.

614-615

Dated 26-9-1866..

***Not to be folded or roughly handled***

*Proceedings of the Madras Government, Revenue Department,*
*26th September* 1866.

No. 614. Read the following Proceedings of the Madras Government in the Public Works Department :—

Passing orders on Board's Proceedings submitting Returns of Agricultural Works in the Cuddapah and North Arcot Districts urgently needing repairs. } (Here enter 19th September 1866, No. 2,998.)

No. 615. ORDER THEREON, 26th September 1866, No. 2,595.

Miscellaneous.

Ordered to be recorded.

(True Extract.)

(Signed) J. GROSE,
*Under Secretary to Government.*

Exd. S. T. Augustin.

Read the following papers:—

Proceedings of the Board of Revenue, dated 30th August 1866, No. 6,185.

Read the following paper from the Collector of Cuddapah, to the Secretary to the Board of Revenue, dated 17th August 1866.

List of the more important Irrigation Works, which are most urgently in need of repair in the District of Cuddapah, specifying the estimated amount of repairs required, the date of last repair, and the irrigable Ayacut under each work, as directed in the Board's Circular, dated 11th June 1866, No. 3,972.

| Táluq and Village. | | Name of Irrigation work. | Total registered Nunjah Ayacut. | Tax payable on whole Nunjah Ayacut. | Average tax actually paid from 1840 to 1850. | Average tax actually paid from 1850 to 1860. | Present cultivation as per account for Fusly 1275. | Present revenue as per account for Fusly 1275. | Rough estimate of repairs needed. | Date of last repair. | Remarks, explaining what repairs are required. |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 |
| Cuddapah. | Camalapuram | Pedda Chervu ... | Acres. 667 | Rs. 4,215 | Rs. 3,601 | Rs. 3,907 | Acres. 570 | Rs. 4,008 | Rs. 5,900 | The exact dates are not known, but the repairs are reported to have been executed six or seven years ago. | An estimate, amounting to Rs. 5,900, for the repairs of the tank bund, which is much worn out, has been framed by the Department of Public Works. |
| | Chadipiralla. | Pullampati Calva. | 169 | 1,058 | 378 | 400 | 64 | 443 | 250 | ..... | For repairing the sluice, which is out of order. |
| | Kutukur ... | Pedda Chervu ... | 449 | 4,325 | 4,173 | 4,107 | 392 | 4,311 | 700 | ..... | For the repairs of the bund. |
| | Pata Cuddapah | Do. ... | 1,066 | 14,373 | 13,818 | 14,069 | 865 | 11,337 | 1,000 | ..... | Do. do. |
| | Putlampally. | Pata Chervu ... | 156 | 1,330 | 1,285 | 1,227 | 156 | 1,330 | 1,000 | ..... | Do. do. |
| | | Total ... | 2,447 | 25,301 | 23,255 | 23,710 | 2,047 | 21,429 | 8,850 | | |
| Voilpaud. | Navabpett... | Pedda Chervu ... | 100 | 926 | 373 | 730 | 79 | 811 | 7,122 | Not known... | For repairing the bund and sluice. |
| | Chinnagottigal | Jantrapupett do. | 109 | 652 | 76 | 455 | 20 | 220 | 300 | 14th May 1852 | For the repairs of the sluice, which is out of order. |
| | Tarigondah. | Ramanayani do. | 190 | 1,463 | 1,267 | 1,122 | 100 | 828 | 1,300 | 27th Dec. 1856 | For the repairs of the bund and sluice. |
| | Manchuru... | Cotta do. ... | 192 | 560 | 111 | 120 | 48 | 194 | 430 | Not known... | Do. do. do. |
| | | Total ... | 591 | 3,601 | 1,827 | 2,427 | 247 | 2,053 | 9,152 | | |

List of the more important Irrigation Works, &c.—(*Continued.*)

| Táluq and Village. | | Name of Irrigation work. | Total registered Nunjah Ayacut. | Tax payable on whole Nunjah Ayacut. | Average tax actually paid from 1840 to 1850. | Average tax actually paid from 1850 to 1860. | Present cultivation as per account for Fusly 1275. | Present revenue as per account for Fusly 1275. | Rough estimate of repairs needed. | Date of last repair. | Remarks, explaining what repairs are required. |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 |
| | | | Acres. | Rs. | Rs. | Rs. | Acres. | Rs. | Rs. | | |
| Kadiri. | Patnam ... | Ranganayani Chervu. | 572 | 3,736 | 2,199 | 2,053 | 313 | 2,523 | 500 | In Feb. 1865. | For repairing the banks of the supplying channel of the tank. |
| | Vankamaddi. | Pedda Chervu ... | 399 | 2,041 | 1,367 | 818 | 278 | 1,366 | 1,000 | ,, Aug. 1865. | For repairing the bund and sluice. |
| | Dhannayani Chervu. | Do. ... | 175 | 743 | 593 | 655 | 150 | 713 | 1,200 | ,, May 1866. | For repairing the sluice and calingulah. |
| | | Total ... | 1,146 | 6,520 | 4,159 | 3,526 | 741 | 4,602 | 2,700 | | |
| Pullampet. | Poli ... | Chervu ... | 1,135 | 7,558 | 5,463 | 5,550 | 937 | 5,294 | 3,000 | ,, 1862 ... | For raising the dam constructed to convey the supply to the tank and strengthening the bund, &c. |
| | Rangampally. | Do. ... | 175 | 843 | 357 | 482 | 163 | 498 | 1,000 | ,, 1861 ... | For repairing the supplying channel and the bund. |
| | Nagiripad ... | Do. ... | 739 | 4,820 | 4,210 | 4,316 | 625 | 2,528 | 1,000 | ,, 1862 ... | For repairing the bund and supplying channel. |
| | Settikunta... | Pedda Chervu ... | 452 | 2,870 | 1,280 | 1,117 | 239 | 1,871 | 500 | ,, 1861 ... | For re-constructing a sluice, &c. |
| | | Total ... | 2,501 | 16,091 | 11,310 | 11,165 | 1,964 | 10,191 | 5,500 | | |
| Jammalmadugu. | Venakiah Kalva. | Chitravati river channel. | 366 | 2,926 | 1,957 | 1,188 | 2,219 | 1,523 | 500 | ,, 1860 ... | For re-excavating the river channel, which has been almost filled up with sand. |
| | Chintakunta. | Govindammah Chervu. | 286 | 3,971 | 905 | 1,065 | 4,345 | 2,450 | 200 | Not known. | For repairing the sluice. |
| | Gudem Chervu. | Penna river channel. | 168 | 1,652 | 1,075 | 676 | 1,594 | 1,164 | 1,200 | In 1858 ... | For clearing the channel, which has been totally filled. |
| | | Total ... | 820 | 8,549 | 3,937 | 2,929 | 8,158 | 5,137 | 1,900 | | |
| Poddatur. | Duvur ... | Tank ... ... | 415 | 7,270 | 6,015 | 6,311 | 406 | 7,149 | 800 | In 1856 ... | For repairing the bund and calingulah. |
| | Pallavolu ... | Do. ... ... | 383 | 707 | 446 | 517 | 373 | 698 | 2,230 | ,, 1865 ... | For re-excavating a new supplying channel, the old one having been entirely filled up by sand. |
| | Wupparapally | Rachervu ... | 157 | 581 | 217 | 233 | 154 | 564 | 300 | ,, 1862 ... | For enlarging the bund. |
| | Civapuram... | Ragadi Chervu... | 162 | 858 | 665 | 619 | 138 | 815 | 450 | ,, 1859 ... | For raising the bund and repairing the sluice. |
| | Ganzikunta. | Anantaraz do. ... | 173 | 964 | 845 | 839 | 149 | 836 | 1,000 | ,, 1863 ... | For repairing the sluice. |
| | Chintakunta. | Chinna Chervu and Pedda Chervu. | 384 | 6,689 | 4,656 | 5,315 | 370 | 6,479 | 5,000 | ,, 1864 ... | For enlarging the bund and repairing the sluice. |
| | Nandialampett. | Settiwaripally Chervu. | 105 | 1,585 | 887 | 1,042 | 89 | 1,403 | 200 | Not known. | For repairing the sluice. |
| | | Yellampally do.... | 113 | 1,377 | 684 | 808 | 86 | 973 | 100 | In 1856 ... | For repairing the bund. |
| | | Tiruvapally do.... | 133 | 1,808 | 1,023 | 1,342 | 91 | 1,243 | 800 | ,, 1861 ... | For clearing the bed of the tank, which has almost been filled with mud, and enlarging the bank. |
| | | Total ... | 2,025 | 21,839 | 15,438 | 17,056 | 1,856 | 20,160 | 10,880 | | |
| | | Grand Total ... | 9,902 | 84,477 | 61,620 | 62,710 | 15,382 | 65,571 | 46,982 | | |

Ordered that the foregoing List be submitted to Government, with reference to Government Order, dated 17th May 1865, No. 1,586, Public Works Department, and in continuation of Board's Proceedings, 17th August 1866, No. 5,813.

(A true Copy and Extract.)

(Signed) W. HUDLESTON, *Secretary.*

Transferred to the Public Works Department.

(Signed) J. GROSE,
*Under Secretary to Government.*

FORT SAINT GEORGE,
*5th September* 1866.

No. 474. Proceedings of the Board of Revenue, dated 31st August 1866.

Read the following letter from the Collector of North Arcot, to the Secretary to the Board of Revenue, dated Chittoor, 11th August 1866, No. 224.

Agreeably to the instructions of the Board contained in Mr. Dalyell's letter of the 11th June last, No. 3,972, I have the honor to forward a statement in the form therein prescribed, giving a selected list of the more important works of irrigation, which are most urgently in need of repair in this District, and explaining what repairs are required, and the date of last repair, with the irrigable ayacut under each work.

STATEMENT giving the names of the more important Works of Irrigation which are urgently in need of repair in the District of North Arcot, and showing also the Revenue derived from them, the Irrigable Ayacut under each work, and the date of last repair.

| Táluqs. | Names of Irrigation Works. | Total registered Nunjah Ayacut. | Tax payable on whole Nunjah Ayacut. | Average Tax actually paid from 1840 to 1850. | Average Tax actually paid from 1850 to 1860. | Present cultivation. | Present Revenue. | Rough estimate of repairs needed. | Date of last repair. | Remarks. |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 |
| | | Acres. | RS. A. P. | RS. A. P. | RS. A. P. | Acres. | RS. A. P. | RS. A. P. | | |
| Chittoor Táluq. | Komati Guruvayagaripalli, eight months' Kona Gutta tank. | 69 | 379 10 3 | 335 0 0 | 315 0 0 | 59 | 346 10 10 | 300 0 0 | ... | Tank breached; bund sunk in; sluice out of repair. |
| | Balejapalli, four months' tank ... | 49 | 335 5 5 | 419 0 0 | 343 0 0 | 49 | 330 12 11 | 200 0 0 | 1838 | Bund very much cut up and sunk in; sluice dilapidated. |
| | Chinnampalli, four months' Perumal's tank. | 55 | 465 1 10 | 592 0 0 | 395 0 0 | 55 | 460 3 1 | 200 0 0 | 1858 | Do. do. |
| | Karakampalli four months' Musti tank. | 33 | 283 3 11 | 238 0 0 | 211 0 0 | 18 | 156 6 9 | 150 0 0 | ... | Do. do. |
| | Makulattur resumed Dulabundum river channel. | 37 | 309 0 10 | 217 0 0 | 293 0 0 | 32 | 267 8 6 | 300 0 0 | ... | Channel choked up and breached in several places. |
| | Total ... | 243 | 1,772 6 3 | 1,801 0 0 | 1,587 0 0 | 213 | 1,561 10 1 | 1,150 0 0 | | |
| Chendragherry Táluq. | Four months' large tank of Tripatti. | 156 | 995 3 6 | 934 10 1 | 1,154 0 6 | 126 | 1,103 3 7 | 3,000 0 0 | About 14 years ago. | The bund sunk in, stone revetment displaced, bed of the tank much silted up. |
| | Do. Venkataroyani tank of Kotarla. | 50 | 416 13 3 | 249 6 1 | 289 14 0 | 28 | 249 6 1 | 800 0 0 | Do. 15 do. ... | Do. do. |
| | Sattari tank of do. ... ... | 36 | 310 14 2 | 165 3 3 | 164 6 3 | 16 | 165 3 3 | 500 0 0 | Do. ... | Channel choked with sand; a rock to be removed. |
| | Three months' Lingalamma tank. Two months' Pata tank and ruined spring channel of Timmenayadipoliem. | 93 | 256 0 8 | Not known, as the village having been included in the Jaripoliem. In 1850 Pymaish was done and the assessment was fixed. | 129 7 2 | 80 | 227 2 5 | 1,000 0 0 | About 15 years back. | Tank breached. Channel choked up. |
| | Total ... | 315 | 1,978 15 7 | 1,349 3 5 | 1,737 11 11 | 250 | 1,744 15 4 | 5,300 0 0 | | |
| Gudiattam Táluq. | Peddakasam spring channel of Perumbadi. | 78 | 468 12 4 | 386 12 10 | 380 12 7 | 35 | 236 8 0 | 200 0 0 | ... | The channel much choked up. |
| | River channel of Melur ... ... | 89 | 736 10 7 | 716 4 1 | 614 3 6 | 79 | 674 15 10 | 500 0 0 | ... | Do. do. |
| | Do. of Kelur ... ... ... | 83 | 776 4 1 | 833 8 8 | 673 6 10 | 76 | 716 13 10 | 500 0 0 | ... | Do. do. |
| | Kalanjur channel ... ... ... | 379 | 1,915 6 2 | 985 12 4 | 1,036 2 5 | 182 | 1,062 5 11 | 1,300 0 0 | ... | Do. do. |
| | Spring channel of Arimbakam ... | 53 | 373 12 7 | 215 8 4 | 303 1 10 | 51 | 360 12 2 | 1,000 0 0 | ... | Do. do. |
| | Do. of Serkad ... ... | 68 | 316 13 3 | 68 14 9 | 96 7 8 | 23 | 101 6 9 | 800 0 0 | ... | Do. do. |
| | Do. of Vovalpattada of Chengundrum. | 26 | 169 0 11 | 310 4 0 | 242 1 5 | 25 | 165 1 2 | 800 0 0 | 1845 | Do. do. |
| | Do. of Tatimampalli ... ... | 20 | 141 9 1 | ... | 147 6 6 | 16 | 105 7 9 | 400 0 0 | ... | Do. do. |
| | Total ... | 796 | 4,898 5 0 | 3,517 1 0 | 3,494 10 9 | 487 | 3,423 7 5 | 5,500 0 0 | | |
| Vellore Táluq. | Pudur Andi tank... ... ... | 86 | 601 7 4 | 1,637 0 0 | 1,846 0 0 | 60 | 414 5 0 | 500 0 0 | Not known ... | Bund of the tank much cut up; sluice out of repair. |
| | Ariyur tank ... ... ... | 284 | 2,125 2 11 | 1,647 0 0 | 1,992 0 0 | 184 | 1,346 11 11 | 500 0 0 | Do. ... | Do. do. |
| | Yelavambadi tank ... ... | 117 | 706 15 6 | 1,541 0 0 | 1,397 0 0 | 96 | 586 9 8 | 300 0 0 | Do. ... | Do. do. |
| | Allapuram tank ... ... ... | 66 | 405 11 11 | 1,051 0 0 | 1,209 0 0 | 59 | 355 7 1 | 400 0 0 | Do. ... | Bund in a dilapidated state. |
| | Yeddayanjadu tank ... ... | 40 | 259 15 2 | 852 0 0 | 841 0 0 | 40 | 259 15 2 | 200 0 0 | Do. ... | Do. do. |
| | Tuttipat tank ... ... ... | 91 | 638 3 6 | 449 0 0 | 884 0 0 | 88 | 607 5 0 | 100 0 0 | 1864-65 | Do. do. |
| | Kottamangalam river channel ... | 103 | 917 15 9 | 1,430 0 0 | 1,396 0 0 | 102 | 908 9 8 | 350 0 0 | Not known ... | Channel choked up. |
| | Sembedu tank ... ... ... | 110 | 747 14 5 | 941 0 0 | 953 0 0 | 86 | 595 12 5 | 400 0 0 | Do. ... | Tank bund is in a ruined state. |
| | Kaniyambadi tank ... ... | 122 | 913 8 3 | 410 0 0 | 615 0 0 | 112 | 840 0 0 | 1,000 0 0 | Do. ... | Do. do. |
| | Total ... | 1,019 | 7,316 14 9 | 9,958 0 0 | 11,163 0 0 | 827 | 5,914 11 11 | 3,750 0 0 | | |
| Poloor Táluq. | Six months' large tank of Mambat. | 303 | 1,228 7 6 | 794 2 3 | 777 12 0 | 113 | 445 6 6 | 1,200 0 0 | In Fusly 1240... | Bund Sluice, and Condam quite out of repair. |
| | Attimur three months' large tank. | 88 | 376 3 3 | 226 10 11 | 222 11 3 | 43 | 168 5 11 | 500 0 0 | In 1854 ... | Do. do. |
| | Terumali four months' large Hissa tank. | 196 | 987 13 11 | 627 5 1 | 637 0 1 | 155 | 793 2 4 | 800 0 0 | In Fusly 1269... | Do. do. |

Statement giving the names of the more important Works of Irrigation which are urgently in need of repair in the District of North Arcot, &c.—(*Continued.*)

| Táluqs. | Names of Irrigation Works. | Total registered Nunjah Ayacut. | Tax payable on whole Nunjah Ayacut. | Average Tax actually paid from 1840 to 1850. | Average Tax actually paid from 1850 to 1860. | Present cultivation. | Present Revenue. | Rough estimate of repairs needed. | Date of last repair. | Remarks. |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 |
| | | Acres. | RS. A. P. | RS. A. P. | RS. A. P. | Acres. | RS. A. P. | RS. A. P. | | |
| Poloor Táluq.—(*Concluded.*) | Mandocolattur, six months' tank... | 635 | 3,245 7 11 | 3,121 10 8 | 3,210 4 8 | 303 | 1,648 15 3 | 800 0 0 | In 1866. | Tank breached in many places. |
| | Mattapattu, six months' tank ... | 343 | 1,652 12 1 | 1,049 10 9 | 828 1 9 | 123 | 578 15 3 | 1,000 0 0 | In 1860. | Sluice and supply channel in ruin. |
| | Verallur, four months' tank .. | 81 | 433 12 10 | 274 7 10 | 215 12 11 | 36 | 199 6 5 | 850 0 0 | ..... | The bund, calingulah, and channel in dilapidated state. |
| | Gengaveram, four months' large tank. | 171 | 821 0 0 | 253 0 7 | 229 1 0 | 59 | 280 4 5 | 600 0 0 | In 1861. | The bund and sluice in need of repair. |
| | Pallur do. ... ... ... | 139 | 717 9 3 | 544 10 4 | 671 8 5 | 118 | 623 12 2 | 1,200 0 0 | No repairs for the last 20 years. | The tank bund in ruin. |
| | Mahadevimangalam, five months' tank. | 243 | 1,713 12 9 | 1,542 4 7 | 1,435 4 0 | 206 | 1,481 6 3 | 1,500 0 0 | 20th Oct. 1855. | Do. |
| | Karepattu, six months' tank ... | 417 | 1,946 2 2 | 1,391 2 8 | 1,392 13 3 | 244 | 1,128 13 5 | 1,500 0 0 | 1854. | Do. |
| | Total ... | 2,616 | 12,923 1 8 | 9,825 1 8 | 8,620 0 4 | 1,398 | 7,248 7 11 | 9,950 0 0 | | |
| Wandawash Táluq. | Hissa tank sluice of Mummani, Kadalvadi and Aunnambut. | 208 | 891 4 10 | 525 0 0 | 578 0 0 | 148 | 656 1 4 | 150 0 0 | About 10 years ago. | The sluice out of repair. |
| | Setteri sluice of Mummani ... | 6 | 35 6 6 | 47 0 0 | 36 0 0 | 6 | 35 6 6 | 35 0 0 | ..... | Do. |
| | Two supplying channels of Vengunam. | 113 | 793 0 0 | 957 0 0 | 802 0 0 | 108 | 753 1 10 | 500 0 0 | ..... | The channel very much choked up; the bund cut up. |
| | Bund of the Hissa tank of Voyapakam, Veyedepattu, Naduppattu, and Kossappatta. | 320 | 1,766 14 11 | 968 0 0 | 1,078 0 0 | 265 | 1,495 14 4 | 900 0 0 | About 8 years ago. | The tank breached in several places; the bund in a weak state. |
| | Bund and sluice of the Agaram tank. | 74 | 421 6 1 | 295 0 0 | 307 0 0 | 48 | 300 13 4 | 300 0 0 | ..... | The bund very much cut up; the sluice out of repair. |
| | Sluice of the Vengada tank ... | 118 | 638 5 10 | 400 0 0 | 446 0 0 | 97 | 565 0 0 | 200 0 0 | 1864. | The sluice dilapidated. |
| | Bund and sluice of the Sittamur tank. | 55 | 239 0 0 | 244 0 0 | 254 0 0 | 49 | 217 1 9 | 230 0 0 | ..... | The bund is cut up in several places; sluice requires repair. |
| | Total ... | 894 | 4,785 6 2 | 3,436 0 0 | 3,501 0 0 | 721 | 4,023 7 1 | 2,315 0 0 | | |
| Arcot Táluq. | Sattur large tank ... ... ... | 480 | 2,852 6 5 | 3,539 0 0 | 3,232 0 0 | 349 | 2,148 9 0 | 700 0 0 | ..... | These being in a dilapidated state, earth and stone works are urgently required. |
| | Do. Sitteri tank ... ... | 50 | 399 12 2 | ..... | ..... | 43 | 260 0 1 | 100 0 0 | ..... | |
| | Kaganam large tank ... ... | 189 | 1,312 7 1 | 1,483 0 0 | 1,356 0 0 | 161 | 1,147 14 11 | 500 0 0 | About 10 years back. | |
| | Do. Setteri tank ... ... | 31 | 207 12 0 | ..... | ..... | 20 | 134 14 11 | 300 0 0 | Do. | |
| | Brammadesem large tank ... | 191 | 1,277 5 5 | 5,003 0 0 | 5,180 0 0 | 134 | 942 3 0 | 500 0 0 | Do. | |
| | Varagur large tank ... ... | 180 | 1,212 4 11 | 2,860 0 0 | 2,621 0 0 | 106 | 715 4 10 | 500 0 0 | Do. | |
| | Attiyanam Setteri ... ... | 74 | 445 3 6 | 638 0 0 | 731 0 0 | 49 | 304 5 10 | 700 0 0 | Do. | |
| | Mandyalam tank ... ... ... | 192 | 1,236 0 10 | 1,999 0 0 | 2,662 0 0 | 130 | 843 11 3 | 300 0 0 | Do. | |
| | Perumantangal tank ... ... | 36 | 246 7 8 | 351 0 0 | 337 0 0 | 31 | 218 5 0 | 100 0 0 | Do. | |
| | Kurambady large tank ... ... | 51 | 303 1 6 | 624 0 0 | 706 0 0 | 47 | 290 5 1 | 200 0 0 | Do. | |
| | Total ... | 1,474 | 9,492 13 6 | 16,497 0 0 | 16,825 0 0 | 1,073 | 7,005 9 11 | 3,900 0 0 | | |
| Wallajah Táluq. | Munjivakam Anicut Kondam ... | 113 | 535 7 5 | 124 6 0 | 240 7 0 | 47 | 255 9 8 | 1,000 0 0 | About 20 or 30 years ago. | These works being in great disrepair, their early restoration is highly desirable. |
| | Bund of the Kelvenumbakum tank.. | 160 | 879 13 11 | 1,085 8 1 | 997 12 3 | 144 | 811 12 7 | 600 0 0 | In 1846. | |
| | Yeralacheri sluice Kondam ... | 35 | 1,336 0 0 | 153 7 7 | 154 13 7 | 14 | 57 7 6 | 900 0 0 | About 20 or 30 years ago. | |
| | Bund of the Yecheruttur large tank. | 202 | 957 14 5 | 874 2 1 | 884 0 6 | 172 | 863 7 1 | 800 0 0 | In 1848. | |
| | Ruined supplying channel of Mangalam. | 252 | 1,089 12 1 | 640 8 8 | 888 12 7 | 200 | 1,112 14 3 | 1,000 0 0 | In 1857. | |

Statement giving the names of the more important Works of Irrigation which are urgently in need of repair in the District of North Arcot, &c.—*(Concluded.)*

| Táluqs. | Names of Irrigation Works. | Total registered Nunjah Ayacut. | Tax payable on whole Nunjah Ayacut. | Average Tax actually paid from 1840 to 1850. | Average Tax actually paid from 1850 to 1860. | Present cultivation. | Present Revenue. | Rough estimate of repairs needed. | Date of last repair. | Remarks. |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 |
| Wallajah Táluq—*(Concluded.)* | Attupakam large tank ... ... | Acres. 114 | RS. A. P. 749 14 3 | RS. A. P. 479 7 9 | RS. A. P. 615 9 9 | Acres. 102 | RS. A. P. 665 2 10 | RS. A. P. 600 0 0 | About 30 years ago. | These works being in great disrepair, their early restoration is highly desirable. |
| | Chittoor large tank ... ... | 376 | 1,982 7 9 | 583 8 10 | 753 10 4 | 173 | 1,288 14 4 | 1,000 0 0 | Do. 40 do. | |
| | Manjambadi ruined spring channel | 42 | 281 8 6 | 280 6 3 | 286 1 0 | 41 | 278 15 11 | 800 0 0 | Do. 20 or 25 do. | |
| | Ganapatipuram spring channel... | 84 | 494 12 5 | 367 9 3 | 416 7 5 | 71 | 412 8 3 | 400 0 0 | Do. 15 do. | |
| | Bund and sluice of the Terumalpuram tank. | 353 | 1,762 9 0 | 1,046 9 5 | 1,331 11 0 | 230 | 1,326 13 3 | 1,000 0 0 | Do. 15 do. | |
| | Total... | 1,731 | 10,070 3 9 | 5,635 9 11 | 6,569 5 5 | 1,195 | 7,073 9 8 | 8,100 0 0 | | |

CHITTOOR,
11*th August* 1866.

(Signed) J. D. ROBINSON,
*Collector.*

*Proceedings of the Madras Government, Public Works Department,*
*19th September* 1866.

Ordered that the foregoing letter be submitted to Government, with reference to Government Order dated 17th May 1866, No. 1,587, Public Works Department, and in continuation of Board's Proceedings of 17th August 1866, No. 5,813.

Transferred to the Public Works Department.

FORT SAINT GEORGE,
*5th September* 1866.

(Signed) J. GROSE,
*Under Secretary to Government.*

No. 475. ORDER THEREON, 19th September 1866, No. 2,998.

CIVIL WORKS, No. 86.

1. With these papers the Board of Revenue submit, in pursuance of G. O. No. 1,587, dated 17th May 1866, Returns of Agricultural Works which are most urgently in need of repair in the Districts of Cuddapah and North Arcot. The amount shown to be required for the purpose is roughly estimated at Rupees 46,982 for the former and Rupees 39,965 for the latter District.

2. It has been already intimated to the Board in separate Proceedings, that the Government are quite unable to make any special assignments for repairs. The Budget for the current official year contains a provision of Rupees 32,500 and Rupees 60,240 respectively for agricultural repairs in the Cuddapah and North Arcot Districts, and, as similar grants are annually assigned, the Government are in hopes that much may be done, in the course of a few years, to place the irrigation works of those Districts in an efficient state.

(True Extract.)

Colonel, R. E.,
*Secretary to Government.*

To the Superintending Engineers, 3rd and 4th Divisions.
,, Board of Revenue, with one Enclosure.
,, Revenue Department.

Exd. S. T. Augustin.

23: May 166 A. 155-6

Revenue 1866 Octr.
Pros: of Govt for September
Nr. 3228.

Proceedings of the
Madras Govt in the
P. W. Depart. —

Dated 19th Sept. 1866
Received 21st " 1866.

Nr. 2998.

Passing orders on
Bds Pros, Returns of Agricultural Works in the
Cuddapah and Nellore
Circle districts urgently
needing repairs. —

Nr. 2595.

RECORDED.

A. 614 & 615

26 Sept. 166