

MADRAS RECORD OFFICE.

Government of Madras.

Revenue DEPARTMENT.

G.O. No. 3314

Press

~~Mis.~~

95.96

Dated

10 - 12 - 1866.

Not to be folded or roughly handled

*Proceedings of the Madras Government, Revenue Department,
10th December 1866.*

No. 95. Read the following Proceedings of the Madras Government in the
Public Works Department:—

Recording letter from Superintending Engineer,
4th Division, forwarding list of Tanks, Tan-
gals, and Channels, which have breached
during the late heavy rains in Madras and
North Arcot Districts. } (Here enter 28th November 1866, No. 3,771.)

No. 96. ORDER THEREON, 10th December 1866, No. 3,314.

Miscellaneous.

Communicated to the Board of Revenue.

(True Extract.)

(Signed) J. GROSE,

Under Secretary to Government.

To the Board of Revenue, with Proceedings Public Works Department, No. 3,771.

Exd. S. T. Augustin.

27

*Proceedings of the Madras Government, Public Works Department,
28th November 1866.*

No. 576. Read the following letter from the Superintending Engineer, 4th Division, to the Secretary to Government, Public Works Department, dated Madras, 15th November 1866, No. 3,106:—

1. I have the honor to forward, for the information of Government, the accompanying List of Tanks, Tangals, and Channels, which have breached during

the heavy rains which fell during the months of August, September, and October 1866, in the North Arcot and Madras Districts.

List of Tanks, Tangals, and Channels which have breached during the late heavy rains in Madras and North Arcot Districts.

Names of Villages and Tanks.	Nature of injury sustained.	Remarks by Range Officers.
NORTH ARCOT.		
<i>Polur Taluq.</i>		
Nambedu Tank	Breached on the 9th October 1866 by heavy rains.	Repairs are being carried out.
Davamungalum Tank	Do. ...	Do.
Thuchambody do.	Do. ...	Do.
Puriculput do.	Do. ...	Do.
Authoray do.	Do. ...	Do.
Calyem do.	Breached by the late heavy rains.	Repairs were carried out at a cost of Rupees 150.
Gengavarum do.	Do. ...	Repairs being carried out.
Vussoor do.	Do. ...	Do.
Cadampolyem do.	Do. ...	Do.
General Mahadamungalum Tank..	Do. ...	Do. Rupees 60.
Carayambody Tank	Breached in places by the recent heavy freshes.	Repairs were carried out on emergency at a cost of Rupees 90.
Polur supply Channel	Do. ...	Do. Rupees 63.
Vadevalapankum Chittary Tank...	Breached by the late heavy rains.	Repairs were carried out at a cost of Rupees 1,200.
Kuttagarampolliem Tank	Breached in consequence of sluice being too short.	Do. at Rupees 100.
Gadampolliem Tank	Breached by the late heavy rains.	Do. at Rupees 90.
Vassoor Tank	Do. ...	Do. at do. 120.
Kuttagarampolliem Ottary Tank..	Do. ...	Do. at do. 170.
Mahadavamungalum do. ...	Do. ...	
<i>Chittoor Taluq.</i>		
Goodanagarum Tank	Breached by the heavy rains which fell on the 21st September 1866.	Repairs ordered by the Collector.
<i>Arcot Taluq.</i>		
Varavoor Tank	Breached in four or five places by water overtopping the bund.	This tank breached last December and was repaired at an expense of 450 Rupees. Estimate Rupees 730 submitted.
Numbee Tangal	Small breach	Do. November 1864 and repaired by the Tahsildar. The present breach is in another place.

*Proceedings of the Madras Government, Public Works Department,
23th November 1866.*

List of Tanks, Tangals, and Channels, &c.—(Concluded.)

Names of Villages and Tanks.	Nature of injury sustained.	Remarks by Range Officers.
<i>Arcot Taluq.—(Concluded.)</i>		
Chetty Tangal	Breached on the south side of the sluice. No revetment to it.	This tank breached in November 1865. The present breach is in another place.
Cuttavady supply Channel	Banks breached in many places.	Channel gradually filling up with sand and unable to bear the sudden mass of water.
Cavanoor do.	A small breach in the channel.	Calls for no remarks.
<i>Vellore Taluq.</i>		
Boothoorandy Tank supply channel.	Breached in several places by the heavy rains.	Repairs ordered at a cost of Rupees 124.
Agaram Tank	A large breach in centre of bund.	The breach occurred from water entering a large crack in the bund and finding its way through, repairs to the amount of Rupees 45 are being carried out.
Koorumbady Tank	Two breaches	From rush of water from Velapakum Tank.
Aryanthangul do.	Bund much washed in many places.	This tank breached once before in 1864-65 and repaired for Rupees 215 by Mr. Howard.
Anamulloor Tank supply channel.	Stone revetment slipped in places.	A new work executed in 1865-66. The damage not very great.
Vellappakum Tank	A large breach in centre of bund.	This was caused by the water entering a crack in the bund which the villagers did not stop, but contented themselves with simply reporting the circumstances to the Tahsildar.
Kuttoovady Tank	Breach at north end of the bund.	Breached in 1864-65 which was repaired by Mr. Howard's estimate, Rupees 270, by the Tahsildar. The present breach is in a different place.
Mungilipet Tank... ..	Two breaches, a small sluice endangered.	Occasioned by the cracked state of the bund owing to long duration of hot weather.
<i>MADRAS DISTRICT.</i>		
Madrantakum Tank	Breached by the late heavy rains.	Repairs being carried out, estimate submitted.
Agaram Tank	Do.	Do. do.
Pudupet do.	Do.	Do. do.
Yedamichy Tank supply channel..	Do.	Do. do.
Chittalpaukum Hissa supply channel	Do.	Do. do.

MADRAS,
15th November 1866.

(Signed) A. J. M. BOILEAU, Colonel, R. E.,
Superintending Engineer, 4th Division.

*Proceedings of the Madras Government, Public Works Department,
23th November 1866.*

No. 577. ORDER THEREON, 28th November 1866, No. 3,771.

CIVIL WORKS, No. 115. Ordered to be recorded.

(True Extract.)

Colonel R. E.

Colonel, R. E.

Secretary to Government.

To the Superintending Engineer, 4th Division.
" Revenue Department.
" Controller of Public Works Accounts.

Erd S. T. Augustin.

Delivered to England
By 13th Decemr 1868
Ellis

Perme 1866. D. Ward
No of Govt Rep. D. Ward

Proceedings in the
J. M. D. Ward

Printed 28th 3rd 1868
Revised 30th 1868

8. 3771.

8. 3814.

Communicated to the
Baron of Darnley

10th Decemr 1868

14th Decemr 1868. 10th Decemr 1868. 10th Decemr 1868.

1868 1868

Proceedings in the
J. M. D. Ward
No of Govt Rep. D. Ward
Revised 30th 1868