Rev= 1869. Dist

Board of Revenue.

MADRAS.

G.O. 3141.

No. 951.

CIRCULAR MEMORANDUM.

Dated 9th September 1869.
Cash 15
Received 16
with Abstract Patent

G.O. 73.

RECORDED.

23 Rev= 169.

Petty Construction and Repairs for 1869-70.—Printed Abstracts of Allotments under—, forwarded to all Collectors, for substitution for Abstracts circulated with Board's Proceedings, No. 3,099, of 7th May 1869.

No. 951.

CIRCULAR MEMORANDUM.

It is requested that the accompanying printed Abstract of the Allotments under Petty Construction and Repairs for 1869-70, may be substituted for that circulated with the Board's Proceedings, dated 7th May 1869, No. 3,099.

Revenue Board Office,
Madras,
9th September 1869.

(By Order.)

Acting Secretary.

To all Collectors, with Abstract Statement.

Copy to the Acting Secretary to Government, Revenue Department, with do.

Exd. J. Tulloch.

Districts.	Land Revenue.				Customs.			Salt.			Grand Total.
	Neer anikum Establishment.	Original works of Revenue buildings.	Repairs of Revenue buildings.	Total.	Original works.	Repairs.	Total.	Original works.	Repairs.	Total.	
	Rs.	Rs.	Rs.	Rs.	Rs.	Rs.	Rs.	Rs.	Rs.	Rs.	Rs.
1. Ganjam...	1,994	.....	.....	1,994	.....	.....	.....	3,300	6,500	9,800	11,794
2. Vizagapatam	528	.....	100	628	.....	.....	.....	21,850	5,900	27,750	28,378
3. Godavery.....	.....	.....	100	100	560	.....	560	.....	1,200	1,200	1,860
4. Kistna.....	.....	.....	100	100	.....	.....	.....	1,920	2,000	3,920	4,020
5. Nellore	.....	.....	100	100	.....	.....	.....	21,112	4,800	25,912	26,012
6. Cuddapah	.....	.....	100	100	.....	.....	.....	.....	.....	.....	100
7. Bellary...	.....	.....	100	100	.....	.....	.....	.....	.....	.....	100
8. Kurnool	.....	.....	100	100	.....	.....	.....	.....	.....	.....	100
9. Madras.....	.....	.....	100	100	.....	.....	.....	35,856	2,000	37,856	37,956
10. North Arcot	.....	66	34	100	.....	.....	.....	.....	.....	.....	100
11. South Arcot...	.....	.....	100	100	1,240	200	1,440	3,715	3,852	7,567	9,107
12. Tanjore	.....	129	71	200	.....	.....	.....	5,824	3,670	9,494	9,694
13. Trichinopoly	.....	50	50	100	.....	.....	.....	.....	.....	.....	100
14. Madura...	192	.....	.....	192	.....	.....	.....	6,926	7,780	14,706	14,898
15. Tinnevelly	1,164	.....	100	1,264	.....	.....	.....	1,500	.....	1,500	2,764
16. Coimbatore	.....	.....	100	100	.....	.....	.....	.....	.....	.... .	100
17. Salem	.....	.....	300	300	.....	.....	.....	.....	.....	.....	300
18. South Canara.....	.....	.....	100	100	.....	.....	.....	19,215	5,080	24,295	24,395
19. Malabar.....	122	.....	100	222	.....	.....	.....	.....	3,000	3,000	3,222
Total...	4,000	245	1,755	6,000	1,800	200	2,000	1,21,218	45,782	1,67,000	1,75,000
Reserve...	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	25,000
											2,00,000

PETTY CONSTRUCTION AND REPAIRS.

PART I.

List of Original Works for 1869-70.

Executive Divisions or Districts	No.	Projets. Locality.	Description.	Amount of estimate.	Computed expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
			Land Revenue.	RS.	RS.	RS.	
Ganjam...	1	.....	Neeranikum Establishment	...	...	1,994	G. O., dated 8th Decr. 1866, No. 3,309.
Vizagapatam ...	2	.....	Do. do.	...	...	528	Do. do.
North Arcot ...	3	Chittoor.....	Pandal in front of Chittoor Taluk Cutcherry...	7	...	7	
	4	Polur.....	Do. of Polur do.	7	...	7	
	5	Wandawash	Do. of Wandawash do.	12	...	12	
	6	Wallajah...	Do. of Wallajah do.	14	...	14	
	7	Kangundi...	Do. of Kangundi Division	10	...	10	
	8	Vellore...	Do. of Vellore Taluk Cutcherry ...	5	...	5	
	9	Venkatagherry Kota Town.	Do. of Vekatagherry Kota Town.....	4	...	4	
	10	Maderpauk.....	Do. of Madarpauk Division.....	7	...	7	
Tanjore...				66	...	66	
	11	Mayaveram	Fixing wooden reepers and doring the verandahs in which the Talook records are kept ...	39	...	39	
	12	Do.	Putting up a screen in the Talook Cutcherry ...	7	...	7	
	13	Sheali.....	Putting up pandal in do.	83	...	83	
Trichinopoly ...	14	.....	Constructing a Pandal behind the Treasury Deputy Collector's room and another in front of the Paper Currency Office in the Collector's Cutcherry of Trichinopoly..	129 50	... ...	129 50	

Madura...	15	.....	Neeranikum Establishment	...	...	192	G. O., dated 8th December 1866, No. 3,309.
Tinnevelly... ...	16	.....	Do. do.	...	...	1,164	Do. do.
Malabar...	17	.....	Do. do.	...	...	122	Do. do.
			Total Land Revenue	...	...	4,245	
			Customs.				
Godavery.....	1	.....	For constructing permanent watching Stations for the Customs and Frontier Establishment.	5,040	...	560	Sanctioned in G. O., dated 7th December 1867, No. 2,929.
South Arcot.....	2	.....	Constructing six Police Constable's huts at Reddy Chavady, Sayer Station...	1,240	...	1,240	Do. do. dated 16th January 1869, No. 118.
			Total Customs...	...	...	1,800	
			Salt.				
Ganjam	1	Ganjam, Itchapur Nowpadah, Womeravelly.	For constructing twenty-two tiled huts for Police Guards at 150 Rupees each.....	3,300	...	3,300	Estimate Sanctioned in G. O., dated 14th September 1867, No. 2,175.
Vizagapatam ...	2	Pentakota	Formation of new Salt pans at Pentakota	16,090	8,240	4,850	Do. do., dated 24th February and 10th March 1866, Nos. 411 and 677, respectively, R. D.
	3	Do.	Tanadar's Cutcherry at Pentakota.....	1,000	...	1,000	Do. do., dated 19th February 1864, No. 303.
	4	Do.	Thatched house at the platform gate Pentakota.	130	...	130	Do. do. do.
	5	Bimlipatam	For constructing two additional fields of Salt pans at Bimlipatam, and for the supply of salt for exportation.....	2,550	...	2,550	Do. do., dated 10th March 1869, No. 645.
	6	Do.	Road to connect the Salt pans at Kuppili with trunk line to Chicacole..... ...	23,200	...	3,500	
	7	Do.	For constructing houses for Polic Constables guarding salt pans at different divisions.....	7,500	...	7,500	Do. do. do.
	8	Do.	Road from Chelakalapalem to Rajam, 25 miles.	12,500	...	2,320	
				62,970	8,240	21,850	

List of Original Wrks for 1869-70.—(Continued.)

Executive Divisions or Districts.	Projects. No.	Locality.	Description.	Amount of estimate	Computed expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
				Rs.	Rs.	Rs.	
Kistna.....	9	Nizampatam	Raising a new platform at Nizampatam Salt Division.....	4,290	6	1,920	Estimate sanctioned in G. O., dated 23rd May 1867, No. 1,168.
Nellore	10	Tummalapenta ...	New Salt Cutcherry	1,195	...	1,195	
	11	Tada...	Constructing a watch tower on the salt platform	520	...	520	
	12	Pakala...	Constructing a watch tower on the salt platform at Pakala.....	240	...	240	Do. do., dated 9th November 1868, No. 2,898.
	13	Iskapalli.....	Do. do. do. at Iskapalli.....	250	...	250	Do. do. do.
	14	Krishnapatnam ...	Do. do. do. at Krishnapatnam ...	280	...	280	Do. do. do.
	15	Pakala.	Extending and improving the salt platforms ...	1,366	...	1,166	Do. Board's Pro., dated 22nd September 1868, No. 6,724.
	16	Iskapalli.....	Extending and improving the inland or northern platform.....	860	...	550	Estimate sanctioned in G. O.,
				500	...	200	dated 24th April 1868, No. 1,105
	17	Do.	Ten Traders' sheds at Rupees 50 each.....	385	...	285	Do. do., dated 15th September 1868, No. 2,391.
	18	Pakala...	Constructing Police huts	200	...	150	Do. do, dated 18th August 1868, No. 2,194.
	19	Krishnapatnam ...	Do. do.	195	...	100	Do. Board's Pro., dated 12th November 1868, No. 8,009.
	20	Do.	Restoring a ruined tank at Krishnapatnam.....	165	...	165	
	21	Do.	Making sundry alterations and improvements to the new Salt Cutcherry.....	50	...	50	
	22	.....	Constructing a palmyra bridge across the trench round the Sunnapagunta platform for the ingress and egress of the Traders.....	7,000	...	4,500	
	23	.....	Digging a trench round the pans at Kanuparti and fencing and protecting them from depredators	5,200	...	5,200	
	24	.....	Do. do. do. round the pans at Krishnapatnam.....				

	No.	Locality	Description.	Amount of estimate.	Computed expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
				RS.	RS.	RS.	
	43	Gundalam	Construction of six sheds for Police Guards at Gundalum platform	96	...	96	
	44	Do.	Do. of eight tiled huts for do. at Gundalum, Coodicadoo, Manavary, and Cumblimodoo stations	400	...	400	
	45	Do	Building a tunnel over channel near Manavary Salt pans.....	163	...	163	
	46	Killay	Cutting a channel around the Salt pans at Killay	600	...	600	
	47	Do.	Building two sluices and fixing shutters across the said channel.....	500	...	500	
	48	Do.	Do. five huts for Police Guards at Killay platform.....	300	...	300	
	49	Do.	Raising an embankment around the Killay, Tillavadangan and Nakravandangoody Salt pans.	679	...	500	
				4,694	...	3,715	
Tanjore	50	.....	Constructing a salt Cutcherry and watch tower at Vadapathi in Neidavassel....	925	...	925	Plan and estimate similar to those sanctioned for Tranquebar, *vide* G. O., P. W. D., No. 578, dated 17th February 1866.
	51	.....	Do. a watch tower at Thenpadi in Neidavassel.....	194	...	194	Do. do.
	52	.....	Forming a recess for the anchorage of boats for unloading salt for the new export platform at Negapatam.....	250	...	250	

	53	.....	Constructing 2 watch towers at Do.....	400	...	400	*Vide* remark for No. 50.
	54	.....	Do. a salt Cutcherry and watch tower at Vedarniem.....	925	...	925	Do.
	55	.....	Do. a watch tower at Tambikkanallavankottai.....	200	...	200	Do.
	56	.....	Do. a Salt Cutcherry and watch tower at Adrampatam.....	925	...	925	Do.
	57	.....	Extending platform No. 2, at Adrampatam.....	300	...	300	
	58	.....	Constructing a tunnel between platform, Nos. 1 and 3 at do.	185	...	185	
	59	.....	Do. do. on the approach leading to platform No. 3 at do.	185	...	185	
	60	.....	Do. a salt Cutcherry and watch tower at Kattumavady.....	925	...	925	Do.
	61	.....	Do. a tunnel over the trench leading to platform at Kattumavady.....	150	...	150	
	62	.....	Reconstructing the Choukandi hut at do.	60	...	60	
	63	.....	Constructing a watch tower at Arasanagari.....	200	...	200	Do.
				5,824	...	5,824	
Madura	64	.....	Raising bund across the Veerasilar river on the west side of the Vettanom salt pan and excavating Channel on the west of Narambel village to gain ground for the extension of pans.....	6,030	...	6,030	Estimate Sanctioned in G. O. dated 3rd April 1869, No. 902.
	65	.....	Raising an embankment for preventing rain-water flowing into the salt pans at Vyravanadapatam.....	21	...	21	Estimate Sanctioned in G. O., dated 14th May 1868, No. 1,339
	66	.....	Constructing Police huts for Station Office at Attengaray.....	1,920	1,500	420	Estimate sanctioned in G. O., dated 18th January 1868, No. 139.
	67	.....	Cutting a Channel at do.	455	...	455	Do. 21st January 1868, No. 154.
				8,426	1,500	6,926	

List of Original Works for 1869-70.—(Continued.)

Executive Divisions or Districts.	Projects. No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
				RS.	RS.	RS.	
Tinnevelly	68	.....	Constructing a Cutcherry on the Platform at Vypar.....	500	...	500	Estimate sanctioned in G. O., dated 20th November 1867, No. 2,746.
	69	.....	Do. do. at Arasadi	500	...	500	Do. do.
	70	.....	Do. do. at Kadpatnam....	500	...	500	
			Total...	1,500	...	1,500	
South Canara....	71	.....	Protection of the southern rough stone revetment of the Salt Depôt yard, and reclamation of a further portion of the river frontage at Mangalore.....	3,700	...	3,700	
	72	.....	Construction of a Koty to contain 150 garces of Salt including junglewood partitions at Pan emangalore.....	1,825	...	1,825	Estimate sanctioned in G. O., dated 16th January 1869, No. 124.
	73	.....	Do. of a do. to contain 100 do, including do., near the Sea Custom House at Baindur and opening a road thereto.....	1,700	...	1,700	Do. do.
	74	.....	Enlarging the Chura or No. 3 Koty at Mangalore including junglewood partitions.....	1,030	...	1,030	Estimate sanctioned in G. O., dated 14th March 1867, No. 623
	75	.....	Construction of the remaining Koty out of two, including junglewood partitions, of Malpe....	1,200	...	1,200	Estimate sanctioned in G. O., dated 22nd December 1865, No 309, R D. Do. 16th January 1866, No 55, P W. D.
	76	.....	Reconstruction of Koty No. 1 including junglewood partitions at Kasargod.....	1,300	...	1,300	Estimate sanctioned in G. O., dated 16th January 1868, No. 124.

	77	.....	Construction of Cutcherry for Salt Superintendent at Mulky.....	220	...	220	Estimate sanctioned in G. O dated 22nd December 1865, No. 309, R. D.. Do. 16th January 1866, No. 55, P. W. D.	
	78	.....	Construction of a Koty to contain 100 garces of Salt, including junglewood partitions at Manjeshwar.	1,200	...	1,200	Do.	do.
	79	.....	Construction of a Koty to contain 100 garces of Salt, including junglewood partitions at Nileshwar.....	1,200	...	1,200	Do.	do.
	80	.....	Do. of a do. do. do., at Kasargod.	1,200	...	1,200	Do.	do.
			Partitioning the existing Koties with Junglewood frame work at Mangalore, namely:—					
	81	.....	1st Salt Koty (now 8th).....	500	...	500	Do.	do.
	82	.....	2nd or Talan do. (now 9th)	290	...	290	Do.	do.
	83	.....	3rd or Chura do.....	335	...	335	Do.	do.
	84	.....	4th or Coir 1st do. (now 1st).....	615	...	615	Do.	do.
	85	.....	5th or Coir 2nd do. (now 2nd).....	615	...	615	Do.	do.
	86	.....	Partitioning 2 Koties at Mulky with junglewood frame work at 340 Rupees each.	680	...	680	Do.	do.
	87	.....	Do. 1 do. at Mabukal with do. ...	320	...	320	Do.	do.
	88	.....	Do. 1 do. at Manjeshwar with do...	255	...	255	Do.	do.
	89	.....	Do. No. 1 Koty at Kasargod.....	255	...	255	Do.	do.
	90	.....	Do. No. 2 do. at do.	243	...	243	Do.	do.
	91	.....	Do. 1 do. at Nileshwar with do. ...	312	...	312	Do.	do.
	92	.....	Construction of a Cutcherry for Salt Superintendent at Baji.....	220	...	220	Do.	do.
			Total Salt...	19,215	...	19,215		
				...	...	1,21,218		

PETTY CONSTRUCTION AND REPAIRS.

PART II.

List of Repairs for 1869-70.

Executive Divisions or Districts.	Projects. No.	Locality.	Description.	Amount of Estimate.	Computed expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
			Land Revenue.	Rs.	Rs.	Rs.	
Vizagapatam	1	.....	Repairs to the Revenue buildings	100	...	100	
Godavery	2	.....	Do. do	...	...	100	
Kistna	3	.....	Do. to Talook Cutcherrie	...	...	100	
Nellore	4	.....	Do. to the Revenue buildngs	...	...	100	
Cuddapah	5	Cuddapah	Pandal in front of the Collector's Office	25	...	25	
	6	Do.	Do. do. of the Deputy Collector's Office.	25	...	25	
	7	Do.	Do. do. of the Head Assistant Collector's Office	12	...	12	
	8	Jummalmadoogoo	Do. for Deputy Collector's Office at Jummalmadoogoo	12	...	12	
	9	Cuddapah	Pandal in front of the Assistant Collector's Office	12	...	12	
	10	Madanapalli	Do. for Sub-Collector's Office at Madanapalli	14	...	14	
	1						
Bellary	11	Collector's Cutcherry.	White washing and sundry repairs	100	...	100	
Kurnool	12	.....	Pandals and occasional white washing of Talook Cutcherries	100	...	100	
Madras	13	.....	Repairs to the Revenue buildings	100	...	100	

North Arcot ...	14	Chittoor Talook ...	Repairing the Record Room doors	1	...	1
	15	Chendragherry Talook.	White washing the inner and outer walls of the Talook Cutcherry Building	1	...	1
	16	Do.	Plastering with Chunam the floor where the Tahsildar sits	2	...	2
	17	Vellore Talook ...	White washidg the Record Room, etc.....	6	...	6
	18	Do.	Blue washing do.	2	...	2
	19	Do.	Repairing the walls	2	...	2
	20	Maderpak Division.	White washing the Cutcherry walls	1	...	1
	21	Sub-Collector's Office at Vellore.	Repairing a pair of doors and four windows, and the walls connected with the windows	5	...	5
	22	Collector's Office...	Repairing windows and doors	14	...	14
				34	...	34
South Arcot ...	23		Repairing Pandals	100	...	100
Tanjore	24		Repairs to the Revenue buildings.....	...	...	71
Trichinopoly ...	25		Repairing the Pandal round the Collector's Cutcherry	50	...	50
Tinnevilly	26		Repairs to the Revenue buildings.....	100	...	100
Coimbatore	27		Repairing Pandal of the building occupied by the Collector, Treasury Deputy Collector and Sheristadar	...	...	67
	28		Repairing the Pandal of the building occupied by the English Clerks.....	...	...	20
	29		Repairing Pandal of the building occupied by the Printing Press Department	...	...	13
				...	...	100
Salem	30	Salem	For a Pandal around the Salem Collector's Huzoor Cutcherry	...	...	100
	31	Do.	For repairing doors and windows including the replacement of broken glasses of the Collector's Cutcherry	...	...	50
	32	Do.	Repairing the Pandal of the Salem Talook Cutcherry	...	...	5

Executive Divisons or Districts.	Projects. No.	Locality.	Description	Amount of Estimate.	Computed expenditue up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
				RS.	RS.	RS.	
Salem	33	Usur.....	Repairing the doors and windows of the Sub-Collector's Office.....	...	...	20	
	34	Kistnagheri.....	For a Pandal of the Kistnagieri Talook Cutcherry.....	...	...	50	
	35	Utengarai	Repairing the Talook Cutcherry of Utengarai...	...	...	5	
	36	Namcul	Repairing a room in the Talook Cutcherry at Namacul.....	...	...	5	
	37	Salem	Repairing the Office of the Deputy Tahsildar and Sub-Magistrate of Tarauungalum.....	...	...	5	
	38	Tripatur	Repairing do. do. of Vaniembady.	...	...	10	
	39	Utengarai	For a Pandal of do. do. at Haroor	...	...	50	
				...	...	300	
South Canara ...	40	.....	Repairs to the Revenue buildings	...	...	100	
Malabar	41	.....	Repairs to the Revenue buildings.....	...	...	100	
			Total Land Revenue...	...	...	1,755	
			Customs.				
South Arcot.....	1	.....	Repairing Sayer Chowkies, Police sheds, etc., at Reddy's Choultry.	60	...	60	
	2	.....	Do. at Mortandy	60	...	60	
	3	.....	Do. at Vurdavoor.....	40	...	40	
	4	.....	Do. at Cundamungalum..	40	...	40	
			Total Customs..	200	...	200	

			Salt.			
Ganjam	1	Ganjam	For clearing channels at Ganjam	...	...	800
	2	Do.	Do. repairing embankments at do.	...	...	300
	3	Do.	Do. do. watch sheds, Police huts, etc., at do.	...	...	100
	4	Do.	Do. do. platforms, hedges, etc. at do. ...	...	...	100
	5	Itchapore	Do. clearing channels at Itchapore	...	...	1,000
	6	Do.	Do. repairing embankments at do. ...	...	...	100
	7	Do.	Do. do. watch sheds, Police huts, etc., at do.	...	...	100
	8	Do.	Do. do. platforms, hedges, etc, at do. ...	...	...	100
	9	Nowpada	Do. clearing channels at Nowpadah	...	...	1,100
	10	Do.	Do. repairing embankments at do. ...	...	...	600
	11	Do.	Do. do. watch sheds, Police huts, etc., at do.	...	...	100
	12	Do.	Do. do. platforms, hedges, etc,, at do....	...	...	100
	13	Womeravelly	Do. clearing channels at Womeravelly.....	...	...	600
	14	.....	Do. repairing embankments at do.	...	...	200
	15	.....	Do. do. watch sheds, Police huts, etc. at do.	...	...	100
			Maintenance Grants.			
	16	.....	Annual repairs to roads from Nos. 1 and 2 Salt Platforms of Ganjam to the Trunk road	...	...	150
	17	.....	Do. to road from Soorla Salt Platforms to the Soonnapoor road	...	...	100
	18	... ..	Do. to road from No. 1 Salt Platforms at Nowpadah to the Trunk Road	...	...	165
	19	.....	Do. to road from Womeravilly Salt Pans to the Trunk Road from Chicacole to Calingapatam via Gara	...	...	230
	20	.....	Do. to roads from Nos. 2 and 3 Salt Platforms at Nowpadah to the Trunk road.	...	...	185
	21	.....	Do. to roads from the Platforms to the Salt Cutcherry and from the Salt Cutcherry to the Trunk road at Calingapatam ...	...	...	270
			Total.....	...	..	6,500

List of Repairs for 1869-70.—(Continued.)

Executive Divisions or Districts.	Projects. No.	Locality.	Description.	Amount of Estimate.	Computed expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
				RS.	RS.	RS.	
Vizagapatam ...	22	.....	For clearing channels and repairing Platform and hedges at Karassa	...	...	700	
	23	.....	Do. at Balacheruvu.....	...	...	900	
	24	.....	Do. at Bimlipatam	...	...	500	
	25	.....	Do. at Kuppili.....	...	...	900	
	26	.....	Do. at Pentakotah	...	...	300	
	27	.....	Petty Establishment to maintain the avenue by watering, etc., from Koppalapalem to Gopalapatnam	...	...	200	
	28	.....	Maintenance allowance, for Road from the second mile of the Jeypore road to Balacheruvu via Karasa and Gajuwaka	...	...	2,000	
	29	.....	Do. do. from Karasa to Gopalapatnam	...	...	400	
			Total.....	...	...	5,900	
Godavery	30	Peneguduru Division.	For deepening the Canal leading from Jakkuva platform to Mandagaruvu Platform	...	...	375	
	31	Do. ...	For deepening the Canal leading from Jakkuvu Platform to Vayachenue Nettu.....	...	...	400	
	32	Do. ...	Shelter for the Police Guards	...	...	150	
	33	Do. ...	For minor works, such as raising cross banks when the Canals are under repair, etc.	...	...	75	
	34	Mogultur	Shelter for the Police guards.....	...	...	100	
	35	Do. ...	Petty repairs	...	...	100	
			Total.....			1,200	

Kistna	36	Pundraka Division	Repairs to Salt Platforms	...	...	100
	37	Manganapudy do.	Do. do.	...	...	200
	38	Nizampatam do.	Do. do.	...	...	50
	39	Chinna Ganjam do.	Do. do.	...	...	150
	40	Pandraka do.	Do. Planting trees, etc., near the Platforms and watering the same	...	...	125
	41	Manganapoody do.	Do. do. do.	...	...	250
	42	Nizmapatam do.	Do. do. do.	...	...	75
	43	Chinna Ganjam do.	Do. do. do.	...	...	100
	44	Manganapoody do.	Do. Repairing Sea Dykes for preventing the Salt pans from being submerged at high tide	...	...	30
	45	Nizampatam do.	Do. do. do.	...	...	50
	46	Chinna Ganjam do	Do. do. do.	...	...	20
	47	Manganapoody do.	Do. Repairing roads within the limits of the divisions	...	...	175
	48	Nizampatam do.	Do. do. do.	...	...	75
	49	Chinna Ganjam do.	Do. do. do.	...	...	150
	50	Pandraka do.	Do. Repairing and erecting sheds for the accommodation of Salt guards	...	...	50
	51	Manganapoody do.	Do. do. do.	...	...	50
	52	Nizmapatam do.	Do. do. do.	...	...	50
	53	Chinna Ganjam do.	Do. do. do.	...	...	50
	54	Do. do.	Do. Repairing certain tanks used by Salt Traders	...	...	250
			Total	...	...	2,000
Nellore	55	Kistnapatam	Repairing and improving the No. 1 or Northern Platforms	366	...	260
	56	Do.	Do. the No. 2 or Eastern Platforms	590	...	400
	57	Do.	Turfing the slopes of the trenches and of the Platform	175	...	175
	58	Gogalapalle	Repairing and improving the Gogalapalli Nadiminatu or Platform	700	...	700
	59	Kanuparti	Repairing the Platforms to be retained at Kanuparti	1,200	...	1,200
	60	Tada	Repairing and improving the tada Salt Platforms	900	...	900
	61	Dugarazapatam	Repairing and improving the Dugarazapatam salt platforms	500	...	500

List of Repairs for 1869-70.—(Continued.)

Executive Divisions or Districts.	Projects. No.	Locality.	Description.	Amount of Estimate.	Computed expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and Reference.
				Rs.	Rs.	Rs.	
Nellore.— (*Concluded.*)	62	.....	Maintenance allowance for the branch road from Trunk Road No. 6 near Thingarayakonda to the Pakala salt stores at Ullapalem	500	...	500	
	63	.....	Minor repairs to buildings, etc.	...	...	165	
			Total.....	4,931	...	4,800	
Madras	64	.....	Repairing and raising portion of Platform No. 1.	2,000	...	2,000	
South Arcot ...	65	Merkanum	Repairing a Head Constable's hut at Merkanum Salt division	20	...	20	
	66	Do. ...	Do. a large channel from Thembakam back-water to the Chunampet pans	1,300	...	1,000	
	67	Do. ...	Do. of do. from do. to the Merkanum do	1,500	...	1,000	
	68	Gundalum	Repairing the embankment around the salt pans at Gundalum	354	...	354	
	69	Do. ...	Do. of do. at Putchyangooppum...	44	...	44	
	70	Do. ...	Do. of do. at Coodicaloo.....	58	...	58	
	71	Do. ...	Do. of do. at Manavary	46	...	46	
	72	Do. ...	Do. of a wall on the Eastern side of Then-coottangaray at Gundalum.....	30	...	30	
	73	Do. ...	Do. of Police huts at Goondalum Coodica-doo, Manavary and Cunbimodoo	100	...	100	
	74	Killay.....	Do. of do. at Killay Salt station	200	...	200	
	75	Do.	Do. 140 wells or Kanees at the rate of Rs. 10 each at Killay Tillavadangum and Nakravandungoody Salt pans	1,400	....	1,000	
			Total... ..	5,052	...	3,852	

Tanjore	76	.....	Repairing approach to the S Depôt at Neidavassel.....	...	...	380	
	77	.....	Do. roof of the Salt Cutcherry at do. ...	...	...	40	
	78	.....	Do. Compound bank around the pans at Tranquebar.....	...	...	220	
	79	.....	Do. approach to the Depôt from the main Road in do.....	...	...	250	
	80	.....	Do. approach to the Depôt at Negapatam...	...	...	200	
	81	.....	Do. Platform of Papacovil at do.....	...	...	100	
	82	.....	Do. new export Platform at do.....	...	...	25	
	83	.....	Removing accumulation of sand in spontaneous Salt Beds and strengthening their banks at Vedaraniam.....	...	...	1,250	
	84	.....	Repairing approach to the Depot at Tambikanellavankotta.....	...	...	250	
	85	.....	Do. Platforms, Nos. 1 and 3 at do...	...	...	50	
	86	.....	Do. approach to the Depôt from the main Road in Adrampatam.....	...	...	250	
	87	.....	Do. trenches around the Salt Platforms, Nos. 1, 2 and 3 at Adrampatam.....	...	...	80	
	88	.....	Planting Talai hedges around the Platforms at Adrampatam.....	...	...	15	
	89	.....	Repairing approach to the Depôt at Kattumavadi.....	...	...	100	
	90	.....	Do. trenches around the Platforms at do...	...	...	100	
	91	.....	Planting Talai hedges around the Platforms at Kattumavadi.....	...	...	10	
	92	.....	Repairing and turfing the approach at Arasanagari.....	...	...	250	
	93	.....	Do. Trenches around the Salt Platforms, Nos. 1 and 3 at Arasanagari.....	...	...	100	
			Total...	...	...	3,670	
Madura	94	.....	Filling up the Salt Pans done away with at Sholeagudy....	1,225	600	405	Estimate sanctioned in G. O., dated 14th May 1868, No. 1,339.
	95	.....	Do. do. at Thiethandathanom...	1,390	...	1,090	Do. 21st January 1868, No. 154.
	96	.....	Do. do. at Tharakudy...	790	...	790	Do. do.
	97	.....	Do. do. at Kadukay.....	1,470	...	995	Do. do.

List of Rej .irs for 1869-70.—(Continued.)

Executive Divisions or Districts.	Projects. No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
				RS.	RS.	RS.	
Madura.—*(continued).*	98	.....	Filling up the Salt Pans done away with at Mukyur.....	1,600	...	1,300	Estimate sanctioned in G. O., dated 21st January 1868 No. 154.
	99	.....	Enlarging Platform at Mootturegunathapatam...	1,382	...	1,382	Do. do.
	100	.....	Repairing do. at Veravanadapatam.....	2,501	1,001	1,500	Do. 15th February 1868, No. 425.
	101	.....	Do. do. at Attengaray.....	130	....	130	Do. 14th May 1868, No. 1,339.
	102	.....	Minor repairs to Salt works.....	...	...	188	
			Total...	10,488	1,601	7,780	
South Canara ...	103	.....	Erecting masonry walls around the Salt Depot yard at Mangalore.....	1,270	...	1,270	Estimate sanctioned in G.O., dated 16th January 1869, No. 124.
	104	.....	Repairing the Salt Koty No. 2 Merdi in Angali Division.....	700	...	700	Do. do.
	105	.....	Do. do. No. 1 at Arebet in Vadehobi Division..... ...	700	...	700	Do. do.
	106	.....	Extension of compound walls around Salt Koties at Chalenmakki and Yelur in Harnad Division.....	...	...	410	Do. do.
			Monsoon repairs to undermentioned Salt Buildings for 1869-70 *Fusly* 1279, *namely*,—				
	107	.....	Baindur.....	55	...	55	Estimate sanctioned in Board's Proceedings, dated 2nd February 1869, No. 708.
	108	.....	Harnad.....	235	...	235	Do. do.
	109	.....	Angali.....	205	...	205	Do. do.
	110	.....	Vaderhobli.....	220	...	220	Do. do.

	111		Vandase			30	...	30
	112		Haladi			55	...	55
	113		Baje			70	...	70
	114		Mabukal			23	...	23
	115		Udiawar			37	...	37
	116		Mulki			75	...	75
	117		Mangalore			590	...	590
	118		Bantwal			180	...	180
	119		Panemangalore			90	...	90
	120		Manjeshwar			25	...	25
	121		Kasargod			50	...	50
	122		Nileshwar			60	...	60
					Total...	4,670	...	5,080
Malabar...	123	Cannanore Division.	Monsoon repairs to the Salt Gollah at Cannanore.			...	...	500
	124	Do. do.	Do.	do.	at Tellicherry...	...	...	100
	125	Calicut do... ...	Do.	do.	at Calicut.....	...	...	400
	126	Do. do... ...	Do.	do.	at Beypore...	...	...	600
	127	Palghaut do... ...	Do.	do.	at Ponani and repairs to partition walls.....	...	...	1,200
	128	Do. do... ...	Do.	do.	at Choughat.....	...	...	50
	129	Do. do... ...	Do.	do.	at Madelagani..	...	...	50
	130	Do. do	Do.	do.	at Cochin.....	...	...	100
					Total...	...	...	3,000
					tal Salt...	...	...	45,782