

Rev- 1869. Dist
Board of Revenue

MADRAS.

70-3141.

No. 951.

CIRCULAR MEMORANDUM.

Dated 9th September 1869:

*Received 15th Sept 1869
with Abstract & Statement*

70-3141.

RECORDED.

23rd Sept 1869.
Petty Construction and Repairs for
1869-70.—Printed Abstracts of, Allotments
under—, forwarded to all Collectors, for sub-
stitution for Abstracts circulated with Board's
Proceedings, No. 3,099, of 7th May 1869.

No. 951.

CIRCULAR MEMORANDUM.

It is requested that the accompanying printed Abstract of the Allotments under Petty Construction and Repairs for 1869-70, may be substituted for that circulated with the Board's Proceedings, dated 7th May 1869, No. 3,039.

(By Order.)

REVENUE BOARD OFFICE,
Madras,

9th September 1869.

Acting Secretary.

To all Collectors, with Abstract Statement.
Copy to the Acting Secretary to Government, Revenue Department, with do.

Kd. J. Tulloch.

[illegible]

PETTY CONSTRUCTION AND REPAIRS.

PART I.

List of Original Works for 1869-70.

Executive Divisions or Districts.	PROJECTS.		Amount of estimate.	Computed expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
	Locality.	Description.				
Ganjam... 1 Vizagapatam ... 2 North Arcot ... 3 Chittoor... 4 Polur... 5 Wandawash ... 6 Wallajah ... 7 Kangundi... 8 Vellore... 9 Venkatagerry Kota Town. 10 Maderpauk..... 11		Land Revenue.	RS.	RS.	RS.	G. O., dated 8th Decr. 1866, No. 3,309. Do. do.
		Neeranikum Establishment	...	...	1,994	
		Do.	...	...	528	
	Chittoor.....	Pandal in front of Chittoor Talook Cutcherry	7	...	7	
	Polur.....	Do. of Polur co.	7	...	7	
	Wandawash	Do. of Wandawash co.	12	...	12	
	Wallajah	Do. of Wallajah co.	14	...	14	
	Kangundi... ..	Do. of Kangundi Division	10	...	10	
	Vellore.....	Do. of Vellore Talook Cutcherry	5	...	5	
	Venkatagerry Kota Town.	Do. of Venkatagerry Kota Town.....	4	...	4	
	Maderpauk.....	Do. of Maderpauk Division.....	7	...	7	
	Mayaveram	Fixing wooden reapers and doring the verandahs in which the Talook records are kept ...	66	...	66	
	Do.	Putting up a screen in the Talook Cutcherry ...	39	...	39	
	Sheali.....	Putting up pandal in do.	7	...	7	
Tanjore... ..		Constructing a Pandal behind the Treasury Deputy Collector's room and another in front of the Paper Currency Office in the Collector's Cutcherry of Trichinopoly.....	83	...	83	
			129	...	129	
Trichinopoly ... 14			50	...	50	
						

Madura... ..	15		Neeranikun Establishment	...	...	192	G. O., dated 8th December 1866, No. 3,309.
Tinnevely... ..	16		Do. do.	...	...	1,164	Do. do.
Malabar... ..	17		Do. do.	...	...	122	Do. do.
			Total Land Revenue	...	...	4,245	
Godavery	1		Customs.				
			For constructing permanent watching Stations for the Customs and Frontier Establishment.	5,040	...	560	
South Arcot.....	2		Constructing six Police Constables huts at Reddy Chavady, Sayer Station....	1,240	...	1,240	Sanctioned in G. O., dated 7th December 1867, No. 2,929. Do. do. dated 16th January 1869, No. 118.
			Total Customs...	...	...	1,800	
Ganjam	1		Salt.				
			For constructing twenty-two tiled huts for Police Guards at 150 Rupees each.....	3,300	...	3,300	Estimate Sanctioned in G. O., dated 14th September 1867, No. 2,175. Do. do., dated 24th February and 10th March 1866, Nos. 411 and 677, respectively, R. D. Do. do., dated 19th February 1864, No. 303. Do. do. do.
Vizagapatam ..	2		Formation of new Salt pans at Pentakota	16,090	8,240	4,850	
			Tanadar's Cutcherry at Pentakota.....	1,000	...	1,000	
			Thatched house at the platform near Pentakota. For constructing two additional sheds of Salt pans at Bimlipatam, and for the supply of salt for exportation.....	130	...	130	
			Road to connect the Salt pans at Suppili with trunk line to Chicacole.....	2,550	...	2,550	
			For constructing houses for Police Constables guarding salt pans at different divisions.....	23,200	...	3,500	
			Road from Chelakalapatem to Rajan, 25 miles.	7,500 12,500	...	7,500 2,320	
				62,970	8,240	21,850	Do. do., dated 10th March 1869, No. 645. Do. do. do.

List of Original Wrks for 1879-70.—(Continued.)

Executive Divisions or Districts.	PROJECTS.		Amount of estimate	Computed expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
	No.	Locality.				
Kistna.....	9	Nizampatam	Rs. 4,290	Rs. 6	Rs. 1,920	Estimate sanctioned in G. O., dated 23rd May 1867, No. 1,168.
Nellore	10	Tummalapenta	1,195	...	1,195	Do. do., dated 9th November 1868, No. 2,898.
	11	Tada.....	520	...	520	Do. do. do.
	12	Pakala.....	240	...	240	Do. do. do.
	13	Iskapalli.....	250	...	250	Do. Board's Pro., dated 22nd September 1868, No. 6,724.
	14	Krishnapatnam	280	...	280	Estimate sanctioned in G. O., dated 24th April 1868, No. 1,105
	15	Pakala.	1,366	...	1,166	Do. do., dated 15th September 1868, No. 2,391.
	16	Iskapalli.....	860	...	550	Do. do., dated 18th August 1868, No. 2,194.
	17	Do.	500	...	200	Do. Board's Pro., dated 12th November 1868, No. 8,009.
	18	Pakala.....	385	...	100	
	19	Krishnapatnam	200	...		
	20	Do.	195	...		
	21	Do.	165	...	165	
	22		50	...	50	
	23		7,000	...	4,500	
	24		5,200	...	5,200	

TABLE 16.

No.		Description.	Amount of estimate.	Computed expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
			RS.	RS.	RS.	
43	Gundalum	Construction of six sheds for Police Guards at Gundalum platform	96	...	96	
44	Do.	Do. of eight tiled huts for do. at Gundalum, Coodicaboo, Manavary, and Cumbli-moodoo stations	400	...	400	
45	Do.	Building a tunnel over channel near Manavary Salt pans	163	...	163	
46	Killay	Cutting a channel around the Salt pans at Killay	600	...	600	
47	Do.	Building two sluices and fixing shutters across the said channel	500	...	500	
48	Do.	Do. five huts for Police Guards at Killay platform	300	...	300	
49	Do.	Raising an embankment around the Killay, Til-lavadangan and Nakravandangoody Salt pans	679	...	500	
			4,694	...	3,715	
50	Panjore	Constructing a salt Cutcherry and watch tower at Vadapathi in Neidavassel	925	...	925	Plan and estimate similar to those sanctioned for Tranquebar, vide G. O., P. W. D., No. 578, dated 17th February 1866.
51		Do. a watch tower at Thenpadi in Neidavassel	194	...	194	Do. do.
52		Forming a recess for the anchorage of boats for unloading salt for the new export platform at Negrapatam	250	...	250	

53		Constructing 2 watch towers at "Co.....	400	...	400	<i>Fide</i> remark for No. 50.
54		Do. a salt Cutcherry and watch tower at Vedarniem.....	925	...	925	Do.
55		Do. a watch tower at Tambikkanallavankottai.....	200	...	200	Do.
56		Do. a Salt Cutcherry and watch tower at Adrampatam.....	925	...	925	Do.
57		Extending platform No. 2, at Adrampatam.....	300	...	300	
58		Constructing a tunnel between platform, Nos. 1 and 3 at do.	185	...	185	
59		Do. do. on the approach leading to platform No. 3 at do.	185	...	185	
60		Do. a salt Cutcherry and watch tower at Kattumavady.....	925	...	925	Do.
61		Do. a tunnel over the trench leading to platform at Kattumavady.....	150	...	150	
62		Reconstructing the Choukandi hut at do.	60	...	60	
63		Constructing a watch tower at Arasanagari.....	200	...	200	Do.
			5,824	...	5,824	
Madura		Raising bund across the Veerasilar river on the west side of the Vettanom salt pan and excavating Channel on the west of Narambel village to gain ground for the extension of pans.....	6,030	...	6,030	Estimate Sanctioned in G. O. dated 3rd April 1869, No. 902.
64						
65		Raising an embankment for preventing rain-water flowing into the salt pans at Vyravandapatam.....	21	...	21	Estimate Sanctioned in G. O. dated 14th May 1868, No. 1,339
66		Constructing Police huts for Station Office at Attengaray.....	1,920	1,500	420	Estimate sanctioned in G. O. dated 18th January 1868, No. 139.
67		Cutting a Channel at do.	455	...	455	Do. 21st January 1868, No. 154.
			8,426	1,500	6,926	

List of Original Works for 1869-70.—(Continued.)

Executive Divisions or Districts.	PROJECTS.		Amount of Estimate.	Computed Expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
	No.	Locality. Description.				
Tinnevely	68		rs. 500	rs. ...	500	Estimate sanctioned in G. O., dated 20th November 1867, No. 2,746. Do. do.
	69		500	...	500	
	70		500	...	500	
		Total...	1,500	...	1,500	
South Canara. ...	71					Estimate sanctioned in G. O., dated 16th January 1869, No. 124. Do. do. Estimate sanctioned in G. O., dated 14th March 1867, No. 623. Estimate sanctioned in G. O., dated 22nd December 1865, No. 303, R. D. No. 16th January 1866, No. 55, P. W. D. Estimate sanctioned in G. O., dated 16th January 1863, No. 124.
	72		3,700	...	3,700	
	73		1,825	...	1,825	
	74		1,700	...	1,700	
	75		1,030	...	1,030	
	75		1,200	...	1,200	
	76		1,300	...	1,300	
		Reconstruction of Koty No. 1 including jungle-wood partitions at Kasargod.....				

77		Construction of Cutcherry for Salt Superintendent at Mulky.....	220	...	220	Estimate sanctioned in G. O. dated 22nd December 1865, No. 309, R. D.. Do. 16th January 1866, No. 55, P. W. D.
78		Construction of a Koty to contain 100 garces of Salt, including junglewood partitions at Manjeshwar.	1,200	...	1,200	Do. do.
79		Construction of a Koty to contain 100 garces of Salt, including junglewood partitions at Nileshtar.	1,200	...	1,200	Do. do.
80		Do. of a do. do. do., at Kasargod.	1,200	...	1,200	Do. do.
81		Partitioning the existing Koties with Junglewood frame work at Mangalore, namely:—				
82		1st Salt Koty (now 8th).....	500		500	Do. do.
83		2nd or Talan do. (now 9th)	290		290	Do. do.
84		3rd or Chura do.	335		335	Do. do.
85		4th or Coir 1st do. (now 1st).....	615		615	Do. do.
86		5th or Coir 2nd do. (now 2nd).....	615		615	Do. do.
87		Partitioning 2 Koties at Mulky with junglewood frame work at 340 Rupees each.	680		680	Do. do.
88		Do. 1 do. at Mabikal with do.	320		320	Do. do.
89		Do. 1 do. at Manjeshwar with do.	255		255	Do. do.
90		Do. No. 1 Koty at Kasargod.....	255		255	Do. do.
91		Do. No. 2 do. at do.	243		243	Do. do.
92		Do. 1 do. at Nileshtar with do.	312		312	Do. do.
		Construction of a Cutcherry for Salt Superintendent at Baji.....	220	...	220	Do. do.
		Total Salt...	19,215	...	19,215	
			...	...	1,21,218	

PETTY CONSTRUCTION AND REPAIRS.

PART II.

List of Repairs for 1869-70.

Executive Divisions or Districts.	Projects.		Amount of Estimate.	Computed expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
	No.	Locality.				
Vizagapatam	1		Rs. 100	Rs. 100	Rs. 100	
Godavery	2					
Kistna	3					
Nellore	4					
Cuddapah	5					
	6	Cuddapah	25		25	
	7	Do.	25		25	
	8	Jummalmadoogoo	12		12	
	9	Cuddapah	12		12	
	10	Madanapalli	12		12	
			14		14	
Bellary	11	Collector's Cut-cherry	100		100	
Kurnool	12		100		100	
Madras	13		100		100	
			100		100	

North Arcot ...	14	Chittoor Talook ...	Repairing the Record Room doors ...	1	...	1	1
	15	Chendragherry Talook.	White washing the inner and outer walls of the Talook Cutcherry Building ...	1	...	1	1
	16	Do.	Plastering with Chunam the floor where the Tahsildar sits ...	2	...	2	2
	17	Vellore Talook ...	White washing the Record Room, etc.	6	...	6	6
	18	Do.	Blue washing do. ...	2	...	2	2
	19	Do.	Repairing the walls ...	2	...	2	2
	20	Maderpak Division.	White washing the Cutcherry walls ...	1	...	1	1
	21	Sub-Collector's Office at Vellore.	Repairing a pair of doors and four windows, and the walls connected with the windows ...	5	...	5	5
	22	Collector's Office ...	Repairing windows and doors ...	14	...	14	14
				34	...	34	34
South Arcot ...	23		Repairing Pandals ...	100	...	100	100
Tanjore	24		Repairs to the Revenue buildings ...	...	...	71	71
Trichinopoly ...	25		Repairing the Pandal round the Collector's Cutcherry ...	50	...	50	50
Tinnevely	26		Repairs to the Revenue buildings ...	100	...	100	100
Coimbatore	27		Repairing Pandal of the building occupied by the Collector, Treasury Deputy Collector and Sheristadar ...	...	...	67	67
	28		Repairing the Pandal of the building occupied by the English Clerks ...	...	...	20	20
	29		Repairing Pandal of the building occupied by the Printing Press Department ...	...	...	13	13
				...	...	100	100
Salem	30	Salem	For a Pandal around the Salem Collector's Illuzoor Cutcherry ...	...	...	100	100
	31	Do.	For repairing doors and windows including the replacement of broken glass of the Collector's Cutcherry ...	...	...	50	50
	32	Do.	Repairing the Pandal of the Salem Talook Cutcherry ...	...	...	5	5

List of Re. for 1869-70.—(Continued.)

Executive Divisions or Districts.	PROJECTS.		Amount of Estimate.	Computed expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
	No.	Locality. Description				
Salem	33	Usur..... Repairing the doors and windows of the Sub-Collector's Office.....	Rs. ...	Rs. ...	Rs. 20	
	34	Kistnagheri..... For a Pandal of the Kistnagheri Talook Cutcherry	Rs. ...	Rs. ...	Rs. 50	
	35	Utengarai Repairing the Talook Cutcherry of Utengarai.....	Rs. ...	Rs. ...	Rs. 5	
	36	Namcul Repairing a room in the Talook Cutcherry at Namacul.....	Rs. ...	Rs. ...	Rs. 5	
	37	Salem Repairing the Office of the Deputy Tahsildar and Sub-Magistrate of Tarauungalum.....	Rs. ...	Rs. ...	Rs. 5	
	38	Tripatur Repairing do. do. of Vanembady.....	Rs. ...	Rs. ...	Rs. 10	
	39	Utengarai For a Pandal of do. do. at Haroor	Rs. ...	Rs. ...	Rs. 50	
	40	 Repairs to the Revenue buildings	Rs. ...	Rs. ...	Rs. 300	
	41	 Repairs to the Revenue buildings	Rs. ...	Rs. ...	Rs. 100	
South Canara		Total Land Revenue.....	Rs. ...	Rs. ...	Rs. 1,755	
Malabar		Customs.				
	1	Repairing Sayer Chowkies, Police sheds, etc., at Keddy's Choultry.....	60	...	60	
	2	Do. at Kortandy	60	...	60	
	3	Do. at Yurdavoor.....	40	...	40	
	4	Do. at Gundamungalum.....	40	...	40	
South Arcot.....		Total Customs..	200	...	200	

Ganjam		Salt.					
1	Ganjam	For clearing channels at Ganjam	...	...	...	800	
2	Do.	Do. repairing embankments at do.	...	...	...	300	
3	Do.	Do. do. watch sheds, Police huts, etc., at do.	...	...	...	100	
4	Do.	Do. do. platforms, hedges, etc. at do.	...	...	...	100	
5	Itchapore	Do. clearing channels at Itchapore	...	...	...	1,000	
6	Do.	Do. repairing embankments at do.	...	...	...	100	
7	Do.	Do. do. watch sheds, Police huts, etc., at do.	...	...	...	100	
8	Do.	Do. do. platforms, hedges, etc. at do.	...	...	...	100	
9	Nowpada	Do. clearing channels at Nowpada	...	...	...	1,100	
10	Do.	Do. repairing embankments at do.	...	...	...	600	
11	Do.	Do. do. watch sheds, Police huts, etc., at do.	...	...	...	100	
12	Do.	Do. do. platforms, hedges, etc., at do.	...	...	...	100	
13	Womeravelly	Do. clearing channels at Womeravelly	...	...	...	600	
14		Do. repairing embankments at do.	...	...	...	200	
15		Do. do. watch sheds, Police huts, etc. at do.	...	...	...	100	
<i>Maintenance Grants.</i>							
16		Annual repairs to roads from Nos. 1 and 2 Salt Platforms of Ganjam to the Trunk road	...	...	...	150	
17		Do. to road from Soorla Salt Platforms to the Soonnappoor road	...	...	...	100	
18		Do. to road from No. 1 Salt Platforms at Nowpada to the Trunk Road	...	...	...	163	
19		Do. to road from Womeravelly Salt Pans to the Trunk Road from Chicacole to Calingapatam via Gari	...	...	...	230	
20		Do. to roads from Nos. 2 and 3 Salt Platforms at Nowpada to the Trunk road	...	...	...	185	
21		Do. to roads from the Platforms to the Salt Cutcherry and from the Salt Cutcherry to the Trunk road at Calingapatam	...	...	...	270	
Total.....						6,500	

List of Repairs for 1869-70.—(Continued.)

Executive Divisions or Districts.	PROJECTS.		Amount of Estimate.	Computed expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
	No.	Locality.				
Vizagapatam ...	22		RS.	RS.	RS.	
		For clearing channels and repairing Platform and hedges at Karasa	...	...	700	
	23		...	...	900	
	24		...	...	500	
	25		...	...	900	
	26		...	...	300	
	27		...	...	200	
Godavery	28		...	...	2,000	
	29		...	...	400	
		Total.....	...	...	5,900	
	30	Peneguduru Division.	...	...	375	
	31	Do.	...	...	400	
	32	Do.	...	...	150	
	33	Do.	...	...	75	
Mogultur	34		...	...	100	
	35	Do.	...	...	100	
		Total.....	...	...	1,000	

Kistna.....	36	Pundraka Division	Repairs to Salt Platforms	...	...	100
	37	Manganapudy do.	Do. do.	...	...	200
	38	Nizampatam do.	Do. do.	...	...	50
	39	Chinna Ganjam do.	Do. do.	...	...	150
	40	Pandraga do.	Do. Planting trees, etc., near the Platforms and watering the same	...	...	125
	41	Manganapoody do.	Do. do.	...	...	250
	42	Nizampatam do.	Do. do.	...	...	75
	43	Chinna Ganjam do.	Do. do.	...	...	100
	44	Manganapoody do.	Do. Repairing Sea Dykes for preventing the Salt pans from being submerged at high tide.....	...	...	30
	45	Nizampatam do.	Do. do.	...	...	50
	46	Chinna Ganjam do.	Do. do.	...	...	20
	47	Manganapoody do.	Do. Repairing roads within the limits of the divisions	...	...	175
	48	Nizampatam do.	Do. do.	...	...	75
	49	Chinna Ganjam do.	Do. do.	...	...	150
	50	Pandraga do.	Do. Repairing and erecting sheds for the accommodation of Salt guards	...	...	50
	51	Manganapoody do.	Do. do.	...	...	50
	52	Nizampatam do.	Do. do.	...	...	50
	53	Chinna Ganjam do.	Do. do.	...	...	50
	54	Do. do.	Do. Repairing certain tanks used by Salt Traders	...	...	250
			Total.....	...	...	2,000
Nellore	55	Kisnapatam	Repairing and improving the No. 1 or Northern Platforms	366	...	260
	56	Do.	Do. the No. 2 or Eastern Platforms...	590	...	400
	57	Do.	Turfing the slopes of the trenches and of the Platform	175	...	175
	58	Gogalapalle	Repairing and improving the Gogalappalli Nadinatu or Platform	700	...	700
	59	Kanuparti	Repairing the Platforms to be retained at Kanuparti	1,200	...	1,200
	60	Tada	Repairing and improving the tada Salt Platforms	900	...	900
	61	Dugarazapatam	Repairing and improving the Dugarazapatam salt platforms	500	...	500

List of Repairs for 1869-70.—(Continued.)

Executive Divisions or Districts.	Projects.		Amount of Estimate.	Computed expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and Reference.
	No.	Locality.	Description.			
Nellore.— (Concluded.)	62		Maintenance allowance for the branch road from Trunk Road No. 6 near Thingarayakonda to the Pakala salt stores at Ulapalem	Rs. 500	Rs. 500	
	63		Minor repairs to buildings, etc.	..	165	
			Total.....	4,931	4,800	
Madras	64		Repairing and raising portion of Platform No. 1.	2,000	2,000	
South Arcot ...	65	Merkanum	Repairing a Head Constable's hut at Merkanum Salt division	20	720	
	66	Do.	Do. a large channel from Thenbakkam back-water to the Chunampet pans	1,300	1,000	
	67	Do.	Do. of do. from do. to the Merkanum do	1,500	1,000	
	68	Gundalum	Repairing the embankment around the salt pans at Gundalum	354	354	
	69	Do.	Do. of do. at Puthyangoppum...	44	44	
	70	Do.	Do. of do. at Condicaloo.....	58	58	
	71	Do.	Do. of do. at Manavary	46	46	
	72	Do.	Do. of a wall on the Eastern side of Then-coottangaray at Gundalum.....	30	30	
	73	Do.	Do. of Police huts at Goondalum Coodicaloo, Manavary and Cumbimodoo	100	100	
	74	Killay.....	Do. of do. at Killay Salt station	200	200	
	75	Do.	Do. 140 wells or Kancees at the rate of Rs. 10 each at Killay Tillavadangum and Nakravandungoody Salt pans	1,400	1,000	
			Total.....	5,052	3,852	

Tanjore	76		Repairing approach to the S Depot at Neidavassel.....	...	...	380	
	77		Do. roof of the Salt Cutcherry at do.	...	...	40	
	78		Do. Compound bank around the pans at Tranquebar.....	...	...	220	
	79		Do. approach to the Depot from the main Road in do.....	...	...	250	
	80		Do. approach to the Depot at Negapatam...	...	...	200	
	81		Do. Platform of Papacovil at do.....	...	...	100	
	82		Do. new export Platform at do.....	...	...	25	
	83		Removing accumulation of sand in spontaneous Salt Beds and strengthening their banks at Vedaraniam.....	...	...	1,250	
	84		Repairing approach to the Depot at Tambikavellavankotta.....	...	...	250	
	85		Do. Platforms, Nos. 1 and 3 at do.....	...	...	50	
	86		Do. approach to the Depot from the main Road in Adrampatam.....	...	...	250	
	87		Do. trenches around the Salt Platforms, Nos. 1, 2 and 3 at Adrampatam.....	...	...	80	
	88		Planting Talai hedges around the Platforms at Adrampatam.....	...	...	15	
	89		Repairing approach to the Depot at Kattuvadi.....	...	...	100	
	90		Do. trenches around the Platforms at do...	...	...	100	
	91		Planting Talai hedges around the Platforms at Kattumaradi.....	...	...	10	
	92		Repairing and turfing the approach at Arasanagari.....	...	...	250	
	93		Do. Trenches around the Salt Platforms, Nos. 1 and 3 at Arasanagari.....	...	...	100	
			Total.....	...	...	3,670	
Madura	94		Filling up the Salt Pans done away with at Sholeagudy.....	1,225	600	405	Estimate sanctioned in G. O., dated 14th May 1868, No. 1,839.
	95		Do. do. at Thiothandathanom.....	1,390	...	1,090	Do. 21st January 1868, No. 154.
	96		Do. do. at Tharakudy.....	790	...	790	Do. do.
	97		Do. do. at Kadukay.....	1,470	...	995	Do. do.

List of Requirements for 1869-70.—(Continued.)

Executive Divisions or Districts.	PROJECTS.		Amount of Estimate.	Computed Expenditure up to 31st March 1869.	Amount required in 1869-70.	Remarks and References.
	No.	Locality. Description.				
Madura.— (continued).	98	 Filling up the Salt Pans done away with at Mukyur.....	RS. 1,600	RS. ...	RS. 1,300	Estimate sanctioned in G. O., dated 21st January 1868 No. 154.
	99	 Enlarging Platform at Mooturegunathapatam...	1,382	...	1,382	Do. do.
	100	 Repairing do. at Veravanadapatam.....	2,501	1,001	1,500	Do. 15th February 1868, No. 425.
	101	 Do. do. at Attengaray.....	130	...	130	Do. 14th May 1868, No. 1,339.
	102	 Minor repairs to Salt works.....	...	...	188	
South Canara ...		Total...	10,488	1,601	7,780	
	103	 Erecting masonry walls around the Salt Depot yard at Mangalore.....	1,270	...	1,270	Estimate sanctioned in G.O., dated 16th January 1869, No. 124.
	104	 Repairing the Salt Koty No. 2 Merdi in Angali Division.....	700	...	700	Do. do.
	105	 Do. do. No. 1 at Arebet in Vadehobi Division.....	700	...	700	Do. do.
	106	 Extension of compound walls around Salt Koties at Chalenmakki and Yelur in Harnad Division.....	...	...	410	Do. do.
	107	 Monsoon repairs to undermentioned Salt Buildings for 1869-70 Fusly 1279, namely,— Baundur.....	55	...	55	Estimate sanctioned in Board's Proceedings, dated 2nd February 1869, No. 708.
	108	 Harnad.....	235	...	235	Do. do.
	109	 Angali.....	205	...	205	Do. do.
	110	 Vadehobi.....	220	...	220	Do. do.

[illegible]