M.R.O. I—77,000—8-6-37.

(1) Number of pages.

(2) Date of repair.

(3) Initials of the Referencer.

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No. 3091 Press / Mis.
417—18
Dated 17—12—1870.

Not to be folded or roughly handled

1C

Proceedings of the Madras Government, Public Works Department, 19th December 1870.

No. 417. Read the following letter from the Superintending Engineer, 4th Division, to the Secretary to Government, Public Works Department, dated Madras, 28th November 1870, No. 3,570 :—

WITH reference to G. O., in the Public Works Department, No. 132, dated 24th November 1870, I have the honour to report that the sum of Rupees 110, for replacing the portion of the copper band of the lightning conductor of the church at Saint Thomas' Mount, can be met from the current year's allotment for Civil Repairs in the Presidency District.

No. 418. ORDER THEREON, 19th December 1870, No. 3,091.

CIVIL WORKS, No. 35.

THE Government approve of the sum of Rupees 110, which is reported in this letter to be available, being appropriated to replacing the portion of the copper band of the lightning conductor of the church at Saint Thomas' Mount, which has been stolen.

(True Extract.)

No. 3570

Supdg Engineer's Office 4th Dn.
Madras 28th November 1870.

From

Colonel C.J. Dickinson R.E.
Supdg Engineer 4th Division

To,

Colonel C.A.J. Orr R.E.
Secretary to Government P.W.D.

Sir,

With reference to G.O. in the P.W.D. Dept. 132 dated 24th November 1870, I have the honor to report that the sum of Rupees 110 for replacing the portion of the Copper band of the Lightning Conductor of the Church at Saint Thomas' Mount can be met from the current years allotment for Civil Repairs in the Presidency District.

I have the honor to be
Sir
Your most obedient servant

C. Dickinson, Colonel R.E.
Supdg Engineer 4th Dn.

P. W. D. 2

No. 3991.

Proceedings of the Madras Government

Read the following

From

The Supdg Engineer
4th Dn } (14. E. No. 3570 of 28th Nov 70)

The Government
approve of the sum of
Rs. 110, which is reported
in this letter to be avail-
-able, being appropria-
-ted to replacing the
portion of the copper
band of the lightning
Conductor of the Church
at Saint Thomas' Mount,
which has been stolen.

The Supdg Engr 4th Dn ✓
Ecclesiastical Dept ✓
Controller ✓
Audit Department ✓

Desp. 29/12/70.

Supdg Engr 4th Dn
No. 3570 dated 28th Nov 70.
Reporting that the
sum of Rs. 110 is required
for replacing a portion
of the copper band
round the Lightning
Conductor of the Church
at St. Thomas' Mount
which has been stolen.

From

The Executive Engr
Fort St. George (Central)
No. 4821
dated 14th Nov 70.

To

The Supdg Engr 4th Dn

Sir,

I have the honor to
request that the
sum of Rs. 110 may be allowed
for replacing a portion of the
copper band round the Lightning
Conductor of the Church
at St. Thomas' Mount
which has been stolen
from the Lightning
Conductor of the Church
at St. Thomas' Mount.
The sum may be drawn from the
Contingencies allotment
for Civil Expenditure in the
Revenue Department.
No. 3991-19 Nov 70.

No. 4/15
Supdg Engr 4th Dn.

Ypr 1821

Govt. of {1870} Madras.

PUBLIC WORKS.

To The Superintending Engineer
4th Circle

Dated

Read.

Read.

G. O. 11 June 1870, No. 3091.

Nos. 419 & 419

Regarding Embankment

63° Dec 1870-6r