123/2

M.R.O. 1—20,002—12-8-65.

(1) Number of Pages 4

(2) Date of repair 26-6-67

(3) Initials of the Referencer 8/23.1.68

MADRAS RECORD OFFICE

GOVERNMENT OF MADRAS

Revenue DEPARTMENT

G.O. No. / ~~B.P. No.~~	123	Press / Mis.
Dated 15-7-1874		196 .

Not to be folded or roughly handled

Proceedings of the Madras G[illegible]nt, Public Works Department,
10th [illegible]374.

No. 171. Read the [illegible]llowing e[illegible]
ment, Revenue Dep[illegible]nt of the Acting Secretary to Government, dated 11th May 1874:—

Read the following Proceedings [illegible]f Revenue, dated 5th May 1874, M[illegible]48.

Read the following letter f[illegible] Esq., Acting Head Assistant Collector, to W. [illegible]ting Collector of the Godavery District, dated C[illegible]874, No. 54.

In forwarding the enclosed petiti[illegible]om the Village Munsif and Curnam of Rajavaram, together with the report [illegible]e Tahsildar on the subject, I have the honour to state that the tank called [illegible]ppa Cheruvu in Rajavaram breached about four years ago, and no repairs [illegible]ade till the end of Fasli 1281. The [illegible]yacut of the tank was in consequence [illegible]eft waste, and remission* granted in Faslies 1280 and 1281. The Munsif [illegible]nd Curnam at last took it upon themselves to repair the tank at their own [illegible]ense at a cost of Rupees 120. There has since then been no occasion for remission, and the Munsif and Curnam request that the sum be refunded to them. The Tahsildar reports, on personal inspection, that the work has been well executed, and suggests at the same time that Department of Public Works be consulted as to the amount of cost. I think, however, that the reference would be useless, as it would be difficult or impossible to estimate the cost now; and I have therefore the honour to recommend that the Rupees 120 be refunded to the petitioners: Rupees 100 were paid to a contractor, and the remaining 20 spent in minor details.

		Assessment.			Remitted		
		Rs.	A.	P.	Rs.	A.	P.
*1280	... ...	121	8	0	61	1	[illegible]
1281	... ...	80	9	0	30	2	[illegible]

No. 88.

Forwarded to the Board of Revenue with the request that sanction may be granted for the payment of Rupees 120 to the Munsif and Curnam of Rajavaram Village, in the Yernagudem Taluq, from the funds at the disposal of the Department of Public Works.

Cocanada,
14*th April* 1874.

(Signed) W. S. FOSTER,
Acting Collector.

Submitted for the favourable consideration of Government.

(True Copy and Extract.)

(Signed) J. GROSE,
Secretary.

Transferred to the Public Works Department.

(Signed) C. G. MASTER,
Acting Secretary to Government, R.D.

No. 172. Order thereon, 10th July 1874, No. 1,847.

IRRIGATION, No. 15.

The Governor in Council sanctions the disbursement by the District Engineer, Godavery, to the Collector of the sum of Rupees 120, expended by the village officers on the repair of the Annappa

Cheruvu tank, which breached about ... ago; bu... it was the duty of the Public Works Department to pro... epair of this tank, the District Engineer will be called upon to ... left unrepaired, the result being that in Faslies 1280 and 1281 ... of 90 Rupees of revenue was sustained. Under the circum... village officers is considered to have been very commenda...

2. The expenditure abc... passed on the Collector's receipt.

(Tru... ract.)

Lieut.-Colonel, R.E.,
Joint Secretary to Government.

To the District Engineer, Godavery.
" Chief Engineer for Irrigation.
" Revenue Department.
" Officiating Controller of Public Works Accounts.

Exd. S. T. Austin.
25 Spare Copies

No. 2314.
Revenue Department.

Govt. of {1874} Madras.

PUBLIC WORKS.

To

THE DISTRICT ENGINEER, GODAVERY.

&c., &c., &c.

16

Dated July 10th.

Recd. — 15 — Encl.

G. O., 10th July, 1874, No. 1,847.

To the Board of Revenue 14-7-74

JULY.

Nos. 171-172

16

Dis[illegible]

15/7

No. 123 Communicated to the Board of Revenue -

15 July '74

Annapur Cheruvu Tank, Godavery District.—The disbursement of Rupees 120, expended by the village officers on the repair of the tank which breached about four years ago, sanctioned. The District Engineer to report why it was left unrepaired, and the action of the village officers considered very commendable.

With Order