

114/5

(1) Number of Pages 10
(2) Date of repair 24-9-66
(3) Initials of the Referencer dlb

MADRAS RECORD OFFICE

GOVERNMENT OF MADRAS

Revenue

DEPARTMENT

G.O. No. 714
B.P. No.

Press
Mis.

Dated 10-6-1874 -196-.

Not to be folded or roughly handled

714

Proceedings of the Madras Government, Revenue Department,
10th June 1874.

No. 94. Read the following Proceedings of the Board of Revenue, dated 1st June 1874, Miscellaneous No. 3,620 :—

Read the following letter from Lieutenant-Colonel W. H. HESSEY, Acting Superintendent of Revenue Survey, to J. GROSE, Esq., Secretary to the Board of Revenue, dated Chepauk, 29th May 1874, No. 1,372-64.

I REGRET to have to report that owing to the carelessness of one of the subordinates of the Survey a fire broke out in the photographic room attached to this Office at 3-30 P.M. The fire was speedily extinguished.

2. I have reason to believe that little damage is done to the photographic room. The ordinary work of the Survey Office will not be interfered with in any way.

3. From inquiries made by Captain Freeth, the officer in charge of the Photographic Establishment, I understand that the fire originated in a pan of charcoal which had been used to heat water for photographic purposes. The water required is generally heated by a spirit lamp; the supply of spirit had unfortunately run out, some delay having occurred in procuring a fresh supply, the photographer, without orders, and I may say contrary to orders, used a pan of charcoal on the central roof of the building. The man, when the fire was no longer needed, extinguished it, as he thought, and placed the fire chatty in a corner under a small thatched shed which covers the tank supplying water to the photographic room. The fire was first discovered by the photographer who was engaged inside the photographic room. There can be no doubt that the fire some how or other was communicated from the fire chatty to the thatch.

4. I have reported the accident to the District Engineer, and have requested him to be so good as to inspect the place and decide what repairs are necessary.

24242424

SUBMITTED for the information of Government.

2. The fire reported by the Superintendent of Revenue Survey was of trifling extent, and was soon put out, water being available in the neighbourhood; but it was sufficient to show that the building may be in danger from fire at any moment, and that fire-buckets and other appliances should be kept in readiness. Only a few sparks were blown down into the record-room before the fire was discovered and the shutters closed. Otherwise the interior might have suffered great damage, and it is so extensive and cut up into so many divisions that one or two fire engines might not have been able to stop the fire.

3. The Board are informed that the subject of protecting public buildings from fire is now before Government, and will be glad to know what is decided. The Chepauk Office will probably need special appliances.

No. 95. ORDER THEREON, 10th June 1874, No. 714.

Miscellaneous.

THE Government are glad to hear that the damage done was insignificant.

2

*Proceedings of the Madras Government, Revenue Department,
10th June 1874.*

2. The person to blame should be punished for his carelessness and disobedience of orders, which might have resulted in the destruction of the building.
3. All thatch should be removed forthwith and absolutely prohibited.
4. The last paragraph of the Board's Proceedings will be dealt with in the Public Department.

(True Extract.)

(Signed) C. G. MASTER,
Acting Secretary to Government.

To the Board of Revenue.
.. the Public Department.

- Sub. to Public Dept.

Ed. F. R. Bantleman.

Photographed from the ordinary

Revenue Department.

Miscellaneous No. 3620.

Proceedings of the Board of Revenue.
Dated 1st June 1874.

Read the following:-

No. 1373
64

From

The Ag. Superintendent
Revenue Survey.

To The Secretary to the
Board of Revenue

Sir, I regret to have to report that
owing to the carelessness of one of the
subordinates of the survey a fire broke
out in the Photographic room attached
to this office at 3.30 P.M. The fire was
speedily extinguished.

2. I have reason to believe
that little damage is done to the
Photographic room. The ordinary work of

8.9.24 II ✓

File of 623 June 74
No 197 full 8/25

Copy
Gobt. of 1874 ~~ST~~ADRS.

REVENUE.

To

THE BOARD OF REVENUE.

Ac., Sec., &c.

Dated June 10th.

Recd.

Encl.

G. O., 10th June 1874, No. 714.

JUNE.

No. 9495.

Fire in Photographic Room of Revenue
Survey Office, Allahabad.—Expresses pleasure in
respect to the insignificant damage done by —;
orders punishment of the person to blame, and
the immediate removal and absolute prohibition of
all thatch; and refers the question of protecting
public buildings from fire to the Public Depart-
ment.



may be in danger from fire at any
moment and that fire buckets and
other appliances should be kept in
readiness. Only a few sparks were
blown down into the Record room
before the fire was discovered and
the shutters closed. Otherwise the in-
terior might have suffered great
damage, and it is so extensive and
cut up into so many divisions that
one or two fire engines might not have
been able to stop the fire.

The Board are informed that
the subject of protecting public buildings
from fire is now before Government,
and will be glad to know what is de-
cided. The Chepauk office will probably
need special appliances.

(True copy, & Extract)

J. Grose
Secretary.

To Mr. Secretary to
Government
Revenue Department
Col. P. Madhav

of the Survey Office will not be inter-
fered with in any way.

3. From enquiries made by Captain
Treeth the officer in charge of the Photo-
graphic Establishment, I understand
that the fire originated in a pan of
Charcoal which had been used to heat
water for photographic purposes. The
water required is generally heated by
a spirit lamp, the supply of spirit had
unfortunately run out, some delay
having occurred in procuring a fresh
supply, the Photographer without orders,
and I may say contrary to orders, used
a pan of Charcoal on the central roof
of the building. The man, when the fire
was no longer needed, extinguished it,
as he thought, and placed the fire
chatty in a corner under a small thatched
shed

shed which covers the tank supplying
water to the Photographic room. The fire
was first discovered by the Photographer
who was engaged inside the Photographic
room. There can be no doubt that the
fire, somehow or other, was communicated
from the fire chatty to the thatch.

4. I have reported the accident to
the District Engineer, and have requested
him to be so good as to inspect the place
and decide what repairs are necessary.
I have &c.

Revenue Survey Office } (Signed) W. H. Hessey, Deputy Ch.
Chepauk } Superintendent
29 May 1874 - } Revenue Survey

Submitted for the information
of Government.
The fire reported by the Superin-
tendent of Revenue Survey was of trifling
extent, and was soon put out, water being
available in the neighbourhood, but it
was sufficient to show that the building
may

1819

December 1874 report
Proceedings of the
Board of Revenue

Dated 1st June.
 Dated 1st July.
 Dated 1st Aug. } 1874.

Richard Lawrence. 183620.

Q8-10 June 74

Order with
Three — in Photographs

room attached to Queen's
drawing office, Chesham St. —

Report of Superintendent

of — on 29 May 1874 — sub.

mitted for information of
Govt with Bivineur's

Continued by
the same
person
for
No 114
in Lake
District
N.H.
April 1890

than the damage
done was insignificant

The last paragraph of

the Board's Proceedings

the Public Defs. 10 June 1874

[Faint handwritten notes and signatures]

26
The first
of the
series
is
the
first
of the
series
is
the
first
of the
series

[Faint handwritten notes, possibly "I have been at it for some time"]

[Handwritten signature]

a