M.R.O. 1—20,002—12-8-65.

(1) Number of Pages 36

(2) Date of repair 17-9-68

(3) Initials of the Referencer

MADRAS RECORD OFFICE

GOVERNMENT OF MADRAS

Revenue DEPARTMENT

G.O. No. 2111 Press
~~B.P. No.~~ Mis.

Dated 9-10-1875 ~~196~~ .

Not to be folded or roughly handled

SALT.

Abstract showing the revised Allotments for Salt Works under Petty Construction and Repairs for 1875-76.

Districts.	Petty Construction and Repairs.			Contingencies.			Grand Total.
	Original Works.	Repairs.	Total.	Original Works.	Repairs.	Total.	
	Rs.	Rs.	Rs.	Rs.	Rs.	Rs.	Rs.
1. Ganjam	3,257	2,870	6,127	...	7,130	7,130	13,257
2. Vizagapatam	9,000	640	9,640	...	8,360	8,360	18,000
3. Godavery	8,000	2,800	10,800	...	2,700	2,700	13,500
4. Kistna	6,052	848	6,900	23,365	1,365	24,730	31,630
5. Nellore	17,810	3,102	20,912	2,588	3,000	5,588	26,500
6. Chingleput	30,715	5,900	56,615	39,865	...	39,865	76,480
7. South Arcot	4,155	2,156	6,311	21,205	8,484	29,689	36,000
8. Tanjore	1,580	5,500	7,080	13,800	4,175	17,975	25,055
9. Madura	2,730	400	3,130	1,370	1,000	2,370	5,500
10. Tinnevelly...	3,200	1,800	5,000	1,100	900	2,000	7,000
11. South Canara	1,000	4,175	5,175	...	...	...	5,175
12. Malabar	...	2,391	2,391	...	...	...	2,391
Total...	87,499	32,582	1,20,081	1,03,293	37,114	1,40,407	2,60,488

GENERAL SERVICES.

Petty Construction and Repairs.

Part I.—List of Original Works for 1875-76.

Districts.	Project. No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
			Salt.	Rs.	Rs.	Rs.	
Ganjam.	1	Ganjam	For constructing a trader's shed	...	...	100	
	2	Do.	,, Sinking a pot well for the use of salt traders ...	...	...	20	
	3	Itchapur	,, Constructing a trader's shed	...	...	100	
	4	Nowpada	,, Do. do.	...	...	100	
	5	Do.	,, Sinking a pot well for the use of traders	...	...	20	
	6	Do.	,, Constructing thatched huts on the platforms for Police guards at 40 Rs. each.	...	...	160	
	7	Womeravilly	,, Constructing two traders' sheds at Rs. 100 each ...	...	...	200	
	8	Do.	,, Digging a tank for the use of salt traders	...	...	200	
	9	Do.	,, Constructing the road from Chicacole to Mofuz Bunder.	..	...	1,757	
	10	Do.	Cost of two boats for Salt and Police duties in the Chilka and the Canal.	...	...	600	
			Total...	...	...	3,257	
Vizagapatam.	11	Konada	Constructing Police huts for Constables guarding the pans.	...	...	3,150	
	12	Do.	Compensation for the land required for do. ...	...	...	72	
	13	Pentacotta	Constructing temporary Police huts at Pentacotta ...	...	...	223	
	14	Do.	Compensation for land required for do.	...	...	120	
	15	Do.	Constructing temporary huts for additional Police guards.	...	...	44	
	16	Balacheruvu	Do. do. ...	...	...	44	
	17	Bimlipatam	Do. do. ...	...	...	44	
	18	Konada	Do. do. ...	...	...	44	
	19	Kuppilly	Do. do. ...	...	...	44	
	20	Bimlipatam	Sinking well for the use of Police, &c.	...	...	90	
Vizagapatam.	21	Karassa	Planting prickly-pear hedge round the salt pans	...	...	125	
	23	Pentacotta	For opening pans in another locality	4,000	...	3,000	
	23	Do.	Constructing the road of Pentacotta	...	...	2,000	
			Total...	4,000	...	9,000	
Godavery.	24	Linganaboyanacherla.	Constructing Police lines and station-house at Linganaboyanacherla.	...	...	3,585	
	25	Do.	Raising banks around salt works and constructing masonry sluices at Linganaboyanacherla.	...	...	415	
	26	Do.	Constructing the road from Narasapur to the Linganaboyanacherla.	...	...	4,000	
			Total...	...	...	8,000	
Kistna.	27	Pondraka	Constructing watch towers on platforms	90	18	72	
	28	Nizampatam	Sinking wells for the use of salt traders	50	...	50	
	29	Chinna Ganjam... ...	For constructing the Police huts at Chinna Ganjam ...	...	...	1,765	
	30	Nizampatam	Do. do. at Nizampatam.. ...	...	...	1,620	
	31	Mangenapudi	Do. do. at Manginapudi ...	...	...	30	
	32	Pondraka	Do. do. at Pondraka	...	...	2,275	
	33	Do.	Temporary employment of four maistries for three months on a monthly salary of Rs. 20 each.	...	...	240	
			Total...	140	18	6,052	
Nellore.	34	Dugarazapatam Division.	Constructing new Police lines for the salt guard... ...	4,500	...	4,500	
	35	Kristnapatam Division.	Do. watch tower on the No. 1, "Uttarapu" Salt Platform.	450	...	450	Collector's letter, dated 5th June 1875 No. 102.
	36	Padarti Division, Biramanganta Station.	Constructing watch-tower on No. 2, Vinayakam Salt Platform.	450	...	450	
	37	Tummalapenta	Making road or approach from trunk road near Kavali to salt platform.	3,210	...	3,210	
	38	Tada Division	Improving the approach to the salt platforms...	4,000	...	4,000	
	39	Kanuparti Division ...	Do. the track leading to this cotaur in the limits of the villages of Raperla and Uppukonduru.	4,000	...	4,000	

Districts.	No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
			SALT.—(Continued.)				
Nellore.—(Concld.)	40	Kanuparti Division ...	Salary for two Overseers at Rs. 50 each per month for superintending the works.	RS. 1,200	RS. ...	RS. 1,200	
			Total...	17,810	...	17,810	
Chingleput.	41	Voyalur	Constructing four wooden bridges at 340 Rs. each ...	1,360	...	1,360	
	42	Puludivak	Do. two do. do.	680	...	680	
	42	Attipat	Do. three do. do.	1,020	...	1,020	
	44	Covelong	Do. two do. do.	680	...	680	
	45	Northern Divisions ...	Do. tops to the Superintendent's boats	45	...	45	
	46	Voyalur	Do. a boat with top and sail	80	...	80	
	47	Puludivak	Do. do. do.	80	...	80	
	48	Attipat	Do. do. do.	80	..	80	
	49	Covelong	Do. do. do.	80	...	80	
	50	Voyalur	Sinking a well near the Police huts at Kalanjee	50	...	50	
	51	Vallur	Do. do. Ennore Depôt	50	...	50	
	52	Puludiwak	Purchasing a piece of land and constructing a road from the canal to the Cutcherry.	230	..	230	
	53	Do.	Road from Poodoopett to Chunambett	...	...	3,250	
	54	Do.	For remedying certain defects in the state of salt roads.	...	...	2,750	
	55	Kattur	Erecting a pandal around the office	30	...	30	
	56	Vallur	Do. do. do.	30	...	30	
	57	Kattur	Do. a shed in the centre of the salt pans	80	...	80	
	58	Vallur	Do. do. do.	100	...	100	
	59	Attipat	Reconstructing the office	1,000	...	1,000	
	60	Madras Cotaur	Constructing a Treasury-room with iron rails	1,900	...	1,900	
	61	Do.	For completing a guard-room	60	...	60	
	62	Divisions	Erecting 200 sentry and temporary huts at Rs. 3 each.	600	...	600	
	63	Madras Cotaur	Do. retaining walls on the west side of the Platform No. 1.	1,000	...	1,000	
Chingleput.	64	.....	Constructing permanent locks or sluices	6,000	...	6,000	Collector's letter, 6th July 1875, No. 382.
	65	.....	From the construction of Inspectors' quarters at Ennore, Covelong and Cheyur.	9,480	...	9,480	
			Total...	24,715	...	30,715	
South Arcot.	66	Merkanum	For building lines for the salt guards of the Merkanum and Kandadu Station.	5,790	2,166	3,624	
	67	Do.	For constructing watch huts in the pans for salt guards	...	...	121	
	68	Do.	Fduring the manufacturing season. or constructing temporary huts for extra Police guards.	215	...	215	
	69	Do.	Do. do. a watch hut on the new platform of Chunampet.	...	...	40	
	70	Gundalum	For constructing watch huts in the pans during the manufacturing season.	...	...	71	
	71	Do.	For constructing six watch huts on the platforms of the Gundalum Division.	...	...	72	
	72	Killai	For constructing watch huts in the pans for salt guards during manufacturing season.	...	...	12	
			Total...	6,005	2,166	4,155	
Tanjore.	73	Negapatam	Constructing a rest-house and extending a tiled shed for the Salt Police guards, &c., near the recess of the Railway platform.	380	...	380	
	74	.....	Constructing two small sluices for the drainage of rain water at Poothoocolum.	250	...	250	
	75	....	Constructing two sluices for supplying the sub-station of Velanganny with sea-water.	400	...	400	
	76	.....	Excavating sea-water supplying channel for supplying the sub-station of Velayangann with sea-water.	100	...	100	
	77	Adrampatam	Constructing (3) three tunnels on the approach leading to the sub-station of Magalenkottai.	450	...	450	
			Total...	1,580	...	1,580	
Madura.	78	Mutturagunadapatam..	Construction of eighteen Police huts	9,240	3,500	2,730	

Part I.—List of Original Works for 1875-76.—(Continued.)

Districts.	No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
			Salt.—(Continued.				
Tinnevelly.	79	Viziapathi...	Constructing six Police Constables' huts	RS. 2,580	RS. ...	RS. 1,000	Collector's letter, 15th July 1875, No. 350.
	80	Levingipuram	Opening a road from Levingipuram to Sevandakolum Salt-pans.	980	...	980	
	81	Do.	Extending the platform at Levingipuram	1,220	...	1,220	
			Total...	4,780	...	3,200	
South Canara.	82	Mangalore...	Construction of one weighing shed with timber flooring at the salt depôt at Mangalore.	715	...	715	
	83	Kundapur Taluq ...	Construction of model pans and experimental manufacture of salt by the Salt Deputy Collector.	...	...	285	
			Total...	715	...	1,000	
			Total Original Works...	...	...	87,499	
			Part II.—Repairs.				
Ganjam.	84	Ganjam	Annual repairs to road from No. 1 Salt Platform of Ganjam to the trunk road.	...	...	80	
	85	Do.	Annual repairs to road from No. 2 Salt Platform of Ganjam to the trunk road.	...	...	70	
	86	Do.	Annual repairs to road from No. 2 to No. 3 Salt Platform of Ganjam.	...	...	50	
	87	Itchapur	Annual repairs to road from Surla Platforms to the Sonnapur branch road.	...	...	400	
	88	Nowpada	Annual repairs to road from No. 1 Salt Platform of Nowpada to the trunk road.	...	...	165	
	89	Do.	Annual repairs to road from No. 2 Platform to the branch road to No. 1 Form.	...	...	80	
	90	Do.	Annual repairs to road from No. 3 Salt Platform to trunk road.	...	...	110	
	91	Do.	Annual repairs to road from No. 4 Salt Platform to the branch road leading to No. 1 Platform.	..	...	100	
	92	Womeravilly	Annual repairs to road from Womeravilly Salt Pans to the branch road from Chicacole to Calingapatam *via* Gara.	...	...	500	
	93	Do.	Annual repairs to road from Womeravilly Salt Platforms to the Port of Calingapatam.	...	...	200	
	94	Do.	Annual repairs to road from Womeravilly Salt Platforms to the branch road from Chicacole to Calingapatam *via* Thanespetta.	...	...	115	
	95	Ganjam	For repairing watch sheds and Police huts	...	...	200	
	96	Itchapur	Do. do. do.	...	...	200	
	97	Nowpada	Do. do. do.	...	...	400	
	98	Womeravilly	Do. do. do.	...	...	200	
			Total...	...	...	2,870	
Vizagapatam.	99	Kuppily	Repairing traders's shed at Kuppily	...	...	25	
	100	Konada	Do. do. at Konada	...	...	25	
	101	Bimlipatam	Do. do. at Bimlipatam	...	...	25	
	102	Karassa	Do. do. at Karassa...	...	...	25	
	103	Balacheruvu	Do. do. at Balacheruvu	...	...	25	
	104	Pentacotta	Do. do. at Pentacotta	...	...	25	
	105	Kuppily	Do. Cutcherry Bungalow at the platform at Kuppily.	...	...	25	
	106	Konada	Do. do. at Konada	...	...	15	
	107	Balacheruvu	Do. do. at Balacheruvu	...	...	15	
	108	Pentacotta	Do. do. at Pentacotta	...	...	15	
	109	Kuppily	Repairing tiled Cutcherry Bungalow at Kuppily	...	...	15	
	110	Konada	Do. do. at Konada	...	...	20	
	111	Bimlipatam	Do. do. at Bimlipatam ...	...	...	20	
	112	Karassa	Do. do. at Karassa	...	...	20	
	113	Balacheruvu	Do. do. at Balachervu ...	...	...	20	
	114	Kuppily	Repairing Police huts at Kuppily	...	...	20	
	115	Bimlipatam	Do. do. Bimlipatam	...	...	100	
	116	Balacheruvu	Do. do. Balacheruvu	...	...	100	
	117	Karassa	Do. do. Karassa	...	...	50	
			Total...	...	...	80	
				...	...	640	

Part II.—List of Repairs for 1875-76.—(Continued.)

Districts.	Project. No.	Locality.	Description	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
				Rs.	Rs.	Rs.	
Godavery.	118	Penuguduru	Clearing out the silt from the salt creeks and repairing the same.	1,500	...	1,500	
	119	.....	Shelter for Police guards	300	...	300	
	120	.....	Repairs of Salt Cutcherry and other public buildings ...	200	...	200	
	121	.....	Repairing and laying gravel on the salt roads	500	...	500	
	122	.....	Shelter for Police guard	100	...	100	
	123	.....	Repair of Salt Cutcherry and other public buildings ...	150	...	150	
	124	.....	Do. of the Palmira bridges	50	...	50	
			Total...	2,800	...	2,800	
Kistna.	125	Manginapudi	Repairing roads within the limits of the cotaur	...	...	75	
	126	Nizampatam	Do. do.	...	...	273	
	127	Chinna Ganjam ...	Do. do.	...	...	150	
	128	Pondraka	Repairing and erecting sheds for the accommodation of salt guards.	...	...	150	
	129	Manginapudi	Do. do. do. ...	...	...	50	
	130	Nizampatam	Do. do. do. ...	...	...	30	
	131	Chinna Ganjam ...	Do. do. do. ...	...	...	40	
	132	....	Whitewashing the office buildings at the four salt stations	...	...	40	
	133	.....	Repairing pandals of the 4 Salt Stations	...	...	40	
			Total...	...	...	848	
Nellore	134	Pakala Division ...	General repairs to Police sentry-guard huts in the salt pans at Pakala Division.	16	...	16	
	135	Padarti Division ...	General repairs to Police sentry-guard huts in the salt pans at Padarti Division.	45	...	45	
	136	Kristnapatam	General repairs to Police sentry-guard huts in the salt pans at Kristnapatam.	22	...	22	
	137	Do.	Pulling down and rebuilding the watch tower on the No. 2 or Turupu Salt platform.	450	...	450	*Vide* Collectors letter, 5th June 1875, No. 102.
	138	Dugarazupatam ...	General repairs to Police sentry-guard huts in the salt pans at Dugarazupatam.	35	...	35	
	139	Remaining Divisions.	General repairs to Police sentry-guard huts in the salt pans at remaining divisions.	60	...	60	
	140	Iskapalli Division ...	General repairs to Police sentry huts on salt platform at Iskapalli Division.	10	...	10	
	141	Kristnapatam Division.	General repairs to Police sentry huts on salt platform at Kristnapatam Division.	19	...	19	
	142	Dugarazupatam Division.	General repairs to Police sentry huts on salt platform at Dugarazupatam Division.	7	...	7	
	143	Remaining Divisions.	General repairs to Police sentry huts on salt platform at remaining divisions.	140	...	140	
	144	Pakala Division ...	General repairs to traders' sheds at Pakala Division ...	50	...	50	
	145	Binginipalli Station.	Do. do. at Binginipalli Station ...	30	...	30	
	146	Padarti Division ...	Do. do. at Padarti Division ...	40	...	40	
	147	Kristnapatam Division.	Do. do. at Kristnapatam Division ...	14	...	14	
	148	Dugarazupatam Division.	Do. do. at Dugarazupatam Division.	7	...	7	
	149	Remaining Division.	Do. do. at remaining division... ...	50	...	50	
	150	Pakala Division ...	Repairing the coping of the compound walls to new Police lines.	140	...	140	
	151	Iskapalli Division ...	Repairing and raising compound walls to Salt Cutcherry.	45	...	45	
	152	Kristnapatnam... ...	General repair to Salt Cutchery at Kristnapatam ...	300	...	300	
	153	Dugarazupatnam ...	Do. do. at Dugarazupatam	130	...	130	
	154	Remaining Divisions.	Do. do. at remaining divisions ...	400	...	400	
	155	Pakala Division ...	Clearing and deepening Guiram Vobayagunta for the benefit of the salt traders, &c.	150	...	150	
	156	Isakapalli Division ...	Clearing and deepening Jangamgunta for the benefit of the salt traders, &c.	100	...	100	
	157	Remaining Divisions.	Tanks, &c., water provisions for the benefit of the salt traders, &c.	240	...	240	
	158	Sunnapagunta do. ...	Maintenance allowances for keeping in repair the new approach to the salt platform at Sunnapugunta.	240	...	240	
	159	Kristnapatam Division.	Maintenance allowances for keeping in repair the new approach to the salt platform at Kristnapatam.	200	...	200	
	160	Binginipalli Division..	Maintenance allowances for keeping in repair the new approach to the salt platform at Binginipalli.	162	...	162	
			Total...	3,102	...	3,102	

Part II.—List of Repairs for 1875-76.—(Continued.)

Districts.	No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
			Salt.—(Continued.)				
Chingleput.	161	All Divisions	Repairing the Superintendent's boats and the other boats.	Rs. 250	Rs. ...	Rs. 250	
	162	Kattur	Do. the fresh-water tank near the office	225	...	225	
	163	Cheyur	Do. do. do. ...	250	...	250	
	164	Attiput	Do. the road at Attiput	500	...	500	
	165	Covelong	Do. the road from the Basin to the platform ...	450	...	450	
	166	Cheyur	Repairing the office...	100	...	100	
	167	All Divisions	Do. Police permanent and temporary huts... ...	1,750	...	1,750	
	168	Vayalur	Do. the wooden foot-bridge	50	...	50	
	169	Vitchur	Do. the well near the Police hut...	7	...	7	
	170	Madras Cotaur	Do. Masonry drains	400	...	400	
	171	Do. ...	Do. twenty-four guard rooms	240	...	240	
	172	Homes Garden	Do. the platform	500	...	500	
	173	Covelong	Do. platform at the beach	600	...	600	
	174	Cheyur	Do. the Platform	250	...	250	
	175	All Divisions	Planting hedges around the platforms	200	...	200	
	176	Madras Cotaur... ...	Remetalling portion of the roads	100	...	100	
	177	Do. ...	Repairing wooden railings in Trevelyan's cut	10	...	10	
	178	Ennore	Do. a pandal around the Cutcherry	18	...	18	
			Total ...	5,900	...	5,900	
South Arcot.	179	Markanum	For annual repairs of the Police lines of Merkanum and Chunampet.	...	...	200	
	180	Do. ...	For repairs of the Police lines of Merkanum...	1,000	374	626	
	181	Do. ...	For annual repairs of watch huts on platforms of Merkanum, Chunampet and Kandadu	...	...	150	
	182	Do. ...	For repairing the approach to the Kandadu Pans ...	670	...	670	
	183	Gundalum...	Annual repairs to Police lines at Gundalum, Kudekadu, Manavari and Kamblimodu.	...	...	300	
	184	Do. ...	For annual repairs of watch huts on the platforms.	...	...	50	
South	185	Killai...	Do. do. of Police lines	...	...	70	
	186	Do.	Do. do. of watch huts on the platforms ...	...	...	30	
	187	Do.	Do. do. of temporary Salt Cutcherry	...	...	10	
	188	Do.	Do. do. of approach to Tillavadangan and Killai Platforms.	...	...	50	
			Total ...	1,670	374	2,156	
Tanjore.	189	Nedavassel	Repairing and turfing the approach branching from Roads Nos. 32 and 44 up to the Vadapathy depot.	600	...	600	
	190	Do.	Repairing and turfing the approach to the Thenpathy depot.	300	...	300	
	191	Do.	Repairing the Salt Cutcherry...	200	...	200	
	192	Do.	Repairing tunnels on the approaches leading to the Thenpathy and Vadapathy depots.	200	...	200	
	193	Do.	Repairing Police Barracks	200	...	200	
	194	Do.	Do. two watch towers at Vadapathy and Thenpathy.	30	...	30	
	195	Do.	Planting aloes around the Vedapathy Platform	20	...	20	
	196	Tranquebar	Repairing approach to the Depôt	400	...	400	
	197	Do.	Do. trenches around the pans	350	...	350	
	198	Do.	Do. Police Barracks	80	...	80	
	199	Do.	Do. a Tunnel in front of the Salt Cutcherry ...	60	...	60	
	200	Do.	Do. drainage tunnel on the compound bank and setting up a shutter to prevent the influx of fresh water from entering into the pans.	100	...	100	
	201	Do.	Repairing watch tower	10	...	10	
	202	Do.	Do. Salt Cutcherry	30	...	30	
	203	Negapatam	Do. the approaches in and out of the Railway Platform with laterite.	350	...	350	
	204	Do.	Do. three tunnels on the compound banks of salt pans.	150	...	150	
	205	Do.	Extending and repairing the Modassel with wooden horses complete on the northern side of Poothoor Alum in Ooppanar river.	100	...	100	
	206	Do.	Repairing Salt Police Station on the Railway platform.	30	...	30	
	207	Do.	Do. the shed and recess of the Budgerow boat ...	30	...	30	
	208	Do.	Do. five huts on the bank of the Salt Canal for watching Peons.	50	...	50	
	209	Do.	Do. Salt Police huts at Pappucovil	340	...	340	

Part II.—List of Repairs for 1875-76.—(Continued.)

Districts.	No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
				RS.	RS.	RS.	
Tanjore.—(*Concluded*)	210	Vedarniem	Plastering four pials and steps of the Salt Cutcherry ...	20	...	20	
	211	Do.	Repairing the shed and recess of the Budgerow boat ...	30	...	30	
	212	Do.	Do. the Salt Police Barracks	360	...	360	
	213	Do.	Do. a pond near the Police Barracks for the use of the Constables.	50	...	50	
	214	Do.	Do. three huts on the bank of the Salt Canal for watching Peons.	30	...	30	
	215	Do.	Do. twelve huts in the Salt Platforms	120	...	120	
	216	Do.	Do. the recess under ground with a new shutter and padlock for safe custody of the cash chest.	30	...	30	
	217	Thumbekinallewan-kottai.	Repairing approach to the depôt	200	...	200	
	218	Adrampatam	Do. do.	200	...	200	
	219	Do.	Do. Chowkandy huts in Platforms Nos. 1 and 2.	30	...	30	
	220	Do.	Do. approach branching from Main Road to the sub-station of Magalenkottai.	200	...	200	
	221	Do.	Repairing and turfing the platform of do.	60	...	60	
	222	Cattumavady	Repairing approach to the depôt	100	...	100	
	223	Do.	Do. Salt Cutcherry	200	...	200	
	224	Do.	Do. watch tower	20	...	20	
	225	Do.	Do. a tunnel on the approach leading to the depôt.	30	...	30	
	226	Arasanagary	Do. approach to the depôt	150	...	150	
	227	Do.	Do. two Chowkandy huts on Platforms Nos. 1 and 3.	40	...	40	
			Total ...	5,500	...	5,500	
	228	Muthuragunadapatam.	Maintenance and repair of the salt branch road	...	...	100	
	229	Viravanadapatam ...	Do. do. do.	...	...	100	
	230	Vattanam	Do. do. do.	...	...	100	
Madura.	231	Mutturagunadapatam..	Repair of the Salt Cutcherry	...	...	20	
	232	Morekulam	Do. do.	...	...	20	
	233	Attengarai	Do. do.	...	...	20	
	234	Viravanadapatam ...	Do. do.	...	...	20	
	235	Vattanam	Do. do.	...	...	20	
			Total ...	...	...	100	
Tinnevelly.	236	Levingipuram	Repairing the road from Tuticorin to Levingipuram Salt pans.	100	...	100	
	237	All Divisions	Do. the Salt Cutcherries, Police huts, Watch shed, Trader's shed, &c.	600	...	600	
	238	Do.	Repairing the hedges around the jungles	600	...	600	
	239	Do.	Annual maintenance of all salt roads	500	...	500	
			Total ...	1,800	...	1,800	
South Canara.	240	Mangalore	Reconstruction of south-eastern corner of the rough stone revetment, and raising a portion of the existing western one, &c., at Mangalore.	1,275	...	1,275	
			Maintenance allowance to keep in repair the following Salt Roads, viz.:—				
	241	.....	From the high road to the Salt depot at Baindur ...	20	...	20	
	242	.....	Do. Neralkatta to Yelur *via* Chelanmukky and Hemmady.	180	...	180	
	243	.....	Do. Hunsemukky to Basrur	100	...	100	
	244	.....	Do. Basrur to Koteshwar *via* Merdi and Arebet ...	90	...	90	
	245	.....	Do. Arebet to Kundapur high road *via* Devaragara ...	30	...	30	
	246	....	Do. the high road Arebet Kotar to river	6	...	6	
	247	.....	Do. river to Mabukal Kotars and thence on to the Brahmawar high road.	20	...	20	
	248	.....	Do. ferry to Mabkal Kotars and thence to the Udipy and Brahmawar road *via* Kameshwar Devastan.	54	...	54	
			Monsoon repairs to the undermentioned Salt buildings for Fasli 1285 (1875-76).:—				
	249	Baindur	Baindur depot	70	...	70	
	250	Harnad	Harnad do.	305	...	305	
	251	Angali	Angali do.	205	...	205	
	252	Woderhobli	Woderhobli do.	295	...	295	

Part II.—List of Repairs for 1875-76.—(Continued.)

Districts.	Project. No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
				Rs.	Rs.	Rs.	
South Canara. (Continued.)	253	Mabukal	Mabukal depot	110	...	110	
	254	Malpe	Malpe do.	110	...	110	
	255	Mulki	Mulki do.	100	...	100	
	256	Mangalore...	Mangalore do.	655	...	655	
	257	Bantwal and Pane-Mangalore.	Bantwal and Pane-Mangalore depot	290	...	290	
	258	Manjeshwar	Manjeswar depot	53	...	53	
	259	Cassergode	Cassergode do.	112	...	112	
	260	Nileshwar	Nileshwar do.	95	...	95	
			Total...	4,175	...	4,175	
Malabar.	261		Repairing Cannanore Salt Gollah	..	...	528	
	262		Do. Tellicherry do.	...	...	87	
	263		Do. Police Station attached to do.	...	...	13	
	264		Do. the Ponany Salt Gollah	...	...	340	
	265		Do. Beypore do.	...	...	334	
	266		Do. Calicut do.	...	...	65	
	267		Do. Cochin do.	...	...	70	
	268		Temporary rooms in the shed attached to the old Sea Custom-house, Calicut.	...	...	208	
	269		Platforms at the Calicut Salt Gollah	...	...	63	
	270		Do. at the Beypore do.	...	...	63	
	271		Temporary sheds at Ponany	...	...	620	
			Total...	...	...	2,391	
			Total Repairs...	...	...	32,582	
			Total Petty Construction and Repairs...	...	...	1,20,981	

Salt Contingencies.

Part III.—List of Original Works.

Kistna.	272		For the Salt Canal from Manganupudy to Masulipatam.	...	...	20,000	
	273	Nizampatam	For raising a new Platform on Nackalagondipara ...	2,440	...	2,440	
	274	Do.	A masonry wall calingulah for the new salt works... ...	85	...	85	
	275	Manginaputy	For raising hedges, &c, around Platform No. 2	240	...	240	
	276	Pondrak	For digging a trench and raising a fence around the Salt Works of Sridiniparra No. 1.	225	...	225	
	277	Do.	For do. Sridiniparra No. 2...	225	...	225	
	278	Do.	For constructing two temporary palmyra sheds with mud walls on the above temporary Platforms.	150	...	150	
			Total...	3,365	...	23,365	
Nellore.	279	Devarampad Station, Padarti Division.	Raising an ana bund for turning off the flood of Gundlakamma river.	400	...	400	
	980	Pakala Division ...	Excavating Channel for turning off the water from the swamp at Binginapalli.	80	...	80	
	281	Dugarazapatam Division	Making reservoir to feed the Salt pans	1,970	480	520	
	282	Do.	Improving the drainage of the Salt Platforms	1,000	446	554	
	283	Pakala Division ...	Completing the palisade round the Pakala Salt Platform.	1,034	...	1,034	
			Total...	4,484	926	2,588	
Chingleput.	284		For clearing the Northern and Southern Canals	15,000	...	15,000	Collector's letter, 6th July 1875, No. 382.
	285	Northern Divisions...	Raising bunds to prevent the submersion of the pans ...	3,200	...	3,200	
	286	Southern do. ...	Do. do. ...	1,100	...	1,100	
	287	Attiput	Excavating a channel to connect two others...	55	...	55	
	288	Do.	Extending the Stodriadar's channel	100	...	100	
	289	Vallur	Extending Channel No. 3	140	...	140	
	290	Vitchur	Excavating a channel and forming a bund	1,000	...	1,000	
	291	All Divisions	Constructing small drying platforms at some of the stations for depositing salt as it is scraped from the pans.	2,000	...	2,000	
	292	Kattur	Clearing Boat Channels	800	...	800	
	293	Voyalur	Do. do.	4,000	...	4,000	

Part III.—List of Original Works for 1875-76.—(Continued.)

Districts.	No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
			SALT.—(*Continued.*)				
Chingleput.—(*Continued.*)	294	Puludivak	Clearing Boat Channels	Rs. 1,200	Rs. ...	Rs. 1,200	
	295	Attiput	Do. do.	2,000	...	2,000	
	296	Vallur and Vitchur ...	Do. do.	4,200	...	4,200	
	297	Madras Cotaur	Do. do.	750	...	750	
	298	Homes' Gardens ...	Do. do.	300	...	300	
	299	Vadasamanjeri	Do. do.	500	...	500	
	300	Covelong	Do. do.	1,200	...	1,200	
	301	Cheyur	Do. do.	920	...	920	
	302	Do.	Clearing Maclean's Channel	300	...	300	
	303	Madras Cotaur	Levelling a portion of the Platform and spreading sand over the same.	800	...	800	
	304	All Divisions	Constructing temporary bridges for the use of the manufacturers to cross the boat channels.	100	...	100	
	305	Cheyur	Experimental ullums	200	...	200	
			Total...	39,865	...	39,865	
	306	Merkanum	Extending the Pulyankal catch drain so as to empty itself into the backwater below the Timbakam Causeway.	7,500	946	154	Collector's letter, 28th June 1875, No. 274.
	307	Do.	Excavating brine supply-channel of the Merkanum Station.	9,000	5,465	3,535	
	308	Do.	Constructing Platform at Chunampett	3,795	2,182	1,613	
	309	Gundalum	For throwing a dam across the backwater at Kudikadu to conserve brine for manufacture	177	121	56	
	310	Do.	For improving the Gundalum pans	128	70	58	
	311	Do.	For filling up hollow between Gundalum and Pacheankuppum pans for new pans.	9,600	7,709	1,891	
	312	Do.	Excavating new kenies	50	10	40	
Arcot.	313	Do.	Experimental pan at Kumblimodu	54	20	34	
South	314	Gundalum	Throwing an embankment to take in ground on the west side of the Gundalam pans for new pans.	1,605	625	980	
	315	Harigosthi	The Harigoshti Project	...	...	12,844	Collector's letter, 28th June 1875, No. 274.
Tanjore.			Total...	31,909	17,148	21,205	
	316	Vedarniem	Extending the canal into the great salt swamp	23,000	10,000	13,500	
	317	Do.	Digging channel for drainage of rain water on the east of the eastern bank up to Platform No. 8.	300	...	300	
			Total...	23,300	10,000	13,800	
Madura.	318	Morekolum	Raising and enlarging the Platform	1,620	...	1,070	
	319	Theathandathanum ...	Enlarging the northern and southern portions of the Platform.	300	...	300	
			Total...	1,920	...	1,370	
Tinnevelly.	320	Vypaur	Cutting a portion of the sea water channel from Sudukattodai.	300	...	300	
	321	Livingipuram	Railing round, digging a trench, and fencing on two sides of the Platform at Tuticorin and guarding the entrance with a gate.	400	...	400	
	322	Arasadi	Constructing a second sluice in the sea water supplying channel.	300	...	300	
	323	Paliacoil	Filling up the ditches &c. where salt forms	100	...	100	
			Total...	1,100	...	1,100	
			Total Original Works...	...	...	1,03,293	
			SALT CONTINGENCIES.				
			Part IV—List of Repairs.				
Ganjam.	324	Ganjam	For clearing channels and bunds	...	...	800	
	325	Do.	Making and repairing temporary embankments	...	...	300	
	326	Do.	Repairing trenches, platforms, hedges, &c.	...	...	400	
	327	Itchapore	Clearing channels and bunds	...	...	1,330	
	328	Do.	Making and repairing temporary embankments	...	...	300	
	329	Do.	Repairing trenches, platforms, hedges, &c.	...	...	500	

Part IV.—List of Repairs for 1875-76.—(Continued.)

Districts.	Project. No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76	Remarks.
				Rs.	Rs.	Rs.	
Ganjam.—(Concld.)	330	Nowpada	Clearing channels and bunds	...	...	1,200	
	331	Do.	Making and repairing temporary embankments	...	...	800	
	332	Do.	Repairing trenches, platforms, hedges, &c.	...	...	300	
	333	Womeravilly	Clearing channels and bunds	...	...	800	
	334	Do.	Making and repairing temporary embankments	...	...	200	
	335	Do.	Repairing trenches, platforms, hedges	...	...	200	
			Total...	...	...	7,130	
Vizagapatam.	336	Kuppili	Clearing channels at Kuppili	...	...	900	
	337	Konada	Do. at Konada	...	...	1,000	
	338	Bimlipatam	Do. at Bimlipatam	...	...	1,200	
	339	Karassa	For clearing channels at Karasa	...	...	1,300	
	340	Balacheruvu	Do. at Balacheruvu	...	...	1,000	
	341	Pentacotta	Do. at Pentacotta	...	...	400	
	342	Kuppili	Deepening and widening platform diches at Kuppili ...	...	...	500	
	343	Konada	Do. do. at Konada ...	...	...	300	
	344	Bimlipatam	Do. do. at Bimlipatam.	...	...	500	
	345	Balacheruvu	Do. do. at Balacheruvu	860	...	860	
	346	Pentacotta...	Do. do. at Pentacotta..	...	...	400	
			Total...	860	...	8,360	
Godavery.	347	Pennuguduru	Repairs to Salt Platforms	500	...	500	
	348	Mogultur	Removing silt from the salt creek...	1,500	...	1,500	
	349	Do.	Repairs to Salt Platforms	500	...	500	
	350	Do.	Repair of Ramannapalem channel...	200	...	200	
			Total...	2,700	...	2,700	
Kistna.	351	Pondraka	Repairs to Salt Platforms	...	...	70	
	352	Manginapudi	Do. do.	...	...	100	
	353	Nizampatam	Do. do.	...	...	100	
	354	Chinna Ganjam	Repairing the hedge round Platform No. 2	...	...	175	
	355	Nizampatam	Do. sea dykes for preventing the submersion of the salt-pans at high tide.	...	...	200	
	356	Manginapudy	Do. do	...	...	40	
	357	Nizampatam	Deepening ditches of Platforms Nos 1 and 2	...	...	200	
	358	Chinna Ganjam... ...	Repairing Kuttupadavulu on Muttadirevu salt creek ...	...	...	20	
	359	Nizampatam	Unforeseen expenses	...	...	300	
	360	Do.		...	...	30	
	361	All Divisions		...	...	130	
			Total ...	...	...	1,365	
Ne lore.	362	Pakala Division ...	Repairing the Platform at Pakala	100	...	100	
	363	Binginapalli Division.	Do. at Binginapalli	80	...	80	
	364	Dugarazapatam... ...	Do. at do	30	...	30	
	365	Kistnapatam	Repairing Platform No. 2 of Kistnapatam	123	...	123	
	366	Isakapalli	Do. trench round the Salt Platform	200	...	200	
	367	Pakala	Clearing out main irrigation channels	70	...	70	
	368	Isakapalli	Do. do...	200	...	200	
	369	Pakala Division ...	Clearing out prickly-pear near the Pakala Platform ...	100	...	100	
	370	Do.	Do do. near the Binginapalli Platform.	100	...	100	
	371	Kistnapatam	Repairing gates of the Platform	47	...	47	
	372	Dugarazapatam... ...	Restoring the hedge round the Platform	100	...	100	
	373	Kanuparti	Repairing Salt Platform No. 4	400	...	400	
	374	Do.	General repairs to irrigation channels and manufacturing works in all the divisions.	1,450	...	1,450	
			Total ...	3,000	...	3,000	

Districts.	Project. No.	Locality.	Description.	Amount of Estimate.	Computed expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
				Rs.	Rs.	Rs.	
South Arcot.—(*Concluded.*)	375	Merkanum	Removing silt from the Chunampett brine supply channel.	1,300	965	300	
	376	Do.	Repairing the embankment of the Chunampett pans ...	2,060	713	1,347	
	377	Do.	Fencing in three platforms at Chunampett	...	...	50	
	378	Do.	Do. in the Platform at Kundadu	...	...	50	
	379	Do.	General repairs to the Platform of Merkanum	11,875	5,432	300	
	380	Merkanum...	Joining the northern embankment of Chunampett to Platforms Nos. 4 and 5.	1,900	1,803	97	
	381	Do.	Repairing moat round the Kondadu pans	824	...	824	
	382	Do.	Do. Platforms Nos. 1, 2, and 3 of Chunampett...	470	...	470	
	383	Do.	Do. embankment of the supply channel of Merkanum.	1,470	...	1,470	
	384	Do.	Do. supply channel of Kondadu	970	...	200	
	385	Gundalum...	Repairing embankment round the Gundalum and the Kudikadu pans.	...	...	1,321	
	386	Do.	Do. kenies	...	...	300	
	387	Do.	Do. fences	...	...	200	
	388	Do.	Do. ditches	...	...	100	
	389	Do.	Enclosing a piece of ground for a salt fish yard including pay of clerk, &c.	...	...	700	
	390	Do.	Repairing the northern platform of Gundalum	420	345	75	
	391	Killai...	Do. fences	...	...	30	
	392	Do.	Do. ditches	...	...	200	
	393	Do.	Do. kenies	1,400	780	400	
	394	Do.	Extending the platform of Nakaravandangudi	700	618	50	
			Total...	23,389	10,656	8,484	
Madura.	395	Nedavassel	Repairing the compound banks	500	...	500	
	396	Do.	Do. the trenches around the Vadapatty Platform.	150	...	150	
	397	Tranquebar	Do. the compound banks	300	...	300	
	398	Negapatam	Do. do. of Payalapoyur	400	...	400	
	399	Do.	Do. the side and drainage channel connecting the straight cut of Cadavyar into the salt pans.	150	...	150	
	400	Do.	Removing accumulation in the recess of the Railway Platform and digging two side channels for access of the salt boats into the recess.	400	...	400	
	401	Vedarniem...	Clearing out the silted portions of the canal from Platforms No. 1 to No. 8.	500	...	500	
	402	Do.	Repairing the compound banks	200	...	200	
	403	Do.	Do. a chowkandy on the bank of the canal... ...	35	...	35	
	404	Do.	Clearing out the sea water-supply channel to the salt beds.	300	...	300	
	405	Do.	Clearing the drainage channel to prevent the rain water from the pans into the canal.	300	...	300	
	406	Thumbinalavankottai.	Repairing trenches around the platform of Thamarankottai.	100	...	100	
	407	Do.	Do. chowkandy on Platform No. 3	50	...	50	
	408	Do.	Filling up two breaches on the eastern and northern sides of the compound banks.	20	...	20	
	409	Do.	Repairing chowkandy on the platform for Thamarankottai.	20	...	20	
	410	Adrampatam	Repairing trenches around the platform	150	..	150	
	411	Do.	Filling up pits and breaches near Platform No. 2 for accommodation of carts resorting to be laden with salt in retail sales.	200	...	200	
	412	.....	Repairing trenches around the platform of Magalenkottai.	100	...	100	
	413	Cuttumavady	Repairing trenches and turfing around the platform ...	200	...	200	
	414	Arasanagery	Repairing trenches round Platforms Nos. 1 and 3 ...	100	...	100	
			Total...	4,175	...	4,175	
	415	All Divisions	Minor repairs to salt works	...	...	1,000	

Part I.—List of Original Works for 1875-76.—(Concluded.)

Districts.	Project. No.	Locality.	Description.	Amount of Estimate.	Computed expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
Tinnevelly.	416	All Divisions	Repairing the platform and its hedges	Rs. 600	Rs. ...	Rs. 600	
	417	Do.	Do. channels and embankments	300	...	300	
			Total...	900	...	900	
			Total Repairs...	...	...	37,114	
			Total Contingencies...	...	...	1,40,407	
			Grand Total ..	...	...	2,60,488	

Amount of the Budget sanctioned.

Districts.	Land Revenue. Original Works.	Repairs.	Total.	Customs. Original Works.	Repairs.	Total.	Grand Total.
	Rs.	Rs.	Rs.	Rs.	Rs.	Rs.	Rs.
Godavery	50	100	150	1,110	250	1,360	1,510
Kistna...	...	600	600	...	50	50	650
Nellore	...	200	200	...	...	...	200
Cuddapah	94	186	280	...	...	...	280
Bellary	150	350	500	...	...	...	500
Kurnool	...	100	100	...	...	...	100
Chingleput	150	...	150	...	...	...	150
North Arcot	275	295	570	...	...	...	570
South Arcot	100	100	200	...	500	500	700
Tanjore	...	680	680	...	500	500	1,180
Trichinopoly	43	287	330	...	...	...	330
Madura	365	125	490	...	...	...	490
Tinnevelly	570	530	1,100	...	20	20	1,120
Coimbatore...	...	750	750	...	...	...	750
Salem	...	300	300	...	...	...	300
South Canara	...	100	100	...	70	70	170
Malabar	...	1,500	1,500	...	500	500	2,000
Total...	1,797	6,203	8,000	1,110	1,890	3,000	11,000
						Minor Department.	
						South Canara...	100
						Malabar	200
						Total...	300
						Grand Total...	11,300

12

PROVINCIAL SERVICES

List of Petty Construction and Repairs for 1875-76.

Districts.	Project. No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
			LAND REVENUE.	RS.	RS.	RS.	
			Original Works.				
Godavery.	1		Pandals or any other sundry works	...	...	50	
Cuddapah.	2	Madanapally	Constructing a shed in the Sub-Collector's office to keep prisoners when brought to trial	20	...	20	
	3	Do.	Erecting a pandal in front of the Taluq Cutcherry during the Jamabundy.	10	...	10	
	4	Raichoti	Do. do. do.	20	...	20	
	5	Voilpaud	Do. do. do.	6	...	6	
	6	Kadiri	Do. do. do.	18	...	18	
	7	Cuddapah	Do. do. do.	10	...	10	
	8	Pulivendla	Do. do. do.	10	...	10	
			Total...	94	...	94	
Chingleput.	9		Providing pandals to Revenue buildings	150	...	150	
Bellary.	10		Constructing pandals	150	...	150	
North Arcot.	11	North Arcot	Erecting pandals in front of the Taluq Cutcherries for the convenience of Curnams at the Jammabundy and other occasions.	125	...	125	
	12	Do.	Erecting pandals in front of the Sub-Magistrate's Cutcherry for the convenience of the parties who attend the Courts.	50	...	50	
	13	Chittoor	Converting a portion of the verandah attached to the Treasury Deputy Collector's office into a private room for the use of the above officer.	75	...	75	
Nellore ...	42	.....	Repairs to Revenue buildings	200	...	200	
Cuddapah ...	43	Cuddapah	Repairs to the pandals in front of the Collector's office and Huzur Sheristadar's Cutcherry.	30	...	30	
	44	Do.	Repairs to the pandals in front of the Treasury Deputy Collector's office.	14	...	14	
	45	Madanapally	Repairs to the pandals in front of the Sub-Collector's office.	20	...	20	
	46	Cuddapah	Repairs to the pandals in front of the Head Assistant Collector's office.	10	...	10	
	47	Do.	Repairs to the pandals in front of the Assistant Collector's office.	10	...	10	
	48	Jamalmadugu	Repairs to the pandals in front of the General Deputy Collector's office.	15	...	15	
	49	Do.	Repairing the doors and roof of the Jamalmadugu Taluq Cutcherry.	17	...	17	
	50	Pullampet...	Repairing a pandal in front of the Taluq Cutcherry of Pullumpett.	10	...	10	
	51	Sidhout	Repairing a pandal in front of the Taluq Cutcherry of Sidhout.	10	...	10	
	52	Budwail	Repairing a pandal in front of the Taluq Cutcherry o Budwail.	10	...	10	
	53	Voilpaud	Repairing and whitewashing the walls of the Voilpaud Taluq Cutcherry.	17	...	17	
	54	Raichoti	Repairing and whitewashing the walls of the Royachotti Taluq Cutcherry.	10	...	10	
	55	Madanapally	Whitewashing the walls of the Madanapally Taluq Cutcherry.	6	...	6	
	56	Kadiri	Whitewashing the walls of the Kadiri Taluq Cutcherry.	7	...	7	
			Total...	186	...	186	
Bellary ...	57	.....	Repairs to Revenue buildings	350	...	350	
Kurnool ...	58	Taluqs	Occasionally whitewashing the Taluq Cutcherries ...	50	...	50	
	59	.....	Pandals in Cutcherries	50	...	50	
			Total...	100	...	100	
North Arcot..	60	North Arcot	Whitewashing the inner and outer walls of the nine Taluq Cutcherries.	150	...	150	
	61	Do.	Whitewashing the Sub-Magistrate's Cutcherry... ...	50	...	50	

List of Petty Construction and Repairs for 1875-76.—(Continued.)

Districts.	Project. No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
			Repairs.—(Continued.)	Rs.	Rs.	Rs.	
North Arcot..	62	North Arcot	Repairing the doors and windows of the Collector's office at Chittoor and the Sub-Collector's office at Vellore.	30	...	30	
	63	Chittoor	Whitewashing the walls and varnishing the doors and windows of the Collector's office.	65	...	65	
			Total...	295	...	295	
South Arcot..	64	.....	Repairing pandals, &c.	100	...	100	
Tanjore ...	65	Mayaveram	Pandal around the Chowkaudy in the Taluq Cutcherry.	50	...	50	
	66	Porayar	Do. on three sides of the Sub-Magistrate's Cutcherry at Porayar.	111	...	111	
	67	Do.	Hedge around the compound of the above...	45	...	45	
	68	Shealli	Shed around the Taluq Cutcherry	200	...	200	
	69	Do.	Hedge around the compound of the same...	75	...	75	
	70	Do.	Gate to the above	50	...	50	
	71	Tanjore	Shed in front of the sub-jail	34	...	34	
	72	Do.	Do. on three sides of the record-room	45	...	45	
	73	Do.	Do. on the western and southern sides of the Tahsildar's office-room.	70	...	70	
			Total...	680	...	680	
Trichinopoly..	74	Trichinopoly	Repairing pandals around the Collector's Cutcherry ..	100	...	100	
	75	Do.	Whitewashing the Collector's Cutcherry, &c.	49	...	49	
	76	Do.	Do. for the five Taluq Cutcherries and five Sub-Magistrate's offices at 5 Rupees each.	50	...	50	
	77	Do.	Trimming the hedges of the compound of the Collector's Cutcherry.	10	...	10	
	14	Chittoor	Constructing a stand and parapet wall with brick and chunam in an open spot for the rain guage which is at present too near the ryot's shed and the trees planted close to it.	25	...	25	
			Total...	275	...	275	
SouthArcot....	15	.....	Constructing pandals, &c	100	...	100	
Trichinopoly..	16	Udiarpalyam	To erect a pandal in front of the Taluq Cutcherry ...	25	...	25	
	17	Keelahpalore	Do. do. do. Sub-Magistrate's office...	18	...	18	
			Total...	43	...	43	
Madura ...	18	Madura Taluq	Constructing a pandal for the accommodation of Curnams at the Jamabundy.	20	...	20	
	19	Tirumangalam	Do. do. do.	20	...	20	
	20	Melur...	Do. do. do.	15	...	15	
	21	Periakolam	Do. do. do.	20	...	20	
	22	Melur	Constructing a thatched verandah on the western and southern sides of the Taluq Cutcherry.	10	...	10	
	23	Pulni...	Constructing a thatched shed and erecting side walls with bricks in front of the Taluq Cutcherry for the accommodation of parties and Curnams at the Jamabundy.	105	...	105	
	24	Usilampatti	Constructing a pandal in front of the Deputy Tahsildar's Cutcherry.	20	...	20	
	25	Tiruchuli	Erecting a pandal around the Deputy Tahsildar's office.	30	...	30	
	26	Sivaganga	Raising the floor of the Deputy Tahsildar's office, and plastering the same with chunam.	45	...	45	
	27	Muthukulathur... ...	Erecting a pandal round the Deputy Tahsildar's Cutcherry newly built.	80	...	80	
			Total...	365	...	365	
Tinnevelly ...	28	Nanguneri...	Building a raised floor in brick and chunam with wooden railings for the use of the Tahsildar, Sub-Magistrate, with a witness box and prisoners' bar.	80	...	80	
	29	Ambasamudram ...	Do. do. do.	85	...	85	

List of Petty Construction and Repairs for 1875-76.—(Continued.)

Districts.	Project. No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
			Original Works.—(Concluded.)				
Tinnevelly.—(*Continued.*)	30	Radapuram	Erecting a pandal in front of the Deputy Tahsildar's Cutcherry.	Rs. 13	...	Rs. 13	
	31	Tenkarei	Constructing a verandah with a tiled roof in place of the present thatched one.	190	...	190	
	32	Do.	Raising the floor of the verandah and smoothening the floor of the hall and verandah.	190	...	190	
	33	Kulasegarapatnam ...	Erecting a wall in front of the Deputy Tahsildar's office compound to keep out stray cattle.	12	...	12	
			Total ..	570	...	570	
			Land Revenue.				
			Repairs.				
Godavery ...	34	.....	Repairing pandals, &c...	...	...	100	
Kistna... ...	35	Masulipatam	Repairing and whitewashing the Collector's Cutcherry.	100	...	100	
	36	Guntur	Repairing and whitewashing the Sub-Collector's Cutcherry.	30	...	30	
	37	Bezwada	Repairing and whitewashing the Head Assistant Collector's Cutcherry.	25	...	25	
	38	Vinukondah	Repairing and whitewashing the General Deputy Collector's Cutcherry.	25	...	25	
	39	.....	Repairing and whitewashing eleven Taluq Cutcherries at 20 Rs. each.	220	...	220	
	40	.....	Repairing and whitewashing ten Sub-Magistrate's do. at 15 Rs. each.	150	...	150	
	41	Masulipatam	Repairing the road within the compound of the Collector's office.	50	...	50	
			Total...	600	...	600	
	78	Musiri	Repairing the thatched verandah of the Head Assistant Collector's Cutcherry Bungalow, to metal its floor and to whitewash the same.	47	...	47	
	79	Do.	Repairing the record-room of the Taluq Cutcherry ...	31	...	31	
			Total...	287	...	287	
Madura ...	80	Madura Taluq	Repairing a pandal in the Taluq Cutcherry where the Tahsildar holds his office.	25	...	25	
	81	Tiruvadanai	Repairing a pandal in the Deputy Tahsildar's office...	10	...	10	
	82	Huzur Cutcherry ...	Do. do. in the Collector's office	70	...	70	
	83	Do.	Whitewashing the Collector's office	20	...	20	
			Total...	125	...	125	
Tinnevelly ...	84	Tenkasi	Flooring a part of the verandah of the Taluq Cutcherry.	5	...	5	
	85	Do.	Placing stone pillars as gate posts on two sides of the Cutcherry and repairing the gates.	10	...	10	
	86	Tinnevelly...	Putting in two doors in the Taluq Cutcherry	30	...	30	
	87	Do.	Do. in half door in a window	3	...	3	
	88	Do.	Removing and restoring four windows in the record-room with kongu frames, iron railing, rain preventing ventilators complete.	156	...	156	
	89	Do.	Renewing a gate	4	...	4	
	90	Do.	Flooring with cut stone for gate wheels	8	...	8	
	91	Do.	Repairs to a well in the Cutcherry compound	6	...	6	
	92	Do.	Sundry repairs to picottahs, treasury doors, &c... ...	6	...	6	
	93	Palamcottah	Repairing the floor	10	...	10	
	94	Kulasegarapatnam ...	Do. the compound wall of the Sub-Magistrate's office.	15	...	15	
	95	Taluq Cutcherries ...	Whitewashing the nine Taluq Cutcherries at 10 Rs. each.	90	...	90	
	96	Sub-Magistrate's do...	Whitewashing the eight Sub-Magistrates' Cutcherries at 5 Rupees each.	40	...	40	
	97	Tinnevelly...	Whitewashing the Huzur Cutcherry	30	...	30	
	98	.....	Minor repairs to Revenue buildings	117	...	117	
			Total...	530	...	530	

List of Petty Construction and Repairs for 1875-76.—(Continued.)

Districts.	Project. No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
				Rs.	Rs.	Rs.	
Coimbatore.	99	Coimbatore	Repairing pandals round the following Cutcherries— Collector's Cutcherry	...	...	70	
	100	Kangayam...	Sub-Collector's Cutcherry	...	...	20	
	101	Coimbatore...	Head Assistant Collector's Cutcherry	...	...	20	
	102	Erode...	Deputy Collector's Cutcherry, Southern Division ...	...	...	20	
	103	Sattimungalum... ...	Do. do. Northern Division ...	...	...	20	
	104	.....	Ten Taluq Cutcherries at 10 Rupees each	...	...	100	
	105	.....	Seven Deputy Tahsildar's Cutcherries at 7 Rupees each.	...	...	50	
	106	.....	Repairing the windows, doors, floors, &c., of the several offices detailed above.	...	...	450	
			Total...	...	...	750	
Salem... ...	107	Salem...	Repairing pandals attached to the Huzur Cutcherry.	40	40	40	
	108	Do.	Do. doors and windows including replacement of broken glasses of the Collector's Cutcherry.	30	30	30	
	109	Usur...	Repairing doors, windows and pandals of the Sub-Collector's office.	40	40	35	
	110	Tripatur	Repairing doors, windows and pandals of the Head Assistant Collector's office.	35	35	30	
	111	Namkul	Repairing doors, windows and pandals of the Deputy Collector's office.	20	20	20	
	112	Kistnageri...	Repairing the office pandal of the Kistnagheri Taluq Cutcherry.	...	...	15	
	113	Darampury...	Repairing the office pandal of the Darampury Taluq Cutcherry.	...	...	15	
	114	Tripatur	Repairing the office pandal of the Tripatore Taluq Cutcherry.	...	...	15	
	115	Uttengeri	Repairing the office pandal of the Uttengeri Taluq Cutcherry.	...	...	15	
	116	Trichengode	Repairing the office pandal of the Trichengode Taluq Cutcherry.	20	20	15	
	117	Salem...	Repairing the office pandal of the Thoramangalam Taluq Cutcherry.	...	...	10	
	118	Do.	Repairing the office pandal of the Razipur Taluq Cutcherry.	...	...	10	
	119	Usur...	Repairing the office pandal of the Denkanikotta Taluq Cutcherry.	...	...	10	
	120	Darampury...	Repairing the office pandal of the Pennagaram Taluq Cutcherry.	...	...	10	
	121	Uttengeri	Repairing the office pandal of the Haroor Taluq Cutcherry.	...	...	10	
	122	Namkal	Repairing the office pandal of the Parametty Taluq Cutcherry.	...	...	10	
	123	Trichengode	Repairing the office pandal of the Senkageri Taluq Cutcherry.	...	...	10	
			Total...	185	185	300	
South Canara.	124	.....	Sundry repairs to Revenue buildings...	100	...	100	
Malabar ...	125	.....	Monsoon repairs to Revenue buildings and sheds attached.	1,500	...	1,500	
			Customs.				
			Original Works.				
Godavery ...	1	Coringa	Construction of a wooden bridge near the watch shed of the Sea Customs office.	...	...	550	
	2	Coringa and Cocanada.	Construction of a tiled shed, &c., for watching peons near the Customs Houses.	...	...	200	
	3	Neelapally and Injaram.	Constructing a watch shed for peons near the frontier Amin Cutcherry.	...	...	200	
	4	Do. do.	Constructing a bridge near the frontier Amin Cutcherry.	...	...	160	
			Total...	...	...	1,110	

List of Petty Construction and Repairs for 1875-76.—(Concluded.)

Districts.	Project. No.	Locality.	Description.	Amount of Estimate.	Computed Expenditure up to 31st March 1875.	Amount required in 1875-76.	Remarks.
			Customs—Repairs.	Rs.	Rs.	Rs.	
Godavery ...	5	Cocanada	Petty repairs to office buildings	...	...	50	
	6	Coringa	Repairs of watching peons' sheds	...	...	50	
	7	Injaram	Do. of wooden bridge	...	...	50	
	8	Do.	Do. of watching peons' sheds	...	...	100	
			Total...	...	...	250	
Kistna	9	.....	Repairs to Sea Customs Cutcherries	50	...	50	
South Arcot..	10	Tooknampaukum ...	For repairing and tiling the Sayer Superintendent's house.	245	...	218	
	11	Kandamangalam ...	For plastering the mud pillars with chunam and flooring the shed in front of the Sayer Cutcherry and for constructing steps around the shed.	75	...	75	
	12	Vurdoor	Plastering the walls with chunam, flooring and tiling the house of the Sayer Superintendent.	113	...	118	
	13	Do.	Repairing the gate	7	...	7	
	14	Mortandy...	Flooring and whitewashing the Sayer Superintendent's house.	70	...	70	
	15	Kottacuppum	Tiling and whitewashing the Sayer Cutcherry	12	...	12	
			Total...	527	...	500	
Tanjore ...	16	.....	Unforeseen contingencies, repairs to Customs offices, &c.	...	...	500	
Tinnevelly ...	17	Tuticorin	Raising, plastering and whitewashing the latrine walls.	13	...	13	
	18	Kulasegarapatnam ...	Repairing the office pandal...	3	...	3	
	19	Do.	Do. the wall in front of the office and rebuilding the pial.	4	...	4	
			Total...	20	...	20	
South Canara.	20	.....	Sundry repairs to Sea Customs buildings	50	...	50	
			Maintenance allowance to keep in repair the quarry at Hangarkotta.	20	...	20	
			Total...	70	...	70	
		Malabar	Monsoon repairs to Sea Customs Houses and sheds attached.	500	...	500	
			Minor Departments.				
South Canara.	21	.....	Sundry repairs to Tappal Huts	100	...	100	
Malabar ...	22	.....	Monsoon repairs to Tappal Huts, &c....	200	...	200	

No. 2,434.

PROCEEDINGS OF THE BOARD OF REVENUE, dated 30th August 1875.

Read the following letters:—

From	Collector of	Ganjam,	dated	12th June 1875,	No. 1,313
,,	,,	of Vizagapatam,	,,	13th May ,, ,,	832
,,	,,	of Godavery District,	,,	7th July ,, ,,	——
,,	,,	of Kistna District,	,,	9th June ,, ,,	776
,,	,,	of Nellore,	,,	7th May ,, ,,	1,212
,,	,,	of Chingleput,	,,	3rd June ,, ,,	309
,,	,,	of South Arcot,	,,	28th May ,, ,,	228
,,	,,	of Tanjore,	,,	17th June ,, ,,	224
,,	,,	of Madura,	,,	11th ,, ,, ,,	246
,,	,,	of Tinnevelly,	,,	12th May ,, ,,	244
,,	,,	of South Canara,	,,	11th ,, ,, ,,	842
,,	,,	of Malabar,	,,	4th ,, ,, ,,	143

WITH reference to the reduction of Rupees 30,600 made by Government in the provision for Salt Petty Construction and Repairs in 1875-76, Collectors were called upon to submit revised lists of works, and the letters above recorded are their replies.

2. The sums stated by the Collectors as most urgently required exceed the grant by Rupees 40,488 as shown below:—

	Amount sanctioned by the Board and Government.	Amount required by the Collectors.
	RS.	RS.
Ganjam	10,900	13,257
Vizagapatam	16,000	18,000
Godavery	9,500	13,500
Kistna	25,700	31,630
Nellore	26,500	26,500
Chingleput...	67,000	76,480
South Arcot	28,000	36,000
Tanjore	15,900	25,055
Madura	5,500	5,500
Tinnevelly...	7,000	7,000
South Canara	5,000	5,175
Malabar	3,000	2,391
Total ...	2,20,000	2,60,488

3. The Board are unable to reduce the provision made by Collectors, and considering the representations of the pressing necessity for the execution of the works, sanction the allotments proposed. The Board think that the excess over and above the budget provision may possibly be met from general savings under the Salt Grant*. Should this, however, be found impossible, application will be made for a special grant.

*Rupees 15,00,000.

4. Some of the works for which provision is made are recommended for execution by the Public Works Department. The amount required to be transferred to the Public Works Department Budget on that account will be reported to Government separately on the receipt of the Collectors' replies to Board's Proceedings, dated 2nd June 1875, No. 1,482.

5. A copy of these Proceedings will be submitted to Government for their approval.

(A true Copy and Extract.)

Acting Sub-Secretary.

To all Collectors, with printed lists of works.
,, the Acting Secretary to Government, Revenue Department, with do.

Copy to the Accountant-General, with do.

Exd. W. H. French.

1 Lake Cy 0 a-8 08 Rec 8 a. 1875
1 Rec Rec and Genl a e S

Rw: 1875-Dup
No 1325 & 3788

1875.

Board of Revenue,

MADRAS.

PROCEEDINGS, 30TH AUGUST 1875, No. 2,434.

Desp. 22 Sept 1875

Encl.

Received 1st Octr

AUGUST.

No. 2,434.

Petty Construction and Repairs.—Revised allotments proposed by Collectors for Salt Works under — for 1875-76, sanctioned with remarks. Copy of these Proceedings submitted for approval of Government.

No 2111

W. approved

9 oct 1875