

(1) Number of Pages.....4
(2) Date of repair.....18-4-68.
(3) Initials of the Referencer.....Z.A.

MADRAS RECORD OFFICE

GOVERNMENT OF MADRAS

Revenue DEPARTMENT

G.O. No.
B.P. No.

246

Press
Mis.

Dated

8-2-1875 196 .

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
3rd February 1875.*

No. 78. Read the following Endorsement of the Chief Engineer for Irrigation, dated Camp at Sooramungalum, 21st December 1874, No. 1,080.
Supplemental List of Tanks breached during the late Rains in the Cuddapah District.

Talug.	Village.	Name of Tank, etc.	Whether Government or Dasabandam.	Nature of Breach.	Remarks.
Kadry.	Numbula Poolikunta.	Peddachervoo.	Govt.	Calingulah washed away.	
	Reddipully ...	Do.	Do.	Calingulah washed away and the bund requires repair.	
	Putnum.	Mullumma-coonta.	Do.	The bund breached and water passes away.	
	Oopalapadoo ...	Yerracoonta ...	Do.	Gaps have been caused in the calingulah and the bund in some parts came down.	
	Kullasamudrum.	Tank.	Do.	Breached and water passes away.	
	Nullachervoo...	Kothacoonta ...	Do.	The northern calingulah is out of order.	
	Obaladavorachervoo.	Peddachervoo.	Do.	Some of the stones of the calingulah washed away, and the bund also requires repairs.	
	Kadry ...	Vittalarayanichervoo.	Do.	Water passes away through gaps in the bund.	It appears that the Overseer has done some repairs.
	Panatulachervoo.	Peddachervoo.	Do.	Breached.	
	Tavalum ...	1. Mubbuvinipully calva. 2. Narayana-chervoopully calva.	Dasabandam. Do.	The sluices of these channels at the Paupugnee washed away, and the cultivation under them is now drying for want of water.	
	Kakunty ...	1. Peddachervoo.	Govt.	Stones to a distance of 20 yards have been carried away, and the southern calingulah and another to a distance of 57 yards in the central one.	
		2. The supply channel from Paupugnee river to Timina, Nayanichervoo.	Do.		The ryots personally complained to the Collector that unless these are early repaired the land under them would be left waste.
	Mooklapooram.	Large tank ...	Do.		Reported to be in damaged state.
	Luckasamudrom.	Luckasemichervoo.	Do.		Reported to be in dangerous condition.
	Malkavomala... Mullapully ...	Large tank ... Nullachervoo.	Do. Do.		Do. Do.

CUDDAPAH,
15th December 1874.

(Signed) A. S. MOBERLY, Colonel, R.E.,
District Engineer, Cuddapah.

*Proceedings of the Madras Government, Public Works Department,
3rd February 1875.*

SUBMITTED for the information of Government in continuation of this Office No. 999-B, dated 2nd December 1874.

2. The District Engineer should have stated what arrangements he has made to provide for the supply of water at the river channels, which need not be affected by the destruction of the head sluices.

(Signed) JOHN MULLINS, Lieut.-Col., R.E.,
Chief Engineer for Irrigation.

No. 79. ORDER THEREON, 3rd February 1875, No. 301.

IRRIGATION, No. 3.

ORDERED to be recorded.

(True Extract.)

Cummins Colonel, R.E.,
Secretary to Government.

To the Chief Engineer for Irrigation.
„ Revenue Department. ✓
„ District Engineer, Cuddapah.

Exd. T. O'Connor.

18 Spare Copies

N^o 426
Revenue Departt:
Govt. of 1875: Madras.
PUBLIC WORKS.

To

THE CHIEF ENGINEER FOR IRRIGATION,

&c., &c., &c.

Dated February 3rd.

Recd. — a — 5th

Encl.

G. O., 3rd February 1875, No. 301.

FEBRUARY.

Nos. 78-79

De M...

Tanks, Cuddapah District. — Supple-
mental Report of the damages done to
tanks during the late heavy rains, re-
corded.

N^o 246
Comm^d to the
Board of Revenue
8: Feb/75

10 to the Board of Revenue, 13 Feb