

- (1) Number of pages 2
(2) Date of repair 6-2-1970
(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

GOVERNMENT OF MADRAS

Revenue DEPARTMENT

G.O. No.	2011	Press
B.P. No.		Mis. ✓
Dated	28-8-1970	196

Not to be folded or roughly handled

21

2011

*Proceedings of the Madras Government, Public Works Department,
5th August 1876. No. 2,009.*

No. 122. Read the following letter from Colonel F. J. MOBERLY, R.E., Superintending Engineer, Chingleput, to Lieutenant-Colonel J. MULLINS, R.E., Chief Engineer for Irrigation, dated Camp at Solanur, 21st July 1876, No. 1,304:—

In reply to paragraph 2 of your memorandum, No. 34-C.N., dated 26th May, I have the honor to report that the Zemindars have not paid anything towards

Enclosure.
1 Copy of G.O., Revenue Department.

No. 962 of 18th June, continued.

construction or repair of the Kesaveram anicut and the works under it.


2. G.O., No. 51, of 11th January 1864, Revenue Department, decides that no claim shall be made. Copy enclosed.

No. 123. ORDER THEREON, 5th August 1876, No. 2,009.

IRRIGATION, No. 13.

RECORDED with reference to paragraph 3 of G.O., No. 1,650, of the 30th June 1876.

(True Extract.)



Colonel,

Offg. Under Secy. to Govt., P.W.D.

To the Superintending Engineer, Chingleput.
„ Chief Engineer for Irrigation.
„ Examiner of Public Works Accounts.
„ Revenue Department.

Exd. J. W. Fischer.

20 Spare Copies

B.P. No.

Mis.

25 July 1876 No 1769 mis.

No 3423

Revenue 1876 D. part

Govt. of 1876 Madras.

PUBLIC WORKS.

To

THE SUPERINTENDING ENGINEER,
CHINGLEPUT,
&c. &c. &c.

Dated August 5th.

Issued

Recd. 21 Aug 1876

Encl.

G. O., 5th August 1876, No. 2019.

AUGUST.

Nos. 122-123.

14-8-76 Rem. Eng. Div. No. 1044

Kanavaram Anicut, Chingleput District.—
Letter from the Superintending Engineer
intimating that the Zemindars have not paid
towards the construction or repair of the —
recorded.

No 2011

Communicated to the Secy of

Rev. L

28 August 1876

DEPARTMENT

G.O. No.
B.P. No.

Press
Mis.