

(1) Number of pages 4

(2) Date of repair 8. 4. 1970

(3) Initials of the Referencer \_\_\_\_\_

# TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

*Revenue* DEPARTMENT

|          |        |        |
|----------|--------|--------|
| G.O. No. | 2970   | Press  |
| B.P. No. |        | Mis. ✓ |
| Dated    | 9. 12. | 1976.  |

Not to be folded or roughly handled

*df*

2970  
1

Read the following:—

No. 252 W.

No. 462.

Note by Chief Engineer for Irrigation.

THE Superintending Engineer, Kistna, forwards, with his letter marginally noted,  
an estimate in connection with the Marripallem Degalapallem tank supply-channel,  
situated in the Bunder Taluq, Masulipatam Range.

2. The nature of the work proposed for execution and the heads of account to which it is chargeable are as follow:—

ORDINARY AGRICULTURAL.

Repairs.

|                                    |     |     |     |       |         |
|------------------------------------|-----|-----|-----|-------|---------|
| Repairing the supply-channel banks | ... | ... | ... | ...   | Rs. 200 |
|                                    |     |     |     | Total | 200     |

3. The following particulars of this tank are recorded—

|                                            |     |     |     |     |            |
|--------------------------------------------|-----|-----|-----|-----|------------|
| Ayacut area                                | ... | ... | ... | ... | Acres 140  |
| Assessment...                              | ... | ... | ... | ... | Rupees 614 |
| Average revenue                            | ... | ... | ... | ... | 336        |
| Highest do.                                | ... | ... | ... | ... | 583        |
| Expenditure during the previous four years | ... | ... | ... | ... | 166        |

The area of the catchment basin is — square miles; the maximum flood-supply is calculated at — cubic feet per second for discharging which as surplus there is no outlet.

The head of the supply-channel was destroyed by the floods of 1874, and the banks in their whole lengths were breached, the tank in consequence did not receive its supply so that the land under it had to be kept uncultivated last year.

The estimate provides for repairing the tank supply-channel.

The channel is in Divi.

The estimate is recommended for sanction.

FORT ST. GEORGE,  
16th November 1876.

(Signed) JOHN MULLINS, Lt.-Col., R.E.,  
Chief Engineer for Irrigation.

To the Secretary to Government, Public Works Department.

No. 463.

ORDER THEREON, 27th November 1876, No. 3,166.

IRRIGATION, No. 39-A.

Account.

MARRIPALLEM DAGALAPALLEM TANK SUPPLY-CHANNEL.

Irrigation.

Group or Project.—

Fund.—Ordinary Agricultural.

Class.—Repairs.

Name of Tank, Canal, or Channel.—Marripallem Degalapallem tank supply-channel.

Particulars of Work.—Repairing the supply-channel banks.

Amount.—Rupees 200.

To be carried out by the Public Works Department Officer in charge Masulipatam Range, I.

THE following estimate from the Masulipatam Range forwarded by the Superintending Engineer, Kistna, is sanctioned:—

*Proceedings of the Madras Government, Public Works Department,  
27th November 1876. No. 3,166.*

2. This sanction has been registered as No. 181 I. of 1876-77.

(True Extract.)

*Comdant*

Major-General, R.E.,  
Secretary to Government.

To the Superintending Engineer, Kistna.

- „ Collector of „
- „ Examiner of Public Works Accounts.
- „ Chief Engineer for Irrigation.
- „ Revenue Department.

Exd. S. T. Austin.

Spare Copies

Revenue Dept  
No. 5570. ✓  
Govt. of Madras.  
PUBLIC WORKS. ✓

To

THE SUPERINTENDING ENGINEER,  
KISTNA,  
&c., &c., &c.

Dated November 27th.

Issued

Recd.

8 Decr.

Encl.

G. O., 27th November 1876, No. 3,163.

*See Memo*

NOVEMBER.

Nos. 462-463.

No. 2970  
Comd to the  
Board of Rees

9 Decr 76

Marrupallu Duguballem Tank, Kistna  
District.— Estimate of Rupees 200 for repair-  
ing the supply-channel of the —, sanctioned.

9 To the Board of Rees on Decr