1726/2

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

REVENUE DEPARTMENT

G.O. No. / B.P. No: 1726	Press. / Mis.
Dated 23-3-1877	~~197 F~~.

Not to be folded or roughly handled

Archives 1—10,006—19-4-79.

No. 67. Read the following letter n Major J. BEATTY, R.E., Officiating Superintending Engineer, G to the Chief Engineer for Irrigation, dated Dowlaishweram, 26th 1877, No. 3,051 :—

I HAVE the honor to forward I a plan and estimate received from the

One Plan.
„ Estimate.
„ Divisional Officer's Report, No. 638 17th January 1877.

er in charge, Eastern Delta Division, unting to Rupees 980, for forming a ed bank along the left side of the creek w the Munjair lock, and to request you will be good enough to obtain san lovernment to the estimate.

2. The necessity for the work i explained in the Divisional Officer's report herewith enclosed.

3. As suggested by Lieutenant ll, I think the sluices over the several creeks through which the bank runs m itted for the present.

4. If the work be sanctioned, fu be allotted under the head "Extensions and Improvements."

From Lieutenant D. McNEIL CAMPBE ., Executive Engineer in charge of Eastern Delta Division, Godavery District or J. BEATTY, R.E., Officiating Superintending Engineer, Godavery Dis ed Dowlaishweram, 17th January 1877, No. 638.

THE Chief Engineer for Irrigation i norandum No. 62, dated 2nd March 1871, again in his memorandum No. 184-C, 26th February 1874, has called attention e want of a towing-path below Munjair ith an estimate for forming a raised bank 3 feet above maximum high tide.

One Plan.
„ Estimate.

lock. I have, therefore, the honor to fo 3 above Colonel Mullins states that the along the left side of the creek, 5 feet wide or three out-fall self-acting sluices will be

2. In the first of the memorandum there are no less than sixteen creeks to be total outlay will be very small, and the ble size will be required; the works would required; but you will perceive from the nder these circumstances, and taking into crossed, at two or three of which sluices of Munjair lock, I have deemed it advisable also be expensive owing to the bad nature consideration that there is not much traffic to omit the sluices for the present.

No. 68. ORDER THEREO 1877, No. 730.

IRRIGATION, No. 8-A.

Account.

SANCTIONED. Care should be taken guing the tow-path; the alignment survey is not everywhere as good ight be.

Proceedings of the Madras Government, Public Works Department,
3rd March 1877. *No.* 730.

2. This sanction has been registered as follows :—

GODAVERY DELTA SYSTEM.
Eastern Delta Section.
Irrigation.
Revenue—Exte[illegible]nd Improvements.
(2) Main [illegible]d Branches.
C[illegible]l.
Na[illegible]s.

Register No. 338—1 of 1876-77. *Name of Wo*[illegible]elow Munjair Lock.
Amount of Estimate—Rupees ([illegible]ed and eighty.
To be carried out by the Publi[illegible]ent.

[illegible] Lieut.-Colonel, R.E.,
[illegible] to Government, P.W.D.

To the District Engineer, Godavery.
„ Collector of Godavery.
„ Chief Engineer for Irrigation.
„ Examiner of Public Works Accou
„ Revenue Department.

Exd. S. T. Austin.
Spare Copies

1726

Rev: Dept
No 1888

Govt. of India Works.

PUBLIC WORKS.

To DISTRICT ENGINEER,
GODAVERY

23 March

MARCH.

Nos. 67-69.

No 1726

Comm^r to the
Board of Revenue

23^d March 77.

Manager Lock Godavery District — Rupees 980 for a tow-path below — sanctioned. Care to be taken in ...ding the tow-path.

9. S. to the Hd of Revenue 27-3-77