

(1) Number of pages 2
(2) Date of repair _____
(3) Initials of the Referencer _____

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

Revenue DEPARTMENT

G.O. No.	185	Press.
B.P. No.		Mis.
Dated	9-1-1877	197

Not to be folded or roughly handled

Archives I-5,806-24-2-78,

82

Proceedings of the Madras Government,
27th December

Public Works Department,
No. 3,552.

Read the

No.

No. 601. Note by the Chief

The District Engineer, Cuddapah,

No. 751, dated 4th July 1876.

2. The nature of the work proposed which it is chargeable are as follow:—

ORDINARY

Repairing the bund
Do. the Waddoo
Repairs and improvements to the we

wing:—

W.

for Irrigation.

ds, with his letter marginally noted, an estimate in connection with the Veerally Poddachervoo tank, situated in the Yachoty taluq, Madanapully range.

execution and the heads of account to

CULTURAL.

	RS.
...	140
...	500
...	4,450
Total ...	5,090

3. The following particulars of this

Ayacut area
Assessment
Average revenue
Highest do.

are recorded:—

...	Acres	451	{	Circar	376
				Inam	75
...	Rupees	971	{	Circar	820
				Inam	151
...	"	897	{	Circar	790
				Inam	107
...	"	1,082	{	Circar	931
				Inam	151
...					Not stated.

Expenditure during the previous four

The area of the catchment basin is 3. is calculated at 4,487 cubic feet per second. a weir with a length of 356 feet available breached by the heavy rains of 1874, at tanks. It is proposed to repair and improve for raising and sectioning the bund, repairs &c., to three Irrigation sluices.

4. The sections and plans which accompany the estimate are numerous and well executed, but there is an absence of clear information as to the general circumstances of the tank such as a report should convey what is called the "Waddoo," and it would be of very small section, and the soil requires to be taken from the channel. As the surroundings, this supposition can only rest on the use of local terms without the English name.

The greater portion of the work provided for in the estimate has apparently been executed in anticipation of sanction on the part of the Government, which was apparently the case.

3 miles; the maximum flood supply discharging which as surplus there is no surplus discharge; this weir was reaching of some of the high lying weir. The estimate also provides for "Waddoo" and constructing cisterns,

the estimate are numerous and well executed, but there is an absence of clear information as to the general circumstances of the tank such as a report should convey what is called the "Waddoo," and it would be of very small section, and the soil requires to be taken from the channel. As the surroundings, this supposition can only rest on the use of local terms without the English name. The greater portion of the work provided for in the estimate has apparently been executed in anticipation of sanction on the part of the Government, which was apparently the case.

*Proceedings of the Madras Government, Public Works Department,
27th December 1876. No. 3,552.*

expenditure is equivalent to about $5\frac{2}{3}$ years average revenue and will have been chiefly incurred in the repairs to the waste weir. It should have been stated whether there had been repairs during the previous four years in accordance with the rules.

Sanction is recommended to the estimates.

(Signed) A. DE C. SCOTT, Major, R.E.,
Dy. Chief Engineer for Irrigation,
for Chief Engineer for Irrigation.

FORT ST. GEORGE,
20th December 1876.

To the Secretary to Government, Public Works Department.

No. 602.

ORDER THEREON, 2th December 1876, No. 3,552.

IRRIGATION, No. 44-C.

Account.

THE following estimate from the
Madanapully Range, forwarded by the
District Engineer, Cuddapah, is sanc-
tioned:—

VEERAPULLY PDDACHERVUO TANK.
Irrigation.

Group or Project.	Fund.	Class.	Name of Tank, Canal or Channel.	Particulars of Work.	Amount.
..	Ordinary Agricul- tural.	Repairs ..	.. Veerapully Pedda- chervu Tank.	1. Repairing the bund ..	rs. 140
				2. Do. the Waddoo.	590
				3. Repairs and improve- ments to the weir and sluices, &c. ..	4,450
				Total ..	5,090

To be carried out by the Public Works Department Officer in charge Madanapully Range.

2. This sanction has been registered as No. 232 I. of 1876-77.

(True Extract.)

Major-General, R.E.,
Secretary to Government.

To the District Engineer, Cuddapah.
" Collector of do.
" Chief Engineer for Irrigation.
" Examiner of Public Works Accounts
" Revenue Department.

Exd. E. C. Shunker.

4 Spare Copies

Revenue Dep

No 185

Govt. of India

PUBLIC WORKS.

THE DISTRICT ENGINEER.

CUDDAPAT

cc. cc.

Dated December 27/06.

For

Recd - 9 Jan 07

Recd.

G. O. 2706 December 1876, No. 2,552.

DECEMBER.

Nos. 601-602.

Side of Board of Rev
Office only

For the purpose of repairing the
road between the