

(1) Number of pages 2

(2) Date of repair

(3) Initials of the Referencer

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

Revenue DEPARTMENT

G.O. No.	189	Press.
B.P. No.		Mis.
Dated	9-1-1877	197

Not to be folded or roughly handled

Archives I—5,806—24-2-78,

82

Read the

No.

No. 601. Note by the Chief Engineer,

The District Engineer, Cuddapah,

No. 791, dated 4th July 1876.

2. The nature of the work proposed which it is chargeable are as follow:—

ORDINARY

Repairing the bund
Do. the Waddoo
Repairs and improvements to the we

3. The following particulars of this

Ayacut area
Assessment
Average revenue
Highest do.

Expenditure during the previous four

The area of the catchment basin is calculated at 4,487 cubic feet per second a weir with a length of 356 feet available breached by the heavy rains of 1874, a tanks. It is proposed to repair and improve for raising and sectioning the bund, repair &c., to three Irrigation sluices.

4. The sections and plans which are executed, but there is an absence of clear of the tank such as a report should convey what is called the "Waddoo," and it work is of very small section, and the soil required to be taken from the channel. As the surroundings, this supposition can only be the use of local terms without the English.

The greater portion of the work proposed executed in anticipation of sanction on the which was apparently the case.

ng:—

for Irrigation.

with his letter marginally noted, an estimate in connection with the Veerachervoo tank, situated in the choty talug, Madanapully range.

execution and the heads of account to

RURAL.

	RS.
...	140
...	500
ces, &c. ...	4,450
Total ...	5,090

as recorded:—

Acres	451	{	Circar	376
			Inam	75
Rupees	971	{	Circar	820
			Inam	151
"	897	{	Circar	790
			Inam	107
"	1,082	{	Circar	931
			Inam	151
...	...		Not stated.	

miles; the maximum flood supply discharging which as surplus there is a surplus discharge; this weir was reaching of some of the high lying weir. The estimate also provides "Waddoo" and constructing cisterns,

the estimate are numerous and well tion as to the general circumstances are are several sheets of sections of to be a supply channel part of which the repair of the banks should appear no general plan of the tank and its gue conjecture. The orders against ent should not have been overlooked. in the estimate has apparently been of its being emergently necessary

*Proceedings of the Madras Government, Public Works Department,
27th December 1876. No. 3,552.*

The expenditure is equivalent to about 5½ years average revenue and will have been chiefly incurred in the repairs to the waste weir. It should have been stated whether there had been repairs during the previous four years in accordance with the rules.

Sanction is recommended to the estimates.

(Signed) A. DEC. SCOTT, Major, R.E.,
Dy. Chief Engineer for Irrigation,
for Chief Engineer for Irrigation.

FORT ST. GEORGE,
20th December 1876.

To the Secretary to Government, Public Works Department.

No. 602. ORDER THEREON, 27th December 1876, No. 3,552.

IRRIGATION, No. 44-C.
Account.

The following estimate from the Madanapully Range, forwarded by the District Engineer, Cuddapah, is sanctioned:—

VEERAPULLY PEDDACHERVUO TANK.
Irrigation.

Group or Project.	Fund.	Class.	Name of Tank, Canal or Channel.	Particulars of Work.	Amount.
	Ordinary Agricultural.	Repairs ..	Veerapully Peddachervu Tank.	1. Repairing the bund .. 2. Do. the Waddoo. 3. Repairs and improvements to the weir and sluices, &c. ...	Rs. 140 600 4,450
				Total ..	5,090

To be carried out by the Public Works Department Officer in charge Madanapully Range.

2. This sanction has been registered as No. 232 I. of 1876-77.

(The Extract.)

(Signed) G. W. WALKER, Major-General, R.E.,
Secretary to Government.

To the District Engineer, Cuddapah.
 „ Collector of do.
 „ Chief Engineer for Irrigation.
 „ Examiner of Public Works Accounts.
 „ Revenue Department.

Exd. E. C. Shunker.

Spare Copies

Govt. of 1876
PUBLIC WORKS.

To

THE DISTRICT ENGINEER,
CUDDAPPA
Co. 2

Dated December 27th.

Issued

Recd.

Encl.

G.O., 27th December 1876, No. 2,552.

DECEMBER.

Nos. 601-602.

No. 189
Communicated to
The District Engineer

A.H.C.

9 Jan 1877

Uppapully Pradachan Tank, Cuddap
District—Estimate for repairing the
sanctioned.