

(1) Number of pages 3
(2) Date of repair _____
(3) Initials of the Referencer _____

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

Revenue DEPARTMENT

G.O. No.	190	Press.
B.P. No:		Mis.
Dated	9-1-1877	197

Not to be folded or roughly handled

Archives I—5,806—24-2-78.

Handwritten mark

by the Chief Engineer for Irrigation.

Cuddapah

No. 958, dated 29th July 1876.

2. The nature of the work proposed which it is chargeable are as follow :—

ORDINARY CULTURAL.

	Rs.
Repairing the bund, Irrigation sluice the two existing escapes ...	5,000
Total ...	5,000

3. The following particulars of the work are recorded :—

Ayacut area	Acres	507
Assessment	Rupces	5,899
Average revenue	"	3,587
Highest do.	"	4,673
Expenditure during the previous four years	"	294

The area of the catchment basin is calculated at 1,002 cubic feet per second two escapes, making a total length of 14 Portions of the escapes were damaged by for the repairs which are as follow :—Repairing the body wall of the south-west escape; and retaining walls, and repacking the stone. The estimate further provides for repairing uniform width of 2 yards at top with a revetment with gravel backing gravelling the in order to secure it from being cut up, and out and under-pinning with brick and covering slab which was displaced.

4. This tank, in addition to the catchment basin, has a supply channel from the Mala Vunkah, for which a head sluice was constructed in G.O., No. 583, dated 3rd March 1876, at a cost of Rupees 1,120 is now under construction. The tank lies above the North-western railway. The estimate is recommended for sanction.

FORT ST. GEORGE, (Signed)
28th December 1876.

with his letter marginally estimate in connection with the Ch. amudinna tank situated in the Cuddapah range.

execution and the heads of account to

are miles; the maximum flood supply is discharging which as surplus there are not available for the surplus discharge. Floods of 1874, and the estimate provides for the stone apron and sundry repairs to reconstructing a portion of the wing and and revetment of the north-east escape. Bund throughout and reforming it to a slope of 2 to 1; also rebuilding the revetment of the bund and portions of the rear slope of Irrigation sluice No. 2, i.e., opening the south side wall and replacing the

nt basin, has a supply channel from the catchment basin, has a supply channel from the Mala Vunkah, for which a head sluice was constructed in G.O., No. 583, dated 3rd March 1876, at a cost of Rupees 1,120 is now under construction. The tank lies above the North-western railway.

A. DEC. SCOTT, Major, R.E.,
Dy. Chief Engineer for Irrigation,
for Chief Engineer for Irrigation.

To the Secretary to Government, Public Works Department.

2nd No. 1.
ORDER THEREON, 2nd January 1877, No. 1.

IRRIGATION, No. 1.

Account.

The following estimate
Cuddapah Range, forwarded by
District Engineer, Cuddapah, is sanctioned.

CHINTACOMMUDINNA TANK.

Irrigation.

Group or Project.—Nil.

Fund.—Ordinary Agricultural.

Class.—Repairs.

Name of Tank, Canal or Channel.—Chintacommudinna tank.

Particulars of Work.—Repairing the bund, Irrigation sluice, and the two existing escapes.

Amount.—Rupees 5,000.

To be carried out by the Public Works Department Officer in charge Cuddapah range.

2. This sanction has been registered as No. 242-I. of 1876-77.

(True Extract.)

Major-General, R.E.,
Secretary to Government.

To the District Engineer, Cuddapah.
" Collector of do.
" Chief Engineer for Irrigation.
" Examiner of Public Works Accounts.
" Revenue Department.

Ext. E. C. Shanker.

14
Spare Copies

Read the following:

No. 31

Note by the Chief Engineer

to the District Engineer, Cuddapah, for
No. 958, dated 29th July 1876.

2. The nature of the work proposed for which it is chargeable are as follow:—

ORDINARY AGRICULTURAL.

Repairs.

Repairing the bund, Irrigation sluice,

ORDINARY AGRICULTURAL.

Rs.

for two existing escapes ... 5,000

Total ... 5,000

3. The following particulars of this work are recorded:—

Ayacut area	...	Acres	507
Assessment	...	Rupees	5,899
Average revenue	...	"	3,587
Highest do.	...	"	4,673
Expenditure during the previous four years	...	"	294

The area of the catchment basin is 5 calculated at 1,002 cubic feet per second, two escapes, making a total length of 142. Portions of the escapes were damaged by the for the repairs which are as follow:—Repair the body wall of the south-west escape; and retaining walls, and repacking the stone at the estimate further provides for repairing uniform width of 2 yards at top with a revetment with gravel backing gravelling the top in order to secure it from being cut up, repaired out and under-pinning with brick and chun covering slab which was displaced.

4. This tank, in addition to the catchment basin, has a supply channel from the catchment basin, for which a head sluice sanctioned in G.O., No. 583, dated 3rd March 1876, at a cost of Rupees 1,120 is now under construction. The tank lies above the North-west line of railway. The estimate is recommended for sanction.

Fort St. George,
28th December 1876.

(Signed)

A. DE C. SCOTT, Major, R.E.,
Dy. Chief Engineer for Irrigation,
for Chief Engineer for Irrigation.

To the Secretary to Government, Public Works Department.

No. 2.

ORDER THEREON, and January 1877, No. 1.

IRRIGATION, No. 1.
Account.

The following estimate
Cuddapah Range, forwarded by
District Engineer, Cuddapah, is sanctioned.

CHINTACOMMUDINNA TANK.

Irrigation.

Group or Project.—Nil.

Fund.—Ordinary Agricultural.

Class.—Repairs.

Name of Tank, Canal or Channel.—Chintacommudinna tank.

Particulars of Work.—Repairing the bund, Irrigation sluice, and the two existing escapes.

Amount.—Rupees 5,000.

To be carried out by the Public Works Department Officer in charge Cuddapah range.

2. This sanction has been registered as No. 242-I. of 1876-77.

(True Extract.)

(Signed) G. W. WALKER, Major-General, R.E.,
Secretary to Government

To the District Engineer, Cuddapah.

- „ Collector of do.
- „ Chief Engineer for Irrigation.
- „ Examiner of Public Works Accounts.
- „ Revenue Department.

Exd. E. C. Shunker.

Spare Copies

190
2

PUBLIC

To

THE DISTRICT ENGINEER,
CUDDAPAH
S.O. & Co.

Dated January 2nd.

Issued

Recd. - 4 - 9

Encl.

G. O., 2nd January 1877, No. 1.

JANUARY.

No. 1.

*To the Board of Rev.
Office copy*

Quintacommunications, Tond, Cuddapah
for the estimate for certain repairs to the
road.