Archives I - 10,006 — 16-8 77.

(1) Number of pages 4

(2) Date of repair 22.1.81

(3) Initials of the Referencer

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

Revenue DEPARTMENT

G.O. No. / B.P. No.	2924	Press. / Mis.
Dated	25.5.1977	197 .

Not to be folded or roughly handled

2924
1

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

15th May No. 27 I.

Irrigation.

A.

Read the following papers :—

No. 52. From Supg. Engineer, Chingleput, dated 16th March 1877, No. 4,415.

No. 52-A. To Supg. Engineer, Chingleput, dated 4th April 1877, No. 32 C N.

No. 52-B. Endorsement of the Chief Engineer for Irrigation, dated Fort St. George, 10th May No. 17 I.

From Colonel F. J. MOBERLY, R.E., intending Engineer, Chingleput, to the Chief Engineer for Irrigation, dated St. Thomas' Mount, 5th May 1877, No. 400.

In reply to memorandum No. 32 C 4th ultimo, I have the honor to report that the water above Kesaveram Anicut

1 Estimate.
2 Plans.
1 Statement.

... ... 204·86 above M.S.L.
elow it ... 204·26 „ „
ven in so bad a year as this.

2. In ordinary years it has been ...raging to the cultivators to see a fine pool of water above the dam lying quite ...ess, for the dam across the Banguru is 1 foot higher than the floor of the Kesave Anicut.

3. I have reason to believe that th...ple interested in the supply have applied frequently for a passage, but have not re...d any attention.

4. It appears from the enclosed st...nt from the Collector that an increase of about Rupees 334 a year will be receive... two villages in the Chingleput District equal to 22 per cent. on the amount of ...te.

5. I would urge early sanction, ...e season is specially favorable for such work

SUBMITTED to Government.

The undersigned is not convinced t...he insertion of a low level sluice vent at the under sluices of the Kesaveram Ani... will appreciably affect the water-supply in the Cortiliar below the weir. There ... present no greater difference, 0·60 foot, between the sub-soil water levels abo... d below the weir than is due probably to the surface slope of water in sand, a... he "fine pool", referred to in the later letter of the Superintending Engineer ... be drawn off to the level of the under sluice sill by the existing vents. H... , as it appears that the Collector and

PUBLIC WORKS DEPART[illegible] MAY 1877, No. 27 I.

Superintending Engineer are both i[illegible] the construction of a low level vent, it may perhaps be considered desirab[illegible]ion the estimate of Rupees 1,780 for the work which it is reported will se[illegible]crease of revenue of Rupees 334.

2. The cost will be chargeable [illegible] Ordinary Agricultural.

(Sig[illegible]OHN MULLINS, Lt.-Col., R.E.,
Chief Engineer for Irrigation.

No. 53.

ORDER THEREO[illegible]ay 1877, No. 27 I.

THE following estimate is sancti[illegible]

ORDINA[illegible]CULTURAL.

[illegible]S.

Original W[illegible]tiliar River.

	RS.
Low level sluice, Kesaveram An[illegible]	1,780

To be carried out by Public Works De[illegible]

2. The work should be provid[illegible]om the District Grant for Minor New Works.

3. This sanction has been regist[illegible]o. 44 I of 1877-78.

(T[illegible]act.)

W. Mullins
Lt.-Col., R.E.,
Joint Secy. to Govt., P.W.D.,
Irrigation Branch.

To the Superintending Engineer, Chinglepu[illegible]
" Collector of Chingleput.
" Chief Engineer for Irrigation.
" Examiner of Public Works Accour[illegible]
" Revenue Department.

2nd 5

Etd. E. C. Shunker.

14 Spare Copies

Revenue Department
№ 2632

IRRIGATION
ACCOUNT.

Cdbl. of 1877 Madras.

PUBLIC WORKS.

To

The SUPERINTENDING ENGINEER
CHINGLEPUT.

Rupees	Annas	Pies

Dated May 1877.

Passed

Rcd. 24th May 77 Exd.

G. O. 15th May 1877, No. 27 P.

Secretary

MAY.

Nos. 52-53.

№ 2924
Comm.r of Lotts
Board of Revenue

25th May 77.

Agreement Amount, Chingleput Division.
The estimated Expense 1,780 for the construction of a low level vent at the under sluice of the Tank mentioned