

(1) Number of pages 5
(2) Date of repair 29.5.81
(3) Initials of the Referencer _____

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

Revenue DEPARTMENT

G.O. No.	4357	Press.
B.P. No.		Mis.
Dated	6.8.1877	197 .

Not to be folded or roughly handled.

List of Irrigation works under the Department of Public Works.

<i>Taluk</i>	<i>Name of works</i>	<i>Amount sanctioned</i>	<i>Date of sanctioning Authority</i>	<i>Remarks</i>
<i>Cumbum</i>	1 <i>Repairing Tadumitha Tank supply channel</i>	320	"	} <i>Adl. Appt. Collector</i>
<i>Do</i>	2 <i>Yamunavallu Catwa Channel</i>	370	"	
<i>Do</i>	3 <i>Tadumitha Tank Head sluice</i>	400	24 Feb'y 1877	
<i>Do</i>	4 <i>" " " " " " " " masonry work</i>	18560	30 August 75	
<i>Do</i>	5 <i>" " " " " " " " " "</i>	1664	"	<i>Adl. Appt. Collector</i>
<i>Marthapur</i>	1 <i>Constructing Tunnels or Dupatta Road</i>	2450	9 Dec'r 1874	<i>Go No 206</i>

Thamrur 3rd July 1877
District Engineer's Office

N. V. A. Goodhat
District Engineer

1st C. P. Kona
Adl. Appt. Collector in charge
Thamrur

[Signature]
District Engineer

[Signature]
CC

Revenue Department

No 3409

Proceedings of the Board of Revenue
dated 21st July 1877.

Read the following

no $\frac{334}{1312}$

From

The District Engineer
Thunroob.

B. & L. R.
no 7896 } To

The Collector of Thunroob

Sir

Adverting to your letter
no 1511 of the 30th June 1877,
requesting an explanation
called for in G.O. no 1999A
dated 15 June 1877)

I have the honor to enclose
a list of works in progress
in the Cumbum & Markapur
Talugs under Departmental
Superintendence

to 75762

Enclosure in 7208.
no 57111 about 100
68901 & 210941/1
no 3409

superintendence. As regards the
Holkuntla Salig, all the
Relief works have been
immediately under the
control of the Dy. Mentor
Peabody, assisted by the
subordinates of the P.W.
Department.

The reason that scale I
is not paid in Chandikottur,
Srinagar, or Pattikonda for
work executed by Relief ^{on irrigation} ^{repairs}
works under the superintendence
of the Department of Public
works is simply, because the
proper percentage of work,
on ordinary District outturn
was not yielded. The
difficulties in the way
of

of procuring the proper
outturn have been great
as pointed out in the report
that accompanied my letter
No. $\frac{320}{1217}$ dated 21 June 1877

District Engineer's office } I have &c
Thumool 327 July 1877 } Jd. M. A. Goodchap
District Eng.

No 639

Submitted to the Board
of Revenue with reference to
their Proceedings dated 26
June 1877 No 9193.

Thumool } Jd. of Thum
Collector's office } Spl. Asst. Collector
11 July 1877 } Incharge

Submitted for the information
of Government with reference
to G.O. No 1999 A 15 June 1877
The

2. The last chief report for
the week ending 7 July shows
no works directly under
the supervision of the D.P.W.
in Kolkumbha & Mankapur.

The higher scale of wages
has been introduced
everywhere under recent
orders.

Stone copy & extract,

Ch. C. L. C.
Ag. Secretary.

To

The Admt. Secy. to Govt. P.D.

with copy of enclosure

D. D. L.
C. M.

9-0-15 1000 3074-300

Dec. 1871 Oct

44061 August 1871 4357

Value - 21

4357

4357

Proceedings of the
Board of Finance

Balance 21st July 1871
Amount 23 11/11

July 6th 1871 a balance
of Coler on letter from
the District Engineer
promoting inspection
entire lot in 8,000
by 1993 of 8 15 June 1871
regarding purchase
of 1000 lbs of
the Public Works
Office in Cambridge
with the on the
amount of the

See Mr. G.

John J. J. J.

025-7-22 30-3-7