

472
2

- (1) Number of pages 4
(2) Date of repair _____
(3) Initials of the Referencer _____

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

REVENUE DEPARTMENT

G.O. No.	472	Press.
~~B.P. No.~~		Mis.
Dated	25-1-1877	197.

Not to be folded or roughly handled

Read the— ing:—
NOR.

No. 226. Note by the Chief Engineer for Irrigation.

THE District Engineer, Cuddapah, forwards, with his letter marginally noted, an estimate in connection with the Chinna No. 2,236, dated 3rd January 1877. Tippasamoodram Reddiacoontah Tank situated in the Madanapully Taluq, Madanapully Range.

2. The nature of the work proposed for execution and the heads of account to which it is chargeable are as follow:—

ORDINARY AGRICULTURAL.

Repairs.

Raising the bund and closing the breach	...	...	...	Rs. 100
			Total ..	100

3. The following particulars of this tank are recorded:—

Ayaut area...	...	...	...	Acre 28	{	Circar 27
						Inam 1
Assessment...	...	...	...	Rupees 59	{	Circar 55
						Inam 4
Average revenue	...	...	...	Rs. 0 12 9	{	Circar 0 12 9
						Inam ...
Highest do.	...	...	...	" 4 0 0	{	Circar 4 0 0
						Inam ...
Expenditure during the previous for	...	...	...	...	...	Not known.

The area of the catchment basin is calculated at 236 cubic feet per second, natural escape 90 feet in length in good discharge.

The tank is situated in latitude 1 and west ends of the bund are very low at the west end, with these exceptions.

The annual average rainfall in the provided with an Irrigation sluice which

The estimate provides for closing the top to be 3 feet and side slopes of 2 to

FORT ST. GEORGE, (S)
10th January 1877.

To the Secretary to Government, Public Works

miles; the maximum flood supply is discharging which as surplus there is a and which is sufficient for the surplus

5", longitude 78° 35' 20". The east short breach 5 yards in length exists is in good order.

rhod is 28.58 inches. The tank is in good order.

and raising the bund, the breadth at is recommended for sanction.

A. DEC. SCOTT, Major, R.E.,
Dy. Chief Engineer for Irrigation,
for Chief Engineer for Irrigation.
sent.

Proceedings of the Madras Government, Public Works Department.
15th January 1877. No. 115.

No. 226-A.

ORDER THEREON, 5th January 1877, No. 115.

IRRIGATION, No. 35.

Account.

CHINNA TIPPASAMOODRAM

THE following estimate from the
Madanapully Range, forwarded by the
District Engineer, Cuddapah, is sanc-
tioned:—

REDDILACCOONTAH TANK.

Group or Project.—

Fund.—Ordinary Agricultural.

Class.—Repairs.

Name of Tank, Canal, or Channel.—Chinna Tippasamoodram Reddilaccoontah Tank.

Particulars of Work.—Repairing bund and closing breach.

Amount.—Rupees 100.

To be carried out by the Public Works Department Officer in charge Madanapully

Range—

Total Rs. 100.

2. This sanction has been registered as No. 261—I. of 1876-77.

(True Extract.)

Major-General, R.E.,
Secretary to Government.

To the District Engineer, Cuddapah.
" Collector of do.
" Chief Engineer for Irrigation.
" Examiner of Public Works Acco.
" Revenue Department.

Exd. E C. Shunker.

1/11 Spare Copies

472

2/2

Revenue Department

No. 773

Govt. of (1877) India

PUBLIC WORKS.

THE DISTRICT ENGINEER

CUTTACK

Dated January 15th.

Issued

Recd. 23

G. O., 18th January 1877, No. 117

JANUARY

Nos. 220-2301.

L:472

communicated to the

25/Jan/77

Chinua Tiprasa...
Tank, Chinua District—The estimate...
Respects 100 for repairs to the...

9 to the Board of Rev. 2/30/77