

(1) Number of pages 8
(2) Date of repair _____
(3) Initials of the Referencer _____

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU
REVENUE DEPARTMENT

G.O. No.	524	Press.
~~H.P. No.~~		Mis.
Dated	27-1-1877	1972

Not to be folded or roughly handled

Read the following:—

No. 31 W.

No. 294.

Note by the Chief Engineer for Irrigation.

The District Engineer, Cuddapah, forwards, with his letter marginally noted, an estimate in connection with the Brahmanapully Kusbah Cheruvoo Tank, situated in the Sidhout Taluq, Sidhout Range.

2. The nature of the work proposed for execution and the heads of account to which it is chargeable are as follow:—

ORDINARY AGRICULTURAL

IRRIGATION.

Original Works.		RS.
Constructing a weir	...	553
Repairs.		
Repairing the bund and weir	...	2,690
Add so as to make the total into a round number	...	7
Total		3,250

3. The following particulars of this tank are recorded:—

Ayacut area	...	{ Circar 97 Inam 40 }	Total 137 Acres.
Assessment	...	{ Circar 508 Inam 217 }	725 Rupees.
Average revenue	...	{ Circar 530 Inam 48 }	578 "
Highest do.	...	{ Circar 564 Inam 46 }	610 "
Expenditure during the previous four years	...	74	"

The area of the catchment basin is 6 square miles; the maximum flood supply is calculated at 1,532 cubic feet per second, for discharging which as surplus there is a weir at the north end of the bund 78 feet in length, this being insufficient to discharge the surplus it is proposed to provide the existing weir with a masonry body wall 80 feet long, and to construct a weir 159 feet in length at the south end of the bund, making an aggregate length of 239 feet available for the surplus discharge.

The bund is low and weak and was breached in 1874, it is proposed to raise and strengthen it, to close the breach, and to extend the bund a length of 200 feet.

The revetment of the front slope of the bund is low, it is intended to raise it and to revet the unrevetted portions.

The estimate provides for the foregoing repairs and improvements.

4. This tank is situated in latitude 14° 35' 0", longitude 79° 14' 0", and is the second of the Gutropally group.

The estimate is recommended for sanction.

(Signed) A. DEC. SCOTT, Major, R.E.,

Dy. Chief Engineer for Irrigation,

for Chief Engineer for Irrigation.

PORT ST. GEORGE,
12th January 1877.

To the Secretary to Government, Public Works Department.

No. 524

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Under date the 29 Jan 77.

Read the following Proceedings of the Board of Revenue:—

Submitting for sanction appoint-
ment of Angara Ramanarasu
to act as Deputy Tahsildar
of Narasannapetah, Ganjam
District

(H. E. 25 January 1877, Mi. no 993

On the recommendation of the Board
of Revenue, ~~the Right Honorable~~ ^{His Grace} the
Governor in Council is pleased to appoint

Angara Ramanarasu
to act as Deputy Tahsildar
of Narasannapetah.

to B. of Revenue }
Auth. G. S. } 2/31/1-
G. S. }
G. S. }

Recd. 1877 Aug
Proceedings of the
Board of Revenue
dated 25 Jan 77
No. 26 :-

7/11/77
10000

Respecting sanction
of grant for the appoint-
ment of Angara
Ramanarasu to
act as Deputy Tahsildar
of Narasannapetah
This is 27 Jan 77
No 524

9.0

Appointment of Captain
Ramonarson to act as
by order of the Government
of the island of
Tahiti

by order

12/11