(1) Number of pages 2 Sheets

(2) Date of repair

(3) Initials of the Referencer

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

Revenue DEPARTMENT

G.O. No. / B.P. No.	6377	Press. / Mis.
Dated	19. 11. 1877.	197 .

Not to be folded or roughly handled.

Archives I—10,006—19-4-79.

GOVERNMEN ADRAS.

PUBLIC WORK EPARTMENT.

10th November , No. 473 I.

Irri on.

Act t.

Read the following paper:—

No. 2 I.

No. 27. *Note by the Chief Er er for Irrigation.*

THE District Engineer, Cuddapah, for rds, with his letter marginally noted, an
No. 1,110, dated 10th August 1877. stimate in connection with the supply
hannel of the Munnoor Kitchumma tank
situated in the Pullumpett Taluq, Sidhout Range.

2. The nature of the work proposed r execution and the heads of account to which it is chargeable are as follow:—

ORDINARY AGRICULTURAL.

IRRIGATION.

Original Works.

	Rs.
Constructing a sluice in the channel bank	35
New stone revetment to the channel bank	535

Repairs.

Closing breach, raising, repairing and extending the channel bank, repacking revetment and gravelling top and rear slope	280
Total...	850

3. The following particulars of this ank are recorded:—

Ayacut area 102 Acres	Circar... ...	27	Acres.
	Inam	75	
Assessment 604 Rupees	Circar... ...	229	Rupees.
	Inam	375	
Average revenue 470 Rupees	Circar... ...	330	"
	Inam	140	
Highest do. 476 Rupees	Circar... ...	283	"
	Inam	193	
Expenditure during the previous four ars		Rupees 820	

Several square miles of th
Kitchumma tank are drained b
tank, and the stream at about or
greater portion of the water into
tank, so that only a portion of t
the Munnoor Kitchumma tank.

At a distance of about 30
above a certain level divides, a po
flows over low ground and esca
Cusbah and Kitchumma tanks, and

To receive the whole of the
Kitchumma tank, a bund was thr
escaped. This bund some years ag
into bad order generally, so that la

The estimate provides for—

(1). Closing breach, raising
repacking the revetment
and gravelling the top a

(2). Constructing an irrigatio

The drainage area of the supply
panied by an index map showing the

From the Chief Engineer for Irri
No. 607, dated 8th March 1877, sanct
tank repairs, &c., the whole drainage
and, as sufficient provision was then m
can be no objection to prevent the spi
its contents into the Kitchumma tank.

And the estimate is accordingly re
mended for sanction.

The body of the irrigation tunnel should be increased in length towards the front as shown on plan.

The following statement shows the proposed distribution of the outlay recommended for sanction to the debit of the several heads of account involved:—

HEAD OF SERVICE—IRRIGATION.

Fund—Ordinary Agricultural.

Name of System or Group	Distinguishing Number or Letter of Group.	Name of Tank or Channel.	De	n of Work.	Main Head.	Class.	Amount of each Item.	Amount to be separately accounted for.
..	..	Supply channel of the Munnoor Kitchumma tank.	C N I	ing sluice .. revetment the channel	Irrigation.	Original Works. Do. Repairs.	Rs. 35 535 280	Rs. 570 280

FORT ST. GEORGE,
27th October 1877.

(Signed) P. MONTGOMERIE, Major, R.E.,
Ag. Dy. Chief Engr. for Irrigation,
for Chief Engr. for Irrigation.

To the Joint Secretary to Government, P

g to the south-west of the Munnoor
nani which flows into the Kitchumma
he tank has an anicut which directs a
ya flowing into the Munnoor Cusbah
wing over the anicut actually reaches

ow the anicut, the water when it rises
ing into the tank, while the remainder
he fields lying between the Munnoor
lost for the purposes of irrigation.

sing over the anicut into the Munnoor
s the low ground over which the water
lly breached and has been allowed to get
been of very little use.

ing and extending the channel bank,
front slope with a portion of new stones,
slope with coarse gravel 3 inches thick.

or sluice in the channel bank.

l is not stated, nor is the estimate accom-
on of the several works and channels.

r's note however which accompanied G.O.,
the estimates of the Munnoor Kitchumma
f this tank is stated to be 9 square miles,
or the disposal of the surplus water, there
the supply channel and turn the whole of

No. 28. ORDER THEREON, 10th

THE following estimates from the Sid
neer, Cuddapah, are sanctioned:—

HEAD OF SERVI
Fund—Ordinar

Supply channel of the M

		Rs.
1	Work—constructing sluice, Origin New stone revetment.	... ... 35 535
2	Repairing channel bank, repairs	 280

To be carried out by the Public Works.

2. These sanctions have been registe

(True E

Major, R.E.,
Under Secy. to Govt., P.W.D.,
Irrigation Branch.

77, No. 473 I.

forwarded by the District Engi-

ION.

ral.

humma tank.

Rs.
... ... 35
... ... 535
... ... 280

t Officer in charge, Sidhout Range.
252 I of 1877-78.

To the District Engineer, Cuddapah.
„ Collector of do.
„ Examiner of Public Works Accounts.
„ Chief Engineer for Irrigation.
„ Revenue Department.

Exd. E. C. Shunker.
Spare Copies

Revenue Dept

No 4829.

DEPARTMENT
ACCOUNTS.

Comm. of Internal Revenue

Special Agents

Collectors

Gaugers, &c.

1 Copy Rec'd

Rec'd & Ref'd Commr Internal Revenue

No. 6377.
Commr. Letter
Board of Revenue
1 Copy Rec'd