

(1) Number of pages 2
(2) Date of repair 6-3-70
(3) Initials of the Referencer _____

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

Revenue DEPARTMENT

G.O. No.	780	Press.
B.P. No.		Mis.
Dated	10. 2. 1877	197 .

Not to be folded or roughly handled

780
1

No. 77. Read the following

Engineer, Kurnool, to

Engineer and Secretary to Government, Public Works Department, dated

Kurnool, 25th January 1877, No. 5:—

A. GOODCHAP, Esq., District

al G. W. WALKER, R.E., Chief

ment, Public Works Department, dated

With reference to G.O. of the 27th September 1876, No. 2,597, paragraph 2, I have the honor to report that the Revenue Department state that it is necessary to close the natural escape of 69 feet on the west end of the Markapur tank, as the discharge from it injures the cultivated land under the tank to the extent of acres 43.57, and that there is no other way of preventing the injury.

2. From my inspection of the tank and surplus channel on the 29th December 1876, I concur in that opinion.

3. The maintenance of the last twenty years, including that provided in the recently sanctioned* estimate for repairs, amounts to Rupees 6,298.

* In G.O., No. 1,370, of 1st June 1876.

4. A copy of a letter* received from the Acting Head Assistant Collector, Kurnool, on the subject is subjoined for information.

* No. $\frac{A}{89}$ of 2nd January 1877.

With reference to your letter* No. 135, dated 23rd October last, I have the honor to inform you that the Tahsildar of Markapur thinks it necessary to close the natural escape at the west end of the bund. The Tahsildar's report† is herein enclosed for your perusal and return. The discharge of water over the cultivated land (acres 43.57) under the tank, preventing this injury than that of closing e erected, in case the escape is closed, to ted.

* Enclosure returned.

† G.O. No. 418, dated 29th November 1876.

escape does no harm to the houses, but injure The Tahsildar says there is no other w the escape finally. He suggests that a sluic admit of the lands under the ceilingula bei

return. The discharge of water over the cultivated land (acres 43.57) under the tank, preventing this injury than that of closing e erected, in case the escape is closed, to ted.

No. 78.

ORDER THEREON, 2nd February 1877, No. 353.

IRRIGATION, No. 7-A.

ORDERED to be recorded.

(True Extract.)

W. Walker

Lieut.-Colonel, R.E.,

Secretary to Government.

To the District Engineer, Kurnool.

„ Chief Engineer for Irrigation.

„ Revenue Department. ✓

Exd. S. T. Austin.

Spare Copies

No. 1207

THE DISTRICT ENGINEER,
KURNOOL

to
to

Dated February 2nd.

From

780

To 10 Febury

to

O. O., 2nd February 1917, No. 353.

To Mr.

FEBRUARY

Nos. 77-78.

713730-11-1917

Markapur Tank, Kurnool District.
Letter from the District Engineer reporting that it will be necessary to close the present escape of —, recorded.

W. 189
C. M. P. to the

No. 1207

THE DISTRICT ENGINEER,
KURNOOL

to
to

Dated February 2nd.

From

780

To 10 Febury

to

O. O., 2nd February 1917, No. 353.

To Mr.

FEBRUARY

Nos. 77-78.

713730-11-1917

Markapur Tank, Kurnool District.
Letter from the District Engineer reporting that it will be necessary to close the present escape of —, recorded.

W. 189
C. M. P. to the