(1) பக்கங்களின் எண்ணிக்கை 26 1988

(2) புதுக்கித் திருப்பிய நாள் டிசம்பர்

(3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 30/9/88

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

வெளியீடுகள் துறை

அரசாணை எண்.
மு. கோப்புத் தாள் எண். 109

அச்சகம்
பலவகை

நாள் : 16 - 1 - 1879 198 .

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

ஆவண. கா-1—18,006—15-6-87.

GOVERNMENT OF MADRAS.

REVENUE DEPARTMENT.

16th January 1879, No. 109.

Famine Relief.

Read the following paper :—

No. 263. Endorsement of the Acting Chief Engineer for Irrigation, dated Fort St. George, 8th January 1879, No. 2-W.

Read the following letter from the Superintending Engineer, Fourth Circle, to Lieutenant-Colonel J. O. HASTED, R.E., Acting Chief Engineer for Irrigation, dated Coimbatore, 19th December 1878, No. 1,046-84. :—

I HAVE the honor to forward, for the sanction of Government from Famine Funds, the estimates (seventy in number) shown in the enclosed list for repairs to irrigation works in the Salem District.

2. Of these works ten belong to the Salem Division, sixty to the Oosoor Division. Of the ten estimates in the Salem, the excess on Nos. 1, 2, 3, and 10 is entirely due to famine, the value of work done being in each case less than the sanctioned estimate.

3. The remaining six estimates were roughly prepared and bore little or no relation to the work required to be done.

4. In the Oosoor Division there are sixty estimates; the first of these is that for the Allalum anicut and channel.

5. The excess expenditure requiring sanction is Rs. 2,110.

The state of the work is as follows :—

	Rs.
Amount of complete estimate at normal rates	9,710
Excess due to famine	2,009
Total Estimate ...	11,719
Amount already sanctioned	2,906
Balance requiring sanction	8,813
Value of work to date	3,007
Excess due to famine	2,009
Total Expenditure ...	5,016

6. The estimate for the completion of this work will be submitted in the ordinary way for sanction when funds are available; the sum required will be Rs. 6,703.

7. The total amount now requiring sanction for this work in the Famine Department is Rs. 2,110.

8. The remaining estimates are divided into eleven groups.

9. Of these the excess of those contained in groups 1, 4, and 9 are entirely due to famine, the actual value of work done being in each case less than the sanctioned estimates.

Proviso 3, 7, and 11 contain estimates which were commenced without sanction under Famine Rules.

Proviso Second 10 comprises estimates which were very roughly prepared in the first instance and bore little or no relation to the actual requirements of the work.

Proviso 9 and 8 contain estimates which were commenced on emergency at the request of the Collector without any previous sanction.

Group 6 comprises eight estimates which were commenced by the Revenue Department and handed over to the Public Works Department upon receipt of orders to that effect.

10. The total amount requiring sanction in the Famine Department for each division is—

		Rs.
Salem Division	... ...	6,813
Coimbatore Division	... ...	18,993

11. The works are all completed or stopped, and completion certificates are being sent in.

ENCLOSURE No. 1.

LIST of Estimates for Famine Relief Works carried out in the Salem District.

Number of Estimates.	Name of Works.	Sanctioned Original Estimates. District Register Number.	Date.	Amount.	Actual Expenditure.	Excess for which Sanction required.	Detail of Charges. Public Works Department.	Famine.	Remarks.
	SALEM DIVISION.								
	Irrigation Works.			Rs.	Rs. A. P.	Rs. A. P.	Rs.	Rs. A. P.	
1	Repairing Karumandaputt'y Karuvandapuram tank,	281	22nd February 1877..	500	531 14 5	31 14 5	408	123 14 5	The excess is entirely due to famine, the value of work done being in each case less than the original sanctions.
2	Repairing Kachirayapur Iyen tank..	81	25th January " ..	300	382 0 11	82 0 11	266	116 0 11	
3	Do. Carupatti Allair	721	31st August " ..	820	1,005 0 0	185 0 0	600	405 0 0	
4	Thorough repairs to Chettieppan new tank ..	217	22nd " 1876..	720	2,137 13 9	1,417 13 9	1,493	644 13 9	The original estimates were roughly prepared and bore little or no relation to the real requirements of the works; hence the excess.
5	Do. to Gangapuramputty Salagan tank ..	87	25th January 1877..	500	1,971 8 6	1,471 8 6	1,189	781 8 6	
6	Do. to Chettiapatti old tank	216	22nd August 1876..	310	1,882 13 4	1,572 13 4	1,339	543 13 4	
7	Do. to Karuppatti Perookkun kottai tank..	283	" February 1877..	200	1,376 1 3	1,176 1 3	1,013	238 1 3	
8	Do. to Kadlanaickcor Elandacottai tank .	327	8th March " ..	450	683 14 [illegible]	233 14 7	636	47 14 7	
9	Do. to Melaputty tank	94	25th January " ..	250	654 8 11	404 8 11	484	171 8 11	
10	Do. to Tattamuttay tank	611	1st August " ..	350	587 6 6	237 6 6	319	268 6 6	Excess entirely due to famine.
			Total ..	4,100	11,213 2 2	6,813 2 2	7,807	3,406 2 2	
	Cauvery Division.								
11	Allalum anicut and distributi	110	27th January 1877 ..	2,000	..	..	..	..	Sanctioned by local authorities in G O, No. 256-I, of 25th March 1878—*vide* remarks in letter.
		892	25th March 1878 ..	906	..	..	..	..	
				2,906	5,016 0 0	2,110 0 0	3,007	2,009 0 0	
12	Repairing Panamputty river channel	137	27th January 1877 ..	250	324 0 0	74 0 0	216	108 0 0	Excess entirely due to famine.
13	Do. Mathampatty tank	680	18th August " ..	174	251 0 0	77 0 0	172	79 0 0	
14	Do. Iryoor Periary tank	124	27th January " ..	150	240 0 0	90 0 0	142	98 0 0	
15	Do. Chinnaiy tank	..	....	..	124 0 0	124 0 0	82	42 0 0	No sanction. Works commenced without estimates.
16	Do. Puram tank	..	....	..	32 0 0	32 0 0	18	14 0 0	
17	Do. Gudiyur Thippampully tank	..	....	..	10 0 0	10 0 0	6	4 0 0	The original approximate estimates bore little or no relation to what was required to be done.
18	Do. Punamangalam tank	481	22nd May 1877 ..	458	1,817 0 0	1,359 0 0	790	1,027 0 0	
19	Do Sarandahully tank	107	27th January " ..	250	987 0 0	737 0 0	492	495 0 0	
20	Do. Kalyanagiri na Puttalamen tank ..	103	" " " ..	200	284 0 0	84 0 0	177	107 0 0	Excess entirely due to famine.
21	Do. Achampudy tank	108	" " " ..	200	236 0 0	36 0 0	116	120 0 0	
22	Do. Perumal Coupum Latchumana Naiken tank.	123	" " " ..	159	222 0 0	72 0 0	133	89 0 0	

List of Estimates for Famine Relief Works carried out in the Salem District—*continued*.

No.	Name of Works.	Sanctioned Original Estimates. District Register Number.	Date.	Amount.	Actual Expenditure.	Excess for which Sanction required.	Detail of Charges. Public Works Department.	Detail of Charges. Famine.	Remarks.
				Rs.	Rs. A. P.	Rs. A. P.	Rs.	Rs. A. P.	
..	Repairing Chinnatholly tank	..	....	..	426 0 0	426 0 0	287	139 0 0	No sanction. These works were undertaken at the request of the Collector on emergency to close breaches.
1..	Do. Karamadai tank	..	....	..	362 0 0	362 0 0	242	120 0 0	
1..	Do. Periyapatty Ratchumanaiken tank ..	..	....	..	297 0 0	297 0 0	201	96 0 0	
1..	Do. do. Muruhanna Cooty tank ..	..	....	..	220 0 0	220 0 0	147	73 0 0	
1..	Do. do. Nagari Cooday tank ..	..	....	..	174 0 0	174 0 0	118	56 0 0	
1..	Pudiyaly tank	..	....	..	145 0 0	145 0 0	104	41 0 0	
19.	Moravoor Madivalum tank	..	....	..	2,596 0 0	2,596 0 0	1,298	1,298 0 0	
1..	Thavesiem tank	..	....	..	1,473 0 0	1,473 0 0	663	810 0 0	
20.	Gopia Bayandoor tank	..	....	..	191 0 0	191 0 0	95	96 0 0	No previous sanction. These works were commenced by the Revenue authorities, and afterwards transferred to the Department Public Works when orders to that effect were issued.
21	Do. Thavayampatty tank	..	....	..	165 0 0	166 0 0	82	83 0 0	
22.	Do. Chetty tank	..	....	..	160 0 0	160 0 0	80	80 0 0	
23.	Do. Kottai Chettypatti tank	..	....	..	129 0 0	129 0 0	81	48 0 0	
24.	Do. Gounderpatty tank	..	....	..	70 0 0	70 0 0	41	29 0 0	
25.	Do. Dasanapuram tank	..	....	..	69 0 0	69 0 0	31	38 0 0	
26.	Do. Oorkaudi Chettypatti tank	..	....	..	28 0 0	28 0 0	16	12 0 0	
27.	Do. Attipallum tank	..	....	..	844 0 0	864 0 0	586	278 0 0	
28.	Do. Ramaswamipatty tank	..	....	..	124 0 0	124 0 0	84	40 0 0	
29.	Do. Badrathalum tank	..	....	..	86 0 0	86 0 0	58	28 0 0	
30.	Do. Thimmanaickenpatty tank	..	....	..	85 0 0	85 0 0	45	40 0 0	
31.	Do. Beranahally tank	..	....	..	55 0 0	55 0 0	38	17 0 0	
32.	Do. Arisampatty river channel ..	..	....	..	50 0 0	50 0 0	34	16 0 0	
33.	Do. Ganganaickenpatty tank	..	....	..	22 0 0	22 0 0	16	6 0 0	
34.	Do. Poolampatty tank	..	....	..	13 0 0	13 0 0	8	5 0 0	
35.	Do. Panampatty tank	..	....	..	11 0 0	11 0 0	8	3 0 0	
36.	Do. Thandal tank	..	....	..	11 0 0	11 0 0	7	4 0 0	
37.	Do. Mullipatty tank	..	....	..	6 0 0	6 0 0	4	2 0 0	
38.	Do. Thippam Cootchi tank	..	....	..	6 0 0	6 0 0	4	2 0 0	
39.	Do. Coolapatty tank	..	....	..	5 0 0	5 0 0	3	2 0 0	
40.	Do. Gungavaram tank	..	....	..	5 0 0	5 0 0	3	2 0 0	
41.	Do. Bethore tank	..	....	..	5 0 0	5 0 0	3	2 0 0	
42.	Do. Lutchumanapuram tank	..	....	..	317 0 0	317 0 0	157	160 0 0	No previous sanction. These works were undertaken at the request of the Collector on emergency in order to close breaches.
43.	Do. Yalachagherry tank	..	....	..	622 0 0	622 0 0	290	332 0 0	
44.	Do. Kothacottai tank	..	....	..	811 0 0	811 0 0	386	425 0 0	
45.	Do. Woodeyadem tank	..	....	..	891 0 0	891 0 0	450	441 0 0	
46.	Do. Thimmapully tank	..	....	..	319 0 0	319 0 0	152	167 0 0	
47.	Do. Thippanore tank	741	2nd February 1878 ..	840	949 0 0	109 0 0	479	470 0 0	Excess due to famine.
48.	Removing prickly-pear on bund of Green Sale tank.	492	18th August „ ..	226	306 0 0	39 0 0	260	105 0 0	
		317	2nd March „ ..	203	351 0 0	148 0 0	236	115 0 0	
49	Repairing Giddamputty Thimmanaiken tank ..	125	27th January 1877 ..	200	224 14 11	24 14 11	153	71 14 11	The original estimates were roughly prepared and bore little or no relation to the requirements of the work.
50	Do. Bayoor Lingan tank	115	„ „ „ ..	120	168 1 2	48 1 2	97	71 1 2	
51	Do. Kaliappa Gounden tank	..	....	..	513 10 7	513 10 7	352	161 10 7	The works were commenced under Famine Rules without sanctioned estimates.
52	Do. Thanasamudram tank	..	....	..	355 6 1	355 6 1	236	120 6 1	
53	Do. Buntharahully tank	..	....	..	11 11 0	11 11 0	8	3 11 0	
54	Do. Thimmapuram tank	..	....	..	637 0 0	637 0 0	431	206 0 0	
55	Do. Thuggapully tank	..	....	..	218 0 0	218 0 0	142	76 0 0	
56	Do. Elathaghery tank	..	....	..	136 0 0	136 0 0	90	46 0 0	
57	Do. Sooriannarayanan tank	..	....	..	124 0 0	124 0 0	83	41 0 0	
58	Do. Othicoopam tank	..	....	..	71 0 0	71 0 0	48	23 0 0	
59	Do. Kooroombaputty tank	..	....	..	43 0 0	43 0 0	28	15 0 0	
60	Do. Pathagaputty	..	....	..					
			Total ..	6,427	24,497 11 9	18,070 11 9	13,793	10,704 11 9	
				4,400	11,213 2 2	6,813 2 2	7,807	3,406 2 2	
				10,827	35,710 13 11	24,883 13 11	21,600	14,110 13 11	

COIMBATORE,
19th December 1878.

(Signed) N. DAVIDSON,
for Supg. Eng. Fourth Circle.

REVENUE DEPARTMENT, 16TH JANUARY 1879, No. 100.

TRANSFERRED to the Secretary to Government, Revenue Department.

(Signed) J. O. HASTED, Lieut.-Col., R.E.,
Acting Chief Engineer for Irrigation.

No. 264. ORDER THEREON, 16th January 1879, No. 100.

Miscellaneous.

THE actual expenditure on the works as detailed in the list submitted with the letter of the Superintending Engineer, Fourth Circle, amounting to Rs. 35,710-13-11, is sanctioned. The sanctions which have been taken on the original estimates appear from the list to be Rs. 10,827 and are cancelled. Of this sum, however, Rupees 2,000 was a sanction locally given for the Allalum anicut. The work to be done with this sum should have been included in the estimate formerly submitted and sanctioned in G.O., P.R. No. 722, dated 19th March 1878, and the sanction seems so far irregular.

2. The sanction to the estimate referred to in paragraph 5 of the Superintending Engineer's letter will, it is observed, have to be reduced by Rs. 3,007, the normal value of the work done for an actual expenditure of Rs. 5,016 now sanctioned.

(True Extract.)

(Signed) G. STOKES.
Addl. Under Secy. to Govt.

To the Chief Engineer for Irrigation, with sixty-nine Enclosures.
„ the Public Works Department.
„ the Financial Department.
„ the Board of Revenue.
„ the Collector of Salem.
„ the Accountant-General.
„ the Examiner of Public Works Accounts.

Ed. T. D. Press

Original

No. 1046/84

Supy. Engineers Office 4th Circle
Coimbatore 19th December 1878

From,
The Superintending Engineer
4th Circle - Coimbatore

To,
The Chief Engineer
for Irrigation D.P.W.
Madras.

Sir,

I have the honor to forward for the sanction of Government from Famine Funds the Estimates (70 in number) shewn in the enclosed list for repairs to irrigation works in the Salem District.

2. Of these works 10 belong to the Salem Division, 60 to the Oossoor Division, Of the ten Estimates in the Salem, the exces on No. 1. 2. 3 and 10 is entirely due to Famine, the value of work done being in each case less than the sanctioned Estimate.

3. The remaining 6 Estimates were roughly prepared and bore little or no relation to the work required to be done.

4. In the Oossoor Division there are 60 Estimates the first of these is that for the Allalum Annicut

and

and Channel.

5. The excess expenditure requiring sanction is Rupees 2110.

The state of the work is as follows.

Amount of Complete Estimate at Normal rates	Rs 9,710.
Excess due to Famine	2,009.
Total Estimate	11,719.
Amount already sanctioned	2,906
Balance requiring sanction	8,813
Value of work to date	3,007
Excess due to Famine	2,009
Total Expenditure	5,016

6. The estimate for the completion of this work will be submitted in the ordinary way for sanction when funds are available. the sum required will be Rs 5,703.

7. The total amount now requiring sanction for this work in the Famine Department is Rupees 2,110.

8. The remaining estimates are divided into 11 groups.

9. Of these the excess of those contained in groups 1, 4, & 9 are entirely due to Famine the actual value of work done being in each case less than the sanctioned estimates

Groups. 2, 7 and 11 contain estimates which were commenced without sanction - under Famine rules.

Groups. 3 and 10 comprise estimates which were very roughly prepared in the first instance, and bore little or no relation to the actual requirements of the work.

Groups. 5 and 8 contains estimates which were commenced on emergency at the request of the Collector without any previous sanction.

Group. 6 comprises 8 estimates which were commenced by the Revenue Department and handed over to the Public Works Department upon receipt of orders to that effect.

10 The total amount requiring sanction in the Famine Department for each Division is.

Salem Division Rs 6813.

Cossoor Division Rs 18,068.

The

10. 11. The works are all completed or stopped and completion certificate are being sent in.

I have the honor to be,

Sir,

Your most obd^t Servant,

H. Davidson

for Supg. Engr. 4th Circle

Revenue Dept

Dec 4/16 Jany 187

B. No. 265

Sheet of Estimates for Revenue Dept. Division Division Division

Name of Works — Division Estimates Charges

Sanctioned Original Estimates — Actual Public Expenditure Sanction Works Remarks

Distribution Works

1 Repairing Harmandu pully Horu-wandapoeram Tank. — 22nd Feb 1877 — 500 — 531 75 — 31 45 408 — 12345 — The excess is entirely due to famine the value of work done being in each case less than the Original Sanction

2 Repairing Kalmera pur Syen Tank. — 81 25 January 1877 — 300 — 382 33 — 82 — 266 — 116 — 11

3 Repairing Kurupatti Alliair — 721 21st August 1877 — 820 — 1005 — 185 — 600 — 405

4 Thorough repairs to Lichettiappanoo Tank. — 22nd Feb 1877 — 217 — 4187 (1720 — 2137 13 9 1417 13 9 1493 — 644 13 9

5 Do — Do — Ijunga puram pully Salagan Tank. — 87 25 January 1877 — 500 — 1971 8 6 1471 8 6 1130 — 791 8 6 — The Original Estimates were wrongly

27	Periyaiya Pettampatty Thegan Cottay Pauk.					Cheaches.
28	Do Andiady Pauk.	174	174	118	56	
29	Do Mariamman Madivalum Pauk.	145	145	104	41	
30	Do Thannimar Pauk.	2596	2596	1298	1298	
31	Do Cotta Parundoor Pauk.	1473	1473	663	810	
32	Do Thevagana patty Pauk.	1912	1912	935	976	No previous mention has been made of these Cheaches
33	Do Vezatty Pauk.	165	165	82	83	appeared by either the present Chachelidar, and Ajthamanadi transferred to the Gl. No. when Cheaches to that effect were issued.
34	Do Kallur Cheddy yeri Pauk.	180	180	58	80	
35	Do Pendigam patty Pauk.	129	129	81	48	
36	Do Vasanajuram Pauk.	70	70	41	29	
37	Do Merigam Cheddy yeri Pauk.	69	69	31	38	
38	Do Attipullam Pauk.	28	28	16	12	
39	Do Ramanaikenpatty Pauk.	844	844	566	278	
40	Do Bodathalum Pauk.	124	124	82	42	
41	Do Thimmalamudrum Pauk.	86	86	58	28	
42	Do Bapanachetty Pauk.	85	85	45	40	
43	Do Arasampatty Periya Cheruvil.	55	55	38	17	No Sanction. The works were Commenced and pursued under Sanction of Sanction Co.
44	Do Thangavelanpatty Pauk.	50	50	34	16	
45	Do Pelyampatty Pauk.	22	22	16	6	
46	Do Pepparapatty Pauk.	13	13	8	5	
47	Do Kandal Pauk.	11	11	8	3	
48	Do Kallipatty Pauk.	11	11	7	4	
49	Do Thippan Cottay Pauk.	6	6	4	2	
50	Do Kottipatty Pauk.	6	6	4	2	
51	Do Thangavaram Pau.	5	5	3	2	

52	Repairing Bellore Tank				317	317	157	160	
53	Do Sulthumana puram Tank				622	622	290	332	No provisions sanctioned, these works being under taken at the request and at the Collectors emergency in order to avoid breaches.
54	Do Pallachagherry Tank				811	811	386	425	
55	Do Kottacottai Tank				891	891	450	441	
56	Do Wanderpolliem Tank				319	319	152	167	
57	Do Thavanthilly Tank	749	2nd Feb 1878	840	949	109	479	470	Excess due to famine.
58	Do Thippanore Tank	682	18th Jan 1878	321	365	37	260	105	
59	Removing Prickly Pear on bund of Greendaikie Tank	311	2nd March 1878	203	351	148	236	115	Excess due to famine
60	Repairing Pyddampetty Thimmanai Tank	125	27th June 1877	220	224 11	24 10	183	71 11	The Original Estimate were carefully prepared & bore little or more relation to the requirements of the works.
61	Do Pagaveragan Tank	115	Do	120	168 12	48 12	97	71 12	
62	Do Thandanadaran Tank				513 10	513 10	352	161 10	
63	Do Kattaikadutty Tank				355 61	355 61	235	120 61	
64	Do Thimmapuram Tank				11	8	5	3	
65	Do Thuggapetty Tank				637	637	415	222	The same remarks as made under Famine Tank estimate.
66	Do Elathagherry Tank				218	218	142	76	
67	Do Soriamarayanan Tank				136	136	95	46	
68	Do Vellicoopan Tank				124	124	83	41	
69	Do Vaiyarumbapetty Tank				71	71	48	23	
	Do Pathagapetty Tank				43	43	28	15	
	Total				6427	2445	1504	1076	9

Eng Engineers Office Circle
Date 19th December 1878

H Davidson
For Superintending Engineer Circle

Enclosure to S.E. 4 Circle No. 1046/84 dated 19 Decr 1878 to the Chief Engineer for Irrigation - Madras

Rev: 19/7/79

List of Estimates for Famine Relief Works Irrigation carried out in Salem District.

Revenue Department
Proceed 16th Jany 1879
Encl in No. 2[illegible]

Rec. 1879. Jany 5th

From No. 197

The Supy Engineer
2nd Circle

To The Chief Engineer
for Irrigation
Madras

Rec. 22 Dec. 78

Dept. Revenue Dept.

Rec. 1878

Dept. Stage } Ag. Chief Engr. & Secy
8th Jany 79

Rec. 9 Jan 79

Proc. 4/16 Jany 1879
B. Pro. 263

No. 1046/84

Dated 19th December 1878

The Supg. Engr. 4th Circle submits herewith the C.E. for Irrigation a list of works for the restoration of irrigation and estimates amounting to Rs. 4870. He was an increase work for which he had without estimate. On the works

Sanctioned expenditure was Rs. 13,517.0.5
Re sanctioned estimate 4870.0.0
Excess requiring sanction 8647.0.5

Of the actual expenditure.
Annual value of estimate 8078.0.0
Excess Famine 6439.0.5
13,517.0.5

The Famine excess was therefore 40 per cent of the expenditure. The sanction here in under.

Estimates were called for as to works for Irrigation from Collectors

And the Supdg Engr. to state that the estimate was annual and the tank was breached during the season of the rains and no allowance for famine was made.

2. That the estimate was annual and was passed at annual value

The annual value of tanks does comprise with the estimate when this was one as follows.

Annual value Rs. 6828
Annual of estimate 4870.
1958

Excess = 40 per cent the estimate

Enclosure

List of estimates for repairs to Irrigation Salem District

Forwards a for sanction in the Famine Department

REVENUE (FAMINE) DEPARTMENT.

No. 7/V.

From Lt. Col. Jn. L.

Dated 8th January 1879.

FOR ORDERS.

With the above endorsement the C.E. Jn. L. transfers Collector's letter from the Superintending Engineer Circle which the tanks under

To estimate for value of expenditure for works situate in the Salem & Coimbatore Divisions of Salem

Division	No. of tanks	Annual value	Actual Expenditure	Excess	Sanctioned Expenditure not required	Excess	Remarks
Salem	10	10	4100.0.0	8213.2.5	16.813.2.5	7500.0.0	9.313.2.5
Coimbr.	60	17	6427.0.0	24.11	30.0.0	13.793.0.0	13.769.11.9
Total.	70		10527.0.0	13.0.5	13.11.21.813.	13.11.21.600.	23.110. 13.11

As the tanks breached during the rains the estimate for restoration

Letter from the Collector

Letter from the Collector

Letter from the Collector

in the case of nine works, to
bad estimating & famine in the
case of four: no explanation is
given in regard to one.
The sanctions in the Salem Divn
all given in order. If the 18 ~~[illegible]~~
sanctions given in the Assoor Divn
13 been in order for 45 works.
then were no estimates or
sanctions in regard to the remaining
work the sanction is shewn at
2906 Rs of this 2000 Rs is sanctioned
locally and 906 on an estimate
submitted to Govt. This is contrary
to the rule that estimates or sanctions
for different parts of the same
work were not to be submitted or
given. The sanction is therefore
really for 906 Rs only. The matter
illustrates the disregard of rule which
largely prevailed in Salem
of the 45 works for which

then were no estimates. 11 works
were undertaken on emergency
remainder the closing of breaches for
14 no estimates were required
in the work cost less than 50 Rs
~~[illegible]~~. Work on 21 was put in
hand without estimates under
"famine rules"

[illegible] 263-264

No. 109
The actual expenditure on the
works as detailed in the list submitted
with the letter of the Supd. Engineer 4th
Circle amounting to Rs 35710-13-11
is sanctioned. The sanctions which have been taken on the
original estimates appear from the
list to be Rs 10807 and are cancelled
of this sum however 2000 Rs was
a sanction locally given for the Allahabad
Circuit. The work to be done with this
sum Rs. have been included in the
estimate formerly submitted and
sanctioned in G.D. F.R. No. 722 dated
19th March 1878 & the sanction herein

FOR ORDERS:

Revenue Depa

Proc of 16 Jany

[illegible] so far unsafe.

2. The Sanction to the estimate referred to in para 5 of the Supt Engr's letter will it is observed have to be reduced by Rs. 3009 the Economical value of the work done for an actual expenditure of 5016 Rs now sanctioned.

16 Jany 1879

[illegible]

69

6 [illegible] for [illegible]

25 [illegible]

[illegible]

[illegible]

[illegible]

[illegible]

9/120

B No 264

[illegible]