

- (1) பக்கங்களின் எண்ணிக்கை 38
(2) புதுக்கித் திருப்பிய நாள் 19 7-88
(3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 109

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

P. W. துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	<u>2421 W</u>	அச்சகம் பலவகை
நாள் :	<u>9-8-1888</u>	<u>108</u> .

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

109

2421
1

9TH AUGUST 1888, No. 2421 W., PUBLIC WORKS.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

READ—the following papers :—

G O., dated 9th July 1888, No. 4013, Revenue.

Read—the following papers :—

Proceedings of the Board of Revenue (Land Revenue), dated 17th May 1888, Mis. No. 3103.

HON'BLE W. S. WHITESIDE.

Read—the following letter from S. H. WYNNE, Esq., Acting Collector of South Canara, to the Secretary to the Commissioners of Land Revenue, dated Mangalore, 7th May 1888, No 1682.

I have the honor to submit, for sanction and the provision of necessary funds, plans and estimates (with their accompaniments) for repairs to the second and third blocks of my office at an aggregate cost of Rs. 15,060, viz. —

	RS.
Repairs to the second or middle block	3,479
Repairs to the third block—	
(1) Sheristadar's Department and Vernacular Records	5,826
(2) Printing Office	5,755
Total ...	15,060

2. A sum of Rs. 34,010 was recently expended for the improvement of the first block of the office under the estimates sanctioned in G.O., dated 29th July 1884, No. 1836 W., and 20th February 1886, No. 416 W., Public Works. The second and third blocks now require repairs and alterations, and these estimates provide for what is necessary at a cost of Rs. 15,060.

3 The roofs of these buildings are in an unsafe condition. The valuable records deposited in a portion of the third block and the press establishment, &c., require to be specially protected. I would, therefore, recommend that the estimates be sanctioned at an early date, and orders given for the execution of the work immediately after the close of the monsoon, arrangements being made in the mean time for procuring materials, &c., so that if the work is once commenced, no interruption may be caused to it on any account. This is necessary, as there will be great difficulty in providing accommodation for the establishment while the work is going on, and the sooner it is finished the better.

4. The only objection I have to the plan is that no covered passage is provided between the second and third blocks, except those communicating direct with the Account Department, so that communication between the Sheristadar's Department and my office room, or the English Correspondence Department cannot take place without

a disturbance to the Account Department. The passage hitherto existing has been removed, as the door leading to it has been replaced by a window (*vide* plan of the second block). I think the verandah should be connected by a passage with the Sheristadar's block (No. 3). This can probably be done out of "contingencies," and I have not thought it necessary to return the estimates.

Resolution—dated 17th May 1888, Mis. No. 3103.

The plans and estimate for Rs. 15,060 for executing repairs and improvements to the Collector's office at Mangalore are submitted for the early sanction of Government.

2. The necessity for the works is explained in para. 3 of the above letter. The office consists of three separate blocks of buildings, all of them apparently old and much dilapidated. The first block was virtually reconstructed between the years 1883 and 1886, at a cost of Rs. 34,010 (*vide* G.O., 29th July 1884, No. 1836 W.), the second and third blocks are now to be taken in hand, at a cost of Rs. 15,060, the work, as will be seen from the specification report, enclosure No. 8, being chiefly re-roofing.

3. It is observed that the estimates have not been countersigned by the Collector as required by para. 988 of the Public Works Code.

4. In para. 4 the Collector suggests that a covered passage should be provided between the second and third blocks, so that communication between the Sheristadar's Department and his own office may be made easier. This may be sanctioned. The charge, he says, can probably be met from the Rs. 683, provided in the estimate for contingencies, and may be approved.

(A true Copy and Extract)

(Signed) H. A. SIM,
Acting Secretary.

Proceedings of the Board of Revenue (Land Revenue), dated 11th June 1888, Mis. No. 3560.

Read—the following letter from S. H. WYNNE, Esq., Acting Collector of South Canara, to the Secretary to the Commissioners of Land Revenue, dated 25th May 1888, No. 1942:—

With reference to para. 3 of Board's Proceedings, dated 17th May 1888, No. 3103, I have the honor to point out that the papers before the Board were copies and not the original estimates. The latter were duly countersigned and returned to the Executive Engineer. The copies forwarded were, I believe, marked below as—

"(Signed) F. J. WILSON, Executive Engineer," and

"(Signed) S. H. WYNNE, Acting Collector."

The Superintending Engineer's signature at foot merely testified to the correctness of the copy.

Resolution—dated 11th June 1888, Mis. No. 3560.

Recorded.

(A true Copy and Extract.)

(Signed) H. A. SIM,
Acting Secretary.

Order—dated 9th July 1888, No. 4013, Revenue.

The plans and estimates are approved and transmitted to the Public Works Department.

2. With reference to para. 3 of the Collector's letter embodied in the first of the papers read above, it will be considered in the Public Works Department whether funds cannot be provided for carrying out the repairs and improvements estimated for during the coming dry season, at least so far as the third block of the Collector's office, which appears to be particularly in need of repair, is concerned.

3. It is observed that the plans have been countersigned by the head-quarters Deputy Collector for Collector. This does not seem to be a proper compliance with the rule

(True Extract)

(Signed) H. A. STUART,
Under-Secretary to Government.

Note by the Chief Engineer, Public Works Department.

The estimate, amounting to Rs. 15,060, for improvements to the second and third blocks of the Collector's office at Mangalore, is submitted for the sanction of Government with the following remarks:—

- (1) The plans submitted do not give as much information as they should.
- (2) No details of wood-work are submitted
- (3) The beams and uprights allowed for supporting the pulins are clumsy. A queen-post truss would probably serve the purpose better and look more workmanlike.

(Signed) J. O. HASTED, Colonel, R.E.,
Chief Engineer, Public Works Department.

4th August 1888.

ORDER—dated 9th August 1888, No. 2421 W., Public Works.

The estimate, amounting to Rs. 15,060, for improvements to the second and third blocks of the Collector's office at Mangalore, in the South Canara District, is sanctioned.

2. No funds are available with the Government at present, and, if the Superintending Engineer cannot propose a re-appropriation from the grants for other works in the Circle, he will apply for an allotment later in the year.

3. Attention is drawn to the Note by the Chief Engineer, Public Works Department, above recorded.

4. The sanction accorded in para. 1 of these Proceedings has been registered as Provincial No. 61 W. of 1888-89, and classified as Civil Buildings, Original Works.

(True Extract.)

Captain, R.E.,
Under-Secy. to Govt., P.W.D.

To the Superintending Engineer, IV Circle, with six enclosures
" Examiner, Public Works Accounts.
" with the duplicate general abstract estimate
" Revenue Department

Ed F R Lambman
Spur Office

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of (1888) Madras.
PUBLIC WORKS.

Dated August, 9th.

Recd.

Encl.

G.O., 9th Aug. 1888, No. 2421 W.

AUGUST.

Collector's Office at Mangalore

Estimate for improvements to the second and third blocks of the —, South Canara District, sanctioned with remarks.

No 249.

West Coast Division Office

Lachadi, 21st April 1888.

From,

Colonel A. J. Fraser, R.E.

Executive Engineer,

West Coast Division.

To,

The Superintending,

Fourth Circle, D. P. W.

Sir,

I have the honor to state in reply to your No. 141 W.C. of the 13th March 1888, that the Collector's Office at Mangalore consisted of 3 separate blocks of Buildings. One was so greatly dilapidated it had to be entirely reconstructed at a cost of Rs. 34,000 between the years 1885 and 1886. The other two are old, but the improvements now estimated are likely to make them last out, and not require any renovation for a long period. The whole of the accommodation is necessary and more if departmental officers such as the Head Assistant Collector and the Local Fund Engineer who now have their offices elsewhere were brought into the Buildings. The rooms and their mode of occupation in the 3 blocks are as follows:—

Block No 1 Reconstructed

In lower story

2. Rooms 18' x 16' are occupied by the Account Department.

2. Rooms 18' x 16' for spare room and Local Fund furniture.

1. Room 34' x 20' by the Assistant Collector.

1. Room 19' x 14' by the Cash-keeper.

1. Room 15' x 14' by the Police guard.

1. Room 34' x 10' as passage for Patrol.

1. Room 18' x 10' as lumber room for empty cash chests.

1. Room 29 1/2' x 25 1/2' for stationery and printed forms.

2. Verandahs.

In upper story

1. Room 18 1/2' x 16 1/2' for Head Clerk and Record Keeper.

1. Room 40 1/2' x 16 1/2' for English Records.

1. Room 60 1/2' x 16 1/2' for English Correspondence Department.

1. Room 26 1/2' x 20' for Forest Officer and Establishment.

1. Room 26 1/2' x 23 1/2' for Forest Officer's records.

Block No. II

Lower Story

1. Room 19 1/2' x 21 1/2' is occupied as 'book-keeping' room. These two rooms are intended for the permanent use of the office.

By the way, the main part of the building is not a permanent structure but is a temporary one. It is built of brick and is very strong. It is built on a foundation of concrete and is very strong. It is built on a foundation of concrete and is very strong.

1. Room 24 1/4' x 21 1/2' for Local Fund Audit, trade and share records.

1. Room 15 1/2' x 33 1/4' by Treasury Deputy Collector.

1. Room 45 3/4' x 8 1/2' as passage and stair case room.

1. Room 36 3/4' x 11' front verandah.

Upper story

2. Rooms 22' x 10' and 24 3/4' x 20' by collector with verandahs on 2 sides, containing 2 small retiring and bath rooms also.

Block No. III

Lower Story

1. Room 50' x 34' as record room.

1. Room 20' x 24 7/8' as record keepers' Room.

1. Room 35' x 24 7/8', Sheristandan's Office, verandah, accounts and correspondence.

1. Room 17 7/8' x 30' Printing Office.

1. Room 17 7/8' x 30'

1. Room 23 1/2' x 30' as lumber room.

1. Room 9 1/2' x 31' store room.

1. Room 9 1/4' x 18' waste paper room.

1. Room 8 1/4' x 18' do do

1. Room 16' x 9 1/2' Bath room for preparing glue, washing types and damping papers etc.

1. Enclosed verandah for Compositors, and 2 open verandahs on either side of

Memorandum office

I have recd.

(Signed) H. T. Fraser, Col. R. E.,

Executive Engineer,

West Coast Division

(True copy)

(Signed) J. Beatty, Col. R. E.,

Supg Engineer, 4th Circle

(True copy)

D. Munn

For Acting Collector.

Compd
A.D.

25/5/88
J. Beatty

No. 142
m

Supg Engineer's Office 4th Circle

Camp Cotacamund 25th April 1888

From

The Superintending Engineer, 2nd/₂
Fourth Circle.

To

The Collector of
South Canara,
Mangalore.

Sir,

I have the honor to forward for
transmission to Government, for sanction, two

Enclosures 7
2 Plans
1 Estimate
2 General Abstracts
1 Specification Report
1 Copy of a letter No
249 dated 21st April
1888 from Executive
Engineer, West Coast Divn

plans and an estimate
amounting to Rs 15,060
prepared at your request
for improvements to the
second and third blocks
of the Collector's Cutcherry
at Mangalore. A speci-

fication report and a general abstract of the
estimate in duplicate are also herewith attached

2. You are aware that the first block
of your office was so greatly dilapidated that
it had to be entirely reconstructed at a cost
of Rs 34,010 between the years 1883 and 1886,
and the improvements now estimated are to
the 2nd and 3rd blocks.

3. The specification report fully details
the

4
34 32/88
Rev.

the several works proposed to be carried out.
4. I send herewith also for your
information copy of the Executive Engineer's
letter No 249 of 31st instant which explains
how the different rooms of the 3 blocks
will be occupied.

I have to
Signed / J. Keatty, Col: R. E.
Supg. Engineer, 4th Lungle...

(True Copy)

D. M. M. M.

For Agricultural Collector

Comd

H. P.

N^o 1682

SOUTH CANARA COLLECTOR'S OFFICE,

c. Mangalore,

7th May 1888.

From

S. H. Nynne, Esquire,

Acting Collector of South Canara

To

GOVERNMENT OF INDIA, 1592 C. 150,

THE SECRETARY TO THE COMMISSIONERS OF

Land Revenue,

Madras

Si

I have the honor to submit, for sanction

- 2 Plans.
- 1 Estimate.
- 2 General Abstracts
- 1 Specification Report
- 1 Copy of letter N^o 249,
of 21st April 88, from Executive
Engineer, West Coast Divⁿ.
- 1 — do — N^o 142 dated
25th April 1888 from
Engineer, 4th Class.

and the provision of
necessary funds, Plans
and Estimates (with
their accompaniments)
for repairs to the
second and third
Blocks of my office,

at an aggregate cost of Rs 15,060,243 -

Repairs to the second or
middle Block — 3479

— do — to the third Block:—

(1) Sheristadar's Dept^t
and Vernacular Records — 5826

(2) Printing Office — 5755

15,060

2. A sum of Rs 34,010 was recently ex-
pended for the improvement of the first
block of the office under the Estimates
sanctioned in G. O. dated 29th July 1884, N^o 1836W
and 20th February 1886, N^o 416 W. P. W. on
the second and third blocks now require
repairs

in 6
9/10/1888

repairs and alterations and these Estimates provide for what is necessary, at a cost of Rs 15,000.

3. The roofs of these buildings are in an unsafe condition. The valuable records now deposited in a portion of the third block and the Press Establishment require to be specially protected. I would therefore recommend that the Estimates be sanctioned at an early date and orders given for the execution of the work immediately, after the close of the monsoon, arrangements being made in the mean time for procuring materials, so that if the work is once commenced no interruption may be caused to it on any account. This is necessary as there will be great difficulty in providing accommodation for the establishment while the work is going on, and the sooner it is finished the better.


4. The only objection I have to the plan is that no covered passage is provided between the second and third blocks except those communicating direct with the Account Department so that communication between the Sheristadar's Department and my office room, in the English

24/5 '11
English Correspondence Department cannot take place without a disturbance to the Account Department. The passage hitherto existing has been removed, as the door leading to it has been replaced by a window (vide Plan of the second block). I think the Verandah should be connected by a passage with the Sheristadar's block (N^o 3). This can probably be done out of "Contingencies," and I have not thought it necessary to return the Estimates.

I have the honor to be,
Sir,

Your most obedient servant,

J. P. [Signature]
For & by Collector



2421/9

Proceedings of the Board of Revenue

(Land Revenue).

Dated 17 May 1888.

No. 3103. Mis

Honorable Mr S Whitcomb.

READ Letter from the Collector of South Canara, dated 7th May 1888. No 1682.

Resolution

The plans and estimates for Rs 15000 for executing repairs and improvements to the Collector's office at Mangalore are submitted for the sanction of Government.

2. The necessity for the work is explained in para 3 of the above letter. The office consists of 3 separate blocks of buildings, all of them apparently old and much dilapidated. The first block was virtually reconstructed, between the years 82 and 86 at a cost of Rs 34010, vide G O 29 July 84, 1836 W. The second and third blocks are now to be taken in hand, at a cost of Rs 15000: the work, as will be

seen

seen from the specification report. enclosure has
been chiefly a roofing.

3 I've observed that the estimates have
not been countersigned by the Collector as required
by para 985 of the Public Works Code

4 In para 4, the Collector suggests that a
covered passage should be provided between the
second and third blocks so that communication
between the two buildings and his
own office may be made easier & this may be
sanctioned. The charge, he says, can probably
be met from Rs 683, provided in the estimate
for contingencies and may be approved.


For Extract

By Secretary

The Secy to Govt R.D. with

letter & the 8 rules & a copy of the same.

Collector of South Canara.



Proceedings of the Board of Revenue

(Land Revenue).

Dated

11th June.

1888.

No.

3560

Mis

READ

The following letter from the Collector of South Canara
dated 28th May 1888 No 1942

With reference to para 3 of Board's
Proceedings dated 17th May 1888 No 3103 I have the
honor to point out that the papers before the Board
were copies and not the original estimates. The
latter were duly countersigned and returned to the
Executive Engineer. The copies forwarded were I believe
marked below as "Signed J. J. Wilson Esq Engineer" and
"Signed J. H. Wynne Esq Collector". The Superintending
Engineer's signature at foot merely testified to the
correctness of the copy.

Resolution :

Recorded

(True copy and extract)

By Secretary

The Collector of South Canara
Copy - to the Secretary to Government R.D.
in continuation of Board's Proceedings 3103 of 17th May 1888

have been countersigned by me



PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read Proceedings of the Board of Revenue (Land Revenue) dated 17th May and 11th June 1888 Nos. 3103 and 3560 this respectively.

Order thereon, 9th July 1888 No. 4013.

The plans and estimates are approved and transferred to the Public Works Department.

2. With reference to para 3 of the collector's letter embodied in the first of the papers read above, it will be considered in the Public Works Department whether funds cannot be provided for carrying out the repairs and improvements estimated for, during the coming dry season, at least so far as the third block of the collector's office, which appears to be particularly in need of repair, is concerned.

3. It is observed that the plans have been counter-signed by the

head-quarters deputy collector for collector. This does not seem to be a proper compliance with the rules.

(True Extract)

H. Altham

Under Secretary, to Govt.

2nd 12/2/84

5/1

To

The Public Works Deptt. with Encls.

Comms of Land Rev.

Q. 11/1/84. 20. 2. 86

Q. 11/1/84. 29. 7. 84

8/2

11/1/84
11/1/84
11/1/84

11/1/84

Note by the Chief Engineer 4/1/84

The estimate amounting to Rs. 15,000, for improvements to the second and third blocks of the collector's office at Mangalore is submitted for the sanction of Govt. with the following remarks:-

- (1) The plans submitted do not give as much information as they should.
- (2) No details of woodwork are submitted.
- (3) The beams and uprights allowed for supporting the purlins are clumsy. A queen post truss would probably serve the purpose better and look more workmanlike.

11/1/84
11/1/84
E. W.

Current No. 6976.

Letter No. 4213

Dated 9th July 1888

From the Secy. to Govt. P.W. Dept.

NOTE OF REMARKS.

The estimate under
series amounting to
Rs 15,000 provided for
the repair and improvement
of the Collector's office
at Mangalore in the
South Canara Dist.

The estimate is
divided as follows

Repairs to the 2nd
or middle block Rs 34,49
- do - to the 3rd
block comprising

- (1) Structures, steps
and common
works. Rs 8,826
- (2) Printing office. Rs 755.

Total Rs 15,000

It is explained that
an estimate amounting
to Rs 34,810 was sanctioned
for the improvement
of the 1st block in the 2nd
in 1886 or 29 July 84.
The following is a
list of the work

1075 8/11/88

proposed to be carried out:

- 1 Dismantling and re-constructing the existing traps and floorings with partly new making.
- 2 Repairing and renewing doors and windows where necessary.
- 3 Painting doors and windows and wood siding roof timbers for
- 4 Washing the interior and exterior washing the exterior of the building.
- 5 Reconstructing and re-constructing cracked or defective walls.
- 6 Providing additional windows, doors, and anchorages where necessary with the object of giving more light and ventilation & other minor repairs and improvements.

The following rates are in excess of those given in the last schedule.

For the Curran Sub ²⁴² 1/2

- 1 Repairing with Curran Sub B-11, in 100 ft against B-2, 8-11 in the Schedule.
- 2 Cut stone work B-4-11 against B-3-8-11.
- 3 Paving with flooring tiles in Curran sub 9" of concrete B-2-11 for 2 1/2' against B-18-11 on 4" of concrete. The quantity for 9" of concrete is not apparent.

If this was of the Curran Sub B-11 and adopted then will be a saving of Rs 70 in the estimate which is hard to worth retaining in an estimate of Rs 15,000.

Pity information and consequences are charged for at 5 p.m. each each.

In brief: in the
 Revenue Dept: in
 approving and transmitting
 the plan and estimate
 to this Dept: remarks
 that the plan had
 been countersigned
 by the land quarter
 mag: instructing the
 Collector, and that
 it had not been so
 in a proper compliance
 with the rule.

P.M. letter June 9.88
 says from the mag: that
 the plan & Est.
 should be countersigned
 by the Collector.

The Collector in his
 letter No 1682 of 7th July 88
 suggests that a covered
 passage be provided
 between the 2nd & 3rd
 blocks the cost of
 which may be
 met from the
 amount provided
 for contingencies.

Encl: 25/7/88

Yours in the dept with

The plan has been
 noticed in the Rev
 Dept. & need not be
 further noticed in
 the Rev Dept.

Cue 6976

To S. J.

25/7/88

These estimates have
 passed through the Supply
 Engrs' Office, for they were
 forwarded to the Collector
 with Colonel Beatty's
 letter No 142 of 25.4.88.

In view
 of this

The two copies
 of General abstr: estimate
 bear Colonel Beatty's
 countersignature,
 but he apparently
 omitted to counter-
 sign the plans by
 oversight.

The Collector
 says that he counter-
 signed the original
 estimate - the two
 fair copies submitted
 are marked "Signed
 S.H. Wynne". He too
 apparently omitted
 by oversight to
 countersign the

plans in the first in-
stance, & they were
afterwards signed for
him by his Dr. Collect.

The matter has
been noticed by the
Rev. Board, & the Rev.
Super of Govt.

In these circum-
stances, it may
perhaps be con-
sidered unnecessary
to return the papers
to the S.D.

The points which
with respect to wood
works might be
embodied in a note
by the Ch. Engr., to
accompany the S.D.
on the estimate.

Yrs if S.W.
abundant
S.

Ce
23.7.88

S. Fox

Engr.

6.4.9.88

and in the last note

2421
16

These estimates don't
appear to have passed
through Engineer's
office or in any way been
approved of by him. a
proceeding which I presume
is necessary - the Mectis
actual signature to the
estimate plans is in
my opinion a necessary
point - there is nothing to show
that the Collector really
approves of what is
proposed - & Revenue
officers are seldom satis-
fied with alterations
once the alterations
are completed.
The plans submitted
don't give as much
information as they ought.

207
The details of woodwork
are submitted.

The beams supports -
allowed for supporting
the joists are clearing
a Queen post truss would
probably serve the purpose
better & costing less here
~~work would~~
work as well as -

The estimate I think
he returned to H.
for his remarks.

J.D.

2/17.

Emory

found in the old book

PROCEEDINGS OF THE MADRAS GOVERNMENT.

L. & R. G. D. Ho.

Read the following

Proceedings of Govt Revenue Deptt N. No. 4013 of 19 July 1888
 Note by the Chief Engineer P. W. D.

The estimate amounting to Rs. 15,000, for improvements to the second and third blocks of the Collector's Office at Bangalore in the South Canara District, is sanctioned. No funds are available with the Govt at present, & if the Suptg. Engineer cannot propose a reappropriation of funds from the grants for other works in the district, he will apply for the same later in the year.

3. Attention is drawn to the note by the Chief Engineer, P. W. Department above recorded

4. The sanction accorded in para 1 of these Proceedings has been registered as Provincial No. 61 W of 1888-89 and classified as Civil Buildings, Original Works

To The Suptg. Engrs. The Circle with bundles
 " Examined of P. W. Deptt with the
 duplicate general abstract estimate
 " Revenue Department

24/7
 25/7

24/7
 25/7

24/7
 25/7

11/1/12

11/1/12
11/1/12

11/1/12

of the 2411 W
Collection of pieces
Manganese
=

Plims to be improved
to the second and third
blocks of the — South
Canal R.R., connected
with the canal.