M.R.O. 14—10,000—21-4-22.

MADRAS RECORD OFFICE.

Government of Madras.

Revenue **DEPARTMENT.**

G.O. No. 629	**Press** ~~**Mis.**~~
323. 324	
Dated	18 - 3 - 1861.

Not to be folded or roughly handled

Proceedings of the Madras Government, Revenue Department,
18th March 1861.

No. 323. Read the following letter from Lord H. ULICK BROWNE, Under Secretary to the Government of India (Home Department), to J. D. BOURDILLON, Esq., Secretary to the Government of Fort Saint George, dated Fort William, 5th March 1861, No. 470:—

SIR,

In reply to your letter No. 431, dated 23rd ultimo, I am directed to state that the Governor General in Council is pleased to sanction the grant of waste land assessed at Rupees 60 per annum in endowment of the Choultry erected by Muttumári Sanyási Chetti at Nakkapilli in the District of Vizagapatam, the land being selected from the waste lying in the Government Táluq of Sarvasiddi.

———

No. 324. ORDER THEREON, 18th March 1861, No. 629.

Ordered to be communicated to the Board of Revenue with reference to their Proceedings, dated 28th January 1861, No. 469.

(Signed) C. G. MASTER,
Deputy Secretary to Government.

R 685/61

In No 6653 of 1860
In Cons 18th Decr 4

R 270/61.

18 March
C of C 629 -
323-324

Estimate of the Gattrum Erected by Motamurri Sanasiretty at Narsapally in Narsapally Taluq in Vizagapatam District

No.	Measurement Length ft.	Breadth ft.	Height ft.	Square Contents ft.	Cubic Contents	Particulars	Rate	Rupees	Amount	Total
1	68	2½	2½			98 1/2	Calculation to find compartments of the principle Building.			
7	9	2½	2½			393 3/4	Do. to Partition walls of Do.			
1	9	2¼	2½			50 5/16				
1	16 1/4	1¾	3			86 2 5/16	Do. to Front Veranda of Do.			
3	4¼	2¼	2½			71 11 1/16	Do. to the walls of Veranda rooms &c.			
1	21¼	1¾	2½			180 7/16				
1	21	1¾	2½			91 2/8	Do. to Rear Veranda &c.			
1	37	1¾	2½			162 7/8				
1	77½	2½	2½			484 3/8	Do. to sidewalls of the rear compartment for Bramins			
1	64½	2½	2½			403 1/8				
5	9¼	2½	2½			289 1/16	Do. to Partition walls of Do.			
3	50¼	2½	2½			94 2 7/16	Do. to the sidewalls of the end compartments of Do			
1	62	2½	2½			387 1/2				
5	9	2½	2½			281/4	Do. to Partition walls of Do			
2	9½	2½	2½			118 3/4				
1	77	1¾	3			404 1/4	Do. to rear Veranda leading to the compound attached to Bramins compartment.			
1	45¼	1¾	2½			180 2 7/16	Do. to Veranda of sides of the court attached to Bramins compartment.			
2	38	2	2½			380				
2	4¼	2½	3			65 3/4	Do. to Partition walls of the rear Veranda rooms			
3	4¼	1¾	3			56 15/16				
1	51	2½	2½			318 3/4	Do. to sidewalls of the cook houses in Bramins compound			
1	51	2¼	2½			286 7/8				
1	6	2½	2½			37 1/2	Do. to Partition walls of Do			
4	6	2¼	2½			135				
1	31½	2½	2½			197 5/8	Do. to Principle walls of the cook houses attached to the Rajahs and Comatties Compartment.			
1	31½	2¼	2½			177 3/16				
1	27	2½	2½			168 3/4				
1	23¾	2¼	2½			130 124/16				
1	16½	2¼	2½			92 13/16				
1	4¾	2½	2½			29 11/16				
1	4¾	2¼	2½			80 2 5/16	Do. to Partition walls of Do.			
3	4¾	2¼	2½			118 1/8				
4	5¼	2¼	2½			210 15/16	Do. to 2 Verandahs of Do.			
1	37½	2¼	2½			303 3/4				
1	54	2¼	2½			281 1/4	Do to Partition wall dividing the Compartments of Rajas and Sudras.			
1	45	2½	2½							
1	70¾	2½	2½			442 5/16				
1	70¾	2¼	2½			397 15/16				
1	81½	2¼	2½			458 7/16	Do. to Principle walls of cook houses of Sudras Compartment.			
1	52	2½	2½			325				
1	47	2¼	2½			264 3/8				
5	6	2¼	2½			168 3/4				
4	4¼	2¼	2½			95 5/8	Do. to Partition walls of Do.			
4	5¼	2½	2½			131 1/4				

1	121/4	2	3	"	"	127 1/2	Lge.	A Piece Coal flour & matts					
1	59	2	3	"	"	35 1/4							
1	46	2	3	"	"	276	Lge.	A Q. Oar Cotton matts					
								Piece Coal flour					
1	163 3/4	2	1/2	"	"	491 1/4		Patent mark & brand Corn flour Twine &c					
1	15 7/2	2	1/2	"	"	472 1/2		Piece A.S. Cotton					
1	9/2	2	1/2	"	"	189 1/2	Lge.	A.S. Oar Cotton matts 9 Lge					
1	163 3/4	1 3/4	2 1/2	"	"	24 15/16							
3	14 3/4	1 3/4	2 1/2	"	"	511/16	Lges	A Frank Pleasbank 9 Age					
1	20 3/4	1 1/2	1	"	"	62 5/16	Lge.	A Cotton matts 9 Age					
1	20 1/2	1 1/2	1	"	"	61 1/8							
1	37 1/2	1 1/2	1	"	"	30 1/4	Lge.	A Cotton Canvas 9 Age					
1	77	2	1	"	"	57 1/4							
1	64	2	1	"	"	154	Lge.	A Victoria 9 Age					
5	9 3/4	6	1	"	"	128		Twill dyed Pin stripe					
3	50 3/4	2	1 1/4	"	"	97 1/2	Lge.	A.S. Oar Cotton					
1	62 1/2	2	1 1/4	"	"	380 5/8	Lge.	A Age matts 9 Age					
5	9 1/2	2	1 1/4	"	"	158 1/4		marked Age.					
2	10	2	1 1/4	"	"	118 3/4	Lge.	A.S. Oar Cotton					
2	41 3/4	1 1/4	1	"	"	59							
2	38 1/2	1 1/2	1	"	"	57 3/16	Lge.	A Victoria 9 Age					
1	51	1 3/4	1	"	"	115 1/2		Attached A Twill Piece 9 Ste Coral					
								Twill Piece Cow Flour					
3	6 3/4	1 3/4	1	"	"	89 1/4	Lge	A Victoria 9 Ste Cork Square in Ste					
								Twill Piece Cow Flour					
						57 16	Lge.	A.S. Oar Cotton matts 9 Age					
1	31 1/2	2	1	"	"	63							
1	27	2	1	"	"	54	Lge	A Piece Coal flour & matts					
1	2 3/2	1 3/4	1	"	"	44 5/8		Attached A Ste Pin stripe Coal flour					
1	17	1 3/4	1	"	"	29 1/4		Cow flour twill					
1	5 1/4	2	1	"	"	10 1/2							
3	5 1/4	1 3/4	1	"	"	27 9/16	Lge.	A.S. Oar Cotton matts 9 Age					
4	5 3/4	1 3/4	1	"	"	40 1/4							
1	37/2	1 3/4	1	"	"	65 5/16	Lge	A 9 Pleasbank 9 Age					
1	5 1/4	1 3/4	1	"	"	95 3/8							
1	45 1/2	2	1	"	"	91	Lge.	A.S. Oar Cotton matts Stamped					
								Ste Cork marked in the Pin stripe					
1	71 1/4	2	1	"	"	142 1/2							
1	71 1/4	1 3/4	1	"	"	124 11/16	Lge.	A.S. Oar Cotton matts 9 Coral					
1	81 1/2	1 3/4	1	"	"	142 10/16		Square 9 Ste Stamped Cork Square					
1	52 1/2	2	1	"	"	105							
1	47	1 3/4	1	"	"	82 1/4							
5	6 1/2	1 3/4	1	"	"	57 7/8							
4	4 3/4	1 3/4	1	"	"	93 1/4	Lge.	A.S. Oar Cotton matts 9 Age					
4	6	1 3/4	1	"	"	42							
						185 99/16		Carried Forward			1 8	Qrs.	1033 4 7

Brought over.

2	157	1½	9½	"	"	4474½	Sidewalls above of the front compart-ment of the Principle Building.
5	10	1½	11½	"	"	862½	
2	10	1½	9½	"	"	285	Partition walls above of Do.
1	10	1¼	11½	"	"	143 3/4	
1	5¼	1¼	9½	"	"	62 5/16	
2	5¼	1¼	7¼	"	"	95 2/16	Walls above of front Verandah rooms.
2	6½	1¼	4	"	"	65	
1	76½	1½	9½	"	"	1090½	Sidewalls above of the rear compart-ment for Ryamins.
1	63½	1½	9½	"	"	903 7/8	
1	10¼	1½	9½	"	"	146 1/16	
4	10¼	1½	11½	"	"	707¼	Partition walls above of Do.
2	51¼	1½	9½	"	"	1460 5/8	
1	43¼	1½	9½	"	"	673 5/16	Walls above of the end compartments of Do.
5	10	1½	11½	"	"	862½	
2	10½	1½	9½	"	"	299¼	Partition walls above of Do Do.
2	5¼	1½	9½	"	"	149 5/8	
3	5¼	1¼	7½	"	"	147 5/8	Partition walls above of the rear Verandah rooms.
1	29	1¼	5	"	"	181¼	Sidewall above of Do Do
1	51	1½	9½	"	"	726¾	Sidewalls above of the cook houses in the Ryamins compound
1	39½	1¼	5½	"	"	271 9/16	
1	7	1½	8	"	"	84	Partition walls above of Do. Do.
1	7	1¼	8	"	"	70	
1	31¼	1½	9½	"	"	455 5/16	
1	26	1¼	5½	"	"	178 3/4	Principle walls above of the cook houses attached to the Rajas and Coomaties Compartment.
1	26½	1½	9½	"	"	377 5/8	
1	23¾	1½	5½	"	"	191 13/16	
1	17½	1¼	5½	"	"	120 5/16	
1	5 3/4	1½	8	"	"	69	
3	5 3/4	1¼	8	"	"	172½	Partition walls above of Do. Do.
4	6¼	1¼	8	"	"	250	
1	71 3/4	1½	9½	"	"	1022 2/16	
1	62½	1¼	5½	"	"	429 11/16	Principle walls above of the cook houses of Cudras compartment.
1	48	1¼	5½	"	"	330	
1	48	1½	9½	"	"	684	
1	32	1¼	5½	"	"	220	
6	7	1¼	5½	"	"	288 2/4	
5	5¼	1¼	5½	"	"	180 7/16	
5	6½	1¼	5½	"	"	223 5/16	Partition walls of Do. Do.
1	5¼	1½	9½	"	"	53 1/16	
1	46	1½	9½	"	"	653½	Partition wall above dividing the Compartments of Rajas and Cudras.
1	120¾	1½	9½	"	"	1720 11/16	Rear Compound wall above
1	59½	1½	9½	"	"	847 2/8	
1	46½	1½	9½	"	"	662 5/8	Partition wall above dividing rear Compound
						22901 15/16	
						4076 15/16	Leonet for doors & Windows.
						18825	or 697-6 Cyd.s of Burnt Brick in Clay.

1033 4 7

14 - Cyd.s 871 8 5

1904 13 0

Brought Over.

											1904	13
1	1129½	1½	1½	-	-	2541 3/8	Filling in the interstices between the rafters of the Building					
1	543	1¼	1½	-	-	1018 1/8						
1	360	1½	1½	-	-	810	Casing the door frames to prevent them from being injured from Whitewash					
1	120¾	1½	2½	-	-	452 13/16	Coping Rear Compound wall					
1	59½	1½	2½	-	-	223 1/8						
1	46½	1½	2½	-	-	174 3/8	Coping to Pantiles dividing rear Compound					
						5219 13/16 or 195-8 13/16	Cyd. of Brick in Lumamba-	2 - -	Cyd.		380	10 4
1	190	1½	1½	-	-	427½	Plaster Archwork over the doors.					
1	154	1¼	1⅛	-	-	216 9/16	Circular Archwork to entrance of cook houses					
						644 1/16 or 23-23 1/16	Cyds of Brick in Lumamba					
			355	25			Square of Plastering Principle Building with one Coat in Lumamba	2 6.	Lds		50	10 5
								1 6.	Sq.		488	7 6
			124	75			Lds. of Flooring with Roughstone Brick Jelly &c in Lumamba (including Plastering)	2 10.	Lds		327	7 6
1	553¾	1	-	5	5 3/4		Facing the Basement of Veranda					
1	189	1	-	1	89		Flooring at door ways.					
				7	40¾		Square of Cutstone in Lumamba	7 8.	Lds		55	8 10
8	"	"	"	"	"		Cutstone Pillars one foot in diameter and 10 feet high to open shed in Brahmins and Rajas Compartments.	4 8.	each		36	. .
22	"	"	"	"	"		Cutstone Pillars ¾ ft in diameter and 4½ ft high to front Veranda of the Principle Building					
28	"	"	"	"	"		Cutstone Pillars ¾ ft in diameter and 6 ft high to the interior Veranda of Brahmins Compartment					
8	"	"	"	"	"		Ds. Ds. to the rear Veranda of Brahmins Compartment.					
20	"	"	"	"	"		Ds. Ds to the interior Veranda of Rajas and Comatties Compartment					
4	"	"	"	"	"		Ds. Ds. to the interior Veranda of Sudras Compartment.					
3	"	"	"	"	"		Ds. Ds. to the exterior of end Veranda of Sudras Compartment.					
87	"	"	"	"	"		Total Pillars.	3 . .	each		261	. .
"	"	"	"	92	20	"	Squares of roofing with country wood timbers king Posts, Ridge Poles, Palmyrah rafters, reepers, mixed Palmyrah & Bamboo, teakwood eaveboard, nails, and Pantiles including Chunam borders.	12 8.	Sq.		1152	8 .
											4669	1 7

							Brought over					4669	1 7
-	"	"	"	38	83½		Squares of roofing with country wood, Bamboo rafters, teakwood ekeboard, nails and Pantiles including chunam borders	10	. .	Sq.	388	5 8
6	4½	6½	"	"	"	"	Pairs of teakwood Battened doors, hinges &c complete.	20	. .	each	120	. .
17	4	6	"	"	"	"	Do.	Do.					
3	2½	5	"	"	"	"	Do.	Do.	15	. .	Do	272	. .
2	3½	5½	"	"	"	"	Do.	Do.	10	. .	Do.	30	. .
2	3½	5¼	"	"	"	"	Do.	Do.	14	. .	Do.	28	. .
6	3	4½	"	"	"	"	Do.	Do	13	8	Do	27	. .
							Pairs of Teakwood Battened Windows, hinges, Iron bars &c Complete.	20	. .	Do	120	. .
							Excavating foundations &c	.	. .		100	. .
							Excavating 2 Wells.	-	. .	-	100	. .
2	36½	1½	36			3900	Casing Do. with cutstone					
2	36	1	3	.	-	216	Parapet wall above					
						4116	or 152-12 Cyds of cutstone in Chunam					
2	90	2½	3	"	"	1440	Foundation to ex walls to detached Building for Christians & Mahomedans	6	8 .	Cyd.	990	14 3
1	15	2½	3	.	.	112½						
1	11	2½	3	"	.	82½						
1	9	2½	3	"	-	67½	Do. to Cross walls of Do					
1	28½	2½	3	"	.	213¾						
2	100	2	3	"	.	1200	Do. to front & rear Verandahs					
1	23	2	3	"	.	138	Do. to end Verandah to Christians compartment.					
2	4½	2½	3	"	"	54						
2	4¼	2	3	"	"	51	Do. to Walls of Verandah rooms					
3	5¼	2	3	"	.	94½						
2	57¾	2	2	.	.	462						
1	54½	2	2	"	.	218	Do. to Compound wall					
2	13	2	2	"	.	104						
1	7½	4	3	.	.	90	Do. to Steps at the entrance of Christians Compartment.					
2	96½	2	2	"	"	772	Basement to Sidewalls to detached Building for Christians & Mahomedans					
1	14½	2	2	.	.	58						
1	11½	2	2	.	.	46						
1	9½	2	2	.	.	38	Do. to Cross walls of Do.					
1	28	2	2	"	-	112						
2	100	1½	2	.	.	600	Do. to front & rear Verandahs					
1	23½	1½	2	.	.	70½	Do. to end Verandah to Christians Compartment.					
2	5	2	2	.	.	40						
2	4¾	1½	2	.	"	28½	Do. to Walls of Verandah rooms					
3	5¾	1½	2	.	"	51¾						
						6144½	or 227-15½ Cyds of Rough stone in Cunamboo	18	.	Cyd.	341	5 9
2	24	1½	10½	"	"	756	Sidewalls above					
2	71	1½	9½	"	"	2023½						
											7186	11 3

Brought Over 7186 11 3

2	12	1/2	10/2	-	-	378	Cross walls above					
2	10	1/2	9	-	-	270						
2	7 1/4	1/4	6 3/8	-	-	115 7/16						
3	6 1/2	3/4	7 3/8	-	-	102 13 3/16						
2	8 3/4	1/2	7 7/8	-	-	147 15 1/2 /16						
1	10 1/2	3/4	4 1/2	-	-	35 5/16	Walls above & Verandah rooms.					
1	6	3/4	4 1/2	-	-	14 1/4						
1	7 1/2	1/4	5 3/4	-	-	53 14 1/2 /16						
1	6 1/4	1/4	5 3/4	-	-	44 14 3/4 /16						
2	5	1/4	8 1/8	-	-	101 9/16						
1	5 0 3/4	1/4	4	-	-	28 3 3/4						
1	5 5 1/2	1/4	4	-	-	27 1/2	Compound wall above					
2	14	1/4	4	-	-	140						
1	4 5	1/4	4	-	-	22 5						
						4974 14 /16	Deduct for doors and Windows.					
						840 14 2 /16						
						4134	or 153-3 Cyds of Burnt Brick in clay.	1 4 -	Cyd.	191	6	3
1	135 1/4	1/2	1 1/2	-	-	304 5/16						
1	23	3/4	1 1/2	-	-	25 2/8	Pulling in the interstices between the rafters					
1	18 3/4	1/4	1 1/2	-	-	35 2 2 /16						
1	5 0 3/4	1/4	1	-	-	70 15/16						
1	5 5 1/2	1/4	1	-	-	69 3/8						
2	14	1/4	1	-	-	35	Coping to Compound wall					
1	4 5	1/4	1	-	-	36 1/4						
2	2	2	6 3/4	-	-	54	Gate Piers.					
						325 1/16	Casing the door frames being injured from Whitants.					
						705 15 1/2 /16	or 26 - 3 15 1/16 Cyd. of Brick in Cunnamba	2 - -	Cyd.	52	4	8
-	-	-	-	23	35		Square of flooring with coyketoon and Brick jelly in Cunnamba (including Plastering)	2 10 -	Sqr.	61	4	8
-	-	-	-	65	50		Yd. Plastering the Christian and Mahomedans Compartments.	1 6 -	Yd.	90	1	-
				2	25		Yd. of Cutstone in Cunnamba for facing the Verandah	7 8 -	Yd.	16	14	-
27	-	-	-	-	-	-	Cutstone Pillars 3/4 foot in diameter and 6 1/2 ft. high to Verandah	3 - -	each	81	-	-
				11	80	-	Square of roofing with the Christian compartment Country wood Palmyrah rafters, rupees, teakwood cuboard, nails and flat and Pantiles including Chunam borders.	18 - -	Sqr.	212	6	5
				22	20	-	Square of roofing the Mahomedan Compartment with country wood Palmyrah rafters, rupees, nails and Pantiles including Chunam borders.	12 8 -	Sqr.	321	14	4
2	4	7/2	-	-	-	-	Pairs of teakwood Venetian doors.	22 - -	each	44	-	-
1	3/2	6/2	-	-			Yd. of Panelled door	16 - -	Yd.	16	-	-
6	3	5	-	-			Yd. of Venetian windows.	16 - -	Yd.	96	-	-
1	3	5/2	-	-			Yd. of Panelled door	12 - -	Yd.	12	-	-
2	2	3	-	-			Yd. of Yd. Windows.	5 - -	Yd.	10	-	-
							Excavating foundations	- - -	-	30	-	-
1	82	2/2	3	-	-	615	Foundation to sidewalls of Bazar					
1	79 1/2	2/2	3	-	-	596 1/4						
7	9 1/2	2/2	3	-	-	498 3/4	Yd. to Partition walls of Yd					
1	79 1/2	2	3	-	-	477	Yd. to front Verandah of Yd					
2	4	2	3	-	-	48	Yd. to Walls of Verandah rooms of Yd					
										8421	14	7

Brought over. 8421 14 7

1	81½	2	2¾	"	"	448¼	Basement to sidewalls of Lr.					
1	79½	2	2¾	"	"	437¼						
7	9½	2	2¾	"	"	365¾	Dr to Partition walls of Dr.					
1	79½	1½	2¾	"	"	327⅝	Dr. to Verandah of Dr.					
2	5¼	1½	2¾	"	"	43 5/16	Dr. to Walls of Verandah rooms.					
						3857½	or 142-23½ Cyds of Roughstone in Cumanbu	1	8	Cyd	214	4 6
2	81	1½	9	"	"	2187	Sidewalls above					
7	10½	1½	10	"	"	1902½	Partition walls above					
2	6	1¼	6½	"	"	97½	Walls of Verandah rooms above					
1	5½	1¼	4¼	"	"	29 3½/16						
5	10½	¾	3½	"	"	137 13/16	Building Partition walls at the roof					
						3554 32/32	Deduct for doors & Windows.					
						416 23/32						
						3138	or 116-6 Cyds of Burnt Brick in clay	1	4	Cyd	145	4 5
2	81	1½	7	"	"	1701						
5	12	¾	1½	"	"	67½	Filling in the interstices between the rafters.					
2	10½	1½	1½	"	"	45						
2	6	1¼	1½	"	"	22½						
1	5½	1¼	1½	"	"	10 5/16						
						161 5/16	Casing the door frames being injured from White ants.					
						2007 5/8	or 74-9 5/8 Cyds of Brick in Cumanbu	2	"	Cyd	148	11 5
							2½ Cyds of Brick in Cumanbu for Arch work over the doors	2	6	Cyd	5	15 "

"	"	"	"	11	69½		Squares of flooring with Roughstone and Brick jelly in Cumanbu including Plastering	2	6	7 Sqr	29	10 6
"	"	"	"	39	"	"	Dr. of Plastering the walls of Bazar (exterior and interior)	1	6	" Dr	53	20 "
12	"	"	"	"	"	"	Cutstone Pillars 3/4 ft in diameter and 5¾ ft high to front Verandah of Bazar	3	"	" each	36	" "
"	"	"	"	20	25	"	Squares of roofing the Bazar with Country wood, Palmyrah rafters, reepers, teakewood eveboard, ridge and Pantiles including Cumanbu borders.	12	8	" Sqr	253	2 "
6	3½	5½	"	"	"	"	Pairs of Battened doors, Iron fixtures &c Complete.	14	"	" each	84	" "
1	2½	4½	"	"	"	"	Dr.	8	"	" Dr	8	" "
							Excavating foundations.	"	"	"	10	" "
							Excavating tank cashew in Survey Pl Can 10,000 Cubic yards of Earthwork.	"	1	" Cyd	625	" "
											10035	8 5

Brought over . . . 10035 8 5

Supplying Canoe to Tank . . . 167 - -

Total . . 10202 8 5

Vizagapatam District
Golgondah Range
Superviser's Office
Camp at Narsipatam
23rd October 1860

Signed
Cole

Approved
[illegible]

M. Bevan Agent
Superviser D.P.W.
Golgondah Range

Copied
[illegible] 6655 of 1862

Section and Elevation of the N.

Section of the O P

Section of the R S

CHURCH
Erected by the Cambridge
Camden Society
A.D.
MUCKAPILLY
1841
V.D

Plan of Church and Premises

10202 & 5

Rec'd

Rec'd

Ra 685/61.

323 & 324

1861

№ 470

From

Lord H. Ulick Browne

Under Secy. to the Govt of India

To

J. W. Boisdillon Esqre

Secretary to the Govt. of

Fort St George

Dated Fort William the 5th March 1861.

Dept.

Sir,

In reply to your letter № 431 dated 23d Ultimo I am directed to state that the Governor General in Council is pleased to sanction the grant of waste land assessed at Rs. 60 per annum in Endowment of the Choultry erected by Muttoomaree Sanyasee Chetty at Nakkapilly in the District of Vizagapatam - the land being selected from the waste lying in the Government Talook of Sarvàsiddee -

I have the honor to be,

Sir,

Your most obedient Servant,

Ulick Browne

Under Secy to the Govt of India

R- 25th February 61 No 347 348

28-6-20

Recd the 18th Sept.r
Pro: of Govt for March
No 685.

No 629.

From
The Under Secy to
the Govt of Madras
Dated 5th March
Recd 14th 1861
Letter
No 470-

Sanction the grant
of waste land assess-
ed at 80.60 per annum
in endowment of the
Choultry erected by
Muttoonaree Sanyasee
Chetty at Rakkapilly
in Vizagapatam.

No 629.

Ordered to be commu-
nicated to the Board of Revenue
in reference to their Proceedings
dated 28th January 1861 No 169.-

Lieut Col Lees:
18th March 1861.

CJW

13 Copies to the Board of Revenue. Disp.d 19.

No 323 & 324.

With an Order
No 629. 18th March